

CITY CAB PTE LTD

REPAIR ESTIMATE*

CHINA

VEHICLE NO : SHC 3617R

DATE 16/10/2018 14:11

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille <i>X</i>			\$ 251.00
	Radiator Grille H Emblem <i>X</i>			\$ 27.50
	Front Bumper Cover <i>/</i>			\$ 544.50
	Front Bumper Grille, LH <i>X</i>			\$ 41.60
	Front Bumper Bracket Top (LH) <i>?</i>			\$ 22.40
	Front Bumper Bracket (LH) <i>/</i>			\$ 24.60
	Headlamp (LH) <i>X old damage</i> <i>cm</i>			\$ 1,388.00
	<i>front LH fender x repair</i>			
	SUB TOTAL			\$ 2,299.60
	LESS 20%			\$ 459.92
	DISCOUNTED TOTAL			\$ 1,839.68
	Front Fender Advertisement Logo (LH) <i>/</i>			\$ 100.00 Nett
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 220.00 <i>200</i>
	Spray Painting Charge			\$ 440.00 <i>400</i>
	Wiring			\$ 30.00 <i>X</i>
	Tuff Kote			\$ 50.00 <i>X</i>
	TOTAL LABOUR			\$ 740.00
	ESTIMATE TOTAL			\$ 2,679.68

Kelvin (UKK)
M
16/10/18 1505hr
2 Pgs
4/5
After Repair photo

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.