

Repair Estimate

Date : 17/10/2018

To Whom It May Concern

Reference:

Make:

Opel
Grandland

Dear Sir,

RE: VEHICLE .: SLZ 8700G**CHASSIS NO.: W0VZRHNY4JS163871****ENGINE NO.: 10XTA41017924**

Name of insured .: Loh Chen Leong Gabriel

Date of accident.: 14/10/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

<u>No.</u>	<u>Qty</u>	<u>Part Description</u>	<u>Price (SGD)</u>
<u>1</u>	1	Rear Bumper Lower(Black)	1,888.00
<u>2</u>	1	Rear Bumper Sill Plate	442.00
<u>3</u>	1	Rear Bumper Absorber	141.00
<u>4</u>	1	Rear Bumper Reinforcement Bar	781.00
<u>5</u>	1	Rear End Panel	854.00
<u>6</u>	1	Rear End Panel Reinforcement	578.00
<u>7</u>	1	Rear End Panel Trim	295.00
<u>8</u>	1	Rear Tailgate	2,742.00
<u>9</u>	1	Rear Tailgate with Windscreen Moulding	924.00
<u>10</u>	1	LHR Tailgate Lamp	545.00
<u>11</u>	1	RHR Tailgate Lamp	545.00
<u>12</u>	1	LHR Taillamp	520.00
<u>13</u>	1	LHR Bumper Upper	754.00
<u>14</u>	1	LHR Bumper Reflector	73.00
<u>15</u>	1	RHR Taillamp	520.00
<u>16</u>	1	RHR Bumper Upper	754.00
<u>17</u>	1	RHR Bumper Reflector	73.00
<u>18</u>	1	Opel Logo	132.00
<u>19</u>	1	Grandland X Lettering	204.00
<u>20</u>	1	Turbo Lettering	110.00
<u>21</u>	1	Rear Bumper Centre Bracket, Guide	310.00
<u>22</u>	1	LHR Bumper Bracket, Guide	227.00
<u>23</u>	1	RHR Bumper Bracket, Guide	227.00
<u>24</u>	1	LHR Lower Bumper Bracket	107.00
<u>25</u>	1	RHR Lower Bumper Bracket	107.00
<u>26</u>	1	Left Rear Bumper Air Ventilator	63.00
<u>27</u>	1	Left Rear Bumper Air Ventilator Panel	212.00
<u>28</u>	1	RH Rear Bumper Air Ventilator	63.00
<u>29</u>	1	RH Rear Bumper Air Ventilator Panel	212.00
<u>30</u>	1	Reverse sensor - Inner	220.00

31 1 Reverse sensor - Outer

274.00

Parts Total: \$14,897.00
Less 10%: \$1,489.70
Total : \$13,407.30

Labour

<u>No.</u>	<u>Labour Description</u>	<u>Price (SGD)</u>
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	2800.00
2	Carry out spray painting on accident affected area. (Rear Bootlid, Rear Bumper, Rear End Panel & Rear spare tyre panel)	2100.00
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	250.00
4	Transfer of parts from old bootlid to new bootlid	180.00
5	Remove and replace reverse sensor (Labour)	80.00
6	To remove and refit rear windscreen	180.00
7	To remove and refit cushion upholstery to facilitate repair	180.00
8	Carry out reseal rear number plate (OPC)	120.00

Labour Total : \$5,890.00

Other


<u>No.</u>	<u>Other Description</u>	<u>Price (SGD)</u>
1	Rear bumper clip set	70.00
2	Tail gate inner trim board clip set	60.00
3	Rear number plate	45.00

Other Total : \$175.00

Total : \$19,472.30
Gst (7%) : \$1,363.06
GRAND TOTAL: \$20,835.36

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully,



Service Advisor
Ronnie Tan

DID: 6844 1985 Fax: 6844 5185