

ASS. REC. BY:

REF:

CS/FCI18018897/ Asd3

Special Instruction:

Surveyor:

CWS

Adrian

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time:

4:21pm @ 17/10/18

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SDY 2233C

Insured:

SH 8278X

at Workshop m/s

MG solution

Tel:

67444165

of

23 kaki Blk Ave 4 #02-03

Policy No:

Claim No:

D18007399MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09/10/2018

CA / REV / REP. / REV 24 HRS

lwp

18/10/18

H.O.D. Endorsement:

Date/Time:

4:33pm @ 17/10/18

Person Contacted:

Sharon

Vehicle:

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SDY 2233C - NA/AIG/18018412/r3

DoA: 9/10/2018

SH 8278X - NA/AIG/18018412/r3

DoA: 9/10/2018

22/10/18

@ 14:29 p.m. revert pending estimate from reporter to Eileen Lee via email

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SDY2233C Yr Regn: 2011 Augst.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 523i

O.C. 2497

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading:

159099

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBAFP320X0C867258

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40R19

R:

245/40R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

18/10/18

Survey held at

MG Solution

Des. of Damages: Frt / Rear / O/S / (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

02/11/18

TP 1st Cap.
Confirmed L/S \$6,400/- @ 5 days with Adrian.
(\$15,861.04 Red - 71%)
MV: 60K.
PV: 49.4K
Nett: 10.6K.

RECEIVED 02 NOV 2018

MV - 60,000/- , LTA - 49,393.00 , NETT = 10,607.00

Date/Time, File Pass to?

02/11/18
Typst

: Preli. Report



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation

\$ + P5 \$

Photo

Cost

TOTAL

13x15 = 195

170 + 195

50

50

44

509

Report Format:

Lump Sum / I.B.I. (\$

6,400/- L/S

MOTOR SURVEY ASSIGNMENT

Date	11-10-2018	Our Ref No. D18007399MFSH
Accident Date	09-10-2018	Claim Type. Third Party
Insured Vehicle	SH8278X	Third Party Vehicle. SDY2233C
Survey Location	23 KAKI BUKIT AVE 4 AAS KAKI BUKIT CENTRE#02-03	
Contact Person.	JAMIE YAN	
Contact No.	67444165/ 0	Fax No. 67444604
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MG SOLUTION PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 22 October 2018 2:29 PM
To: 'Eileen Lee'; 'CWS Motor Claims'
Cc: 'assignments'; 'SUR'; 'Admin-D (LKKAuto)'
Subject: RE: SURVEY ASSESSMENT - D18007399MFSH/1

Dear Eileen,

Please be informed that we have inspected the vehicle SDY 2233C on 18/10/2018.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 17 October 2018 4:38 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007399MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 17 October 2018 4:24 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007399MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

**Cheap Car Insurance Renewal**

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)
New 5 Years Coe Renewal Honda Stream 1.8A

\$2000 Downpayment Monthly
From \$638 Onwards. Lowest
3.18% P.A. @ Gv Cars Financing
GV Credit Pte Ltd - StarAd



- Free VICOM evaluation
- Free grooming and 8 months maintenance
- In-house workshop ensures quality service
- Member of SVTA and hire purchase association
- 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

[Save Search](#)[Print](#)[Back \(1 2 \) Next »](#)

Sort by Date Posted

20 results/page

32 vehicles

Search 5 Series 523i[Advanced Search](#)[Search](#)[View All](#)

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection	5 Series 523i	Any	Any	2011	Any	Any	Any	Available
------------------	---------------	-----	-----	------	-----	-----	-----	-----------



☐	BMW 5 Series 523i	\$63,000	\$14,860 /yr	28-Jul-2011	2,497 cc	74,000 km	Luxury	Available
--------------------------	-------------------	----------	--------------	-------------	----------	-----------	--------	-----------

Luxurious And Spacious, Low Mileage Done! Beautiful On Brown Dakota Leather. Very Well Maintained! Superb Condition! 100% Accident-Free. Owner Rebuilt A Lot Of Accessories For Next Buyer. Owner Loss I...

DIRECT OWNER

☆ Posted: 03-Oct-2018 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW



☐	BMW 5 Series 523i	\$59,800	\$13,730 /yr	29-Jul-2011	2,497 cc	119,000 km	Luxury	Available
--------------------------	-------------------	----------	--------------	-------------	----------	------------	--------	-----------

Come With M-Body Kit, 19" M-Rims, M-Exhaust, Superb Condition, Accident Free, PML Unit, Regularly Service/Well Maintained, Flexible Loan Available. Oscars Auto

☆ Posted: 17-Oct-2018 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW



☐	BMW 5 Series 523i	\$59,000	\$12,950 /yr	31-Aug-2011	2,497 cc	125,000 km	Luxury	Available
--------------------------	-------------------	----------	--------------	-------------	----------	------------	--------	-----------

Superb Condition And Lovingly Handwash By Owner Weekly. Servicing From Day 1 By BMW Authorized Agent, Performance Motors With Full Service Record. WiFi Front/Rear Camera. Good Fuel Efficient. Don't M...

DIRECT OWNER

☆ Posted: 10-Sep-2018 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW



☐	BMW 5 Series 523i	\$60,888	\$13,490 /yr	09-Sep-2011	2,497 cc	113,888 km	Luxury	Available
--------------------------	-------------------	----------	--------------	-------------	----------	------------	--------	-----------

PML Unit, 2nd Owner, Nice Bidded Number, Accident Free, Free Road Tax, Legal Tinted Film, Well Maintained And No Repair Required, Service Records Provided, Black Leather Seats, Drive Away Condition, S...

DIRECT OWNER

☆ Posted: 16-Aug-2018 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW

**Audi MIB2 System With Apple CarPlay**

Audi MIB2 System with Apple CarPlay & Andriod Auto

[More info about this product](#)

☐	BMW 5 Series 523i	\$60,800	\$13,760 /yr	13-Sep-2011	2,497 cc	99,500 km	Luxury	Available
--------------------------	-------------------	----------	--------------	-------------	----------	-----------	--------	-----------

1 Owner Non-Smoker Car. Accident Free. Fully Serviced By Juzz For Cars Since 1st Day Until Today With Genuine Mileage. We Don't Charge Admin Fee. 1 Year Engine Gearbox Warranty. New "SME" Car Number. ...

PREMIUM AD

☆ Posted: 14-Oct-2018 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW



☐	BMW 5 Series 523i	\$58,000	\$12,310 /yr	29-Sep-2011	2,497 cc	126,000 km	Luxury	Available
--------------------------	-------------------	----------	--------------	-------------	----------	------------	--------	-----------

1 Owner Since New, Last Svc At Agent On June 2017. Addition Feature Comfort Access, Driving Modes Selection, Rear Electric Boot, High ARF \$43,442. Most Of The Wear And Tear Parts Replaced, No Oil Leak...

☆ Posted: 18-Oct-2018 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW



☐	BMW 5 Series 523i Highline	\$63,800	\$13,530 /yr	30-Sep-2011	2,497 cc	-	Luxury	Available
--------------------------	----------------------------	----------	--------------	-------------	----------	---	--------	-----------

\$0 Driveaway Scheme. 1 Owner, From \$2800 Monthly. 100% Accident Free, Low Mileage Done. Full Service Record. Call Now! High Trade-In Available For All Makes. Please Contact Our Friendly Salesperson Fo...

Privilege Motors Pte Ltd

☆ Posted: 18-Oct-2018 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW

SHORTLISTED HISTORY

[Compare](#)

☐	BMW 5 Series 523i Highline	\$62,800	\$12,960 /yr	30-Sep-2011	2,497 cc	105,000 km	Luxury	Available
--------------------------	----------------------------	----------	--------------	-------------	----------	------------	--------	-----------

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8032A
Vehicle Details	
Vehicle No.:	SDY2233C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Oct 2018
Vehicle Make:	B.M.W.
Vehicle Model:	523i 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Primary Colour:	Grey
Manufacturing Year:	2011
Engine No.:	08127819N52B25AF
Chassis No.:	WBAFP320X0C867258
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$48,836.00
Original Registration Date:	31 Aug 2011
First Registration Date:	31 Aug 2011
Transfer Count:	1
Actual ARF Paid:	\$48,836.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2021
PARF Rebate Amount:	\$29,301.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$70,117.00
COE Rebate Amount:	\$20,092.00
Total Rebate Amount:	\$49,393.00

The information contained herein is correct as at 18 Oct 2018

OK

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO : FIRST CAPITAL DATE : 17/10/2018
ATTENTION : MOTOR CLAIMS DEPT JOB TYPE : T/P CLAIM
ESTIMATE REPORT :

VEHICLE DETAILS

VEHICLE NO : SDY2233C

MODEL : B.M.W. 523i

Shirley.

CHASSIS NO

WBAFP320x0c867258

ACCIDENT DETAILS DATE : 9-Oct-18
TIME : 14:30HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR <i>Dented</i>	1	\$ 1,688.90	\$ 1,688.90
2	REAR FENDER <i>Repair</i>	1	\$ 1,988.70	\$ 1,988.70
3	REAR FENDER INNER COWLING <i>New</i>	1	\$ 190.80	\$ 190.80
4	REAR LOWER ARM LH <i>New</i>	1	\$ 620.00	\$ 620.00
5	REAR UPPER ARM LH (FRONT) <i>Best</i>	1	\$ 830.30	\$ 830.30
6	REAR UPPER ARM LH (REAR) <i>Best</i>	1	\$ 711.30	\$ 711.30
7	REAR SWING ARM LH <i>New</i>	1	\$ 685.00	\$ 685.00
8	REAR KNUCKLE ARM LH <i>2nd</i>	1	\$ 1,150.30	\$ 1,150.30
9	REAR SHOCK ABSORBER LH <i>1st</i>	1	\$ 890.40	\$ 890.40
10	REAR LINKAGE LH <i>New</i>	1	\$ 233.60	\$ 233.60
11	REAR WHEEL HUP LH <i>2nd</i>	1	\$ 580.30	\$ 580.30
12	REAR WHEEL HUP BEARING LH <i>New</i>	1	\$ 360.00	\$ 360.00
13	REAR DRIVESHAFT <i>New</i>	1	\$ 2,350.30	\$ 2,350.30
14	REAR WINDSCREEN MOULDING <i>New</i>	1	\$ 222.30	\$ 222.30
15	REAR BUMPER <i>ton</i>	1	\$ 1,855.30	\$ 1,855.30
16	REAR BUMPER SIDE RETAINER <i>New</i>	1	\$ 188.10	\$ 188.10

Side skirl.

ton

850 680

TOTAL PRICE \$ 14,545.60

LESS 10% \$ 1,454.56

SUB TOTAL PRICE \$ 13,091.04

5505.2
4954.68

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR FENDER INNER COWLING CLIPS(SET) <i>1st</i>	1	\$ 30.00	\$ 30.00
2	REAR WINDSCREEN SEALANT <i>2nd</i>	1	\$ 150.00	\$ 150.00
3	REAR WINDSCREEN INNER SEAL	1	\$ 120.00	\$ 120.00
4	WHEEL TYRE <i>cut</i>	1	\$ 650.00	\$ 650.00
5	WHEEL RIM <i>cut</i>	1	\$ 4,500.00	\$ 4,500.00
6	REAR BUMPER CLIP(SET) <i>1st</i>	1	\$ 30.00	\$ 30.00

TOTAL \$ 5,480.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	600	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	800	
3	WIRING CHECK	\$ 120.00	30	
4	TO REMOVE AND REFIX REAR DOOR MECHAISM	\$ 80.00		
5	REMOVE AND REFIX REAR BUMPER AND DISTANCE SETTING	\$ 80.00	50	
6	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 350.00	200	
7	FOUR WHEEL ALIGNMENT	\$ 120.00	80	
8	TO REMOVE AND REFIX REAR WINDSCREEN	\$ 160.00	X	
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices to be subject to confirmation
- This estimate is on a "No Prejudice" basis
- No illegal modification(s) is allowed
- Supplier's terms and conditions apply and is subject to final approval from Insurance Company

ESTIMATE REPORT

TOTAL PARTS COST : \$

TOTAL LABOUR COST : \$

TOTAL REPAIR COST : \$

APPROVED DETAILS

Acknowledged by Repairer

Signature:

Date:

TOTAL

\$3,690.00

18,571.04

3,690.00

22,261.04

23026.04

Adrian King - total: 8074.68
h/s 18/10/18. h/s: 6.4K
05 Pags.

SURVEYOR :
CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
NO OF DAYS :



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18018897/Asd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8278X	Veh. Inspected	SDY 2233C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007399MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	17/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	BMW 523i	c.c	2497	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WBAFP320X0C867258	Colour	BLACK	
Odometer	159099	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R19	YOKOHAMA	6 mm	
L/H Front Tyre	245/40 R19	YOKOHAMA	6 mm	
R/H Rear Tyre	245/40 R19	YOKOHAMA	6 mm	
L/H Rear Tyre	245/40 R19	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/10/2018	Inspection Date	18/10/2018	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDY 2233C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR DOOR	DENTED	1,688.90	1,688.90
1	REAR FENDER	TO REPAIR SEE LABOUR	1,988.70	-
1	REAR FENDER INNER COWLING	NOT NECESSARY	190.80	-
1	REAR LOWER ARM LH	NOT NECESSARY	620.00	-
1	REAR UPPER ARM LH (FRONT)	BENT	830.30	308.00
1	REAR UPPER ARM LH (REAR)	BENT	711.30	298.00
1	REAR SWING ARM LH	NOT NECESSARY	685.00	-
1	REAR KNUCKLE ARM LH	NOT NECESSARY	1,150.30	-
1	REAR SHOCK ABSORBER LH	NOT NECESSARY	890.40	-
1	REAR LINKAGE LH	NOT NECESSARY	233.60	-
1	REAR WHEEL HUP LH	DAMAGED	580.30	580.30
1	REAR WHEEL HUP BEARING LH	NECESSARY	360.00	360.00
1	REAR DRIVESHAFT	NOT NECESSARY	2,350.30	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	222.30	-
1	REAR BUMPER	TORN	1,855.30	1,495.00
1	REAR BUMPER SIDE RETAINER	NECESSARY	188.10	95.00
1	SIDE SKIRT	TORN	850.00	680.00
	LESS 10% DISCOUNT		-1,539.56	-550.52
			13,856.04	4,954.68
SPECIAL NETT ITEMS				
1	SET REAR FENDER INNER COWLING CLIPS (SN)	NOT NECESSARY	30.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	150.00	-
1	REAR WINDSCREEN INNER SEAL (SN)	NOT NECESSARY	120.00	-
1	WHEEL TYRE (SN)	CUT	650.00	350.00
1	WHEEL RIM (SN)	CUT	4,500.00	900.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	30.00	30.00
			5,480.00	1,280.00
LABOUR				
	PANEL BEATING, REMOVING AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER.		1,400.00	600.00

Report Ref No. CS/FC118018897/Asd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING TO AFFECTED AREA.		1,200.00	800.00
	WIRING CHECK.		120.00	30.00
	TO REMOVE AND REFIX REAR DOOR MACHANISM.		80.00	80.00
	REMOVE AND REFIX REAR BUMPER SENSOR AND DISTANCE SETTING.		80.00	50.00
	REMOVE AND REFIX REAR UNDERCARRIAGE.		350.00	200.00
	FOUR WHEEL ALIGNMENT.		120.00	80.00
	TO REMOVE AND REFIX REAR WINDSCREEN.	NOT NECESSARY	160.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			3,690.00	1,840.00
	GRAND TOTAL		23,026.04	8,074.68
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,400.00

Report Ref No. CS/FCI18018897/Asd3n2

MARKET VALUE: \$60,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$49,393.00=NETT VALUE: \$10,607.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.