

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1177/2018/PH
Date : 16-Oct-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Low Wee Siong
Address : 19 Mount Sinai View
Singapore 276812
Telephone : HP +65 98457238
Type of Claim : Own Damage Claims
Policy No. : 1800110324
Vehicle No : **SKA 178 K**
Model Code : Audi A6 1.8 TFSI S-Tronic
Model / Year : Sep-18
Engine No : CYG 024872
Chassis No : WAUZZZ4G4JN062432
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Oct-18
Place of Accident : Traffic light U-turn along Clementi Rd opp Clementi

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKA 178 K.

| S/n | Nature of Jobs | Estimated Charges | Surveyor's Recommendation |
|---------------------------------|--|------------------------|---------------------------|
| 1 | To remove and reinstall rear parking aid rear lid kick sensor. Check function. | S/N \$ 360.00 ✓ | |
| 2 | To renew rear windscreen and lhs 1/4 glass for fender renewal. | S/N \$ 600.00 ✓ | |
| 3 | To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment. | S/N \$ 1,400.00 ✓ | |
| 4 | To remove and reinstall rear seat assy, back rest, ABCD pillar trims, curtain airbags, safety belts, carpets, roof liner, carpets, sill trims, etc. | S/N \$ 1,400.00 ✓ | |
| 5 | To dismantle rear bumper, lhs sill panel trim and rear lid. Cut out and reweld lhs rear fender, lhs bottom plate, lhs wheel housing inner and outer and lhs connecting plate. Renew rear bumper and lhs sill panel trim. Inspect for further damages. Reinstall all parts removed. | \$ 8,400.00 | 3500. |
| SUB TOTAL LABOUR CHARGES | | : \$ 12,160.00 | |

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKA 178 K.

| <u>S/n</u> | <u>Nature of Jobs</u> | <u>Estimated Charges</u> | <u>Surveyor's Recommendation</u> |
|-----------------------------|---|--------------------------|----------------------------------|
| 6 | To respray rear bumper, lhs rear fender, lhs wheel housing inner and outer, lhs bottom plate, lhs connecting plate, lhs sill panel, lhs sill panel trim, door entrances, roof channel, drain channel and end panelling. To carry out joint sealant work and stone chip treatment. | \$ 6,800.00 | 2800 2750. |
| 7 | To renew lhs rear rim and carry out wheel alignment. S/N | \$ 280.00 | ✓ |
| 8 | To carry out diagnostic check. S/N | \$ 192.00 | ✓ |
| TOTAL LABOUR CHARGES | | : \$ 19,432.00 | |

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKA 178 K.

| S/N | Parts Description | Damaged Parts & Prices | |
|--------------------------------------|---|------------------------|--------|
| | | S/Nett | Remark |
| 1 | REAR BUMPER <i>Distorted</i> | \$ 2,519.00 | ✓ |
| 2 | FIXING PARTS FOR REAR BUMPER <i>new</i> | \$ 234.00 | X |
| 3 | REAR BUMPER SPOILER <i>new</i> | \$ 416.00 | X |
| 4 | SECURING STRIP <i>new</i> | \$ 191.00 | X |
| 5 | CLOSING ELEMENT - LH | \$ 69.00 | X |
| 6 | TRIM FOR EXHAUST TAIL PIPE - LH <i>new</i> | \$ 497.00 | X |
| 7 | REAR BUMPER CARRIER <i>new</i> | \$ 851.00 | X |
| 8 | SEAL - LH/RH ? | 2 \$ 24.00 | ? |
| 9 | GUIDE SECTION - LH <i>new</i> | \$ 46.00 | ✓ |
| 10 | GUIDE SECTION - LH | \$ 28.00 | ✓ |
| 11 | CONNECTING PIECE ? | \$ 11.00 | ? |
| 12 | GUIDE PROFILE - LH <i>new?</i> | \$ 57.00 | ? |
| 13 | HOLDING STRAP - LH | \$ 54.00 | ? |
| 14 | REAR BUMPER SENSOR <i>new</i> | \$ 211.00 | X |
| 15 | SECTIONAL PART - SIDE PANEL - LH <i>Distorted</i> | \$ 2,739.00 | ✓ |
| 16 | REAR WINDSCREEN <i>new</i> | \$ 1,017.00 | ✓ |
| 17 | PRIMER <i>new</i> | 2 \$ 38.00 | ✓ |
| 18 | REAR 1/4 GLASS - LH <i>new</i> | \$ 344.00 | ✓ |
| 19 | TRIM STRIPS FOR SIDE WINDOW CHROME - LH REAR <i>new</i> | \$ 222.00 | X |
| 20 | MOLDING - ROOF CHROME <i>new</i> | \$ 440.00 | X |
| SUB-TOTAL SPARE PARTS CHARGES | | \$ 10,008.00 | |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKA 178 K.

| S/N | Parts Description | Damaged Parts & Prices | |
|--------------------------------------|--|------------------------|--------|
| | | S/Nett | Remark |
| 21 | SIDE MEMBER TRIM - LH <i>Repair</i> | \$ 752.00 | X |
| 22 | ATTACHMENT PARTS - CLIP <i>new</i> | \$ 77.00 | ✓ |
| 23 | ADHESIVE TAPE <i>new</i> | \$ 14.00 | ✓ |
| 24 | SILL TRIM STRIP SATIN BLACK - LH REAR <i>new</i> | \$ 104.00 | X |
| 25 | WHEEL HOUSING LINER - LH <i>Dented</i> | \$ 246.00 | ✓ |
| 26 | ATTACHMENT PARTS FOR WHEEL HOUSING LINER ? | \$ 62.00 | ? |
| 27 | WHEEL HOUSING - LH OUTER ? | \$ 655.00 | ? |
| 28 | CONNECTING PLATE ? | \$ 85.00 | ? |
| 29 | BOTTOM PLATE - LH OUTER ? | \$ 605.00 | ? |
| 30 | WHEEL HOUSING - LH INNER ? | \$ 655.00 | ? |
| 31 | LED TAIL LIGHT - LH <i>new</i> | \$ 1,094.00 | X |
| 32 | TRIM FOR TAIL LIGHT <i>new</i> | \$ 26.00 | X |
| 33 | LUGGAGE COMPARTMENT TRIM SOUL BLACK - LH ? | \$ 676.00 | ? |
| 34 | REAR BOOT AMPLIFIER BRACKET ? | \$ 100.00 | ? |
| 35 | REAR SILENCER - LH <i>Dented</i> | \$ 1,157.00 | ✓ |
| 36 | DUAL CLIP ? | \$ 53.00 | ? |
| 37 | BRACKET ? | \$ 50.00 | ? |
| 38 | REAR LHS ALUMINIUM RIM <i>ut</i> | \$ 726.00 | ✓ |
| 39 | ARCYLIC SEALANT } <i>new</i> | S/N \$ 180.00 | ✓ |
| 40 | CAVITY WAX } | S/N \$ 140.00 | ✓ |
| SUB-TOTAL SPARE PARTS CHARGES | | \$ 7,457.00 | |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKA 178 K.

| S/N | Parts Description | Damaged Parts & Prices | |
|----------------------------------|-------------------------|------------------------|--------|
| | | S/Nett | Remark |
| 41 | STONE CHIP TREATMENT | S/N \$ 180.00 | ✓ |
| 42 | METAL FILLER POWDER | S/N \$ 280.00 | ✓ |
| 43 | REAR WINDSCREEN SEALANT | S/N \$ 200.00 | ✓ |
| 44 | 1/4 GLASS SEALANT | S/N \$ 100.00 | ✓ |
| 45 | SUNDRIES ? | \$ 500.00 | ? |
| TOTAL SPARE PARTS CHARGES | | : \$ 18,725.00 | |
| TOTAL LABOUR CHARGES | | : \$ 19,432.00 | |
| GRAND TOTAL | | : \$ 38,157.00 | |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 18/10/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 14 Days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant