

ASS. REC. BY:

REF:

CS/ICS18018903/T1td30

Special Instruction:

Surveyor:
Menmen

From (Person):

Taufik
Desmond Lee

ASSIGNMENT (Office)

of ICS

Date/Time: 17/10/18 @ 2:34pm

Estimated Cost:

Bill to:

① TP/WS/TP RES / OD RES / EVA / INV / MV7 CS

To Inspect Vehicle No:

SLC 9991 Y

Insured:

at Workshop m/s

Performance

Tel: 9116 5600

of

303 Alexandra Road

Policy No:

MPCL18A00140400

Claim No:

DMPL1800392H.

Sum Insured:

Excess:

TBA

Make of Veh:

(Client's Record)

D.O.A.

14/10/18

CA / (REV) / REP. / REV 24 HRS

18/10/2018

H.O.D. Endorsement:

Date/Time:

3:06pm @ 17/10/18

Person Contacted:

Kevin

Vehicle ② IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLC 9991 Y - NBA / MSG18000478/k4

DUA: 15/01/2018

18/10 -

Revert via Menmen

22/10 @

6:42pm authorise by Crystabelle via email mandate m menmen
will follow up.

Part by Part \$31,033.30 (Red: 3351.85; 90%)

REF:

ICS

ASSIGNMENT

From _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

tbn

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

485K

IDAC Accident Rpt: _____

Consistent? Yes or No

GIA / PR Seen: _____

Consistent? Yes or No

Est. Repairs: _____

days

Res: Yes or No

Lum Sum: _____

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted _____

Vehicle: IN / OUT

kwin

Veh No: _____

SLC 99919

Yr Regn: _____

2016 Apr

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

BMW 116D

CC 1496

Colour: _____

white

A/C

Insured / Std / NI / NA

Sp. Reading: _____

57577

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

WBAIV720804724322

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal: _____

6

mm

R/Bal: _____

6

mm

L/Bal: _____

6

mm

L/Bal: _____

6

mm

D.O.A: _____

D.O.I: _____

18/10/18 @ 1045

Survey held at _____

PML

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Tarfikh,

As see my remarks.

RECEIVED 17 MAY 2019

17/5/2019

23/10

Date/Time, File Pass to?



Prell. Report

1) P/B Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

14

Resurvey No. of Trip: _____

1

Survey Fee: _____

450

Transportation: _____

S + RS, SI

Photo

Other

TOTAL

Add Fee: ☐

Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format: _____

OD

Lump Sum / (B): (\$

31,033.30

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 27 March 2019 3:46 PM
To: 'Crystabelle Tan Gek Peng (ECICS, Claims)'
Subject: RE: Alert - Adj Mandate Maintained - SLC9991Y - Claim Handler: Crystabelle Tan - Ref: DMPC1800392H/CT
Attachments: SLC 9991Y ESTIMATE.pdf; SUPPLEMENTARY.PDF

Dear Crystabelle,

The increase in the repair cost is due to the increment of the labour and supplementary.

Enclosed breakdown.

Revised Labour	: \$18,847.00
Revised Parts	: \$8,471.75
Supp Labour	: \$2,674.00
Supp parts	: \$3,150.55
Sub - Total	: \$33,143.30

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Crystabelle Tan Gek Peng (ECICS, Claims) <Crystabelle_Tan@ecics.com.sg>
Sent: Wednesday, 27 March 2019 3:00 PM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Subject: RE: Alert - Adj Mandate Maintained - SLC9991Y - Claim Handler: Crystabelle Tan - Ref: DMPC1800392H/CT

Dear Denise

Previously we have approved COR at \$24,985.05.

The supplementary is \$5,824.55.

How you arrive the figure at \$33,143.30?

Best regards

Crystabelle Tan

Senior Associate | Claims



Regards,

Kevin Leong

Customer Service Advisor | Body and Paint

Performance Motors Limited

303 Alexandra Road

Sime Darby Performance Centre

Singapore 159941

Hp (+65) 9116 5600 | Fax (+65) 6479 4601

Kevin.leong.waikit@sime-darby.com.sg

**BRING IT ON.
THE ALL-NEW BMW X4.**

[Find out more](#)



From: Kevin Leong Wai Kit

Sent: Tuesday, October 16, 2018 10:29 AM

To: 'claims@ecics.com.sg'

Subject: OD Claim - SLC9991Y - 14/10/18

Dear All,

Kindly refer to above attach OD Claim for : SLC9991Y

Please arrange for survey on this car.

Car is in workshop.

Thank you

Regards,

Kevin Leong

Customer Service Advisor | Body and Paint

Performance Motors Limited

303 Alexandra Road

Sime Darby Performance Centre

Singapore 159941

Hp (+65) 9116 5600 | Fax (+65) 6479 4601

Kevin.leong.waikit@sime-darby.com.sg

**BRING IT ON.
THE ALL-NEW BMW X4.**

[Find out more](#)



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Denise Tay (LKKAuto)

Dear Crystabelle,

The increase in repair cost due to parts opined to be repaired initially were consequently replace. The replacement of the parts were due to these items being observed from view during the initial inspection.

Labour: \$21,521.00

Parts: \$5,797.75 inclusive confirm check item.

Supp: \$5,824.55

Total \$33,143.30

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLC9991Y (DMPC1800392H)**

OD

Oct 14 2018 4:00AM

[KOH YU]

Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From ECICS Limited (HQ) (ECICS), sent on 18/03/2019 10:41 AM.

To LKK_HQ

Subject Alert - Adj Mandate Maintained - SLC9991Y - Claim Handler: Crystabelle Tan

Maintained:How you arrive the figure at \$33,143.30.

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7253A
Vehicle Details	
Vehicle No.:	SLC9991Y
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Oct 2018
Vehicle Make:	B.M.W.
Vehicle Model:	116D 5DR HATCHBACK DSC LED
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	33929525B37D15A
Chassis No.:	WBA1V72080V724322
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$23,752.00
Original Registration Date:	18 Apr 2016
First Registration Date:	18 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$10,253.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Apr 2026
PARF Rebate Amount:	\$7,689.00
Intended COE Rebate Details	
COE Expiry Date:	17 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,009.00
COE Rebate Amount:	\$34,501.00
Total Rebate Amount:	\$42,190.00

The information contained herein is correct as at 18 Oct 2018

OK

Denise Tay (LKKAUTO)

From: Crystabelle Tan Gek Peng (ECICS, Claims) <Crystabelle_Tan@ecics.com.sg>
Sent: Monday, 22 October 2018 6:42 PM
To: Denise Tay (LKKAUTO); Admin-D (LKKAUTO); assignments
Cc: SUR; ECICS Claims
Subject: RE: OD Claim - SLC9991Y - 14/10/18 - Ref : DMPC1800392H

WITHOUT PREJUDICE

Dear Denise

Please proceed to authorise repair.

Will approve mandate tomorrow in merimen.

Best regards,
Crystabelle Tan
Claims Division
DID: +65 6303 0190
FAX: +65 6338 9267
Email: crystabelle_tan@ecics.com.sg

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Friday, 19 October, 2018 4:46 PM
To: Desmond Lee Ker Wen (ECICS, Claims); Admin-D (LKKAUTO); ECICS Claims; assignments
Cc: SUR; Crystabelle Tan Gek Peng (ECICS, Claims); Janice Goh Siew Geok (ECICS, Claims)
Subject: RE: OD Claim - SLC9991Y - 14/10/18

Dear All,

Kindly advise on authorization, mandate has put up in merimen.

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Desmond Lee Ker Wen (ECICS, Claims) <Desmond_Lee@ecics.com.sg>
Sent: Wednesday, 17 October 2018 3:43 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; ECICS Claims <claims@ecics.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Crystabelle Tan Gek Peng (ECICS, Claims) <Crystabelle_Tan@ecics.com.sg>; Janice Goh

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 23 October 2018 8:49 AM
To: Kevin Leong Wai Kit
Cc: SUR
Subject: SLC 9991Y / OD / ECICS

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLC 9991Y (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/10/2018 15:43
Date Of Accident	14/10/2018 04:30
Exact Location Of Accident	AYE EXPRESSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC9991Y
Insured/Policyholder	
Name Of Registered Owner	KOH YU
NRIC No	S9317253A
Email Address	ZACLIF93@GMAIL.COM
Mobile Phone No	(LOCAL) +65-85187568
Alternative Phone No	OFFICE-85187568
Vehicle Particulars	
Manufacturer	BMW
Model	116D 5DR HATCHBACK DSC LED
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USED
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC18A00140400
Cover Note Number	

Driver

Name of Driver	KOH YU
NRIC No	S9317253A
Date Of Birth	20/05/1993
Occupation	INDOOR
Date Of Driving Pass	04/04/2013
Driving Experience	5 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85187568
Fax Number	
Contact Number	OFFICE-85187568
Email Address	ZACLIF93@GMAIL.COM

Address	5 WEST COAST WALK #21-09
Postcode	127146
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT BY FALLEN TREE / OTHER OBJECTS
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

Many say on APR is 9.40% - On standard and Right side of the car
but the ~~rate~~ middle rating of the company

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name: _____
NRIC/ID No: _____

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulatory, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

Accident Photo





CERTIFICATE OF INSURANCE

Motor Vehicle (Third-Party Risks Compensation) Act (Chapter 145)
Motor Vehicle (Third-Party Risks and Compensation) Rules, 1993
Road Transport Act, 1987 (Malaysia)
Motor Vehicle (Third-Party Risks) Rules, 1959 (Malaysia)

**E-DRIVE PREMIER
(ANY WORKSHOP)**

ME300
COMPREHENSIVE
ORIGINAL

CERTIFICATE NO: MFC15A0014040
Agency Name: AUTOSHIELD PTE LTD
Agency Code: A000066

Chassis No: WHA1V72000V714312
Engine No: 33024625037D145A

1. Index Mark and Registration Number of Vehicle: SLC9991Y

2. Name of Policyholder: KOH YU

3. Period of Insurance (both dates inclusive): 18 April 2018 to 17 April 2019

4. Attached Clauses of Policies attached to this:

a) The Policyholder and all named drivers declared under the policy
do hereby warrant that they are driving on the Policyholder's vehicle with full permission.

Declared that the named driving is permitted in accordance with the licensing or other law or regulations
to drive the Motor Vehicle as has been so permitted and is not disqualified by being in a Default List or
by breach of any enactment or regulation in their behalf from driving the Motor Vehicle.

5. Limitations to use are:

Use for social, domestic and pleasure purposes and for the policyholder's business. The policy does not
cover use for hire or reward, touring, driving test, taxi, passenger, school bus, school, school-bus,
the carriage of goods or use in connection with any trade or business or use for any purpose in
connection with the Motor Trade.

6. EXCESS APPLICABLE:

WHOLETIME	RM 400.00
SECTION 1 - WHOLETIME DRIVE	RM 400.00
SECTION 2 - PARTIALTIME DRIVE	RM 400.00
SECTION 3 - PARTIALTIME DRIVE	RM 400.00

Signed for and on behalf of ECICS Limited

Chief Executive Officer

Important Notice:

- Policyholders are hereby warned that it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid insurance under the Act.
- On the sale of a motor vehicle, Policyholders must warrant that insurance papers issued including the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 145).
- The Certificate of Insurance and the Policy will cease to be valid once the motor vehicle has been stolen or destroyed.
- The Payment Before Cover Warranty or Payment Before Cover Warranty End in the Policy must be complied with otherwise there would be no liability under the Policy and Certificate of Insurance.

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. NO. WD 0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Tampong Arang Road
East Coast Centre
Singapore 436189
Tel: 63190888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 48806
Date Estimated : 16/10/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Koh Yu
5 West Coast Walk
#21-09

Singapore 127146

- ACCOUNT - 144674

ECICS Limited
7 Temasek Boulevard, #10-03 Suntec Tower
Singapore 038987

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLC9991Y	V724322	18/04/2016	116d	0

DESCRIPTION

To replace frt bumper, frt RH side panel, frt RH door, rear RH door, rear RH side panel & all attachments cause by accident. To repair on rear bumper panel

Painting on frt bumper, frt RH side panel, frt RH door, rear RH door, rear RH side panel & rear bumper

To remove and install fuel tank to facilitate repairs including extract fuel and conduct leak tests.

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.

To check steering geometry and conduct wheel alignment according to BMW specification (1x)

To replace tyre and wheel rim including balancing. (1x).

To check electrical wiring systems for proper function.

To replace right headlight.

To carry out body cavity preservation.
(Per panel) Frt side panel

To carry out body cavity preservation.
(Per panel) Frt & Rear RH doors

To carry out body cavity preservation.
(For cut panel) Rear RH side panel

Sundries.

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

how many days?
pls justify - res

DESCRIPTION	VALUE
To replace frt bumper, frt RH side panel, frt RH door, rear RH door, rear RH side panel & all attachments cause by accident. To repair on rear bumper panel	8500 7650 10,200.00
Painting on frt bumper, frt RH side panel, frt RH door, rear RH door, rear RH side panel & rear bumper	5054 5,616.00
To remove and install fuel tank to facilitate repairs including extract fuel and conduct leak tests.	451? photo 531.00
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.	742 873.00
To check steering geometry and conduct wheel alignment according to BMW specification (1x)	451 531.00
To replace tyre and wheel rim including balancing. (1x).	80 94.00
To check electrical wiring systems for proper function.	150 177.00
To replace right headlight.	408 481.00
To carry out body cavity preservation. (Per panel) Frt side panel	100 118.00
To carry out body cavity preservation. (Per panel) Frt & Rear RH doors	200 236.00
To carry out body cavity preservation. (For cut panel) Rear RH side panel	451 531.00
Sundries.	150.00

Total Labour 1: 19,538.00



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190928 (AfterSales)
63190933/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 48806
Date Estimated : 16/10/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLC9991Y	V724322	18/04/2016	116d	0

DESCRIPTION

QTY PRIC

VALUE

BLIND PLUG	1	1.00	1.00
CLAMP	10	3.20	32.00
ALLOY RIM 7JX16 STAR SPK 654	1	724.05	724.05
RR RH FENDER	1	1,295.95	1,295.95
REINFORCEMENT PLATE C-PILLAR RH	1	49.20	49.20
REINFORCEMENT PLATE ROCKER PLATE RH	1	49.20	49.20
FRT RH DOOR	1	1,051.10	1,051.10
FRT RH FENDER	1	546.00	546.00
REINFORCEMENT PLATE UNIVERSAL	1	27.75	27.75
SIDE PANEL BRACKET FRT RH 3	1	32.15	32.15
FRT RH 2 SIDE PANEL BRACKET	1	32.15	32.15
FRT RH 2 SIDE PANEL BRACKET	1	32.15	32.15
RR RH DOOR	1	1,051.10	1,051.10
FRT BUMPER LH INSERT	1	32.15	32.15
FRT BUMPER RH INSERT	1	32.15	32.15
FRT BUMPER PANEL PRIMED	1	786.20	786.20
SET PDC HOLDER FRONT	1	23.10	23.10
SET PMA HOLDERS FRT/REAR	1	21.25	21.25
FRT DOOR JOINT SEAL	1	49.65	49.65
FRT RH DOOR CHANNEL INSIDE SEALING	1	59.45	59.45
FRT RH DOOR CHANNEL SEALING	1	69.95	69.95
B PILLAR FINISHER OUTER RH	1	49.25	49.25
COVER WHEEL HOUSING FRT RH	1	79.75	79.75
FRT RH WHEEL HOUSING COVER FRT SECT	1	104.90	104.90
RH HEADLIGHT LED TECHNOLOGY	1	2,263.60	2,263.60
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
BLIND RIVET AVIBVLB	320	0.55	176.00
SCREW (SF PLUS M5X15)	10	0.55	5.50
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	281.55
(DG) BODYWORK ADHESIVE K5A (50ML)	1	118.35	118.35
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) ADHESIVE SET K6	1	53.05	53.05
PUNCH RIVET N4	32	0.55	17.60
(S/L) SEAM SEAL 300ML	1	33.80	33.80

32 new 1.00
32 new 3.20
1 out 724.05
1 bt 1,295.95
1 unk 49.20
1 unk 49.20
1 bt 1,051.10
1 bt 546.00
1 unk 27.75
1 unk 32.15
1 bt 32.15
1 unk 32.15
1 bt 1,051.10
1 unk 32.15
1 new 32.15
1 new 786.20
1 new 23.10
1 unk 21.25
1 new 49.65
1 new 59.45
1 new 69.95
1 new 49.25
1 new 79.75
1 new 104.90
1 new 2,263.60
4 new 20.20
320 new 176.00
10 new 5.50
1 new 281.55
1 new 118.35
1 new 26.15
1 new 53.05
32 new 17.60
1 new 33.80

Total Parts : 9,022.60

20 / 3rd Party / Uninsured losses / Direct Settlement

Claim No. : 16/10/18
Claim Date : 16/10/18

Surveyor's Name : Tanjun
Surveyor's Tel : 97495349
Authorized Date : 16/10/18
Authorized Signature : [Signature]
Surveyor's Email : tanjun@thelawson.com
Holding Days Recommended : 12 days

Labour 1 : 19,538.00
Parts : 9,022.60
Labour 2 : 0.00
Excess : 0.00
Total GST @ 7% : 1,999.24
Grand Total : 30,559.84

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 48806
Date Estimated : 16/10/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Koh Yu
5 West Coast Walk
#21-09

- ACCOUNT - 144674
ECICS Limited
10 Eunos Road 8
Singapore Post Centre #09-04A
Singapore 408600

Singapore 127146

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLC9991Y	V724322	18/04/2016	116d	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To remove and install front suspension for inspection include replacement of damaged parts	1128.00		1,128.00 ✓
# To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function (2x)	902.00		902.00 ✓
# To replace rear RH door fixed quarter glass include conducting water leak tests	413.00		413.00 ✓
# To remove and install boot compartment carpet and garnish to facilitate repairs	231.00		231.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RH WISHBONE *	262.20	1.00		262.20 ✓
# RH TENSION STRUT W/HYDRAULIC MOUNT *	262.20	1.00		262.20 ✓
# SPHERICAL COLLAR SCREW M12X1.25X45 *	7.70	4.00		30.80 ✓
# WHEEL HUB WITH BEARING FRT *	465.75	1.00		465.75 ✓
# FRT RH CARRIER *	439.10	1.00		439.10 ✓
# FRT GUIDE SUPPORT *	232.00	1.00		232.00 ✓
# FRT SPRING STRUT *	484.55	1.00		484.55 ✓
# COMBINATION NUT M14X1.5 *	5.55	2.00		11.10 ✓
# HEX NUT WITH FLANGE *	2.35	1.00		2.35 ✓
# ALLOY RIM 7JX16 STAR SPK 654 *	724.05	1.00		724.05 ✓
# RIVET *	0.45	3.00		1.35 ✓
# HOUSING LOWER SECTION RH (GENARBT) *	23.85	1.00		23.85 ✓
# RR RH DOOR QUARTER GLASS *	134.00	1.00		134.00 ✓
# PLAQUE 82MM *	71.25	1.00		71.25 ✓
# EXPANDING NUT (4.8) *	1.00	6.00		6.00 ✓

Total Labour : 2,674.00
Total Parts : 3,150.55
Total Labour & Parts : 5,824.55

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401999N GST Reg. No. M2-0000081-0



FINAL REPORT

Estimate No. : b1 48806
Date Estimated : 16/10/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Koh Yu
5 West Coast Walk
#21-09

- ACCOUNT - 144674
ECICS Limited
10 Eunus Road #
Singapore Post Centre #09-04A
Singapore 408600

Singapore 127146

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE	0	ORIGINAL PRICE	DISC. %	NETT
SLC9991Y	V724322	18/04/2016	116d					
DESCRIPTION								
To replace front bumper and attachments, front/rear RH doors and attachments, front RH fender and attachments, rear RH fender include making good the rear bumper, rear RH wheelhousing, tail end panel and knocking out dents caused by the accident						8500.00		8,500.00
* To spray paint front bumper, front RH fender, front RH door, rear RH door, rear RH fender, rear bumper, rear RH wheelhousing, tail end panel, RH 'C' pillar and RH roof frame						6933.00		6,933.00
* To remove and install fuel tank to facilitate repairs include extracting fuel and conducting leak tests						451.00		451.00
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs						742.00		742.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)						451.00		451.00
* To replace wheel rim include balancing (2x)						160.00		160.00
* To reconnect all electrical components and wiring at the rear section and conducting checks for proper function (For cut panel)						301.00		301.00
To replace RH LED technology headlight include programming and conducting tests for proper function						408.00		408.00
To carry out body cavity preservation (3x) (Per panel)						300.00		300.00
To carry out body cavity preservation (For cut panel)						451.00		451.00
# To remove and install front suspension for inspection include replacement of damaged parts						1128.00		1,128.00
# To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function (2x)						902.00		902.00

Performance Motors Limited

A member of the Sims Carby Group
 Co. Reg No. 19740155BN GST Reg No. WQ-0220091-9



FINAL REPORT

# To replace rear RH door fixed quarter glass include conducting water leak tests	413.00	413.00
# To remove and install boot compartment carpet and garnish to facilitate repairs	231.00	231.00
Sundries	150.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
CLAMP	3.20	10.00		32.00
EXPANDING NUT *	2.00	6.00		12.00 (A) not
# RH WISHBONE *	262.20	1.00		262.20
# RH TENSION STRUT W/HYDRAULIC MOUNT *	262.20	1.00		262.20
# SPHERICAL COLLAR SCREW M12X1.25X45 *	7.70	4.00		30.80
# WHEEL HUB WITH BEARING FRT *	465.75	1.00		465.75
# FRT RH CARRIER *	439.10	1.00		439.10
# FRT GUIDE SUPPORT *	232.00	1.00		232.00
# FRT SPRING STRUT *	484.55	1.00		484.55
# COMBINATION NUT M14X1.5 *	5.55	2.00		11.10
# HEX NUT WITH FLANGE *	2.35	1.00		2.35
# ALLOY RIM 7JX16 STAR SPK 654 *	724.05	1.00		724.05
ALLOY RIM 7JX16 STAR SPK 654	724.05	1.00		724.05
RR RH FENDER ✓	1,295.95	1.00		1,295.95
FRT RH DOOR ✓	1,051.10	1.00		1,051.10
FRT RH FENDER ✓	546.00	1.00		546.00
FRT RH 2 SIDE PANEL BRACKET ✓	32.15	1.00		32.15
RR RH DOOR ✓	1,051.10	1.00		1,051.10
FRT BUMPER RH INSERT ✓	32.15	1.00		32.15
FRT BUMPER PANEL PRIMED ✓	786.20	1.00		786.20
SET PDC HOLDER FRONT ✓	23.10	1.00		23.10
# RIVET *	0.45	3.00		1.35
# HOUSING LOWER SECTION RH (GENARBT) *	23.85	1.00		23.85
FRT DOOR JOINT SEAL ✓	49.65	1.00		49.65
# RR RH DOOR QUARTER GLASS *	134.00	1.00		134.00
# PLAQUE 82MM *	71.25	1.00		71.25
RH HEADLIGHT LED TECHNOLOGY	2,263.60	1.00		2,263.60 (A) not
EXPANDING NUT *	0.55	2.00		1.10
# EXPANDING NUT (4.8) *	1.00	6.00		6.00
DECOUPLING RING PDC TORQUE CONVERTE ✓	5.05	4.00		20.20
BLIND RIVET AMBVLB ✓	0.55	20.00		11.00
SCREW (SF PLUS MSX15) ✓	0.55	10.00		5.50
(DG/SL) BODY ADHESIVE K5B (195ML) ✓	281.55	1.00		281.55
PUNCH RIVET N4	0.55	40.00		22.00
(DG) BODYWORK ADHESIVE K5A (50ML) ✓	118.35	1.00		118.35
(DG) CLEANER R1 (100ML) ✓	26.15	1.00		26.15
(DG/SL) ADHESIVE SET K6 ✓	53.05	1.00		53.05
(S/L) SEAM SEAL 300ML ✓	33.80	1.00		33.80

SUPPLEMENTARY ITEMS

Total Labour :	21,521.00
Total Parts :	11,622.30
Total Labour & Parts :	33,143.30
Deduction for Excess :	500.00
Total Repair Costs less Excess:	32,643.30
GST @7%:	2,285.03
Grand Total :	34,928.33

FACSIMILE MESSAGE

DATE <u>06/03/19</u>	TIME _____
TO <u>LKK</u>	FAX NO. _____
ATTN <u>Mr Taufikh</u>	NO OF PAGES _____ (INCLUSIVE OF THIS PAGE)
CC _____	FAX NO. _____
ATTN _____	FAX NO. _____
FROM <u>Kevin Leong</u>	TEL NO. <u>91165600</u>

If this fax is not received in order, please do call us. Thank you.

Dear Sirs,

Supplementary repair for BMW	<u>BMW 116</u>
Vehicle Registration No.	<u>SLC9991Y</u>
Vehicle Chassis No.	<u>V724322</u>

Supplementary Parts to be replaced:	Qty	Price (nett)
CLAMP	9	\$ 28.80 <i>re✓</i>
EXPANDING NUT	6	\$ 12.00 <i>re✓</i>
RH WISHBONE	1	\$ 262.20 <i>ht✓</i>
RH TENSION STRUT W/HYDRAULIC MOUNT	1	\$ 262.20 <i>ht✓</i>
SPHERICAL COLLAR SCREW M12X1.25X45	4	\$ 30.80 <i>re✓</i>
WHEEL HUB WITH BEARING FRT	1	\$ 465.75 <i>ht✓</i>
FRT RH CARRIER	1	\$ 439.10 <i>ht✓</i>
FRT GUIDE SUPPORT	1	\$ 232.00 <i>ht✓</i>
FRT SPRING STRUT	1	\$ 484.55 <i>ht✓</i>
COMBINATION NUT M14X1.5	2	\$ 11.10 <i>re✓</i>
HEX NUT WITH FLANGE	1	\$ 2.35 <i>re✓</i>
ALLOY RIM 7JX16 STAR SPK 654	1	\$ 724.05 <i>re✓</i>
RIVET	3	\$ 1.35 <i>re✓</i>
HOUSING LOWER SECTION RH (GENARBT)	1	\$ 23.85 <i>re✓</i>
RR RH DOOR QUARTER GLASS	1	\$ 134.00 <i>re✓</i>
PLAQUE 82MM	1	\$ 71.25 <i>re✓</i>
EXPANDING NUT	2	\$ 1.10 <i>re✓</i>
EXPANDING NUT (4.8)	6	\$ 6.00 <i>re✓</i>
PUNCH RIVET N4	40	\$ 22.00 <i>re✓</i>
Total	:	\$ 3,214.45

WORKSHOP QUOTATION

GST REG NO : M2 - 0020081 - X

Vehicle No : SLC 9991Y
 Chassis No : V 724322
 CSA Name : Kevin
 Model Year : Ecics Limited

Quotation No : 0000504472
 Date : 25/10/2018
 Time : 17:29:22
 Page : 1
 Partsman : s25786
 Del Doc : 003606769

S/N	PART NUMBER	DESCRIPTION	STK	PDC	ISS.	SELLING	DIS	NET	PRICE
***	*****	*****	CT	AT	SOH	QTY	PRICE	%	PRICE
***	*****	*****	**	***	***	****	*****	*****	*****
		V724322							
1	41357284650	FRT RH 2 SIDE PANE		P	I	1	32.15		32.15

bt-
 25/10

CSA Signature : _____
 Date : _____
 Time : _____

Parts Total : 32.15
 Labour Charges : *****

Sub Total :
 Add 7% GST : *****

Customer's Name
 or Contact Person : _____

TOTAL AMOUNT : *****

- Note: (1) The above quotation is based on visual inspection only and may change based on further checks.
 (2) The validity of this quotation is 14 days from the above date.
 (3) Parts are subject to availability.
 (4) Any prices change is without prior notice.

If the quotation is acceptable to you, please confirm your authorization for us to proceed with the job on the understanding that prior approval will be obtained from you before we carry out any further repair or replacement of parts that will affect the safety of the vehicle.

WORKSHOP QUOTATION

GST REG NO : M2 - 0020081 - X

Vehicle No : SLC 9991Y Quotation No : 0000504661
 Chassis No : V 724322 Date : 29/10/2018
 CSA Name : Kevin Time : 12:01:44
 Model Year : Ecjcs Limited Page : 1
 Partsman : p13tansb
 Del Doc : 003608006

S/N	PART NUMBER	DESCRIPTION	CT	AT	SOH	QTY	STK PDC ISS.	SELLING PRICE	DIS %	NET PRICE
1	51357269562	RR RH DOOR QUARTER		P		1		134.00		134.00

CSA Signature : _____ Parts Total : 134.00
 Date : _____ Labour Charges : _____
 Time : _____ Sub Total : _____
 Add 7% GST : _____
 Customer's Name : _____ TOTAL AMOUNT : _____
 or Contact Person : _____

Note: (1) The above quotation is based on visual inspection only and may change based on further checks.
 (2) The validity of this quotation is 14 days from the above date.
 (3) Parts are subject to availability.
 (4) Any prices change is without prior notice.

If the quotation is acceptable to you, please confirm your authorization for us to proceed with the job on the understanding that prior approval will be obtained from you before we carry out any further repair or replacement of parts that will extend the total charges beyond the sum stated.

WORKSHOP QUOTATION

RO: 1309293

GST REG NO : M2 - 0020081 - X

Vehicle No : SLC 9991Y
 Chassis No : V724322
 CSA Name : Kevin
 Model Year : _____

Quotation No : 0000504316
 Date : 24/10/2018
 Time : 10:53:44
 Page : 1
 Partsman : s25786
 Del Doc : 003605562

S/N	PART NUMBER	DESCRIPTION	CT	STK	POC	ISS.	SELLING	DIS	NI
***	*****	*****	**	AT	SOH	QTY	PRICE	%	PRI
		V724322							
1	31126852992	RH WISHBONE	—	P	2	1	262.20		262.20
2	31126855742	RH TENSION STRUT W	—	P	1	1	262.20		262.20
3	33306787062	COMBINATION NUT M1	—	P	2	2	5.55		11.10
4	31316873762	FRT SPRING STRUT	—	P	2	1	484.55		484.55
5	31216792286	FRT RH CARRIER	—	P	1	1	439.10		439.10
6	31206876840	WHEEL HUB WITH BEA	—	P	1	1	465.75		465.75
7	31206783065	COLLAR NUT M12X1.5	—	P	4	4	7.30		29.20
8	31306881929	FRT GUIDE SUPPORT	—	P	X	1	232.00		232.00
9	33326760668	HEX NUT WITH FLANG	—	P	1	1	2.35		2.35
10	36116866302	ALLOY RIM 7JX16 ST	—	P	1	1	724.05		724.05

Rear RH

pyhi 24/10/18 @ 11:35

CSA Signature : _____
 Date : _____
 Time : _____

Parts Total : 2,912.5
 Labour Charges : _____

Sub Total : _____
 Add 7% GST : _____

Customer's Name : _____
 or Contact Person : _____

TOTAL AMOUNT : _____

- Note: (1) The above quotation is based on visual inspection only and may change based on further checks.
 (2) The validity of this quotation is 14 days from the above date.
 (3) Parts are subject to availability.
 (4) Any prices change is without prior notice.

If the quotation is acceptable to you, please confirm your authorization for us to proceed with the job on the understanding that prior approval will be obtained from you before we carry out any further repair or replacement of parts that will extend the total charges beyond the sum stated.

Vehicle ident no.
V724322

Repair order no.
1309293

Technician
4007

Date
24.10.18

License plate no.
SLC9991Y

First reg. date
18.4.16

Model
F20 1 SERIES 2012

Odometer reading: km/miles
54577

Complaints or reason for alignment check

			BEFORE	Target Data		Actual
Rear axle	Camber	left		-1°30'	+/-0°25'	
		right				
		cross		0°00'	+/-0°30'	
	Toe	left	0°13'	0°09'	+/-0°02'	
		right	0°05'			
		total		0°18'	+/-0°04'	
Geometrical driving axis				0°00'	+/-0°12'	
Front axle	Camber	left		-0°20'	+/-0°30'	
		right	-1°07'			-1°10'
		cross	0°46'	0°00'	+/-0°30'	0°49'
	Caster	left	6°09'			6°06'
		right	6°01'			5°57'
		cross		0°00'	+/-0°30'	
	SAI	left	13°05'			12°54'
		right	12°11'			12°39'
		cross	0°54'	0°00'		0°15'
	Track differential angle		left			
			right			
	Toe	left		0°07'	+/-0°02'	
		right	-0°04'			
		total	0°02'	0°14'	+/-0°04'	
Setback				0°00'		
Max steering lock	left steer	left				
		right				
	right steer	left				
		right				



SUPPLEMENTARY

Estimate No. : b1 48806
Date Estimated : 16/10/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Koh Yu
5 West Coast Walk
#21-09

- ACCOUNT - 144674
BCICS Limited
10 Eunus Road 8
Singapore Post Centre #09-04A
Singapore 408600

Singapore 127146

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLC9991Y	V724322	18/04/2016	116d	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

# To remove and install front suspension for inspection include replacement of damaged parts	1128.00		1,128.00	
# To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function (2x)	902.00		902.00	
# To replace rear RH door fixed quarter glass include conducting water leak tests	413.00		413.00	
# To remove and install boot compartment carpet and garnish to facilitate repairs	231.00		231.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# RH WISHBONE *	262.20	1.00		262.20 <i>ht</i>
# RH TENSION STRUT W/HYDRAULIC MOUNT *	262.20	1.00		262.20 <i>ht</i>
# SPHERICAL COLLAR SCREW M12X1.25X45 *	7.70	4.00		30.80 <i>ht</i>
# WHEEL HUB WITH BEARING FRT *	465.75	1.00		465.75 <i>ht</i>
# FRT RH CARRIER *	439.10	1.00		439.10 <i>ht</i>
# FRT GUIDE SUPPORT *	232.00	1.00		232.00 <i>ht</i>
# FRT SPRING STRUT *	484.55	1.00		484.55 <i>ht</i>
# COMBINATION NUT M14X1.5 *	5.55	2.00		11.10 <i>ht</i>
# HEX NUT WITH FLANGE *	2.35	1.00		2.35 <i>ht</i>
# ALLOY RIM 7JX16 STAR SPK 654 *	724.05	1.00		724.05 <i>ht</i>
# RIVET *	0.45	3.00		1.35 <i>ht</i>
# HOUSING LOWER SECTION RH (GENARBT) *	23.85	1.00		23.85 <i>ht</i>
# RR RH DOOR QUARTER GLASS *	134.00	1.00		134.00 <i>ht</i>
# PLAQUE 82MM *	71.25	1.00		71.25 <i>ht</i>
# EXPANDING NUT (4.8) *	1.00	6.00		6.00 <i>ht</i>

Total Labour : 2,674.00
Total Parts : 3,150.55
Total Labour & Parts : 5,824.55



FINAL REPORT

proper function (2x)

# To replace rear RH door fixed quarter glass include conducting water leak tests	413.00	413.00
# To remove and install boot compartment carpet and garnish to facilitate repairs	231.00	231.00
Sundries	150.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
CLAMP	3.20	10.00		32.00
EXPANDING NUT	2.00	6.00		(h) 12.00
# RH WISHBONE *	262.20	1.00		262.20
# RH TENSION STRUT W/HYDRAULIC MOUNT *	262.20	1.00		262.20
# SPHERICAL COLLAR SCREW M12X1.25X45 *	7.70	4.00		30.80
# WHEEL HUB WITH BEARING FRT *	465.75	1.00		465.75
# FRT RH CARRIER *	439.10	1.00		439.10
# FRT GUIDE SUPPORT *	232.00	1.00		232.00
# FRT SPRING STRUT *	484.55	1.00		484.55
# COMBINATION NUT M14X1.5 *	5.55	2.00		11.10
# HEX NUT WITH FLANGE *	2.35	1.00		2.35
# ALLOY RIM 7JX16 STAR SPK 654 *	724.05	1.00		724.05
ALLOY RIM 7JX16 STAR SPK 654	724.05	1.00		724.05
RR RH FENDER	1,295.95	1.00		1,295.95
FRT RH DOOR	1,051.10	1.00		1,051.10
FRT RH FENDER	546.00	1.00		546.00
FRT RH 2 SIDE PANEL BRACKET	32.15	1.00		32.15
RR RH DOOR	1,051.10	1.00		1,051.10
FRT BUMPER RH INSERT	32.15	1.00		32.15
FRT BUMPER PANEL PRIMED	786.20	1.00		786.20
SET PDC HOLDER FRONT	23.10	1.00		23.10
# RIVET *	0.45	3.00		1.35
# HOUSING LOWER SECTION RH (GENARBT) *	23.85	1.00		23.85
FRT DOOR JOINT SEAL	49.65	1.00		49.65
# RR RH DOOR QUARTER GLASS *	134.00	1.00		134.00
# PLAQUE 82MM *	71.25	1.00		71.25
RH HEADLIGHT LED TECHNOLOGY	2,263.60	1.00		2,263.60
EXPANDING NUT	0.55	2.00		(h) 1.10
# EXPANDING NUT (4.8) *	1.00	6.00		6.00
DECOUPLING RING PDC TORQUE CONVERTE	5.05	4.00		20.20
BLIND RIVET AVIBVLB	0.55	20.00		11.00
SCREW (SF PLUS M5X15)	0.55	10.00		5.50
(DG/SL) BODY ADHESIVE K5B (195ML)	281.55	1.00		281.55
PUNCH RIVET N4	0.55	40.00		22.00
(DG) BODYWORK ADHESIVE K5A (50ML)	118.35	1.00		118.35
(DG) CLEANER R1 (100ML)	26.15	1.00		26.15
(DG/SL) ADHESIVE SET K6	53.05	1.00		53.05
(S/L) SEAM SEAL 300ML	33.80	1.00		33.80

SUPPLEMENTARY ITEMS



FINAL REPORT

Total Labour :	19,411.00
Total Parts :	11,622.30
Total Labour & Parts :	31,033.30
Deduction for Excess :	500.00
Total Repair Costs less Excess:	30,533.30
GST @7%:	2,137.33
Grand Total :	32,670.63

...CLAIM SUBFOLDER...(Pending for Survey Report)

Midnight Accident

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Oct 2018 14:25 Edit Reg		17 Oct 2018 00:00 Edit Adj Rpt	\$431,033.30 Edit Estimates	\$431,033.30 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: KOH YU , ID: S9317253A, Email: ZACLI93@GMAIL.COM									
Vehicle Reg. No.: SLC9991Y		Date of Loss: 14/10/2018 04:00 - :59 [29 Months and 26 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / DMPC1800392H		Policy/Cover Note No.: MPC18A00140400 (Comprehensive) Excess: S\$500.00							
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Crystabelle Tan - 6303 0190]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 29/10/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• ECICS (16/05/2019): Alert - Adj Mandate Approved (\$431033.30) - SLC9991Y - Claim Handler: Crystabell... • ECICS (08/05/2019): Alert - Adj Mandate Maintained - SLC9991Y - Claim Handler: Crystabelle Tan • ECICS (27/03/2019): Alert - Adj Mandate Maintained - SLC9991Y - Claim Handler: Crystabelle Tan • ECICS (18/03/2019): Alert - Adj Mandate Maintained - SLC9991Y - Claim Handler: Crystabelle Tan • ECICS (23/10/2018): Alert - Adj Mandate Approved (\$24985.05) - SLC9991Y - Claim Handler: Crystabell...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLC9991Y (DMPC1800392H)
OD
Oct 14 2018 4:00AM
[KOH YU]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/10/18 14:28	Adjuster Immediate Advice	 Load HTM	
2	16/03/19 10:24	Adjuster Immediate Advice	 Load HTM	
3	16/03/19 10:26	Adjuster Immediate Advice	 Load HTM	
4	07/05/19 13:31	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/10/18 15:02	General View	 Load JPG	☒
2	19/10/18 15:02	General View	 Load JPG	☒
3	19/10/18 15:02	General View	 Load JPG	☒
4	19/10/18 15:02	General View	 Load JPG	☒
5	19/10/18 15:02	General View	 Load JPG	☒
6	19/10/18 15:02	General View	 Load JPG	☒
7	19/10/18 15:02	General View	 Load JPG	☒
8	19/10/18 15:02	General View	 Load JPG	☒
9	19/10/18 15:02	General View	 Load JPG	☒
10	19/10/18 15:02	General View	 Load JPG	☒
11	19/10/18 15:02	General View	 Load JPG	☒
12	19/10/18 15:02	General View	 Load JPG	☒
13	19/10/18 15:02	General View	 Load JPG	☒
14	19/10/18 15:02	General View	 Load JPG	☒
15	19/10/18 15:02	General View	 Load JPG	☒
16	19/10/18 15:02	General View	 Load JPG	☒
17	19/10/18 15:02	General View	 Load JPG	☒
18	19/10/18 15:02	General View	 Load JPG	☒
19	19/10/18 15:02	General View	 Load JPG	☒
20	19/10/18 15:02	General View	 Load JPG	☒
21	19/10/18 15:02	General View	 Load JPG	☒
22	19/10/18 15:02	General View	 Load JPG	☒
23	19/10/18 15:02	General View	 Load JPG	☒
24	19/10/18 15:02	General View	 Load JPG	☒
25	19/10/18 15:02	General View	 Load JPG	☒
26	19/10/18 15:02	General View	 Load JPG	☒
27	19/10/18 15:02	General View	 Load JPG	☒
28	19/10/18 15:02	General View	 Load JPG	☒
29	19/10/18 15:02	General View	 Load JPG	☒
30	19/10/18 15:02	General View	 Load JPG	☒
31	19/10/18 15:02	General View	 Load JPG	☒
32	19/10/18 15:02	General View	 Load JPG	☒
33	19/10/18 15:02	General View	 Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
34	19/10/18 15:02	General View	 Load JPG	☒
35	19/10/18 15:02	General View	 Load JPG	☒
36	19/10/18 15:02	General View	 Load JPG	☒
37	19/10/18 15:02	General View	 Load JPG	☒
38	19/10/18 15:02	General View	 Load JPG	☒
39	19/10/18 15:02	General View	 Load JPG	☒
40	19/10/18 15:02	General View	 Load JPG	☒
41	19/10/18 15:02	General View	 Load JPG	☒
42	19/10/18 15:02	General View	 Load JPG	☒
43	19/10/18 15:02	General View	 Load JPG	☒
44	19/10/18 15:02	General View	 Load JPG	☒
45	19/10/18 15:02	General View	 Load JPG	☒
46	19/10/18 15:02	General View	 Load JPG	☒
47	19/10/18 15:02	General View	 Load JPG	☒
48	19/10/18 15:02	General View	 Load JPG	☒
49	19/10/18 15:02	General View	 Load JPG	☒
50	19/10/18 15:02	General View	 Load JPG	☒
51	19/10/18 15:02	General View	 Load JPG	☒
52	19/10/18 15:02	General View	 Load JPG	☒
53	19/10/18 15:02	General View	 Load JPG	☒
54	19/10/18 15:02	General View	 Load JPG	☒
55	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
56	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
57	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
58	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
59	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
60	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
61	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
62	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
63	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
64	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
65	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
66	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
67	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
68	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
69	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
70	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
71	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
72	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
73	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
74	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
75	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
76	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
77	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
78	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
79	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
80	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
81	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
82	16/03/19 10:28	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
83	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
84	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
85	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
86	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
87	16/03/19 10:28	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/10/18 14:58	estimate	 Load PDF	
2	16/03/19 10:37	SUPPLEMENTARY	 Load PDF	
3	27/03/19 10:41	ESTIMATE 2	 Load PDF	
4	14/06/19 12:01	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS18018903/T1TD3E2

Date: 14/06/2019

REFERENCE

Insured/Claimant: KOH YU Policy No: MPC18A00140400
Date of Loss: 14/10/2018 Nature of Claim: OD Claim No: DMPC1800392H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLC9991Y
Make & Model: BMW 116D, 1.6 (A) Engine No: 33929525B37D15A
Reg. Date: 18/04/2016 (Man. Year: 2016) Chassis No: WBA1V72080V724322
Colour: White Odometer: 54577 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$85,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,380.45	11,772.30	608.15	4.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	22,062.00	19,261.00	2,801.00	12.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	34,442.45	31,033.30	3,409.15	9.90
+ GST 7.00/7.00% (S\$)	2,410.97	2,172.33	238.64	9.90
Nett Amount (S\$)	36,853.42	33,205.63	3,647.79	9.90

INSPECTION

Date of Assignment: 17/10/2018
Date Inspected: 18/10/2018 Inspected At: Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 14.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jun 2019)
Parts:	144	BMW 116D 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC9991Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*BLIND PLUG	Not Necessary	1.00 FS	*- FS
3	10		*CLAMP	Necessary	32.00 FS	*32.00 FS
4	1		*ALLOY RIM 7JX16 STAR SPK 654	Cut	724.05 FS	*724.05 FS
5	1		*RR RH FENDER	Bent	1,295.95 FS	*1,295.95 FS
6	1		*REINFORCEMENT PLATE C-PILLAR RH	Not Necessary	49.20 FS	*- FS
7	1		*REINFORCEMENT PLATE ROCKER PLATE RH	Not Necessary	49.20 FS	*- FS
8	1		*FRT RH DOOR	Bent	1,051.10 FS	*1,051.10 FS
9	1		*FRT RH FENDER	Bent	546.00 FS	*546.00 FS
10	1		*REINFORCEMENT PLATE UNIVERSAL	Not Necessary	27.75 FS	*- FS
11	1		*SIDE PANEL BRACKET FRT RH 3	Not Necessary	32.15 FS	*- FS
12	1		*FRT RH 2 SIDE PANEL BRACKET	Bent	32.15 FS	*32.15 FS
13	1		*FRT RH 2 SIDE PANEL BRACKET	Not Necessary	32.15 FS	*- FS
14	1		*RR RH DOOR	Bent	1,051.10 FS	*1,051.10 FS
15	1		*FRT BUMPER LH INSERT	Not Necessary	32.15 FS	*- FS
16	1		*FRT BUMPER RH INSERT	Necessary	32.15 FS	*32.15 FS
17	1		*FRT BUMPER PANEL PRIMED	Cut	786.20 FS	*786.20 FS
18	1		*SET PDC HOLDER FRONT	Necessary	23.10 FS	*23.10 FS
19	1		*SET PMA HOLDERS FRT / REAR	Not Necessary	21.25 FS	*- FS
20	1		*FRT DOOR JOINT SEAL	Necessary	49.65 FS	*49.65 FS
21	1		*FRT RH DOOR CHANNEL INSIDE SEALING	Not Necessary	59.45 FS	*- FS
22	1		*FRT RH DOOR CHANNEL SEALING	Not Necessary	69.95 FS	*- FS
23	1		*B PILLAR FINISHER OUTER RH	Not Necessary	49.25 FS	*- FS
24	1		*COVER WHEEL HOUSING FRT RH	Not Necessary	79.75 FS	*- FS
25	1		*FRT RH WHEEL HOUSING COVER FRT SECT	Not Necessary	104.90 FS	*- FS
26	1		*RH HEADLIGHT LED TECHNOLOGY	Cut	2,263.60 FS	*2,263.60 FS
27	4		*DECOUPLING RING PDC TORQUE CONVERTE	Necessary	20.20 FS	*20.20 FS
28	20		*BLIND RIVET AVIBVLB	Necessary	11.00 FS	*11.00 FS
29	10		*SCREW (SF PLUS M5X15)	Necessary	5.50 FS	*5.50 FS
30	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	281.55 FS	*281.55 FS
31	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	118.35 FS	*118.35 FS
32	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
33	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
34	1		*PUNCH RIVET N4 (40PCS)	Necessary	22.00 FS	*22.00 FS
35	1		*(S/L) SEAM SEAM 300ML	Necessary	33.80 FS	*33.80 FS
36	1		*RH WISHBONE	Bent	262.20 FS	*262.20 FS
37	1		*RH TENSION STRUT W/HYDRAULIC MOUNT	Bent	262.20 FS	*262.20 FS
38	4		*SPHERICAL COLLAR SCREW M12X1.25X45	Necessary	30.80 FS	*30.80 FS
39	1		*WHEEL HUB WITH BEARING FRT	Bent	465.75 FS	*465.75 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRT RH CARRIER	Bent	439.10 FS	*439.10 FS
41	1		*FRT GUIDE SUPPORT	Bent	232.00 FS	*232.00 FS
42	1		*FRT SPRING STRUT	Bent	484.55 FS	*484.55 FS
43	2		*COMBINATION NUT M14X1.5	Necessary	11.10 FS	*11.10 FS
44	1		*HEX NUT WITH FLANGE	Necessary	2.35 FS	*2.35 FS
45	1		*ALLOY RIM 7JX16 STAR SPK 654	Cut	724.05 FS	*724.05 FS
46	3		*RIVET	Necessary	1.35 FS	*1.35 FS
47	1		*HOUSING LOWER SECTION RH (GENARBT)	Necessary	23.85 FS	*23.85 FS
48	1		*RR RH DOOR QUARTER GLASS	Necessary	134.00 FS	*134.00 FS
49	1		*PLAQUE 82MM	Necessary	71.25 FS	*71.25 FS
50	6		*EXPANDING NUT (4.8)	Necessary	6.00 FS	*6.00 FS
51	6		*EXPANDING NUT	Necessary	12.00 FS	*12.00 FS
52	2		*EXPANDING NUT	Necessary	1.10 FS	*1.10 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	12,380.45	11,772.30
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRT BUMPER, FRT RH SIDE PANEL, FRT RH DOOR, REAR RH DOOR, REAR RH SIDE PANEL & ALL ATTACHMENTS CAUSE BY ACCIDENT. TO REPAIR ON REAR BUMPER PANEL	New	10,200.00	8,500.00
2	PAINTING FOR FRT BUMPER, FRT RH SIDE PANEL, FRT RH DOOR, REAR RH DOOR, REAR RH SIDE PANEL & REAR BUMPER	New	5,616.00	5,054.00
3	TO REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIRS INCLUDING EXTRACT FUEL AND CONDUCT LEAK TESTS	New	531.00	451.00
4	TO REMOVE AND INSTALL REAR HAT-TRAY, REAR SEAT, CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS	New	873.00	742.00
5	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION (1X)	New	531.00	451.00
6	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING (1X)	New	94.00	80.00
7	TO CHECK ELECTRICAL WIRING SYSTEMS FOR PROPER FUNCTION	New	177.00	150.00
8	TO REPLACE RIGHT HEADLIGHT	New	481.00	408.00
9	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL) FRT SIDE PANEL)	New	118.00	300.00
10	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL). FRT & REAR RH DOORS)	New	236.00	0.00
11	TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL) REAR RH SIDE PANEL	New	531.00	451.00
12	TO REMOVE AND INSTALL FRONT SUSPENSION FOR INSPECTION INCLUDE REPLACEMENT OF DAMAGED PARTS	New	1,128.00	1,128.00
13	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDE CONDUCTING CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (2X)	New	902.00	902.00
14	TO REPLACE REAR RH DOOR FIXED QUARTER GLASS INCLUDE CONDUCTING WATER LEAK TESTS	New	413.00	413.00
15	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	231.00	231.00
Gross Labour Cost (S\$)			22,062.00	19,261.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >