

ASS. REC. BY:

REF: CS/CTI18018906/R1td3d

Special Instruction:

Surveyor:
Neman

ASSIGNMENT (Office)

From (Person): Elaine Cheong

of CFE

Date/Time: 17/10/18 @ 3:16pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJS 2151 R

Insured: SKT 1430A

at Workshop w/s: Neavnes Automotive
249 Alexandra Road

Tel: 9818 7217

Policy No: DMPCSN3036871803

Claim No: SNM18D04901C02

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 14/10/18

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 3:23pm @ 17/10/18

Person Contacted: Dereck

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJS 2151 R - X
	SKT 1430A - X
	Part by Part \$19,247.60.
	(Red: 5871.15, 23%)

Summary *Pass*

REF: CTL

4800

ASSIGNMENT

From: _____ Date: 22-10-2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: SJS 2151R

at Workshop with: Wearnes

of: 249 Alexandra Rd

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Derek

(Policy Condition) Morning

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No


GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: SJS 2151R Yr Regn: 2016 / MG

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: VOLVO XC90TS cc 1969

Colour: GREY A/C: Insured / Std / NI / NA

Sp Reading: 24862 T/Ratio: Insured / Std / NI / NA

Eng/No: _____

C/No: 4V1LF10AC41110609

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / R/Rim / STD A/Rim or

Tyre Size: F: 235/55R19
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. <u>14/10/18</u>		D.O.I. <u>22/10/18</u>

Survey held at: WEARNES

Des. of Damages: Frt Res / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
RECEIVED 28 NOV 2018.	

Date/Time, File Pass to? : Prel. Report
 : Final Report
 Date/Time, File Return to?

Days Of Repair: 11
 Resurvey No. of Trip: 1

Survey Fee:	<u>270</u>
Transportation:	
S + RS:	
Photos:	
Titles:	
TOTAL:	<u>270</u>

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech Isss (\$)
 Weekend (\$)

Report Format: TP
 Lump Sum / B (\$): 19,247.60

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Oct 2018		17 Oct 2018 15:16 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	WEE YONG KHIM, ID: S8010143J		
Main Claimant:	NG CHEE PENG, ID: S7504890D		
Vehicle Reg. No.:	SJS2151R	Date of Loss:	14/10/2018 13:00 - :59
Claim Type:	TP / SNM18D04901C02	Policy/Cover Note No.:	DMPCSN3036871803 (Comprehensive)
Vehicle Reg. No. (Insured):	SKT1430A	Policy No. (Claimant):	GA247997/1
		Excess:	S\$0.00
Repairer:	Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road, 159935 Alexandra - Tel: 63789370		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/10/2018]		
Driver/Custodian (Insured):	WEE YONG KHIM (38 / Female), NRIC: S8010143J		
Adj Ass. Remarks:	EST \$19,544.18, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/10/2018 11:31
Date Of Accident	14/10/2018 13:30
Exact Location Of Accident	JUNCTION OF QUEENSWAY AND COMMONWEALTH DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS2151R
Insured/Policyholder	
Name Of Registered Owner	NG CHEE PENG
NRIC No	S7504890D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98424365
Alternative Phone No	OTHERS-98424365

Vehicle Particulars

Manufacturer	VOLVO
Model	XC90-2.0 T5 (A)
Exact Purpose for which vehicle was being used at time of accident	SOCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA247997/1
Cover Note Number	

Driver

Name of Driver	NG CHEE PENG
NRIC No	S7504890D
Date Of Birth	15/02/1975
Occupation	INDOOR
Date Of Driving Pass	09/12/1995
Driving Experience	22 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98424365
Fax Number	
Contact Number	OTHERS-98424365
EMail Address	NOEMAIL

Address	9 LEEDON HEIGHTS #20-22
Postcode	267954
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	1
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NG XUAN QING
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT TIMAH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 1 DUKE ROAD , POSTCODE: 268914 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4629999 - FAX NO: 64628933
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please refer attachments.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT1430A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WEE YONG KHIM
NRIC/Passport Number	S8010143J
Contact Number	94515643
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name WEE YONG KHIM

Approximate Age

Injuries Sustain

Injured person in which vehicle? SKT1430A

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing w ith my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as w ell as on the external cover of envelopes/mail packages); and/or
 - (v) complying w ith applicable law in administering, processing, handling and/or dealing w ith my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]
15/10/18
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Refer to sketch plan attached

Commonwealth Dr

SKT1430A SJS2151R



1000

Queensway

→ Farren Road

Zhi

Describe Circumstance of the Accident


Refer to police report attached.

IMPORTANT NOTE

Under **General Condition – Conduct of Claim** of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

Declaration

I/We declare the foregoing particulars are true in every respect.

 15/10/18
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



**SINGAPORE
POLICE FORCE**



T/20181015/2020

1 of 4

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

Report No. T/20181015/2020

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/10/2018 09:10	Vide Report No.:	Station Diary No.: 13
--	------------------	--------------------------

Informant's Particulars

Name of Informant: NG CHEE PENG		Address: 9 LEEDON HEIGHTS #20-22 SINGAPORE 267954	
ID Type / ID No.: NRIC NO / S7504890D		Contact No.: Home/Office: Mobile: 98424365	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 43	Date of Birth: 15/02/1975	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: INTERNAL AUDITOR		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 14/10/2018 13:30	Type of Location: T-Junction
Location: Along Road 1 Traveling Toward Road 2 QUEENSWAY FARRER ROAD ALONG QUEENSWAY TOWARDS FARRER ROAD, AT THE TRAFFIC JUNCTION OF QUEENSWAY AND COMMONWEALTH DRIVE				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJS2151R	Car	VOLVO	XC90 T5 MOMENTU M (A) AWD	Grey	Slightly Damaged	1
SKT1430A	Car	HYUNDAI	HD AVANTE 1.6 A	Beige	Seriously Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJS2151R	AXA INSURANCE SINGAPORE PTE LTD	GA247997	31/08/2018	30/08/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Passenger				
Name	NG XUAN QING		ID No.	T1242131H
Related Vehicle	SJS2151R (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	NG CHEE PENG		ID No.	S7504890D
Related Vehicle	SJS2151R (Car)		Contact No.	98424365
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	WEE YONG KHIM		ID No.	S8010143J
Related Vehicle	SKT1430A (Car)		Contact No.	94515643
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	Slight



**SINGAPORE
POLICE FORCE**



T/20181015/2020

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

3 of 4

Report No. T/20181015/2020

CONTINUATION OF REPORT

Brief Details.

On 14/10/2018 at about 1.30pm, I was driving my car (SJS2151R) along Queensway towards Farrer Road, at the traffic junction of Queensway and Commonwealth Drive. As the traffic light had turned red, I stopped my vehicle at the stop line when another car (SKT1430A) suddenly collided into the rear of my car.

At the point of time, the road surface was wet and the weather was drizzling. Both the other driver and I stepped out of our cars to make a check. At the point of time, my daughter and I were not injured. The rear bumper as well as the exhaust pipe of car (SJS2151R) was damaged. The rear panel of my car also sustained some dents.

The other front of the other car SKT1430A damaged. We then exchanged our particulars and left. I was informed by the other driver at 10.04pm that she had received 7 days medical leave due to the accident.



**SINGAPORE
POLICE FORCE**



T/20181015/2020

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

4 of 4


Report No. T/20181015/2020

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: E / Sgt 2 NURFARRAH ADTIQAH BINTE ADNAN	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 15/10/2018 09:10
Officer In Charge Of Case: TP / AEIT / SSI 2 JUREMAH BINTE AHMAD Contact No.: 65472076	Classification Of Case:
Authentication Stamp NP168	



WEARNES

✓
in 22/10/18

SERVICE ESTIMATE

86752 - C00001 SL: SERVICE SALES - PC

Mr Ng Chee Peng
9 Leedon Heights
#20-22

Singapore 269754

GST Reg.No:M28920628X
Inv.No. : B&P 0 Page 1
Inv.date: : 16/10/2018
WIP No. : 33006
Veh.In/Out: 15/10/2018
*Tel.No. : Mobile: 98424365
Reg.No. : SJS2151R
Reg.date : 31/08/2016
Mileage : 0
Chassis No: YV1LF10ACH1110609

Closed by : Derek Oh Siong Mee
Svc Consultant :
Remarks : Mr Ng Chee Peng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BOOT LID,REAR EMBLEM,REAR BUMPE,REAR LOWER SPOILER,REAR SKID PLATE,REAR SENSOR, REAR BRACKET,REAR BEAM,REAR END PANEL,.ETC	0	5600.00	0		5,600.00 S	4000 ✓
800	TO PUTTY SPRAY PAINT ON REAR BOOT LID,REAR BUMPER,REAR LOWER SPOILER,ETC	0	3500.00	0		3,500.00 S	2800 ✓
802	TO TRANSFER REAR BOOT LID PART	0	250.00	0		250.00 S	✓
802	TO REPLACE REAR EXHAUST	0	1000.00	0		1,000.00 S	800 ✓
802	TO REPLACE REAR WINDSCREEN	0	800.00	0		800.00 S	✓
89994	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00 S	✓
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00 S	✓
	BUMPER COVER REAR UP	1.0 EA	1447.80			1,447.80 S	PE- 1303.02
	BUMPER SPOILER REAR	1.0 EA	472.50			472.50 S	PE- 425.25

SERVICE ESTIMATE

86752 - C00001
 Mr Ng Chee Peng
 9 Leedon Heights
 #20-22

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Singapore 269754

Inv.No. . : B&P 0 Page 2
 Inv.date. : 16/10/2018
 WIP No. . : 33006
 Veh.In/Out: 15/10/2018
 *Tel.No. . : Mobile: 98424365
 Reg.No. . : SJS2151R
 Reg.date. : 31/08/2016
 Mileage . : 0
 Chassis No: YV1LF10ACH1110609

Closed by : Derek Oh Siang Wee
 Svc Consultant :
 Remarks : Mr Ng Chee Peng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	U
	BUMPER BRACKET LHR X	1.0 EA	79.10			79.10	\$ M-
	BUMPER BRACKET RHR X	1.0 EA	79.10			79.10	\$ M-
	BUMPER REFLECTOR LHR	1.0 EA	71.00			71.00	\$ SCA-
	BUMPER REFLECTOR RHR	1.0 EA	71.00			71.00	\$ SCA-
	PROTECTING PLATE REA	1.0 EA	253.00			253.00	\$? PA/
	HEAT SHIELD REAR XC9	1.0 EA	426.00			426.00	\$ PA-
	SILENCER TS MOH XC90	1.0 EA	732.50			732.50	\$ M-
	EXHAUST PIPE LH T5 H	1.0 EA	156.20			156.20	\$ PA-
	EXHAUST PIPE RH T5 H	1.0 EA	156.20			156.20	\$? PA/
	END PIPE CHROME XC90	1.0 EA	123.20			123.20	\$ SCA-
	EXHAUST CLAMP 65mm X	1.0 EA	114.10			114.10	\$ M-
	BUMPER RAIL (BEAM) R	1.0 EA	1360.60			1,360.60	\$? M-
	TAILGATE REAR XC90 I	1.0 EA	3285.80			3,285.80	\$ M-
	EMBLEM 'VOLVO' REAR	1.0 EA	92.00			92.00	\$ M-
	EMBLEM 'XC 90' XC90	1.0 EA	95.90			95.90	\$ M-
	EMBLEM 'T5' XC60 S80	1.0 EA	88.00			88.00	\$ M-
	EMBLEM	1.0 EA	23.90			23.90	\$ M-

SERVICE ESTIMATE

86752 - C00001
Mr Ng Chee Peng
9 Leedon Heights
#20-22

SL: SERVICE SALES - PC

Singapore 269754

Closed by : Derek Oh Siong Wee
Svc Consultant :
Remarks : Mr Ng Chee Peng

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 3
Inv.date. : 16/10/2018
WIP No. . : 33006
Veh.In/Out: 15/10/2018
*Tel.No. . : Mobile: 98424365
Reg.No. . : SJS2151R
Reg.date. : 31/08/2016
Mileage . : 0
Chassis No: YV1LF10ACH1110609

Op.No	Description	Mech Qty	Price	Disc%	PKG	Amount	G
	Emblem 'AWD' XC90 16	1.0 EA	78.10			78.10	S
	WINDSCREEN REAR XC90	1.0 EA	1461.40			1,461.40	S
	O WINDSCREEN SEALA	2.0 EA	122.10			244.20	S
	O PRIMER GLASS & P	1.0 EA	37.40			37.40	S
	O GLASS CLEANER H	1.0 EA	55.40			55.40	S
	Parking assistance,	1.0 EA	999.10			999.10	S
	BLIND RIVET 4.0*21 P	10.0 EA	3.00			30.00	S
	BUMPER CLIP	10.0 EA	5.40			54.00	S
	ADHESIVE TUBE CHEMIC	4.0 EA	75.80			303.20	S
	BUMPER INSTALLING MT	1.0 EA	83.40			83.40	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____
Date: _____

Labour Total 11,880.00
Parts Total 12,474.10
Package Total 0.00

Gross Total. 24,354.10
Net..... 24,354.10
GST @ 7.0% 1,704.79
Total..... 26,058.90
Paid..... 0.00
Please Pay.. 26,058.90

Handwritten notes:
Resurvey 54 part
24/10/18
11 days
24/10/18 @ 1100
Hp 900 10068

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

25/11/18

SERVICE ESTIMATE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 3 ANSON ROAD Inv.No. . : B&P 0 Page 1
 #16-00, SPRINGLEAF TOWER Inv.date. : 09/11/2018
 SINGAPORE 079909 WIP No. . : 33006
 Veh.In/Out: 22/10/2018 05/11/2018

Closed by : Richmond Ho
 Svc Consultant : ACC
 Remarks : Mr Ng Chee Peng

*Tel.No. . : 63896111
 Reg.No. . : SJS2151R
 Reg.date . : 31/09/2016
 Mileage .. : 25,985
 Chassis No: YVILF10ACH1110609

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BOOT LID,REAR EMBLEM,REAR BUMPE,REAR LOWER SPOILER,REAR SKID PLATE,REAR SENSOR, REAR BRACKET,REAR BEAM,REAR END PANEL,..ETC	0	4000.00	0		4,000.00	
800	TO PUTTY SPRAY PAINT ON REAR BOOT LID,REAR BUMPER,REAR LOWER SPOILER,ETC	0	2800.00	0		2,800.00	
802	TO TRANSFER REAR BOOT LID PART	0	250.00	0		250.00	
802	TO REPLACE REAR EXHAUST	0	800.00	0		800.00	
802	TO REPLACE REAR WINDSCREEN	0	800.00	0		800.00	
89994	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00	
280	TO CHECK WIRING INCLUDE	0	450.00	0		450.00	
	RESETTING OF ALL ELECTRICAL MODULES						
	BUMPER COVER REAR UP ①	1.0 EA	1447.80	10		1,303.02	S
	BUMPER SPOILER REAR ②	1.0 EA	472.50	10		425.25	S

SERVICE ESTIMATE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 3 ANSON ROAD Inv.No. . : B&P 0 Page 3
 #16-00, SPRINGLEAF TOWER Inv.date: : 09/11/2018
 SINGAPORE 079909 WIP No. . : 33006
 Veh.In/Out: 22/10/2018 05/11/2018

*Tel.No. . : 63896111
 Reg.No. . : SJS2151R
 Reg.date: : 31/08/2016
 Mileage . : 25,985
 Chassis No: YV1LF10ACH1110609

Closed by : Richmond Ho
 Svc Consultant : ACC
 Remarks : Mr Ng Chee Peng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	D PRIMER GLASS & P (25)	1.0 EA	37.40	10		33.66	S
	D GLASS CLEANER H (24)	1.0 EA	55.40	10		49.86	S
	BLIND RIVET 4.0*21 P (66)	10.0 EA	3.00	10		27.00	S
	BUMPER CLIP (67)	10.0 EA	5.40	10		48.60	S
	ADHESIVE TUBE CHEMIC (28)	4.0 EA	75.80	10		272.68	S
	EXHAUST PIPE RH T5 M (27)	1.0 EA	156.20	10		140.58	S
	SENSOR	2.0 EA	139.30	10		250.74	S
	FMD SENSOR XC90 16-	1.0 EA	365.00	10		320.50	S
	PROTECTING PLATE REA	1.0 EA	253.00	10		227.70	S
	END PIPE CHROME XC90	1.0 EA	123.20	10		110.88	S
	PARK HOLDER CTR LH X	1.0 EA	41.40	10		37.26	S
	PARK HOLDER CTR RH X	1.0 EA	41.40	10		37.26	S
	BUMPER INSTALLING M (21) Acc	1.0 EA	83.40	10		75.06	S

Gross Total. 19,247.60

Labour Total 9,380.00
 Parts Total 9,867.60
 Package Total 0.00

Net..... 19,247.60
 GST @ 7.0% 1,347.32
 Total..... 20,594.92
 Paid..... 0.00
 Please Pay.. 20,594.92

GSI: S=StdRated; O=OutOfScope; Z=ZeroRated

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Oct 2018		17 Oct 2018 15:16 Edit Adj Rpt	S\$19,247.60 Edit Estimates	S\$19,247.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	WEE YONG KHIM , ID: S80101433								
Main Claimant:	NG CHEE PENG , ID: S7504890D								
Vehicle Reg. No.:	SJS2151R	Date of Loss:	14/10/2018 13:00 - :59 [25 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04901C02	Policy/Cover Note No.:	DMPCSN3036871803 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKT1430A	Policy No. (Claimant):	GA247997/1						
		Excess:	S\$0.00						
Repairer:	Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road, 159935 Alexandra - Tel: 63789370								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 26/10/2018]								
Driver/Custodian (Insured):	WEE YONG KHIM (38 / Male), NRIC: S80101433								
Adj Asg. Remarks:	EST \$19,544.18, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJS2151R (SNM18D04901C02)
[SKT1430A]
TP
NG CHEE PENG
Oct 14 2018 1:00PM
[WEE YONG KHIM]
Wearnes Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Assessment Reports									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)		Thumbnail	Print					
1	15/10/18 11:59	Accident Statement		Load HTML	<input checked="" type="checkbox"/>					
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)		Thumbnail	Print					
1	15/10/18 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
2	15/10/18 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
3	15/10/18 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
4	15/10/18 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
5	15/10/18 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
6	15/10/18 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
7	15/10/18 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
8	15/10/18 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
9	15/10/18 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
10	15/10/18 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
11	15/10/18 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
12	15/10/18 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
13	15/10/18 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
14	15/10/18 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
15	15/10/18 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>					
2	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>					
3	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>					
4	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>					
5	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>					
6	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>					
7	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>					
8	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>					
9	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>					
10	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>					
11	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>					
12	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>					
13	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>					

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)		Thumbnail	Print
					<input checked="" type="checkbox"/>
14	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>
15	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>
16	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>
17	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>
18	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>
19	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>
20	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>
21	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>
22	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>
23	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>
24	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>
25	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>
26	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>
27	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>
28	23/11/18 13:30	General View		Load JPG	<input checked="" type="checkbox"/>
29	23/11/18 13:31	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
30	23/11/18 13:31	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
31	23/11/18 13:31	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
32	23/11/18 13:31	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
33	23/11/18 13:31	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
34	23/11/18 13:31	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
35	23/11/18 13:31	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
36	23/11/18 13:31	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	17/10/18 15:15	EMAIL FM WEARNES		Load PDF	
2	17/10/18 15:15	REPAIR EST WITH TP GIA		Load PDF	
3	17/10/18 15:16	OI GIA		Load PDF	
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)		Thumbnail	Print
1	15/10/18 11:53	Sketch Plan [Linked Accident Report Documents]		Load TIF	
2	15/10/18 11:53	Sketch Plan #2 [Linked Accident Report Documents]		Load TIF	
3	15/10/18 11:53	Sketch Plan #3 [Linked Accident Report Documents]		Load TIF	
4	15/10/18 11:53	Sketch Plan #4 [Linked Accident Report Documents]		Load TIF	
5	15/10/18 11:53	Sketch Plan #5 [Linked Accident Report Documents]		Load TIF	
6	15/10/18 11:53	Sketch Plan #6 [Linked Accident Report Documents]		Load TIF	
7	15/10/18 11:54	Accident Sketch Plan [Linked Accident Report Documents]		Load TIF	
8	15/10/18 11:54	Accident Sketch Plan [Linked Accident Report Documents]		Load TIF	
9	15/10/18 11:54	Accident Sketch Plan [Linked Accident Report Documents]		Load TIF	
10	15/10/18 11:54	Accident Sketch Plan [Linked Accident Report Documents]		Load TIF	
11	15/10/18 11:54	Accident Sketch Plan [Linked Accident Report Documents]		Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/12/18 10:41	Supplementary		Load PDF	

Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	Thumbnail	Print
1	15/10/18 11:59	Accident Statement	Load HTM	<input type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	Thumbnail	Print
1	15/10/18 11:56	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	15/10/18 11:56	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	15/10/18 11:56	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	15/10/18 11:56	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	15/10/18 11:56	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	15/10/18 11:56	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	15/10/18 11:56	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	15/10/18 11:56	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	15/10/18 11:56	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	15/10/18 11:56	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	15/10/18 11:56	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	15/10/18 11:56	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	15/10/18 11:56	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	15/10/18 11:56	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	15/10/18 11:56	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	Thumbnail	Print
1	15/10/18 11:53	Sketch Plan	Load TIF	<input type="checkbox"/>
2	15/10/18 11:53	Sketch Plan #2	Load TIF	<input type="checkbox"/>
3	15/10/18 11:53	Sketch Plan #3	Load TIF	<input type="checkbox"/>
4	15/10/18 11:53	Sketch Plan #4	Load TIF	<input type="checkbox"/>
5	15/10/18 11:53	Sketch Plan #5	Load TIF	<input type="checkbox"/>
6	15/10/18 11:53	Sketch Plan #6	Load TIF	<input type="checkbox"/>
7	15/10/18 11:54	Accident Sketch Plan	Load TIF	<input type="checkbox"/>
8	15/10/18 11:54	Accident Sketch Plan	Load TIF	<input type="checkbox"/>
9	15/10/18 11:54	Accident Sketch Plan	Load TIF	<input type="checkbox"/>
10	15/10/18 11:54	Accident Sketch Plan	Load TIF	<input type="checkbox"/>
11	15/10/18 11:54	Accident Sketch Plan	Load TIF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118018906/R1TD3E2

Date: 04/12/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN3036871803	
Claimant Vehicle No: SJS2151R	Insured Vehicle No: SKT1430A	
Date of Loss: 14/10/2018	Nature of Claim: TP	Claim No: SNM18D04901C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJS2151R	Engine No: B4204T231667127
Make & Model: VOLVO XC90, 2.0 T5 (A)	Chassis No: YV1LF10ACH1110609
Reg. Date: 31/08/2016 (Man. Year: 2016)	Odometer: 24862 km
Colour: Grey	
Engine Capacity: 1969 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,238.74	9,867.60	3,371.14	25.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,880.00	9,380.00	2,500.00	21.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	25,118.74	19,247.60	5,871.14	23.37
+ GST 7.00/7.00% (S\$)	1,758.31	1,347.33	410.98	23.37
Nett Amount (S\$)	26,877.05	20,594.93	6,282.12	23.37

INSPECTION

Date of Assignment:	17/10/2018	
Date Inspected:	22/10/2018 Inspected At:	Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road Singapore 159935
Estimated Period of Repair:	11.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Dec 2018)
Parts:	M1-SUV	VOLVO XC90 2.0 T5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS2151R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR UP	Deformed	1,447.80 FS	*1,303.02 FS
2	1		*BUMPER SPOILER REAR	Deformed	472.50 FS	*425.25 FS
3	1		*BUMPER BRACKET LHR X	Necessary	79.10 FS	*71.19 FS
4	1		*BUMPER BRACKET RHR X	Necessary	79.10 FS	*71.19 FS
5	1		*BUMPER REFLECTOR LHR	Scratched	71.00 FS	*63.90 FS
6	1		*BUMPER REFLECTOR RHR	Scratched	71.00 FS	*63.90 FS
7	1		*PROTECTING PLATE REA	Bent	253.00 FS	*227.70 FS
8	1		*HEAT SHIELD REAR XC9	Bent	426.00 FS	*383.40 FS
9	1		*SILENCER T5 MOM XC90	Bent	732.50 FS	*659.25 FS
10	1		*EXHAUST PIPE LH T5 M	Bent	156.20 FS	*140.58 FS
11	1		*EXHAUST PIPE RH T5 M	Bent	156.20 FS	*140.58 FS
12	1		*END PIPE CHROME XC90	Scratched	123.20 FS	*110.88 FS
13	1		*EXHAUST CLAMP 65MM X	Necessary	114.10 FS	*102.69 FS
14	1		*BUMPER RAIL (BEAM) R	Serviceable	1,360.60 FS	*- FS
15	1		*TAILGATE REAR XC90 1	Bent	3,285.80 FS	*2,957.22 FS
16	1		*EMBLEM VOLVO REAR	Necessary	92.00 FS	*82.80 FS
17	1		*EMBLEM XC 90 XC90	Necessary	95.90 FS	*86.31 FS
18	1		*EMBLEM T5 XC60 S80	Necessary	88.00 FS	*79.20 FS
19	1		*EMBLEM	Necessary	23.90 FS	*21.51 FS
20	1		*EMBLEM AWD XC90 16	Necessary	78.10 FS	*70.29 FS
21	1		*WINDSCREEN REAR XC90	Necessary	1,461.40 FS	*1,315.26 FS
22	2		**D* WINDSCREEN SEALA	Necessary	244.20 FS	*219.78 FS
23	1		**D* PRIMER GLASS & P	Necessary	37.40 FS	*33.66 FS
24	1		**D* GLASS CLEANER H	Necessary	55.40 FS	*49.86 FS
25	1		*PARKING ASSISTANCE	Serviceable	999.10 FS	*- FS
26	10		*BLIND RIVET 4.0*21 P	Necessary	30.00 FS	*27.00 FS
27	10		*BUMPER CLIP	Necessary	54.00 FS	*48.60 FS
28	1		*BUMPER INSTALLING MT	Necessary	83.40 FS	*75.06 FS
29	2		*SENSOR	Not Working	250.74 FS	*250.74 FS
30	1		*FMD SENSOR XC90 16-	Not Working	328.50 FS	*328.50 FS
31	1		*END PIPE CHROME XC90	Scratched	110.88 FS	*110.88 FS
32	1		*PARK HOLDER CTR LH X	Cracked	37.26 FS	*37.26 FS
33	1		*PARK HOLDER CTR RH X	Cracked	37.26 FS	*37.26 FS
34	4		*ADHESIVE TUBE CHEMIC	Necessary	303.20 FS	*272.88 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	13,238.74	9,867.60
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BOOT LID, REAR EMBLEM, REAR BUMPE, REAR LOWER SPOILER, REAR SKID PLATE, REAR SENSOR, REAR BRACKET, REAR BEAM, REAR END PANEL, ETC	New	5,600.00	4,000.00
2	TO PUTTY SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, REAR LOWER SPOILER, ETC	New	3,500.00	2,800.00
3	TO TRANSFER REAR BOOT LID PART	New	250.00	250.00
4	TO REPLACE REAR EXHAUST	New	1,000.00	800.00
5	TO REPLACE REAR WINDSCREEN	New	800.00	800.00
6	TO INSTALL REAR WINDSCREEN FIL	New	280.00	280.00
7	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	450.00	450.00
Gross Labour Cost (S\$)			11,880.00	9,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >