



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLG 4299 A

Not Authorized

Parts	(a) Cost / List Price Items	\$	1,382.50
	Plus/Less 25%	\$	345.63
	Total of Cost / List	\$	1,036.88
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost			
Labour		\$	1,420.00
Total		\$	2,456.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 24/1/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / ~~is not~~ authorized until further notice.

(b) Recommended Days of Repair : 2-3 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Lc Date: 24/1/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLG 4299 A**
Make & Model : **TOYOTA PRIUS**
Chassis No. : **JTDKB3FU803535154**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear bumper	1	\$497.50		?
2	Rear bumper clip	10	\$40.00		?
3	Rear bumper side retainer RH	1	\$112.70		?
4	Rear bumper lower garnish centre	1	\$582.60		✓
5	Rear bumper lower garnish RH	1	\$149.70		X
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

