

22/03/2018

A.S. REC. BY:

REF: CS3/MSG18004539/R18b⁰⁷

Special Instruction:

Survivor:

Menner

Result

ASSIGNMENT (Office)

From (Person):

Elaine Ngu

of

MSG

Date/Time:

17/10/2018

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 7703X

Insured:

SLF 220H

at Workshop m/s

MJE Motor

Tel:

6454 2203

of

Blk 7 Sin Ming Sec C #01-96

Policy No:

D29032791QMY

Claim No:

551379

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 5/3/2018

CA / REV / REP. / REV 24 HRS

'wp'

Date/Time:

9:17am 9/3/18

Person Contacted:

joyce

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction

(x) Estimate

Do Not Finalize

SJR 7703X - x

SLF 220H - x

After repair: 15/3/2018

07/11/18

Submit L/s \$2,650/- @ 5 days
checked by Simon.

(\$1,850/- Red - 41%)

Submit report by 26 Oct 2018

RECEIVED 07 NOV 2018

Repair days 5

TEAM

lim

7/11/18

Rasm

MSIG

6288F

ASSUMED

Date 9/3/18

Estimated Cost

OD (P) NS/TP RES/OD RES/EVA/INV/MY

To Insure Vehicle No

SJR 7703 X

at Workshop No

MJE Motor

Blk 7 Sin Ming Sec C #01-96

Insured

Policy No

Claims No

Sum Insured

Excess

Clients Record

Make of Van

Policy Condition

Remarks: The van had commenced its repair at the time of inspection.

NS	OS

Sal. or Market Value

23K

DAD Accident Report

Consistent? Yes or No

GIA PP Seen

Consistent? Yes or No

Est. Records

5

days

Yes or No

Lim Sum

5

Yes or No

CA / REV / REP / 24 HRS

Wp

Date

Person Contacted

Vehicle IN / OUT

Date Time Action Instruction

* Repair Estimate : S\$ 4000-5000

* 5 days

If/ Submit PRE report.

RECEIVED 6/11/2018

Date Time File Passed

☐

Preli. Report

☐

Final Report

Date Time File Returned

Days Of Repair

Resurvey No. of Trip

Surf Fee

120

50

Add Fee

☐

Shoring

☐

Shoring

☐

Shoring

☐

Shoring

10

180

Record Format

PRE

Auto Sum

SJR 7703 X

2009 July

2009 11/03/18

Track The end

Name

TOYOTA COROLLA ALTIS 1.6A 1598

Color

Grey

St. Record

115147

Eng No

Chassis

MR053200106148930

Get into Good

Pool Burnt

Steering

Jammed Leaked Burnt or

Brake

Jammed Leaked Burnt or

Mod

STD Air Pump or

Tire Size

195/65R15

BS/DUN EXNOVA 3Y FS LIA MR CHSL PR SUM

TOYO YOKO

Body

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Fea

5

Days Of Repair

Resurvey No. of Trip

Surf Fee

120

50

Add Fee

☐

Shoring

☐

Shoring

☐

Shoring

☐

Shoring

☐

Shoring

☐

Shoring

☐

Shoring

☐

Shoring

☐

Shoring

10

180

Catherine Chong (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 17 October, 2018 5:13 PM
To: assignments; Admin-D (LKKAuto)
Subject: RE: Your ref: CS3/MSG18004539/R1D3E2 Our ref: 551379 Paper reinspection for SJR7703X

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Keny Ong [mailto:Keny_Ong@sg.msg-asia.com]
Sent: Wednesday, 17 October 2018 1:49 PM
To: sur@lkkauto.com
Subject: Your ref: CS3/MSG18004539/R1D3E2 Our ref: 551379 Paper reinspection for SJR7703X

Dear Nivitha

We had appointed your firm to carry out a PRI on TP vehicle SJR7703X recently.

Please carry out a paper reinspection of SJR7703X and let us have the report by 26 Oct 2018.

The survey report and photos of SJR7703X had been uploaded in merimen.

Please acknowledge receipt of this email.

Have a great day !

Keny Ong

Senior Executive, Claims Services (Motor)

Direct line +65 6643 1309 | Direct fax +65 6225 7402 | keny_ong@sg.msg-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg   

A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Mar 2018		08 Mar 2018 17:18 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																																								
<div style="border: 1px solid black; padding: 5px;"> CLAIM SUBFOLDER DETAILS [Created by insurer] <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Insured:</td> <td colspan="3">NGIAM HIAN YONG, JEFFREY, ID: S8907931D, Tel: +6591195676</td> </tr> <tr> <td>Main Claimant:</td> <td colspan="3">CHIA HWEE KHIANG VICTOR, ID: S7106268F</td> </tr> <tr> <td>Vehicle Reg. No.:</td> <td>SJR7703X</td> <td>Date of Loss:</td> <td>05/03/2018 06:00 - :59 [103 Months and 20 Days From LTA Reg Date (Man Yr)]</td> </tr> <tr> <td>Claim Type:</td> <td>TP / 551379</td> <td>Policy/Cover Note No.:</td> <td>D29032791QMY (Comprehensive) Coverage: 31/10/2017 - 30/10/2018</td> </tr> <tr> <td>Vehicle Reg. No. (Insured):</td> <td>SLF220H</td> <td>Policy No. (Claimant):</td> <td></td> </tr> <tr> <td>Repairer:</td> <td colspan="3">Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82, 575642 Sin Ming - Tel:</td> </tr> <tr> <td>Handling Insurer:</td> <td colspan="3">MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]</td> </tr> <tr> <td>Adjuster:</td> <td colspan="3">LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 19/10/2018]</td> </tr> <tr> <td>Driver/Custodian (Insured):</td> <td colspan="3">NGIAM HAN YONG, JEFFREY (), NRIC: S8907931D, Tel: +6591195676</td> </tr> <tr> <td>Adj Asg. Remarks:</td> <td colspan="3">MJE Motor Block 7 Sin Ming Industrial Estate Sector C #01-96 S(575642) Tel No.: 6454-2203; Fax No. 6452-3308</td> </tr> </table> </div>					Insured:	NGIAM HIAN YONG, JEFFREY, ID: S8907931D, Tel: +6591195676			Main Claimant:	CHIA HWEE KHIANG VICTOR, ID: S7106268F			Vehicle Reg. No.:	SJR7703X	Date of Loss:	05/03/2018 06:00 - :59 [103 Months and 20 Days From LTA Reg Date (Man Yr)]	Claim Type:	TP / 551379	Policy/Cover Note No.:	D29032791QMY (Comprehensive) Coverage: 31/10/2017 - 30/10/2018	Vehicle Reg. No. (Insured):	SLF220H	Policy No. (Claimant):		Repairer:	Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82, 575642 Sin Ming - Tel:			Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]			Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 19/10/2018]			Driver/Custodian (Insured):	NGIAM HAN YONG, JEFFREY (), NRIC: S8907931D, Tel: +6591195676			Adj Asg. Remarks:	MJE Motor Block 7 Sin Ming Industrial Estate Sector C #01-96 S(575642) Tel No.: 6454-2203; Fax No. 6452-3308		
Insured:	NGIAM HIAN YONG, JEFFREY, ID: S8907931D, Tel: +6591195676																																											
Main Claimant:	CHIA HWEE KHIANG VICTOR, ID: S7106268F																																											
Vehicle Reg. No.:	SJR7703X	Date of Loss:	05/03/2018 06:00 - :59 [103 Months and 20 Days From LTA Reg Date (Man Yr)]																																									
Claim Type:	TP / 551379	Policy/Cover Note No.:	D29032791QMY (Comprehensive) Coverage: 31/10/2017 - 30/10/2018																																									
Vehicle Reg. No. (Insured):	SLF220H	Policy No. (Claimant):																																										
Repairer:	Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82, 575642 Sin Ming - Tel:																																											
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]																																											
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 19/10/2018]																																											
Driver/Custodian (Insured):	NGIAM HAN YONG, JEFFREY (), NRIC: S8907931D, Tel: +6591195676																																											
Adj Asg. Remarks:	MJE Motor Block 7 Sin Ming Industrial Estate Sector C #01-96 S(575642) Tel No.: 6454-2203; Fax No. 6452-3308																																											
<div style="border: 1px solid black; padding: 5px;"> ASSOCIATED MAIL RECEIVED View All Compose Case Mail <ul style="list-style-type: none"> MSIG_SG (17/10/2018): Report Send Back Alerts - SJR7703X (TP) </div>																																												
<div style="border: 1px solid black; padding: 5px;"> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.																													
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?																																			
No results.																																												



LEE AUTOMOBILE APPRAISERS SERVICES

CORRESPONDENCE : BUKIT PANJANG POST OFFICE P.O.BOX 244, SINGAPORE 916809
FAX: (65) 6763 3827, HANDPHONE: 8188 2833
BUSINESS REG. NO.: 52891429D

TO: **CHIA HWEE KHLANG VICTOR**
c/o BLK 7 SIN MING IND. EST. SECTOR C
#01-96
SINGAPORE 575642

INVOICE NO. L18030832
YOUR REF
OUR REF LEE/TP/03/2030/18
DATE 26 MAR 2018

PARTICULARS		AMOUNTS (\$\$)
VEHICLE REGISTRATION NO.	SJR 7703 X	\$605.00
MAKE/MODEL	TOYOTA ALTIS	
TO OUR PROFESSIONAL CHARGES FOR		
<input checked="" type="checkbox"/> INSPECTION OF VEHICLE		
<input checked="" type="checkbox"/> APPRAISAL REPORT		
<input checked="" type="checkbox"/> PHOTOGRAPHY		
<input checked="" type="checkbox"/> TRANSPORT CHARGES		
<input checked="" type="checkbox"/> REINSPECTION OF VEHICLE		
<input type="checkbox"/> AUTOMOTIVE CONSULTATION		
<input checked="" type="checkbox"/> CORRESPONDENCE, POSTAGE & OTHER DISBURSEMENT		
<input type="checkbox"/> OTHERS		
<input type="checkbox"/>		
<input type="checkbox"/>		
DOLLARS:	SIX HUNDRED AND FIVE ONLY	

(* CHEQUE SHOULD BE CROSSED AND MAKE PAYABLE TO "LEE AUTOMOBILE APPRAISERS SERVICES")



LEE AUTOMOBILE APPRAISERS SERVICES



LEE AUTOMOBILE APPRAISERS SERVICES

CORRESPONDENCE : BUKIT PANJANG POST OFFICE P.O.BOX 244, SINGAPORE 916809
FAX: (65) 6763 3827, HANDPHONE: 8188 2833
BUSINESS REG. NO.: 52891429D

TO: CHIA HWEE KHIANG VICTOR

c/o BLK 7 SIN MING IND. EST. SECTOR C

#01-96

SINGAPORE 575642

OUR REF.LEE/TP/03/2030/18

DATE 26 MAR 2018

AUTOMOBILE APPRAISAL REPORT

Vehicle Registration No. : SJR 7703 X
Make/Model : Toyota Altis
Year Manufacture/Register : 2009
Colour : Green
Engine No. : Obscure
Chassis No. : MR053ZEE10615248930
Odometer Reading : 115147km
Nature Of Inspection : Third Party
Date Of Accident : 05 Mar 2018
Date Of Inspection : 09 Mar 2018
Name of Workshop : MJE Motor
Place Of Inspection : Blk 7 Sin Ming Ind. Est. Sector C #01-96
: Singapore 575642

TYRE CONDITION ON VEHICLE

Location	Make	Size	Thread Balance
Nearside Front	Michelin	195/65R15	8mm
Offside Front	Michelin	195/65R15	8mm
Nearside Rear	Michelin	195/65R15	8mm
Offside Rear	Michelin	195/65R15	8mm

*(The above represent on estimated remaining life of the tyre thread in mm)

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The damages sustained on the vehicle were apparently confined at its rear portion.

(Details are describe in the attached schedule)

NOTE : This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items in this survey, kindly notify the company within (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.

LEE AUTOMOBILE APPRAISERS SERVICES

CORRESPONDENCE : BUKIT PANJANG POST OFFICE P.O.BOX 244, SINGAPORE 916809
FAX: (65) 6763 3827, HANDPHONE: 8188 2833
BUSINESS REG. NO.: 52891429D

APPRAISEMENT SCHEDULE

Vehicle Registration No: SJR 7703 X

Our Ref.LEE/TP/03/2030/18

S/NO.	Qty	Description	Comments/ Conditions	Repairer's Estimate	Assessed Amount	
		(LIST ITEMS)				
1	1	Rear boot lid	distorted/cut/bent	\$ 528.80	\$ 528.80	DDV
2	1	Rear boot lid weatherstrip	essential	\$ 68.00	\$ 68.00	DD
3	1	Rear boot lid inner lock	bent	\$ 95.00	\$ 95.00	BT V
4	1	Boot '1.6' word	essential	\$ 30.94	\$ 30.94	
5	1	Boot 'Altis' word	essential	\$ 21.60	\$ 21.60	
6	1	Boot 'Toyota' logo	essential	\$ 36.40	\$ 36.40	NECV
7	1	Boot 'Corolla' word	essential	\$ 35.60	\$ 35.60	
8	1	Rear end panel	buckled	\$ 486.80	\$ 486.80	DDV
9	1	Rear end panel top garnish	deformed	\$ 193.05	\$ 193.05	DLV
10	2	Rear bumper reflector @\$31.03	cut/essential	\$ 62.06	\$ 31.03 62.06	DLV
11	1	Rear bumper	distorted/torn	\$ 404.80	\$ 404.80	BRV
12	2	Rear bumper bracket-top @\$42.00	bent - RH, LH - NN	\$ 84.00	\$ 42 84.00	BT V
13	2	Rear bumper side retainer @\$59.50	essential - RH - DIS	\$ 119.00	\$ 59.50 119.00	NECV
14	1	Rear exhaust silencer	bent/resonance	\$ 785.00	\$ 785.00	RX
15	2	Rear taillamp @\$373.00	bent	\$ 317.85	\$ 317.85	DLV
		Less 25%		\$ 3,268.90	\$ 3,268.90	
		Sub total parts		-	\$ (817.22)	
				\$ 3,268.90	\$ 2,451.68	
		(SPECIAL NETT ITEMS)				
1	1 set	Rear reverse sensor	cut/shorted/malfunction	\$ 300.00	\$ 200.00 280.00	shurt BT V
		Total parts		\$ 3,568.90	\$ 2,731.68	
		To check wiring & function including to remove & refix rear reverse sensor.		\$ 100.00	\$ 50.00 80.00	
		To remove & refix exhaust silencer.		\$ 85.00	\$ 60.00	
		Labour charge as recommended for repaired & replaced damaged parts.		\$ 1,250.00	\$ 1,000.00	600.00
		To mount vehicle onto chassis alignment bench to facilitate repair.		\$ 850.00	\$ 600.00	NNX
		To putty and spraypainting including touch up all affected areas.		\$ 1,300.00	\$ 1,000.00	600.00
		To apply rustproof treatment to the replaced/repaired panels.		\$ 150.00	\$ 120.00	60.00
		GRAND TOTAL		\$ 7,303.90	\$ 5,591.68	

Repair days 5

TGLim

7/1/18



LEE AUTOMOBILE APPRAISERS SERVICES

CORRESPONDENCE : BUKIT PANJANG POST OFFICE P.O.BOX 244, SINGAPORE 916809
FAX: (65) 6763 3827, HANDPHONE: 8188 2833
BUSINESS REG. NO.: 52891429D

Vehicle Number: - SJR 7703 X

Our Ref: LEE/TP/03/2030/18

ASSESSMENT SUMMARY

The damages sustained on the vehicle were thoroughly inspected and every item that was mentioned in the repair estimate against the actual damages found on the vehicle. Before we arrived at our recommendation as to whether the parts needed to be replaced or repair.

We have listed the breakdown of our finding and our recommendation as per schedule attached.

Our assessment to reinstate the vehicle is **\$5591.68** revised amount of the repairer's estimate of **\$7303.90**. The aforesaid recommendation, in our opinion, is fair and reasonable for the restoration of the vehicle to its pre-accident condition.

However, after taken into consideration the age and condition of the vehicle and the availability of the recondition components and to economize the repair, we therefore recommend a contract **Lump Sum at \$4500.00** corresponding to supply of parts, labour and spray painting charges.

45 photographs were taken at the times of static inspection.

Under normal circumstances, the repairs should be completed within a reasonable period 07 full working days

This inspection was conducted entirely on a 'Without Prejudice' basis and we have not given authorization and instruction to the repairer to proceed with the repair.

We are reverting the matter to you for your discretion.

Very truly yours



.....
K. W. LEE Dip.Auto. Engrg.
MIAME, AMIMI, CAE, ENG. TECH, MSAE, AMIRTE, AMSOE
AUTOMOTIVE ENGINEER ASSESSOR



































...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Mar 2018		08 Mar 2018 17:18 Edit Adj Rpt	S\$2,650.00 Edit Estimates	S\$2,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: NGIAM HIAN YONG, JEFFREY , ID: S8907931D, Tel: +6591195676									
Main Claimant: CHIA HWEE KHIANG VICTOR , ID: S7106268F									
Vehicle Reg. No.: SJR7703X		Date of Loss: 05/03/2018 06:00 - :59 [103 Months and 20 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 551379		Policy/Cover Note No.: D29032791QMY (Comprehensive) Coverage: 31/10/2017 - 30/10/2018							
Vehicle Reg. No. (Insured): SLF220H		Policy No. (Claimant):							
		Excess: S\$1,500.00							
Repairer: Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82, 575642 Sin Ming - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 19/10/2018]									
Driver/Custodian (Insured): NGIAM HAN YONG, JEFFREY (), NRIC: S8907931D, Tel: +6591195676									
Adj Asg. Remarks: MJE Motor Block 7 Sin Ming Industrial Estate Sector C #01-96 S(575642) Tel No.: 6454-2203; Fax No. 6452-3308									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (17/10/2018): Report Send Back Alerts - SJR7703X (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJR7703X (551379)**
[SLF220H]
TP
CHIA HWEE KHIANG VICTOR
Mar 5 2018 6:00AM
[NGIAM HIAN YONG, JEFFREY]
Mje Motor

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/03/18 17:17	Accident Statement <small>From: OD - Reg. No: SLF220H, Claimant: NGIAM HIAN YONG, JEFFREY</small>	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
2	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
3	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
4	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
5	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
6	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
7	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
8	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
9	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
10	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
11	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
12	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
13	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
14	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
15	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
16	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
17	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
18	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
19	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
20	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
21	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
22	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
23	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
24	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
25	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
26	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
27	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
28	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
29	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
30	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
31	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
32	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
33	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
35	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
36	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
37	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
38	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
39	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
40	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
41	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
42	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
43	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
44	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
45	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
46	07/05/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
47	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	07/05/18 11:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
84	07/05/18 11:58	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
85	07/05/18 11:58	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
86	07/05/18 11:58	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
87	07/05/18 11:58	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
88	07/05/18 11:58	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	08/03/18 17:14	TPD SJR7703X GIA REPORT		Load PDF	
2	17/10/18 11:04	SJR7703X survey report and photos		Load PDF	
3	17/10/18 11:04	SJR7703X photos		Load PDF	
4	17/10/18 11:04	SJR7703X photos		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/11/18 17:50	PRS Invoice		Load PDF	
2	07/11/18 17:51	Colour Photo		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18004539/R1SBE2-1

Date: 08/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: D29032791QMY

Claimant Vehicle
No : SJR7703X

Insured Vehicle No : SLF220H

Date of Loss: 05/03/2018

Nature of Claim: TP

Claim No: 551379

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR7703X**

Make & Model: TOYOTA COROLLA, 1.6 (A)

Engine No: 3ZZ4907581

Reg. Date: 13/07/2009 (Man. Year: 2009)

Chassis No: MR053ZEE106148930

Colour: Grey

Odometer: 115147 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,568.90	1,963.53	1,605.37	44.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,735.00	1,350.00	2,385.00	63.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,303.90	3,313.53	3,990.37	54.63
Approved Total (Overridden) (S\$)		2,650.00		
Nett Amount (S\$)	7,303.90	2,650.00	4,653.90	63.72

INSPECTION

Date of Assignment: 08/03/2018

Date Inspected: 09/03/2018 Inspected At:

Mje Motor (HQ)
BLK 7 SIN MING IND EST SEC C
#01-96 SINGAPORE 575642

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2018)
Parts: 143	TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR7703X)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	528.80 F	*528.80 FL
2	1		*REAR BOOT LID WEATHERSTRIP	Dented	68.00 F	*68.00 FL
3	1		*REAR BOOT LID INNER LOCK	Bent	95.00 F	*95.00 FL
4	1		*BOOT 1.6 WORD	Necessary	30.94 F	*30.94 FL
5	1		*BOOT ALTIS WORD	Necessary	21.60 F	*21.60 FL
6	1		*BOOT TOYOTA LOGO	Necessary	36.40 F	*36.40 FL
7	1		*BOOT COROLLA WORD	Necessary	35.60 F	*35.60 FL
8	1		*REAR END PANEL	Dented	486.80 F	*486.80 FL
9	1		*REAR END PANEL TOP GARNISH	Dislodged	193.05 F	*193.05 FL
10	1		*REAR BUMPER REFLECTOR	O/S Dislodged/N/SNotNecessary	62.06 F	*31.03 FL
11	1		*REAR BUMPER	Broken	404.80 F	*404.80 FL
12	1		*REAR BUMPER BRACKET-TOP	O/S Bent / N/S Not Necessary	84.00 F	*42.00 FL
13	1		*REAR BUMPER SIDE RETAINER (N/S NOT NECESSARY)	O/S Distorted/Necessary	119.00 F	*59.50 FL
14	1		*REAR EXHAUST SILENCER	Repair	785.00 F	*- FL
15	1		*REAR TAILLAMP (2PCS)	Dislodged	317.85 F	*317.85 FL
16	1		*SET REAR REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,568.90	2,551.37
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	587.84
Total Parts (S\$)	3,568.90	1,963.53

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING & FUNCTION INCLUDING TO REMOVE & REFIX REAR REVERSE SENSOR	New	100.00	30.00
2	TO REPAIR EXHAUST SILENCER	New	85.00	60.00
3	LABOUR CHARGE AS RECOMMENDED FOR REPAIRED & REPLACED DAMAGED PARTS	New	1,250.00	600.00
4	TO MOUNT VEHICLE ONTO CHASSIS ALIGNMENT BENCH TO FACILITATE REPAIR	New	850.00	0.00
5	TO APPLY RUSTPROOF TREATMENT TO THE REPLACED / REPAIRED PANELS	New	150.00	60.00
6	TO PUTTY AND SPRAYPAINTING INCLUDING TOUCH UP ALL AFFECTED AREAS	New	1,300.00	600.00
Gross Labour Cost (\$\$)			3,735.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >