

Adnan

cc 4, Asm

18427, A pass

LKK:
IDAC:

75723

3.7/2000

DOI:

ASSIGNMENT

18/10/18

Date/Time:

12/10/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLF 2377B

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A: 18/10/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SLU 536B



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kah
motor
ubi

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

19/10

SLU 536B - X; SLF 2377B - X

GK7

17/10/18 - DS ✓

24/10/18 - OIB rear end hit.

31/10/18 - DV sent

17/12/18 - File → MX to close

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

selh 24/10/18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Maintenance/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. 24

If NO or B 28, Ass. Lia:

Repair Cost:

SS

5831.21

Loss of Rental (LOR):

SS

535.00

(

5 days)

YB 1W

Loss of Use (LOU):

SS

-

(\$

x days)

Loss of Income (LOI):

SS

-

(\$

x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search:

SS

Medical:

SS

Disbursement:

SS

Legal Cost:

SS

Total:

SS

6366.21

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

6366.21

Name 1:

Kah Motor Co. Sdn. Bhd.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$350.00

Surveys

REF: ASM(AXA)

18427 / Apr 27 / (P)

ASSIGNMENT

From: Date: 18/10/2018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLU 5236B

at Workshop m/s Kah Motor

of 15 Ubi Rd 4

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Mr Lim

(Policy Condition)

4pm

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLU5236B. Yr Regn: 2017 Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda HRV C.C. 1496.

Colour: Red. A/C: Insured / Std / NI / NA

Sp. Reading: 19021 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMR418306X203433.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: 215/60R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 18/10/18.

Survey held at Kah Motor.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP AXA.

PIP \$ 5449.73 (Red \$ 4557.82 / 46%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Kindly Help to arrange
Surveyor to Survey this
Vehicle
Thanks

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLU5236B
Chassis No : JHMRU1830GX203433
Model : HRV LX-SIN CVT YM 2016
Owner's Name : CHAN WEIXIANG, EDWARD
Ins Policy No :
Date of Accident : 15/10/2018

Document No. : SQT18004419
Date : 15. Oct 2018
Customer No. : WZA006
Svc Advisor : LIM CHOU SIONG
Engine No : L15B4533431
Date | Time : 15. Oct 2018 6:39:44 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: CHAN WEIXIANG, EDWARD						
	OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L						
	ACC DATE: 15/10/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SLF2377B						
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	✓ 14.47	✓ 1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	✓ 6.22	✓ 0.44	6.66
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	✓ 14.47	✓ 1.01	15.48
76711-T6A-003	CAPPIVOT	1	4.70	25	✓ 3.52	✓ 0.25	3.77
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	✓ 9.60	✓ 0.67	10.27
91502-S70-003	FASTENER B	2	4.90	25	✓ 7.35	✓ 0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	25	✓ 5.25	✓ 0.37	5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		✓ 120.00	✓ 8.40	128.40
68100-T7A-J20ZZ	TAIL GATE COMP	1	838.90	25	✓ 629.17	✓ 44.04	673.21
74440-T7A-003	WEATHERSTRIPTAILGATE	1	96.80	25	+ 72.60	✓ 5.08	77.68
74800-T7A-J02	LOCK ASSYTAILGATE	1	81.90	25	+ 61.42	✓ 4.30	65.72
74813-T5A-003	STRIKER ASSYTAILGATE	1	24.70	25	+ 18.52	✓ 1.30	19.82
84431-T7A-J01ZA	LINING ASSYTAILGATE	1	133.40	25	+ 100.05	✓ 7.00	107.05
84441-S2K-000ZB	POCKETTAILGATE PULL	1	14.90	25	+ 11.17	✓ 0.78	11.95
75722-T7W-A01	EMBLEMRR.	1	12.90	25	✓ 9.67	✓ 0.68	10.35
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.10	25	✓ 10.57	✓ 0.74	11.31
75701-T5A-000	EMBLEMH	1	10.70	25	✓ 8.02	✓ 0.56	8.58
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	✓ 2.85	✓ 0.20	3.05
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		✓ 320.00	✓ 22.40	342.40
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	✓ 347.77	✓ 24.34	372.11



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLU5236B
Chassis No : JHMRU1830GX203433
Model : HRV LX-SIN CVT YM 2016
Owner's Name : CHAN WEIXIANG, EDWARD
Ins Policy No. :
Date of Accident : 15/10/2018

Document No. : SQT18004419 Page 2
Date : 15. Oct 2018
Customer No. : WZA006
Svc Advisor : LIM CHOU SIONG
Engine No : L15B4533431
Date | Time : 15. Oct 2018 6:39:44 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71593-T7A-J00	SPACER R,RR.BPR S	1	19.20	25	✓ 14.40	1.01	15.41
71598-T7A-J00	SPACER,L,RR.BPR S	1	19.20	25	✓ 14.40	1.01	15.41
91505-TM8-003	CLIPBUMPER	8	2.00	25	✓ 12.00	0.84	12.84
66100-T7A-300ZZ	PANEL COMPRR.	1	365.70	25	✓ 274.27	19.20	293.47
84521-T7A-J01ZA	BOARD ASSYTRUNK FLOOR	1	186.00	25	✓ 139.50	9.77	149.27
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	43.00	25	✓ 32.25	2.26	34.51
38387-TZ5-A01	ANTENNA ASSYL.F.	1	58.10	25	✓ 43.57	3.05	46.62
74940-TZ5-A01	BUZZER ASSYSMART	1	59.30	25	✓ 44.47	3.11	47.58
Sum Item					2347.55	164.33	2,511.88

BOSUN	SUNDRIES	1	50.00		✓ 50.00	3.50	53.50
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	80.00		✓ 80.00	5.60	85.60
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		✓ 100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00		✓ 130.00	9.10	139.10
BP00R	APPLY BODY UNDERSIDE COATING (N)	1	250.00		✓ 250.00	17.50	267.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN (N)	1	300.00		✓ 300.00	21.00	321.00
BOMISC1	REMOVE, INSTALL & RESET REAR VIEW CAMERA (N)	1	320.00		✓ 320.00	22.40	342.40
BOMISC1	RESET SMART ENTRY SYSTEM & REMOVE NECESSARY	1	320.00		✓ 320.00	22.40	342.40
BMI02D	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR1		350.00		✓ 350.00	24.50	374.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	380.00		✓ 380.00	26.60	406.60
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	2400.00		✓ 2400.00	168.00	2568.00
BP06R	SPRAY PAINTING ON TAILGATE, RR BUMPER, RR PANEL	1	2900.00		✓ 2900.00	203.00	3103.00
BOJSE	BODY JOINT SEALANT.	1	80.00		✓ 80.00	5.60	85.60
Sum Labor					7660.00	536.20	8,196.20

Survey By : Adrian King ne Authorized
Date & Time : 18/10/18 S. S. D. S.
Excess :
Total Amount 10,007.55 700.53 10,708.08
Total (Inclusive of GST) 10,708.08

Printed on 17/10/2018 9:41:52 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

R-1229.73
? 714.56 5564.56
L-1750



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLU5236B
Chassis No : JHMRU1830GX203433
Model : HRV LX-SIN CVT YM 2016
Owner's Name : CHAN WEIXIANG, EDWARD
Ins Policy No. :
Date of Accident : 15/10/2018

Document No. : SQT18004419 **Page** 3
Date : 15. Oct 2018
Customer No. : WZA006
Svc Advisor : LIM CHOU SIONG
Engine No : L15B4533431
Date | Time : 15. Oct 2018 6:39:44 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Status							
Signature							

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 17/10/2018 9:41:52 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

Hsiao Tong (LKKAuto)

From: Shiao Chan (LKKAuto)
Sent: Monday, 5 November 2018 9:27 AM
To: Hsiao Tong (LKKAuto)
Subject: FW: Pre-Invoice Of Vehicle No: SLU5236B For Finalising
Attachments: 1455_001.pdf

Dear Hsiao Tong,

FYNA.

Best Regards,

Shiao Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lim Chou Siong <cslim@honda.com.sg>
Sent: Monday, 5 November 2018 9:26 AM
To: SUR <sur@lkkauto.com>
Cc: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>
Subject: Pre-Invoice Of Vehicle No: SLU5236B For Finalising

Dear,

We enclosed the total final repair costs of...

Vehicle No. SLU5236B

Final Repair Costs (include GST) \$5,831.21

Repair Period* (Working Day) 05

*Note: Repair period does not include Sunday And Public Holiday.

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thanks & best regards,

Lim Chou Siong

Contact No: 81006303 HP

KAH MOTOR CO. SDN. BHD.

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre


15 Ubi Road 4 Singapore 408610

Tel: +65 6841 3838 Fax: +65 6748 0770

This is a computer-generated e-mail no signature is necessary Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is

strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you

From: Printer Service <printservice@honda.com.sg>
Sent: Monday, 5 November, 2018 9:22 AM
To: Lim Chou Siong <cslim@honda.com.sg>
Subject: Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



05/11/2018 Page 1/2
 (C) SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Attn: Adrian Ling (L.K.K.)

5 days.

Customer: WZA006 / AXA INSURANCE
 Chassis No: JHMRU1830GX203433
 License No: SLU5236B
 Mileage: 19821
 Engine No: L15B4533431

Document No: SVO18063941
 Printed By: CSLIM
 Order Date: 29. October 2018
 Order Time: 8:50:58 AM
 Service Advisor: LIM CHOU SIONG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	incld GST
	TP DIRECT SETTLEMENT (J/NO: 71498) OWNER: CHAN WEIXIANG, EDWARD OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L ACC DATE: 15/10/2018 SURVEYED BY: ADRIAN LING (L. K. K.) DATE: 18/10/2018 @ 16:00PM REF NO: TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: SLF2377B						
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47 ✓	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22 ✓	0.44	6.66
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47 ✓	1.01	15.48
76711-T6A-003	CAPPIVOT	1	4.70	25	3.52 ✓	0.25	3.77
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	9.60 ✓	0.67	10.27
91502-S70-003	FASTENER B	2	4.90	25	7.35 ✓	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	25	5.25 ✓	0.37	5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00 ✓	8.40	128.40
68100-T7A-J20ZZ	TAIL GATE COMP	1	838.90	25	629.17 ✓	44.04	673.21
75722-T7W-A01	EMBLEMRR.	1	12.90	25	9.67 ✓	0.68	10.35
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.10	25	10.57 ✓	0.74	11.31
75701-T5A-000	EMBLEMH	1	10.70	25	8.02 ✓	0.56	8.58
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	2.85 ✓	0.20	3.05
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77 ✓	24.34	372.11
71593-T7A-J00	SPACER R,RR.BPR S	1	19.20	25	14.40 ✓	1.01	15.41
71598-T7A-J00	SPACER,L,RR.BPR S	1	19.20	25	14.40 ✓	1.01	15.41
91505-TM8-003	CLIPBUMPER	8	2.00	25	12.00 ✓	0.84	12.84
	SUM PARTS:				1,229.73	86.08	1,315.81
BOSUN	0672 SUNDRIES	1	20.00		20.00 ✓	1.40	21.40
BML011	EXT-YJ INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)	1	80.00		80.00 ✓	5.60	85.60
BA02R	EXT-YJ REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00		130.00 ✓	9.10	139.10
BG02D	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN. (N)	1	300.00		300.00 ✓	21.00	321.00
BOMISC1	EXT-YJ REMOVE, INSTALL & RESET REAR VIEW CAMERA.(N)	1	320.00		320.00 ✓	22.40	342.40
BOMISC1	0626 RESET SMART ENTRY SYSTEM & REMOVE NECESSARY COMPONENT.(N)	1	320.00		320.00 ✓	22.40	342.40
BMI02D	EXT-YJ REMOVE & INSTALL REAR COMPARTMENT LININGS, RR SEATS, TRUNK LININGS, GARNISHES & ETC.(N)	1	200.00		200.00 ✓	14.00	214.00



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer:	WZA006 / AXA INSURANCE	Document No:	SVO18063941
Chassis No:	JHMRU1830GX203433	Printed By:	CSLIM
License No:	SLU5236B	Order Date:	29. October 2018
Mileage:	19821	Order Time:	8:50:58 AM
Engine No:	L15B4533431	Service Advisor:	LIM CHOU SIONG

BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	380.00	380.00	26.60	406.60
BKRP02M	EXT-YJ REPLACE RR BUMPER, REPAIR RR PANEL & OTHER DAMAGE PARTS.	1	1,120.00	1,120.00	78.40	1,198.40
BP06R	EXT-YBH SPRAY PAINTING ON TAILGATE, RR BUMPER & RR PANEL	1	1,350.00	1,350.00	94.50	1,444.50
SUM LABOUR:				4,220.00	295.40	4,515.40
TOTAL SGD				5,449.73	381.48	5,831.21
Total Payable (SGD)						5,831.21

GST Amount is calculated from individual line(s)



Service Request Details

Claim

S8M00Z74

Reference

None 

Loss Date

October 15, 2018

Request Date

October 17, 2018

Due Date

October 24, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

17-10-2018 @ 10:45am
Mr. Lim veh not in.

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLU5236B

Make

TPVD HONDA

Model

HRV 1.5 LX CVT

Service Address

...

Primary Contact/Insured

LEONG HUEY YEE CHRISTINE

34 PARBURY AVENUE, #04-04, PARBURY HILL CONDOMINIUM, 467302, Singapore
98425748

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



<SEEK MANDATE> - S8M00Z74 [ACCIDENT INVOLVING SLF 2377B(OI) & SLU 5236B(TP) ON 15/10/2018]

Type

🔗 Question

Message

Liability: 100%. Insured rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate as follows: - 1)\$6,258.70(all-in *if third party claimed LOU) - 2)\$6,587.70(all-in *if third party claimed LOR). IA with mandate had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 07 Nov 2018

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 07.11.2018

Survey Details:

Date of loss	15-Oct-18
Date of appointment	17-Oct-18
Date of survey	18-Oct-18
Location of survey	KAH MOTOR CO SDN BERHAD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SLU5236B
Make and Model	HONDA HRV 1.5 LX CVT - 1496cc
Date of registration	5-Dec-17
Excess	
Market Value	\$ 28,000.00
Parf Rebate	\$ 20,556.00
Nett Loss	\$ 7,444.00

Repair details:

Initial Estimate	10,007.55
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 1,229.73
Check items (estimate)	NIL
Labour	\$ 4,220.00
Total	\$ 5,449.73
Lump Sum(if applicable)	\$ -

Number of days for repair	\$ 5.00
---------------------------	---------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 5,831.21	\$ 5,831.21
Loss of use (7days x \$60.00)	\$ 420.00	NIL
Loss of rental (7days x \$100)(w/GST)	NIL	\$ 749.00
Loss of income	NIL	NIL
LTA search fees	\$ 7.49	\$ 7.49
Others	NIL	NIL
Proposed Total	\$ 6,258.70	\$ 6,587.70



Re:<SEEK MANDATE> - S8M00Z74 [ACCIDENT INVOLVING SLF 2377B(OI) & SLU 5236B(TP) ON 15/10/2018]

Type

Question

Message

PLS PROCEED.

Reply

Hsiao Tong (LKKAUTO)

From: Emillin Liew <emillinliew@honda.com.sg>
Sent: Tuesday, 20 November 2018 10:11 AM
To: Admin A; Hsiao Tong (LKKAUTO)
Cc: Adrian Ling (LKKAUTO); Daryle Tan; Faeaz
Subject: LKK C/O AXA- Submission of Third Party Direct Settlement, Y/R: CC4/ASM18018927/pa3 : O/R: SLU5236B
Attachments: AXA-LKK SLU5236B.pdf

Dear Hsiao Tong,

RE: ACCIDENT INVOLVING SLU5236B AND SLF2377B ON 15.10.18

Attached please find our repair invoice and other relevant documents for the above direct settlement claim.

Kindly email me the DV as soon as possible.

Warmest Regards,

Emillin Liew
DID: +65 6514 5684
Email: emillinliew@honda.com.sg

KAH MOTOR CO. SDN. BHD.
(A member of Oriental Holdings Berhad)
15 Ubi Road 4 Singapore 408610
Tel: +65 6743 4333 Fax: +65 6748 0770



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLF 2377B (Insd veh)	Model:	HONDA HRV
	SLU 5236B (TP veh)		
Date of Accident:	15/10/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	10,708.08
Final Repair Cost	:	\$	5,831.21
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	535.00 5 days
LTA / GIA Search Fee	:	\$	

Others:	:	\$
---------	---	----

	:	\$
Final Settlement Sum	:	\$ 6,366.21

Is Third Party Workshop GIA Registered?		[X] YES	[] NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____(%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No- BOLA Scenario No: _____		
BOLA Liability: _____100_____(%)		Assessed Liability (*): _____(%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	KAH MOTOR CO. SDN. BHD.	:	\$ 6,366.21

NUR SHAQILAH BTE ABDOL
WAHAB

03/01/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18018927/Apa3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: KIAN CHUAN

Date : 03-01-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLF 2377B	Veh. Inspected	SLU 5236B
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00Z74	Excess (\$)	0.00
Assign From	KIAN CHUAN	Assign Date	17/10/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA HRV	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JHMRU1830GX203433	Colour	RED
Odometer	19021	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	DUNLOP	6 mm
L/H Front Tyre	215/60R16	DUNLOP	6 mm
R/H Rear Tyre	215/60R16	DUNLOP	6 mm
L/H Rear Tyre	215/60R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/10/2018	Inspection Date	18/10/2018
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 5236B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RUBBER CR.WINDSHIELD DAMPER (SN) (CONSISTENT)	NECESSARY	14.47	14.47
1	DAMPERSTD 5X5 (SN) (CONSISTENT)	NECESSARY	6.22	6.22
1	RUBBER CL.WINDSHEILD DAMPER (SN) (CONSISTENT)	NECESSARY	14.47	14.47
1	CAPPVOT (SN) (CONSISTENT)	NECESSARY	3.52	3.52
4	FASTENER BW/SHIELD (SN) (CONSISTENT)	NECESSARY	9.60	9.60
2	FASTENER B (SN) (CONSISTENT)	NECESSARY	7.35	7.35
2	FASTENER AW/SHIELD (SN) (CONSISTENT)	NECESSARY	5.25	5.25
2	WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	120.00	120.00
1	TAIL GATE COMP (SN) (CONSISTENT)	DENTED	629.17	629.17
1	WEATHERSTRIP TAILGATE (SN) (CONSISTENT)	NOT NECESSARY	72.60	-
1	LOCK ASSY TAILGATE (SN) (CONSISTENT)	NOT NECESSARY	61.42	-
1	STRIKER ASSY TAILGATE (SN) (CONSISTENT)	NOT NECESSARY	18.52	-
1	LINING ASSY TAILGATE (SN) (CONSISTENT)	NOT NECESSARY	100.05	-
1	POCKET TAILGATE PULL (SN) (CONSISTENT)	NOT NECESSARY	11.17	-
1	EMBLEMRR. (SN) (CONSISTENT)	NECESSARY	9.67	9.67
1	EMBLEM,RR. I-VTEC (SN) (CONSISTENT)	NECESSARY	10.57	10.57
1	EMBLEMH (SN) (CONSISTENT)	NECESSARY	8.02	8.02
2	NUTPUSH 3MM (SN) (CONSISTENT)	NECESSARY	2.85	2.85
4	ACT RR.SENSOR (SN) (CONSISTENT)	NOT NECESSARY	320.00	-
1	FACE,RR.BUMPER (SN) (CONSISTENT)	DEFORMED	347.77	347.77
1	SPACER R,RR.BPR S (SN) (CONSISTENT)	NECESSARY	14.40	14.40
1	SPACER,L,RR.BPR S (SN) (CONSISTENT)	NECESSARY	14.40	14.40
8	CLIPBUMPER (SN) (CONSISTENT)	NECESSARY	12.00	12.00
1	PANEL COMPRR. (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	274.27	-
1	BOARD ASSY TRUNK FLOOR (SN) (CONSISTENT)	NOT NECESSARY	139.50	-
1	LINING ASSYRR.PANEL (SN) (CONSISTENT)	NOT NECESSARY	32.25	-
1	ANTENNA ASSYL.F. (SN) (CONSISTENT)	NOT NECESSARY	43.57	-
1	BUZZER ASSYSMART (SN) (CONSISTENT)	NOT NECESSARY	44.47	-
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	50.00	20.00
			2,397.55	1,249.73

Report Ref No. CC4/ASM18018927/Apa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	INSPECT FR LIGHTING MECHANISMS & FOCUS.		80.00	80.00
	BODY UNDERSIDE COATING.	NOT NECESSARY	100.00	-
	REMOVE & RENEW REVERSE SENSORS.		130.00	130.00
	APPLY BODY UNDERSIDE COATING.	NOT NECESSARY	250.00	-
	REMOVE & INSTALL RR. WINDSCREEN.		300.00	300.00
	REMOVE, INSTALL & RESET REAR VIEW CAMERA.		320.00	320.00
	RESET SMART ENTRY SYSTEM & REMOVE NECESSARY.		320.00	320.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR.		350.00	200.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE, ADJUST &.		380.00	380.00
	CUR OFF & RENEW RR PANEL. STRAIGHTEN, INCLUSIVE OF THE REPAIR OF PANEL COMPRR.		2,400.00	1,120.00
	SPRAY PAINTING ON TAILGATE, RR BUMPER, RR PANEL,		2,900.00	1,350.00
	BODY JOINT SEALANT.	NOT NECESSARY	80.00	-
			7,610.00	4,200.00
	GRAND TOTAL		10,007.55	5,449.73

RECOMMENDED COST OF REPAIRS			5,449.73
------------------------------------	--	--	-----------------

Report Ref No. CC4/ASM18018927/Apa3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.