

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref: CC4/ASM18018927/Apa3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date: 03-01-2019		
	N: KIAN CHUAN		Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLF 2377B	Veh. Inspected	SLU 5236B
	Policy No.	VA1/GA060939	Coverage (\$)	0.00
	Claim No.	S8M00Z74	Excess (\$)	0.00
	Assign From	KIAN CHUAN	Assign Date	17/10/2018
2. Vehicle Particulars & Condition				
	Make & Model	HONDA HRV	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JHMRU1830GX203433	Colour	RED
	Odometer	19021	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60R16	DUNLOP	6 mm
	L/H Front Tyre	215/60R16	DUNLOP	6 mm
	R/H Rear Tyre	215/60R16	DUNLOP	6 mm
	L/H Rear Tyre	215/60R16	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	15/10/2018	Inspection Date	18/10/2018
	Survey held at	KAH MOTOR CO SDN BERHAD)	
		15 UBI ROAD 4 SINGAPORE 408610		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			