



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

*Kindly Help to arrange
Surveyor to Survey this
Vehicle. Thanks.*

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLU5236B
Chassis No : JHMRU1830GX203433
Model : HRV LX-SIN CVT YM 2016
Owner's Name : CHAN WEIXIANG, EDWARD
Ins Policy No. :
Date of Accident : 15/10/2018

Document No. : SQT18004419 **Page** 1
Date : 15. Oct 2018
Customer No. : WZA006
Svc Advisor : LIM CHOU SIONG
Engine No : L15B4533431
Date | Time : 15: Oct 2018 6:39:44 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: CHAN WEIXIANG, EDWARD						
	OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L						
	ACC DATE: 15/10/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SLF2377B						
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	✓ 14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	✓ 6.22	0.44	6.66
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	✓ 14.47	1.01	15.48
76711-T6A-003	CAPPVOT	1	4.70	25	✓ 3.52	0.25	3.77
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	✓ 9.60	0.67	10.27
91502-S70-003	FASTENER B	2	4.90	25	✓ 7.35	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	25	✓ 5.25	0.37	5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		✓ 120.00	8.40	128.40
68100-T7A-J20ZZ	TAIL GATE COMP	1	838.90	25	✓ 629.17	44.04	673.21
74440-T7A-003	WEATHERSTRIPTAILGATE	1	96.80	25	✗ 72.60	5.08	77.68
74800-T7A-J02	LOCK ASSYTAILGATE	1	81.90	25	✗ 61.42	4.30	65.72
74813-T5A-003	STRIKER ASSYTAILGATE	1	24.70	25	✗ 18.52	1.30	19.82
84431-T7A-J01ZA	LINING ASSYTAILGATE	1	133.40	25	✗ 100.05	7.00	107.05
84441-S2K-000ZB	POCKETTAILGATE PULL	1	14.90	25	✗ 11.17	0.78	11.95
75722-T7W-A01	EMBLEMRR.	1	12.90	25	✓ 9.67	0.68	10.35
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.10	25	✓ 10.57	0.74	11.31
75701-T5A-000	EMBLEMH	1	10.70	25	✓ 8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	✓ 2.85	0.20	3.05
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		✓ 320.00	22.40	342.40
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	✓ 347.77	24.34	372.11

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLU5236B
Chassis No : JHMRU1830GX203433
Model : HRV LX-SIN CVT YM 2016
Owner's Name : CHAN WEIXIANG, EDWARD
Ins Policy No :
Date of Accident : 15/10/2018

Document No. : SQT18004419 Page 2
Date : 15. Oct 2018
Customer No. : WZA006
Svc Advisor : LIM CHOU SIONG
Engine No : L15B4533431
Date | Time : 15: Oct 2018 6:39:44 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl'd GST
71593-T7A-J00	SPACER R,RR.BPR S	1	19.20	25	✓ 14.40	1.01	15.41
71598-T7A-J00	SPACER,L,RR.BPR S	1	19.20	25	✓ 14.40	1.01	15.41
91505-TM8-003	CLIPBUMPER	8	2.00	25	✓ 12.00	0.84	12.84
66100-T7A-300ZZ	PANEL COMPRR.	1	365.70	25	? 274.27	19.20	293.47
84521-T7A-J01ZA	BOARD ASSYTRUNK FLOOR	1	186.00	25	x 139.50	9.77	149.27
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	43.00	25	? 32.25	2.26	34.51
38387-TZ5-A01	ANTENNA ASSYL.F.	1	58.10	25	? 43.57	3.05	46.62
74940-TZ5-A01	BUZZER ASSYSMART	1	59.30	25	? 44.47	3.11	47.58
Sum Item					2347.55	164.33	2,511.88
BOSUN	SUNDRIES	1	50.00		20 50.00	3.50	53.50
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	80.00		✓ 80.00	5.60	85.60
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		x 100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00		✓ 130.00	9.10	139.10
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		x 180.00	17.50	267.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00		✓ 300.00	21.00	321.00
BOMISC1	REMOVE, INSTALL & RESET REAR VIEW CAMERA.(N)	1	320.00		✓ 320.00	22.40	342.40
BOMISC1	RESET SMART ENTRY SYSTEM & REMOVE NECESSARY	1	320.00		✓ 320.00	22.40	342.40
BMI02D	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR1	1	350.00		200 350.00	24.50	374.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	380.00		✓ 380.00	26.60	406.60
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	2400.00		Repair Rep'd 1120 2240	168.00	2568.00
BP06R	SPRAY PAINTING ON TAILGATE, RR BUMPER, RR PANEL,	1	2900.00		1320 2250	203.00	3103.00
BOJSE	BODY JOINT SEALANT.	1	80.00		? 80.00	5.60	85.60
Sum Labor					7660.00	536.20	8,196.20

Survey By

Date & Time

Excess

Adrian King

18/10/18

we Authorized

Sgt Dimp.

Sgt

Total Amount 10,007.55 700.53 10,708.08

Total (Inclusive of GST) 10,708.08

Printed on 17/10/2018 9:41:52 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

R-1229.73

? 214.56 5564.56

L-1750



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLU5236B
Chassis No : JHMRU1830GX203433
Model : HRV LX-SIN CVT YM 2016
Owner's Name : CHAN WEIXIANG, EDWARD
Ins Policy No. :
Date of Accident : 15/10/2018

Document No. : SQT18004419 **Page** 3
Date : 15. Oct 2018
Customer No. : WZA006
Svc Advisor : LIM CHOU SIONG
Engine No : L15B4533431
Date | Time : 15. Oct 2018 6:39:44 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Status							
Signature							

C SLM
81006303 (H2)

Printed on 17/10/2018 9:41:52 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)