



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	/Mr Seah Kok Hwee
	Reg No/Reg Date	SKH8892S / 23/10/2017
	Date In/Mileage	17/10/2018/ 17975
	Chassis No	JMYXTGF3WJZ000487
	Engine No	4B12TQ6850
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E04)
	Colour/Trim	P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
F0000018	Credit	18/10/2018/ 09:45	DS	218 / MarsLer	12034				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
S	MIPNT88088	DIAGNOSTIC / SCANNING				60			250.00
S	MIPNT88088	TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS				11	X		80.00
S	MIPNT88088	TO REMOVE AND RE-INSTALL RAD & A/C CONDENDER TO GIVE WAY ACCESS REPAIR ON FRONT ACCIDENT AFFECTED AREAS	600			1500			280.00
S	MIPNT88088	TO REPLACE FRONT BUMPER,REINFORCEMENT,RH SUPPORT PANEL,RH FENDER PANEL,ETC							3600.00
		-REPAIR FRONT BONNET							
		STRAIGHTEN,REFORM,ALIGN ON FRONT ACCIDENT AFFECTED AREAS							
S	MIPNT88088	TO APPLY SEALANT KIT ON NEW PANEL				11	X		100.00
S	MIPNT98088	SPRAY PAINTING ON FRONT BUMPER,SUPPORT PANEL,BONNET, RHF FENDER,ETC	420			1680			2100.00
P	JJMZ553141EX	ENGINE HOOD EMBLEM	1.00			80.00	0.00		80.00
M	JJ6400H881	FACE,FR BUMPER	1.00			810.00	0.00		810.00
P	JJ6405A197	EXTENSION, FR BUMPER	1.00			421.00	0.00		421.00
M	JJ6400H313	LH SIDE BRACKET,FR B	1.00			18.00	0.00		18.00
M	JJ6400H314	RH SIDE BRACKET,FR B	1.00			18.00	0.00		18.00
M	JJ6407A142	GARNISH, FR BUMPER S	1.00			48.00	0.00		48.00
P	JJ6407A146	GARNISH, FR BUMPER S	1.00			218.00	0.00		218.00
P	JJ6407A144	GARNISH, FR BUMPER S	1.00			110.00	0.00		110.00
M	JJ6400J047	COVER, FR BUMPER BLA	1.00			277.00	0.00		277.00
M	JJ6400H568	REINFORCEMENT, FR BU	1.00			549.00	0.00		549.00
M	JJ6400G576	REINFORCEMENT,FR BUM	1.00			133.00	0.00		133.00
M	JJ6400D977	REINFORCEMENT,FR BUM	2.00			21.00	0.00		42.00
M	JJ7450A967	GRILLE ASSY, RADIATO	1.00			564.00	0.00		564.00
M	JJ7415A485	MARK,THREE-DIA	1.00			45.00	0.00		45.00
P	JJMR200300	CLIP, BUMPER	15.00			2.00	0.00		30.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	/Mr Seah Kok Hwee
	Reg No/Reg Date	SKH8892S / 23/10/2017
	Date In/Mileage	17/10/2018/ 17975
	Chassis No	JMYXTGF3WJZ000487
	Engine No	4B12TQ6850
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E04)
	Colour/Trim	P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	18/10/2018/ 09:45	DS	218 / MarsLer	12034

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
P JJMU488006 CLIP,BUMPER	15.00	2.00	0.00	30.00
M JJ8301C856 HEADLAMP ASSY,RH	1.00	802.00	0.00	802.00
M JJ5256C260 UPR RH PANEL, HEADLA	1.00	57.00	0.00	57.00
P JJ5256B735 UPR PANEL, HEADLAMP	1.00	226.00	0.00	226.00
M JJ5220K686 FENDER,FR RH	1.00	621.00	0.00	621.00
M JJ7407A316 RH MOULDING, FR BUMP	1.00	114.00	0.00	114.00
M JJ7407A302 MOULDING, FR WHEEL A	1.00	197.00	0.00	197.00
P JJM2313950 COOLANT	4.00	26.00	0.00	104.00

Z NOTES

ACCIDENT ON 17/10/2018 ALONG HOUGANG AVENUE 10 BLOCK 448 OPEN CARPARK

OWNER CLAIMING THIRD PARTY

REQUIRED REPLACEMENT CAR

TP # YP3751R TP INS : CHINA TAIPING

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not attached
LKK
Take photo 3rd party.
18/10/18
4 day.

Confirm & accepted by

Parts	5,514.00
Labour	0.00
Standard Menu	0.00
Specialist Job	6,410.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	11,924.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.