

泛舟修理汽車私人有限公司
PUAN CHEW MOTOR WORK PTE LTD

BLK K, PANDAN LOOP INDUSTRIAL ESTATE #01-12 SINGAPORE 128219

TEL: 6773 0073 FAX: 6773 0928

GST REGN NO: 19-8700614-G

Date: 24.10.2018

Sompo Insurance Singapore Pte Ltd
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623

Attn: Motor Claims Dept

Dear Sir / Mdm,

OD CLAIM

INSURED'S NAME : MR. TAY YEW NGUAN
VEH. REG. NO : SKV 7579 E
MODEL : VOLKSWAGEN GOLF
ACCIDENT DATE : 16.10.2018


Below are the estimate for SKV 7579 E

1	1 bonnet	Bt	\$	550.00	✓
2	1 front bumper	Tn	\$	625.00	✓
3	1 front bumper o/s retainer	cra	\$	25.00	✓
4	2 front bumper sensor		<i>mis/shen</i> \$	180.00	✓
5	1 front bumper centre grille		\$	85.00	?
6	1 front bumper o/s nozzle		\$	96.00	?
7	1 front bumper o/s nozzle cover		\$ <i>nd</i>	18.00	✓
8	1 front o/s headlamp	Bro	\$	1,200.00	✓
9	1 front o/s headlamp module		\$	550.00	?
10	1 front o/s headlamp HID bulb		\$	280.00	
11	1 front o/s headlamp top panel	Buc	\$	30.00	✓
12	1 front o/s fender	Bt	\$	365.00	✓
13	1 front o/s fender inner shield	cra	\$	150.00	✓
14	1 front o/s fender inner shield square cover		\$ <i>mis</i>	30.00	✓
15	1 front o/s fog lamp	<i>mtg cra</i>	\$	110.00	✓
16	1 front o/s fog lamp cover		\$	60.00	?
17	1 power module	?	\$	320.00	
18	1 power module HID control	?	\$	380.00	
19	1 radiator panel	?	\$	585.00	
20	1 radiator (1)	<i>su</i>	\$	280.00	
21	1 radiator (2)	<i>su</i>	\$	280.00	
22	1 air-con condenser	<i>suc</i>	\$	375.00	
23	1 horn	<i>suc</i>	\$	65.00	
			\$	6,639.00	
Cost + 10%:			\$	663.90	
Total:			\$	7,302.90	

PAGE 1

We Specialised in Servicing and Repairing all kinds of Motor Vehicles, Panel Beating, Spray Painting

專修各種汽車 噴漆打馬呷 燒焊汽車服務。



泛舟修理汽車私人有限公司
PUAN CHEW MOTOR WORK PTE LTD

BLK K, PANDAN LOOP INDUSTRIAL ESTATE #01-12 SINGAPORE 128219
TEL: 6773 0073 FAX: 6773 0928
GST REGN NO: 19-8700614-G

PAGE 2 (SKV 7579 E)

24	1 front o/s sport rim (s.nett)	DD	\$	650.00
25	Top up coolant (s.nett)		\$	80.00 ?

Labour Charges

26	Computerise 4 wheel alignment.		\$	150.00 60/-
27	Programming of headlamp lighting.		\$	280.00 150/-
28	To remove and replace air-con condenser, vacuum and refill in A134 gas.		\$	150.00 ?
29	To remove and replace damaged parts, to repair chassis knock out, cut and weld body panel parts where necessary, straighten and reshape, re-position and realign replacement parts to the original position.		\$	1,280.00 600/-
30	Spray painting of accident sections.		\$	980.00 700/-
Grand Total:			\$	<u>10,872.90</u>

PRICES QUOTED EXCLUDE GST CHARGES

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

We Specialised in Servicing and Repairing all kinds of Motor Vehicles, Panel Beating, Spray Painting

專修各種汽車 噴漆打馬呷 燒焊汽車服務。