

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 25 Oct 2018

Preliminary Advice

Vehicle No	: SKV7579E	Accident Date	: 16/10/2018
Make	: VOLKSWAGEN GOLF	Policy No.	: D18MTPV01014062
Assignment Date	: 18/10/2018	Excess	: S\$0.00
Date of Inspection	: 18/10/2018	Est. Duration of Repair	: 7.00
Inspection At	: COMPLETE VMS PTE LTD (HQ) 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,872.90
Revised Amount	:S\$	5,771.30
Check Items (Estimated)	:S\$	2,821.60
Total	:S\$	8,592.90

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	63,000.00
COE / PARF Rebate	:S\$	48,745.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,255.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Vehicle repair on Lump Sum basis.