

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 19 Oct 2018

Preliminary Advice

Vehicle No	: SKV7579E	Accident Date	: 16/10/2018
Make	: VOLKSWAGEN GOLF	Policy No.	: D18MTPV01014062
Assignment Date	: 18/10/2018	Excess	: S\$500.00
Date of Inspection	: 18/10/2018	Est. Duration of Repair	: 7.00
Inspection At	: COMPLETE VMS PTE LTD (HQ) 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,843.18
Revised Amount	:S\$	11,149.69
Check Items (Estimated)	:S\$	7,303.01
Total	:S\$	18,452.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	63,000.00
COE / PARF Rebate	:S\$	48,745.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,255.00

Remarks

() The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Vehicle repair on part by part basis.

Repairer not agree on cost plus .

Please note the margin repair cost is \$14,255.00