

ASS. REC. BY:

REF: CS/SMO18018934/KVD302

Special Instruction:

Surveyor:  
Merimen

Kenneth

ASSIGNMENT (Office)

From (Person):

Thelma Choo

of

SMO

Date/Time:

18/10/18 @ 9:54am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKV 7579E

Insured:

at Workshop m/s

Complete VMS from

Tel:

6455 0012

of

176 Sin Ming Drive # 03-14

9833 8187

9623 8181

Policy No:

D18MTPV01014062

Claim No:

CMTD1804541

Sum Insured:

Excess:

TBA

0

Make of Veh:

(Client's Record)

D.O.A.

16/10/2018

CA / (REV) / REP. / REV 24 HRS

Date/Time:

10:32am 18/10/18

Person Contacted:

Li Hui / Rose

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKV 7579E - X
19/10/18	Revert via merimen
23/10/18	@ 3:58pm Rose said pending for pending for parts prices
25/10/18	Revert via merimen, - base on Puan Chew Est.
25/10/18	Rere approved from Thelma by merimen

28/12/18 @ 10:31am Rose will check.

28/12/18 @ 10:40am Rose said close at LS \$8000?

4/1/19 Mr Lau said use Complete VMS est to submit + report

9/1/19 LS \$8000 confirmed by email (Ref 12, 843.18, 6/1/19)

RECEIVED 8 APR 2019

REF: SMO

## ASSIGNMENT

From: Date: 18/10/2018

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SKV 7579E  
at Workshop m/s Complete VMS  
of 176 Sin Ming Drive # 03-14

Insured:

Policy No.

Claims No.

Sum Insured Excess: TBA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: 863k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 1.8.1 % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted

Veh No: SKV 7579E Regn: 09 15

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Golf <sup>A1</sup> c.c. 1395

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 43376 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVW 888 AU ZFW 356123

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD / ☒ R/Rim or

Tyre Size: F: 225/40 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

Rear

R/Bal. 8 mm

L/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 18/10/18


D.O.I. 18/10/18

Survey held at ☒

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rm O/S

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

19/10 File pass to Catherine

Workshop not agree on Cost plus.

22/10 Mr Chew will check whether can repair below 814k ~~863.1.3.1~~

25/10/18 Informal Rose cla on LS repair ex \$0 by email

21/11/18 @356pm Rose said vehicle completed repair

Date/Time: File Pass to?

☐ : Preli. Report

Days Of Repair: 7

1)

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time: File Return to?

2) 9/4 - typst

Add Fee: ☐ Site Insp (\$)

Survey Fee: 450

Transportation:

) S + RS \$

) Photos

) Others

Report Format: merimen

Lump Sum / I.B.I. (\$) 8000+

☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

TOTAL

10

450

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Est Audit #	Status
Main	17 Oct 2018		18 Oct 2018 09:59 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

## CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	TAY YEW NGUAN, ID: S0053343B, Tel: +6597390283, Email: uquantay@gmail.com		
Vehicle Reg. No.:	SKV7579E	Date of Loss:	16/10/2018 19:00 - :59
Claim Type:	OD / CMTD1804541	Policy/Cover Note No.:	D18MTPV01014062 (Comprehensive)
		Excess:	
Repairer:	COMPLETE VMS PTE LTD (HQ) 176 Sin Ming Drive #03-14 Sin Ming Autocare Complex, 575721 Sin Ming - Tel: 6455 0012		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by <b>Thelma Choo</b> - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Final Rpt due 29/10/2018]</b>		
Driver/Custodian:	TAY YEW NGUAN (64 / Male), NRIC: S0053343B, Tel: +6597390283		
Adj Asg. Remarks:	Excess to be advised Please revert with your preliminary report upon completion of survey to my colleague, Thelma.		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 25 October 2018 2:04 PM  
**To:** 'puanchew@singnet.com.sg'; SUR  
**Subject:** RE: SKV 7579 E-DOA: 16/10/2018

Dear Rose,

As instructed by our client , please proceed to repair the **insured vehicle SKV 7579E on Lump Sum basis (Excess S0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 25 October 2018 1:44 PM  
**To:** 'puanchew@singnet.com.sg' <puanchew@singnet.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** RE: SKV 7579 E

Dear Rose,

We are pending approval from insurance.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** puanchew@singnet.com.sg <puanchew@singnet.com.sg>  
**Sent:** Thursday, 25 October 2018 12:55 PM  
**To:** SUR <sur@lkkauto.com>  
**Subject:** Re: SKV 7579 E

Dear Miss Veron,

We would like to know is the vehicle SKV 7579 E been authorized to repair?

Thank you.

Regards

Rose

**From:** puanchew@singnet.com.sg

**Sent:** Wednesday, October 24, 2018 12:13 PM

**To:** sur@lkkauto.com

**Subject:** SKV 7579 E

Dear Miss Veron,

Please see attached our estimate for SKV 7579 E as per requested.

Kindly be informed that we would like lump sum repair for the vehicle.

Thank you.

Regards

Rose

## View Received Message

This mail is associated with :

**SKV7579E (CMTD1804541)**

OD

Oct 16 2018 7:00PM

[TAY YEW NGUAN]

Puan Chew Motor Work Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** Sompo Insurance Singapore Pte. Ltd. (SOMPO\_SG), sent on 25/10/2018 13:39 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$8592.90) - SKV7579E - Claim Handler: Thelma Choo

Approved:8592.90.

### DOCUMENTS SUMMARY

There are no documents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Thelma Choo

Date: 25 Oct 2018

**Preliminary Advice**

Vehicle No	: SKV7579E	Accident Date	: 16/10/2018
Make	: VOLKSWAGEN GOLF	Policy No.	: D18MTPV01014062
Assignment Date	: 18/10/2018	Excess	: S\$0.00
Date of Inspection	: 18/10/2018	Est. Duration of Repair	: 7.00
Inspection At	: COMPLETE VMS PTE LTD (HQ) 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,872.90
Revised Amount	:S\$	5,771.30
Check Items (Estimated)	:S\$	2,821.60
Total	:S\$	8,592.90

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	63,000.00
COE / PARF Rebate	:S\$	48,745.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,255.00

**Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired. you are advised to invite tender for the wreck.

( X ) Other comments : Vehicle repair on Lump Sum basis.

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Monday, 22 October 2018 10:14 AM  
**To:** Jenny Lim  
**Subject:** ASSIST ON COST PRICE (SOMPO INSURANCE)  
**Attachments:** ESTIMATE.pdf

Dear Jenny,

Kindly assist to check on cost price.

MODEL: VOLKSWAGEN GOLD TSI (A)  
YEAR : 2015 , 1395 cc  
CHASSIS NO: WWZZZAUZFW 356123

Many thanks.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Monday, 22 October 2018 10:15 AM  
**To:** 'Selamatshahh Zainal'  
**Subject:** FW: ASSIST ON COST PRICE (SOMPO INSURANCE)  
**Attachments:** ESTIMATE.pdf

Dear Shahh,

Kindly assist to check on cost price.

MODEL: VOLKSWAGEN GOLD TSI (A)  
YEAR : 2015 , 1395 cc  
CHASSIS NO: WVVZZZAUZFW 356123

Many thanks.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Monday, 22 October 2018 10:17 AM  
**To:** June Phua (Cheng Hoe)  
**Subject:** FW: ASSIST ON COST PRICE (SOMPO INSURANCE)  
**Attachments:** ESTIMATE.pdf

Dear June,

Kindly assist to check on cost price.

MODEL: VOLKSWAGEN GOLD TSI (A)  
YEAR : 2015 , 1395 cc  
CHASSIS NO: WWZZZAUZFW 356123

Many thanks.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**SOMPO INSURANCE SINGAPORE PTE LTD**

50 Raffles Place #05-01/06

Singapore Land Tower, Singapore 048623

Attention : MOTOR CLAIM DEPT

Contact : 64616555 Fax No. : 62213147

Date : 17/10/2018

Vehicle Num. : SKV7579E

Make/Model : VOLKSWAGEN GOLF A7 1.4-2015

Chassis/Eng# : WVVZZZAUZFW356123/CXS258796

Accident Date : 16/10/2018

Claim No. :

Reference : OD

Policy No. : D18MTPV01014062

S/N	Quantity	Particular	Unit Price	Amount S\$
<hr/>				
		NETT ITEMS :		
1.	1	FRONT BONNET		
2.	1	FRONT FENDER R/H		
3.	1	FRONT FENDER INNER SHIELD R/H		
4.	6	FRONT FENDER INNER SHIELD CLIP R/H		
5.	1	HEADLAMP R/H		
6.	1	HEADLAMP LOWER BRACKET R/H		
7.	1	BONNET LOCK		
8.	1	FRONT HEADLAMP TOP PANEL		
9.	1	HEADLAMP PANEL R/H		
10.	1	FRONT BUMPER		
11.	6	FRONT BUMPER CLIP		
12.	1	FRONT BUMPER SIDE RETAINER R/H		
13.	1	FRONT FOG LAMP R/H		
14.	1	FOG LAMP GARNISH		
15.	1	FRONT BUMPER LOWER GRILLE		
16.	1	FRONT BUMPER LOWER GARNISH CENTER		
17.	1	FRONT BUMPER TOW COVER		
18.	1	FRONT BUMPER BRACKET R/H		
19.	1	FRONT BUMPER SPONGE		
20.	1	FRONT BUMPER REINFORCEMENT		
21.	1	HORN		
22.	1	FRONT BUMPER WIPER NOZZLE PUMP		
23.	1	HEADLAMP NOZZLE BRACKET		
24.	1	HEADLAMP NOZZLE COVER		
25.	1	ENGINE UNDER COVER R/H		
26.	1	ENGINE UNDER COVER CENTRE		
27.	1	RADIATOR GRILLE		
28.	1	PARK ASSIST SENSOR R/H		
29.	1	FRONT SENSOR R/H		

CONTINUE / ...

**SOMPO INSURANCE SINGAPORE PTE LTD**

50 Raffles Place #05-01/06

Singapore Land Tower, Singapore 048623

Attention : MOTOR CLAIM DEPT

Contact : 64616555 Fax No. : 62213147

Date : 17/10/2018

Vehicle Num. : SKV7579E

Make/Model : VOLKSWAGEN GOLF A7 1.4-2015

Chassis/Eng# : WVVZZZAUZFW356123/CXS258796

Accident Date : 16/10/2018

Claim No. :

Reference : OD

Policy No. : D18MTPV01014062

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	2	SENSOR HOLDER		
31.	1	FRONT BUMPER GUARD		
32.	1	FRONT BUMPER LOWER GARNISH R/H		
33.	1	FRONT SUPPORT PANEL		
34.	1	AIR CON CONDENSER		
35.	1	FRONT SPORT RIM R/H		
36.	1	FRONT TIRE R/H		
37.	1	FRONT WHEEL BEARING R/H		
38.	1	FRONT LOWER ARM R/H		
39.	1	FRONT KNUCKLE ARM R/H		
40.	1	FRONT SHOCK ABSORBER R/H		
41.	2	FRONT TRAILING ARM R/H		
42.	1	FRONT 1/4 GLASS W/SEAL R/H		
43.	1	HEADLAMP HID BULB		
44.	1	PARKING SENSOR BRACKET		

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Thelma Choo

Date: 19 Oct 2018

## Preliminary Advice

Vehicle No	: SKV7579E	Accident Date	: 16/10/2018
Make	: VOLKSWAGEN GOLF	Policy No.	: D18MTPV01014062
Assignment Date	: 18/10/2018	Excess	: S\$500.00
Date of Inspection	: 18/10/2018	Est. Duration of Repair	: 7.00
Inspection At	: COMPLETE VMS PTE LTD (HQ) 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,843.18
Revised Amount	:S\$	11,149.69
Check Items (Estimated)	:S\$	7,303.01
Total	:S\$	18,452.70

Lump Sum Repair	:S\$	
-----------------	------	--

## Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	63,000.00
COE / PARF Rebate	:S\$	48,745.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,255.00

## Remarks

( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Vehicle repair on part by part basis.

Repairer not agree on cost plus .

Please note the margin repair cost is \$14,255.00

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	3343B
<b>Vehicle Details</b>	
Vehicle No.:	SKV7579E
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Oct 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF A7 1.4 TSI AT 5G13GZ SR HID
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	CXS258796
Chassis No.:	WVWZZZAUZFW356123
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$22,642.00
Original Registration Date:	30 Sep 2015
First Registration Date:	30 Sep 2015
Transfer Count:	0
Actual ARF Paid:	\$13,699.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2025
PARF Rebate Amount:	\$10,274.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Sep 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,399.00
COE Rebate Amount:	\$38,471.00
<b>Total Rebate Amount:</b>	<b>\$48,745.00</b>

The information contained herein is correct as at 19 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

ED Sampo

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	17/10/2018 15:44
Date Of Accident	16/10/2018 19:15
Exact Location Of Accident	JUNCT-COMMONWEALTH AVE WEST BTW CLEMENT AVE-3/6
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKV7579E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAY YEW NGUAN
NRIC No	S0053343B
Email Address	UGUANTAY@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97390283
Alternative Phone No	OFFICE-NOPHONE
<b>Vehicle Particulars</b>	
Manufacturer	VOLKSWAGEN
Model	GOLF
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01014062
Cover Note Number	30/09/2018 TO 29/09/2019
<b>Driver</b>	
Name of Driver	TAY YEW NGUAN
NRIC No	S0053343B
Date Of Birth	14/08/1954
Occupation	OUTDOOR
Date Of Driving Pass	28/07/1977
Driving Experience	41 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97390283
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	UGUANTAY@GMAIL.COM

Address	48 TOH TUCK ROAD #03-02
Postcode	596739
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : HO POH LIAN
	GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLF33G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	OW YONG WEI HENG ALFRED
NRIC/Passport Number	S8235172H
Contact Number	84992740
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

GIA/PAAC (app - filled form)\_v4

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# Sketch Plan Pg. 2

## SKETCH PLAN

Date of Accident: 16/10/18 Time: 7.15pm Location: Commonwealth Ave West.  
 My Vehicle A: SKV7579E Vehicle B: SLF33G Vehicle C/Others: \_\_\_\_\_



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16 Oct 2018 at about 7.15pm, I was driving my car SKV7579E, along Commonwealth Ave West, between Clementi Ave 3 and Clementi Ave 6, towards Jurong. I was on 3rd lane and about 3-car length behind car SLF33G. As I was approaching the yellow box and traffic lights, the car SLF33G stopped suddenly. I immediately jammed my brakes and swerved to the left to avoid the car. This caused the front right-hand side of my car hitting the rear left-hand side of SLF33G. There were no injuries to both parties. My wife is the only passenger in my car. The driver of SLF33G was alone. The cars were towed away from the accident site same evening.

( ) Claim OD/TP at Ah Lim Motor (x) Claim OD/TP at other workshop ( ) Reporting Only

Remarks : Please forward a copy of my efile accident report to:

My workshop :

email address : lihui@completevms.com.sg & darren@completevms.com.sg

& myself :

email address :

Note : Please take note that your insurer have **14 days timeframe** for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

GA830C Form 1 (2018) 5/1

Email : darren@completevms.com.sg ( )  
lily@completevms.com.sg ( )  
lihui@completevms.com.sg ( )

**SOMPO INSURANCE SINGAPORE PTE LTD**

50 Raffles Place #05-01/06

Singapore Land Tower, Singapore 048623

Attention : MOTOR CLAIM DEPT

Contact : 64616555 Fax No. : 62213147

**Estimate : ES006480**

Date : 17/10/2018

Vehicle Num. : SKV7579E

Make/Model : VOLKSWAGEN GOLF A7 1.4-2015

Chassis/Eng# : WVWZZZAUZFW356123/CXS258796

Accident Date : 16/10/2018

Claim No. :

Reference : OD

Policy No. : D18MTPV01014062

*Not Authorized*  
*1-B-1*  
*Resurvey B & paint*  
*7 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
NETT ITEMS :				
1.	1	FRONT BONNET	1,239.25	✓
2.	1	FRONT FENDER R/H	685.05	✓
3.	1	FRONT FENDER INNER SHIELD R/H	197.60	✓
4.	6	FRONT FENDER INNER SHIELD CLIP R/H	15.00	✓
5.	1	HEADLAMP R/H	2,687.00	✓
6.	1	HEADLAMP LOWER BRACKET R/H	253.00	✓
7.	1	BONNET LOCK	264.00	✓
8.	1	FRONT HEADLAMP TOP PANEL	74.60	✓
9.	1	HEADLAMP PANEL R/H	325.00	✓
10.	1	FRONT BUMPER	1,378.67	✓
11.	6	FRONT BUMPER CLIP	15.00	✓
12.	1	FRONT BUMPER SIDE RETAINER R/H	51.50	✓
13.	1	FRONT FOG LAMP R/H	286.30	✓
14.	1	FOG LAMP GARNISH	45.82	✓
15.	1	FRONT BUMPER LOWER GRILLE	160.45	✓
16.	1	FRONT BUMPER LOWER GARNISH CENTER	210.75	✓
17.	1	FRONT BUMPER TOW COVER	65.85	✓
18.	1	FRONT BUMPER BRACKET R/H	83.97	✓
19.	1	FRONT BUMPER SPONGE	68.71	✓
20.	1	FRONT BUMPER REINFORCEMENT	693.00	✓
21.	1	HORN	133.75	✓
22.	1	FRONT BUMPER WIPER NOZZLE PUMP	195.82	✓
23.	1	HEADLAMP NOZZLE BRACKET	158.32	✓
24.	1	HEADLAMP NOZZLE COVER	36.71	✓
25.	1	ENGINE UNDER COVER R/H	99.72	✓
26.	1	ENGINE UNDER COVER CENTRE	227.75	✓
27.	1	RADIATOR GRILLE	495.30	✓
28.	1	PARK ASSIST SENSOR R/H	233.12	✓
29.	1	FRONT SENSOR R/H	233.12	✓

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Email : darren@completevms.com.sg ( )  
lily@completevms.com.sg ( )  
lihui@completevms.com.sg ( )

SOMPO INSURANCE SINGAPORE PTE LTD  
50 Raffles Place #05-01/06  
Singapore Land Tower, Singapore 048623

Attention : MOTOR CLAIM DEPT  
Contact : 64616555 Fax No. : 62213147

Estimate : ES006480

Date : 17/10/2018  
Vehicle Num. : SKV7579E  
Make/Model : VOLKSWAGEN GOLF A7 1.4-2015  
Chassis/Eng# : WVWZZZAUZFW356123/CXS258796  
Accident Date : 16/10/2018  
Claim No. :  
Reference : OD  
Policy No. : D18MTPV01014062

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

30.	2	SENSOR HOLDER	35.97	71.94
31.	1	FRONT BUMPER GUARD		60.85
32.	1	FRONT BUMPER LOWER GARNISH R/H		287.15
33.	1	FRONT SUPPORT PANEL		1,295.42
34.	1	AIR CON CONDENSER		657.40
35.	1	FRONT SPORT RIM R/H		1,995.20
36.	1	FRONT TIRE R/H		385.00
37.	1	FRONT WHEEL BEARING R/H		563.42
38.	1	FRONT LOWER ARM R/H		468.75
39.	1	FRONT KNUCKLE ARM R/H		753.95
40.	1	FRONT SHOCK ABSORBER R/H		367.62
41.	2	FRONT TRAILING ARM R/H	269.20	538.40
42.	1	FRONT 1/4 GLASS W/SEAL R/H		280.10
43.	1	HEADLAMP HID BULB		553.97
44.	1	PARKING SENSOR BRACKET		60.05

Nett Total S\$ :

5.00% Discount S\$ :

19,103.35

955.17

18,148.18

LABOUR :

TOW VEHICLE

REMOVE & REINSTALL FRONT SUSPENSION R/H

COMPUTER WHEEL ALIGNMENT

CHANGE HEAD LAMP & DO LIGHT BEAM LEVEL ADAPTATION

REMOVE AIR CON CONDENSER AND REFILL GAS

SPRAY PAINT DAMAGED AREA AFFECTED

TO CUT OFF FRONT SUPPORT PANEL, KNOCK AND STRAIGHTEN

FRONT CHASSIS FRAME, RE-ALIGN BODY AND CHANGE ALL

NECESSARY PARTS

501

65.00

250.00

120.00

90.00

120.00

900.00

601 1,150.00

Labour Total S\$ :

2,695.00

SingDollars : Twenty Thousand Eight Hundred Forty-Three & Cents Eighteen Only

Total S\$ : 20,843.18

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



泛舟修理汽車私人有限公司  
**PUAN CHEW MOTOR WORK PTE LTD**

BLK K, PANDAN LOOP INDUSTRIAL ESTATE #01-12 SINGAPORE 128219  
TEL: 6773 0073 FAX: 6773 0928  
GST REGN NO: 19-8700814-G

Date: 24.10.2018

Sompo Insurance Singapore Pte Ltd  
50 Raffles Place #05-01/06  
Singapore Land Tower  
Singapore 048623

Attn: Motor Claims Dept

Dear Sir / Mdm,

**OD CLAIM**

INSURED'S NAME : MR. TAY YEW NGUAN  
VEH. REG. NO : SKV 7579 E  
MODEL : VOLKSWAGEN GOLF  
ACCIDENT DATE : 16.10.2018

Below are the estimate for SKV 7579 E

1	1 bonnet	Bt	\$	550.00	✓
2	1 front bumper	Tn	\$	625.00	✓
3	1 front bumper o/s retainer	crq	\$	25.00	✓
4	2 front bumper sensor		<i>mis/shen</i> \$	180.00	✓
5	1 front bumper centre grille		\$	85.00	?
6	1 front bumper o/s nozzle		\$	96.00	?
7	1 front bumper o/s nozzle cover		\$ <i>red</i>	18.00	✓
8	1 front o/s headlamp	Bro	\$	1,200.00	?
9	1 front o/s headlamp module		\$	550.00	?
10	1 front o/s headlamp HID bulb		\$	280.00	
11	1 front o/s headlamp top panel	Buc	\$	30.00	✓
12	1 front o/s fender	Bt	\$	365.00	✓
13	1 front o/s fender inner shield	crq	\$	150.00	✓
14	1 front o/s fender inner shield square cover		\$ <i>mis/shen</i>	30.00	✓
15	1 front o/s fog lamp	<i>m+g</i> crq	\$	110.00	✓
16	1 front o/s fog lamp cover		\$	60.00	?
17	1 power module	?	\$	320.00	
18	1 power module HID control	?	\$	380.00	
19	1 radiator panel	?	\$	585.00	
20	1 radiator (1)	sm	\$	280.00	
21	1 radiator (2)	sm	\$	280.00	
22	1 air-con condenser	svc	\$	375.00	
23	1 horn	svc	\$	65.00	
			\$	6,639.00	
			Cost + 10%:	\$ 663.90	
			Total:	\$ 7,302.90	

PAGE 1

We Specialised in Servicing and Repairing all kinds of Motor Vehicles, Panel Beating, Spray Painting

專修各種汽車 噴漆打馬甲 燒焊汽車服務。



泛舟修理汽車私人有限公司  
**PUAN CHEW MOTOR WORK PTE LTD**

BLK K, PANDAN LOOP INDUSTRIAL ESTATE #01-12 SINGAPORE 128219  
TEL: 6773 0073 FAX: 6773 0928  
GST REGN NO: 19-6700614-G

PAGE 2 (SKV 7579 E)

24	1 front o/s sport rim (s.nett)	DD	\$	650.00
25	Top up coolant (s.nett)		\$	80.00 ?

Labour Charges

26	Computerise 4 wheel alignment.		\$	150.00 601
27	Programming of headlamp lighting.		\$	280.00 1501
28	To remove and replace air-con condenser, vacuum and refill in A134 gas.		\$	150.00 ?
29	To remove and replace damaged parts, to repair chassis knock out, cut and weld body panel parts where necessary, straighten and reshape, re-position and realign replacement parts to the original position.		\$	1,280.00 601
30	Spray painting of accident sections.		\$	980.00 701
Grand Total:			\$	<u>10,872.90</u>

PRICES QUOTED EXCLUDE GST CHARGES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

We Specialised in Servicing and Repairing all kinds of Motor Vehicles, Panel Beating, Spray Painting

專修各種汽車 噴漆打馬呷 燒焊汽車服務。

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Tuesday, 9 April 2019 9:14 AM  
**To:** puanchew@singnet.com.sg  
**Cc:** SUR  
**Subject:** RE: AFTER PAINT PHOTO OF SKV 7579 E

Dear Rose,

Close at lump sum of \$8,000/- @ 7 working days.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** puanchew@singnet.com.sg <puanchew@singnet.com.sg>  
**Sent:** Monday, 14 January 2019 11:36 AM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Subject:** Re: AFTER PAINT PHOTO OF SKV 7579 E

Dear Veron,

As spoken to you on this case, can we close this matter at lump sum of \$8,000/-?

Please revert to us soonest.

Thank you.

Regards  
Rose

**From:** Veron Chen (LKKAUTO)  
**Sent:** Tuesday, December 11, 2018 1:27 PM  
**To:** puanchew@singnet.com.sg  
**Subject:** FW: AFTER PAINT PHOTO OF SKV 7579 E

Dear Rose,

Offer Lump Sum \$4600/- @ 7 working days.

Please check and confirm.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)

**Sent:** Monday, 3 December 2018 11:08 AM

**To:** 'puanchew@singnet.com.sg' <puanchew@singnet.com.sg>; SUR <sur@lkkauto.com>

**Cc:** Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>

**Subject:** RE: AFTER PAINT PHOTO OF SKV 7579 E

Dear Rose,

Offer Lump Sum \$4600/- @ 7 working days.

Please check and confirm.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)

**Sent:** Thursday, 29 November 2018 2:57 PM

**To:** 'puanchew@singnet.com.sg' <puanchew@singnet.com.sg>; SUR <sur@lkkauto.com>

**Cc:** Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>

**Subject:** RE: AFTER PAINT PHOTO OF SKV 7579 E

Dear Rose,

Please refer attached.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



---

**From:** puanchew@singnet.com.sg <puanchew@singnet.com.sg>  
**Sent:** Thursday, 29 November 2018 11:12 AM  
**To:** SUR <sur@lkkauto.com>  
**Cc:** Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>  
**Subject:** AFTER PAINT PHOTO OF SKV 7579 E

Hi Veron,

Please see attached the after repair photo of SKV 7579 E.

Kindly let us have the final amount so as to enable us to close this claim.

Thank you.

Regards  
Rose



Virus-free. [www.avg.com](http://www.avg.com)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18018934/Kvd3e2		
50 RAFFLES PLACE		Date : 15-04-2019		
#05-01/06		Code : SMO		
SINGAPORE LAND TOWERSINGAPORE 048623				
<b>1. Policy Particulars :- OWN DAMAGE</b>				
Insured Veh.		Veh. Inspected	SKV 7579E	
Policy No.	D18MTPV01014062	Coverage (\$)	0.00	
Claim No.	CMTD1804541	Excess (\$)	0.00	
Assign From	THELMA CHOO	Assign Date	18/10/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	VOLKSWAGEN GOLF TSI (A)	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WWWZZZAUZFW356123	Colour	METALLIC BLACK	
Odometer	43376	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	PIRELLI	8 mm	
L/H Front Tyre	225/40 R18	PIRELLI	8 mm	
R/H Rear Tyre	225/40 R18	PIRELLI	8 mm	
L/H Rear Tyre	225/40 R18	PIRELLI	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	16/10/2018	Inspection Date	18/10/2018	
Survey held at	BLK 176 SIN MING DRIVE #03-14, SIN MING AUTOCARE CO			
Repairer	PUAN CHEW MOTOR WORK PTE LTD			
<b>5a. Remarks</b>				
A)THE MARKET VALUE IS S\$63,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 7579E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	FRONT BONNET (N)	BENT	1,239.25	1,239.25
1	FRONT FENDER R/H (N)	BENT	685.05	685.05
1	FRONT FENDER INNER SHIELD R/H (N)	CRACKED	197.60	197.60
6	FRONT FENDER INNER SHIELD CLIP R/H @\$15.00 (N)	NECESSARY	90.00	90.00
1	HEADLAMP R/H (N)	BROKEN	2,687.00	2,687.00
1	HEADLAMP LOWER BRACKET R/H (N)	BENT	253.00	253.00
1	BONNET LOCK (N)	TO REPAIR SEE LABOUR	264.00	-
1	FRONT HEADLAMP TOP PANEL (N)	BUCKLED	74.60	74.60
1	HEADLAMP PANEL R/H (N)	SERVICEABLE	325.00	-
1	FRONT BUMPER (N)	TORN	1,378.67	1,378.67
6	FRONT BUMPER CLIP @\$15.00 (N)	NECESSARY	90.00	90.00
1	FRONT BUMPER SIDE RETAINER R/H (N)	CRACKED	51.50	51.50
1	FRONT FOG LAMP R/H (N)	MTG CRACKED	286.30	286.30
1	FOG LAMP GARNISH (N)	CUT	45.82	45.82
1	FRONT BUMPER LOWER GRILLE (N)	DISTORTED	160.45	160.45
1	FRONT BUMPER LOWER GARNISH CENTER (N)	SERVICEABLE	210.75	-
1	FRONT BUMPER TOW COVER (N)	SERVICEABLE	65.85	-
1	FRONT BUMPER BRACKET R/H (N)	SERVICEABLE	83.97	-
1	FRONT BUMPER SPONGE (N)	SERVICEABLE	68.71	-
1	FRONT BUMPER REINFORCEMENT (N)	TO REPAIR SEE LABOUR	693.00	-
1	HORN (N)	SERVICEABLE	133.75	-
1	FRONT BUMPER WIPER NOZZLE PUMP (N)	SERVICEABLE	195.82	-
1	HEADLAMP NOZZLE BRACKET (N)	SERVICEABLE	158.32	-
1	HEADLAMP NOZZLE COVER (N)	DENTED	36.71	36.71
1	ENGINE UNDER COVER R/H (N)	CRACKED	99.72	99.72
1	ENGINE UNDER COVER CENTRE (N)	SERVICEABLE	227.75	-
1	RADIATOR GRILLE (N)	SERVICEABLE	495.30	-
1	PARK ASSIST SENSOR R/H (N)	MISSING	233.12	233.12
1	FRONT SENSOR R/H (N)	SHORTED	233.12	233.12

Report Ref No. CS/SMO18018934/Kvd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	SENSOR HOLDER @\$35.97 (N)	NECESSARY	71.94	71.94
1	FRONT BUMPER GUARD (N)	SERVICEABLE	60.85	-
1	FRONT BUMPER LOWER GARNISH R/H (N)	SERVICEABLE	287.15	-
1	FRONT SUPPORT PANEL (N)	SERVICEABLE	1,295.42	-
1	AIR CON CONDENSER (N)	SERVICEABLE	657.40	-
1	FRONT SPORT RIM R/H (N)	DENTED	1,995.20	1,995.20
1	FRONT TIRE R/H (N)	SERVICEABLE	385.00	-
1	FRONT WHEEL BEARING R/H (N)	NOT NECESSARY	563.42	-
1	FRONT LOWER ARM R/H (N)	SERVICEABLE	468.75	-
1	FRONT KNUCKLE ARM R/H (N)	SERVICEABLE	753.95	-
1	FRONT SHOCK ABSORBER R/H (N)	SERVICEABLE	367.62	-
2	FRONT TRAILING ARM R/H @\$269.20 (N)	SERVICEABLE	538.40	-
1	FRONT 1/4 GLASS W/SEAL R/H (N)	DISTORTED	280.10	280.10
1	HEADLAMP HID BULB (N)	SERVICEABLE	553.97	-
1	PARKING SENSOR BRACKET (N)	TO REPAIR SEE LABOUR	60.05	-
	LESS 5% DISCOUNT		-955.17	-509.46
			18,148.18	9,679.69
	<b>LABOUR</b>			
	TOW VEHICLE.		65.00	50.00
	REMOVE & REINSTALL FRONT SUSPENSION R/H.	NOT NECESSARY	250.00	-
	COMPUTER WHEEL ALIGNMENT.		120.00	60.00
	CHANGE HEAD LAMP & DO LIGHT BEAM LEVEL ADAPTATION.		90.00	60.00
	REMOVE AIR CON CONDENSER AND REFILL GAS.	NOT NECESSARY	120.00	-
	SPRAY PAINT DAMAGED AREA AFFECTED.		900.00	700.00
	TO CUT OFF FRONT SUPPORT PANEL, KNOCK AND STRAIGHTEN FRONT CHASSIS FRAME, RE-ALIGN BODY AND CHANGE ALL NECESSARY PARTS. INCLUSIVE OF THE REPAIR OF BONNET LOCK, FRONT BUMPER REINFORCEMENT AND PARKING SENSOR BRACKET.		1,150.00	600.00
			2,695.00	1,470.00
	<b>GRAND TOTAL</b>		<b>20,843.18</b>	<b>11,149.69</b>

Report Ref No. CS/SMO18018934/Kvd3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,000.00
---	--	--	----------

Report Ref No. CS/SMO18018934/Kvd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.