(W/ -)	ASSIGNMENT (Office)
	found forg of FCI Date/Time: 17/10/180 5:08p1
Estimated Cos	
	S/TP RES/OD RES/EVA/INV/MV7CS
To Inspect Ve	
at Workshop i	
of	No 18 Defu Avenue 2
Policy No:	Claim No:
Sum Insured:	Excess:
Make of Veh: (Client's Record	D.O.L. IIII 10 100 0
	REP. / REV 24 HRS DS) H.O.D. Endorsement:
CA / KEY	H.O.D. Entorisement.
	11:0
Date/Time:	18/10/18/09/19 am Person Contacted: Karen Vehicle IN OUR
	Action/Instruction () Estimate
Date/Time:	Action/Instruction () Estimate PC 28847-X
Date/Time:	Action/Instruction () Estimate

Burmuit	REF: FCL		102
zairan i		ASSIGNMENT	
		2 2880	014
From:	Date: 24.102618	Veh No:	Yr Regn:
Estimated Cost:		Type: M.Car / M.Cycle / Bus / Van / Lor	Ty / Taxt / Frime mover /
OD ITP I WS I TP RES I OD RES I EV		Make: GOLDENDRI	1000) 6/0
To Inspect Vehicle No: PC	2889Y	100 100 100 100 100 100 100 100 100 100	, ,
at Workshop m/s	nink One	colour Multicolone	A/C: Insured / Std / NI / NA
of No. 18	Defu Ave 2.	Sp.Reading /47739	T/Radio: Insured / Std / NI / NA
Insured		Eng/No:	
Policy No.		C/No: LL3BEC	DH2DA013844
Claims No.		Gen. Cond. Good / Fair / Poor / Burnt	/ (2/
Sum Insured	Excess:	Steering: Inorder / Jammed / Leaked /	Burnt or
(Client's Record)		Brake: Inorder / Jammed / Leaked /	Burnt or
Make of Veh:		Modi: (MI / S/Rim / STD A/Rim_or	4
Altitude of Total		Tyre Size: F: 25F/	10127-c
104m-	1030um	Tyre Size. P. 7	
(Policy Condition)	ts N/S	O/S BS / DUN / EXNOVA / GY / FS / LIZA /	MIC / OHTSI / PIP / SHMI /
Remark: The veh had commenced i repair at the time of inspe		00,000,000	ct loke
107			
Bal. or Market Value:	90h.	Front	Rear
John Hodgen House	nsfstent? : Yes or No	R/Bal. 9 mm	R/Bal. 6/6 mm
GIA / PR Seen Co	nsistent? : Yes or No	L/Bal. mm	L/Bal. 0/6 mm
Est. Repairs: 4 days	Res.: Yes or No	D.O.A. / 1 / 10 / 18	D.O.I. 29/10/16
Lum Sum: 20 %	3 Val.: Yes or No	Survey held at	
CA / REV / REP. / 24 HRS	11A252	Des. of Damages : Frt / Rear / O/S /	N/S / U/C / Rooftop or
	Vehicle: IN		
Date: Person Conta	cted:	The U/C / Chassis frame / Body	Structure affected due to collision.
Date / Time Action / Instruction			
1 0548	love. Deple	o with Leren.	
15/11/18 Conf. (and	45 \$ 6200	o with theren.	
1 1 0	409.30, EP1.		
rea: 9 45,	101.50, 267.	2010	•
	RE(SEIVED 1 6 NOV 2018	
	4		
Date/Time, File Pass to?	ili. Report	Days Of Repair: 4	39×12:58
11 7	al Report	Resurvey No. of Trip:	Survey Fee: 170 + 585
Date/Time, File Return to?	ai riopoti		Transportation 50
2)	Add	d Fee: Site Insp (\$)_s+ps_s
*/	17.77.77	Interview (\$) Photo \$80 42
Report Format:		Tech Invs (\$) Others
-	0.00	Weekend (\$	023
some want ment of	V XXXX		10/11/18



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D18007471MFSH

Date: 15 November 2018

Our Ref: CS/FCI18018936/Urd3

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. PC 2884Y .

Please be informed that we had conducted the inspection of the above mentioned vehicle on <u>29/10/2018</u> at the premises of M/s <u>THINK ONE AUTOCARE PTE LTD</u> and have the following to report:-

Workshop Estimate Amount	: S\$	49,609.30	
Revised Estimate Amount	: S\$	7,852.00	
"Check" Items Amount	: <u>S\$</u>		
Market Value	: <u>S\$</u>	#	
LTA Reimbursement Value	: <u>S</u> \$	2	
Nett Value	: <u>S</u> \$	-	


Description of Damage:

<u>The vehicle sustained damages</u>
at the rear portion.



Yours faithfully

MARCUS CHUA Automotive Assessor



MS First Capital Insurance Limited to Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims 8 Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

15-10-2018

Our Ref No. D18007471MFSH

Accident Date

11-10-2018

Claim Type. Third Party

Insured Vehicle

SHA2787A

Third Party Vehicle. PC2884Y

Survey Location

NO.18 DEFU AVENUE 2

Contact Person.

KAREN TAN

Contact No.

68443300/ 91288488

Fax No. 68424988

Survey Type

WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop

THINK ONE AUTOCARE

Attention, NIL

Cc : TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

JOANNEY

PTE LTD

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

					+
Job Sheet (/C	ClaimWS/Surveyor/JobSheet/	245057) 🚣 PR	Il Documents 🙆 Clos	se 🗶	
			PRI Header Detai	ls	
Claim No	D18007471MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & THINK ON
Workshop Name	THINK ONE AUTOCARE PTE LTD (Contact Person : KAREN TAN)	Survey Location & Contact Details	NO.18 DEFU AVENUE Mobile: 91288488, EmailId: KARENTAN	Phone: 68443300	
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE	E: WE ADMIT LIABIL	.ITY QUANTUM
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA2787A	TP Vehicle No	PC2884Y
PRI Recieved Date	15-10-2018 09:00:18 PM	Surveyor Appointed Date	17-10-2018 05:07:5	Surveyor 3 PM Accept Date	18-10-2018 1
			Survey Report Uplo	oad	
Surveyor Inspection Date *:		Surveyor Report Date	18-10-2018	Upload Survey Report *:	Choose File
			Vehicle Particula	rs	
Make	Please Select Make ▼	Model	Please Select Model	Year	Select Year •
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			
Multiple D	ocuments Upload				
		Upload Multiple	e Documents		
File Nan	ne			Action	
Surveyor	Job Remarks				
Remarks				Save	

Janice Lee (LKKAuto)

From:

Janice Lee (LKKAuto)

Sent:

Thursday, November 15, 2018 6:58 PM

To:

'CWS Motor Claims'

Cc:

'Joanne Yong Lai fong'

Subject:

RE: SURVEY ASSESSMENT - D18007471MFSH/1

Attachments:

PC 2884Y.pdf

Dear Sir/ Madam,

Enclosed preliminary revised for PC 2884Y.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>janicelee@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, October 18, 2018 9:22 AM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18007471MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Wednesday, 17 October 2018 5:08 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims < cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong

<Joanneyong@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D18007471MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards, Admin Team Claim Workflow System Motor Claims Department MS First Capital Insurance Limited

Tel: 6507 3848 Fax: 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	Set Miller Transaction (Section
Owner ID Type:	Company
Owner ID:	9323E
Vehicle Details	700 00 00 00 00 00 00 00 00 00 00 00 00
Vehicle No.:	PC2884Y
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Oct 2018
Vehicle Make:	GOLDEN DRAGON
Vehicle Model:	XML6957J14B TURBO MANUAL 41 SEATER
Primary Colour:	Multi-Colour
Manufacturing Year:	2013
Engine No.:	22099395
Chassis No.:	LL3BECDH2DA013854
Maximum Power Output:	*
Open Market Value:	\$97,151.00
Original Registration Date:	22 Aug 2014
First Registration Date:	22 Aug 2014
Transfer Count:	0
Actual ARF Paid:	\$4,858.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	545
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Aug 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$43,390.00
COE Rebate Amount:	\$25,217.00
Total Rebate Amount:	\$25,217.00

The information contained herein is correct as at 29 Oct 2018

ОК

SGCARMART.COM

Sign Login

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forur

500+ dealers competed to buy my car!



- Sell ur Car for More Cash
- Highest Price or Get \$100 Free
- Get Paid Now, Handover Later

SELL YOUR CAR

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

٧

Ways of Selling

New 5 Years Coe Renewal Honda Stream 1,8A



2,88%P.A Lowest Interest@Gv Cars Financing \$2000 Downpayment Monthly From GV Credit Pte Ltd StarAd



Browse by Category

2 vehicles

Golden Dragon

Depreciation

Advanced Search

Mileage

Sort by Date Posted

Veh T

Make

Model

Price Anv

Any

Απν

Reg Date

Any

Eng Cap

Any



Search Selection

Golden Dragon XML6957

\$75,000

\$15,110 /yr

16-Oct-2013

6,693 cc

E

Fuel Type: Diesel

Golden Dragon

43 Seater Bus, Good Condition, Auto Transmission, Suitable For Carry Tourists, Students, Workers & Chartered Bus Services! Call Me Now.

Tags: 2013 Golden Dragon XML6957, 2013 golden dragon xml6957, Golden Dragon XML6957, golden Posted: 05-Oct-2018 dragon xml6957, Golden Dragon, XML6957, xml6957, Used Golden Dragon

Golden Dragon XML6118

\$23,000

\$13,430 /yr

16-Jul-2010

8.849 cc

Fuel Type: Diesel

49 Seater Bus, Lifespan Expiry Date: 15 July 2030, Depreciation Less Than \$14K / Year.

Posted: 06-Sep-2018

Tags: 2010 Golden Dragon XML6118, 2010 golden dragon xml6118, Golden Dragon XML6118, golden dragon xml6118, Golden Dragon, XML6118, xml6118, Used Golden Dragon

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Depreciation

Reg Date

Eng Cap

Mileage

Veh T

For old advertisements, view Expired ads

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sa cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark buy used Golden Dragon, Golden Dragon Singapore, used Golden Dragon Singapore, used Golden Dragon, used vehicles Singapore or even buy used Golden Dragon dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. V openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, b that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2018 sgCarMart. All rights reserved.

Compare

Think One Autocare Pte Ltd No.18 Defu Avenue 2 Singapore 539522

Tel: 6844 3300 Fax: 6842 4988

Total parts

PC2	884Y	Golden Dragon XML6957J14B	
			Estimated he the
No	Qty	Parts Description	Parts Price
1	1	Rear bumper assy Rear side reflector	\$ 4,800.00
2	2	Rear side reflector 41	\$ 282.00 <
2	1	Rear tailgate assy	\$ 6,700.00 [∞]
4	1	Rear tailgate centre logo	\$ 120.00 ×
5	1	Rear tailgate outer handle	\$ 195.00 ≺
6	1	Rear left taillamp	\$ 750.00~
7	1	Rear right taillamp	\$ 750.00 \(\)
8	1	Rear lower panel assy	\$ 4,870.00 X
9	1	Rear left lower side panel Sylone 2900	\$ 3,600.00
10	1	Rear right lower side panel	s 3,600.00 ×
11	1	Rear air con compressor 1	s 2,600.00 Q
12	1	Rear air con fan cowling 10	s 450.00 q
13	1	Rear air con fan blade 1	\$ 250.00 ∝
14	1	Rear air con fan pulley 1	\$ 650.00 ∝
15	1	Rear air con fan belt	\$ 240.00@
16	1	Rear air con fan motor assy 17	\$ 360.00 ℃
17	1	Rear power steering pump assy 11	\$ 4,500.00 Ø
18	1	Rear power steering pump belt \checkmark	s 200.00 ≪
19	1set	Rear power steering pump pulley 11	S 1,200.00 🗷
20	1	Rear engine crankshaft pulley belt 🖊 🤊	S 240.00 ≪
21	1	Rear engine crankshaft pulley 🗸 🤊	\$ 1,400.00
22	1	Rear engine alternator assy 🔨 ^	\$ 2,800.00 X
23	1	Rear engine air con compressor fan belt 💋 🤊	\$ 200.00 ×
24	1 set	Rear engine wire harness complete assy	\$ 800.00 ⋞
25		Rear left engine mounting \checkmark 7	\$ 380.00
26	1set	Rear right engine mounting	\$ 380.00 🔾
27	1set	Rear centre engine mounting	\$ 380.00 ×
28		Rear gearbox mounting	\$ 380.00 ×
			\$ 43,077.00
		Less 10%	\$ 4,307.70
			\$ 38,769.30
		Special Nett Items	1,2
1	1	Rear 60km/h sticker	s 30.00 / O
2	1set	Rear company advertisement sticker	s 450.00 300
3	1	Rear no plate	\$ 80.00 40
		S - W	\$ 560.00

\$ 39,329.30

Think One Autocare Pte Ltd No.18 Defu Avenue 2 Singapore 539522

Tel: 6844 3300 Fax: 6842 4988

Signature: Date:

No	Description			Labour Charges
1	Labour for panel beating, cut, weld, straight replace rear damaged parts.	ten rear affected area and	S	3,500.00
2	To putty and spray painting rear portion.		\$	3,500.00
3	To apply anti rust proofing to rear affected	area.	8/	180.00
4	To remove and install rear engine to facilita	ate the repair.	\$	V 7650.00
5	To remove and install rear alternator assy.		\$-	d =350.00
6	To remove and install rear power steering p	oump assy.	\$	350.00
7	To remove and install rear engine pulley an		S	350.00
8	To remove and install rear air con compress		81	7 350.00
9	To remove and install rear engine mounting		S	7 400.00
10	To remove and install rear gearbox mounting		8	400.00
11	Towing service.	(C)	5	250.00
		Total labour :	\$	10,280.00
	LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting			
	 To display damaged part(s) during resurvey 	Total parts:	S	39,329.30
	Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis **Third party survey is on a "Without Prejudice" basis.**	Total labour :	\$	10,280.00
	 No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 	Total repair cost :	_\$	49,609.30
	Acknowledged by Repairer			
		l .		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Intern	ationale Des Experts En Autom	obile
MS F	IRST CAPITAL IN	SURANCE LTD	Ref : CS/FCI1801893	36/Urd3n2
36 R(‡16-(OBINSON ROAD 11 CITY HOUSESI	NGAPORE 068877	Date : 20-11-2018 Code : FCI2	
1.		Policy Particula	ars :- THIRD PARTY CLAI	M
	Insured Veh.	SHA 2787A	Veh. Inspected	PC 2884Y
	Policy No.	D-18088936MFSH	Coverage (\$)	0.00
	Claim No.	D18007471MFSH	Excess (\$)	0.00
	Assign From	JOANNE YONG	Assign Date	17/10/2018
2.	ANY STEEL U.S.	Vehicle Pa	articulars & Condition	
	Make & Model	GOLDEN DRAGON	c.c	6690
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	LL3BECDH2DA013854	Colour	MULTI COLOUR
	Odometer	147739	Steering	IN ORDER
-	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.	Manager Manager	Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	255/70 R22.5	WEST LAKE	6 mm
	L/H Front Tyre	255/70 R22.5	WEST LAKE	6 mm
	R/H Rear Tyre	255/70 R22.5 (D)	WEST LAKE	6/6 mm
	L/H Rear Tyre	255/70 R22.5 (D)	WEST LAKE	6/6 mm
4.			iption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	REAR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Ger	neral Information	
	Accident Date	11/10/2018	Inspection Date	29/10/2018
	Survey held at	THINK ONE AUTOCARE P	TE LTD	
	1.5	NO.18 DEFU AVENUE 2 SINGAPORE 539522		
5a.	A LESS TO		Remarks	
	B)THE INSPECTI	NSISTENT TO ACCIDENT RE ON WAS CONDUCTED ON A ICE TO YOUR INSTRUCTION	"WITHOUT PREJUDICE" BA	SIS. ISED REPAIRS.
5b.			nate Days of Repair	Sales Sa
	ESTIMATED NO	RMAL PERIOD FOR REPAIR:	4 Working Da	iys



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 2884Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)	
	REPLACEMENT OF PARTS				
1	REAR BUMPER ASSY	CRACKED	4,800.00	2,880.00	
1.00		NOT NECESSARY	282.00	-	
	REAR TAILGATE ASSY	TO REPAIR SEE LABOUR	6,700.00		
1	REAR TAILGATE CENTRE LOGO	NOT NECESSARY	120.00		
	REAR TAILGATE OUTER HANDLE	NOT NECESSARY	195.00	:	
1	REAR LEFT TAILLAMP	NOT NECESSARY	750.00	-	
	REAR RIGHT TAILLAMP	NOT NECESSARY	750.00		
	REAR LOWER PANEL ASSY	TO REPAIR SEE LABOUR	4,870.00	-	
1	REAR LEFT LOWER SIDE PANEL	BENT / CRACKED	3,600.00	2,900.00	
	REAR RIGHT LOWER SIDE PANEL	TO REPAIR SEE LABOUR	3,600.00	-	
- 1	REAR AIR CON COMPRESSOR	NOT NECESSARY	2,600.00	-	
1	REAR AIR CON FAN COWLING	NOT NECESSARY	450.00		
	REAR AIR CON FAN BLADE	NOT NECESSARY	250.00	-	
- 1	REAR AIR CON FAN PULLEY	NOT NECESSARY	650.00)	
	REAR AIR CON FAN BELT	NOT NECESSARY	240.00)	
- (-	REAR AIR CON FAN MOTOR ASSY	NOT NECESSARY	360.00		
	REAR POWER STEERING PUMP ASSY	NOT NECESSARY	4,500.00		
10	REAR POWER STEERING PUMP BELT	NOT NECESSARY	200.00)	
	SET REAR POWER STEERING PUMP PULLEY	NOT NECESSARY	1,200.00		
	REAR ENGINE CRANKSHAFT PULLEY BELT	NOT NECESSARY	240.00		
	REAR ENGINE CRANKSHAFT PULLEY	NOT NECESSARY	1,400.00	0	
	REAR ENGINE ALTERNATOR ASSY	NOT NECESSARY	2,800.00	0	
	REAR ENGINE AIR CON COMPRESSOR FAN BELT	NOT NECESSARY	200.00		
	SET REAR ENGINE WIRE HARNESS COMPLETE ASSY	NOT NECESSARY	800.00	D .	
	1 SET REAR LEFT ENGINE MOUNTING	NOT NECESSARY	380.00	0	
	1 SET REAR RIGHT ENGINE MOUNTING	NOT NECESSARY	380.0	0	
	1 SET REAR CENTRE ENGINE MOUNTING	NOT NECESSARY	380.0	0	
	1 SET REAR GEARBOX MOUNTING	NOT NECESSARY	380.0	0	

Report Ref No. CS/FCI18018936/Urd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LESS 10% DISCOUNT		-4,307.70	-578.00
			38,769.30	5,202.00
	SPECIAL NETT ITEMS			
1	REAR 60KM/H STICKER (SN)	NECESSARY	30.00	10.00
1	SET REAR COMPANY ADVERTISEMENT STICKER (SN)	NECESSARY	450.00	300.00
1	REAR NO PLATE (SN)	BENT	80.00	40.00
	LABOUR		560.00	350.00
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR TAILGATE ASSY, REAR LOWER PANEL ASSY AND REAR RIGHT LOWER SIDE PANEL.		3,500.00	1,500.00
	TO PUTTY AND SPRAY PAINTING REAR PORTION.		3,500.00	800.00
	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA.	NOT NECESSARY	180.00	
	TO REMOVE AND INSTALL REAR ENGINE TO FACILITATE THE REPAIR.	NOT NECESSARY	650.00	e e
	TO REMOVE AND INSTALL REAR ALTERNATOR ASSY.	NOT NECESSARY	350.00	S S
	TO REMOVE AND INSTALL REAR POWER STEERING PUMP ASSY.	NOT NECESSARY	350.00	
	TO REMOVE AND INSTALL REAR ENGINE PULLEY AND BELTING ASSY.	NOT NECESSARY	350.00	
	TO REMOVE AND INSTALL REAR AIR CON COMPRESSOR ASSY.	NOT NECESSARY	350.00	
	TO REMOVE AND INSTALL REAR ENGINE MOUNTING.	NOT NECESSARY	400.00	
	TO REMOVE AND INSTALL REAR GEARBOX MOUNTING.	NOT NECESSARY	400.00	
	TOWING SERVICE.	NOT NECESSARY	250.00	
	-		1	1 8
	•		10,280.00	2,300.0
	GRAND TOTAL		49,609,30	

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	6,200.00
--	----------

Report Ref No. CS/FCI18018936/Urd3n2





Report Ref No. CS/FCI18018936/Urd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.