

22/03/2001

ASS. REC. BY:

REF: CS/FCI 18018943/ Gg d3/n2

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office) ↓

From (Person): Eileen Lee

of

FCI

Date/Time: 17/10/2018 04:51pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

81L 8226H

Insured:

SHA 3948X

at Workshop m/s

Trans Eurokars

Tel:

8128 9802

of

Subiclose

Policy No:

Claim No:

D1800 7509MFst

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/10/2018

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time: 09:07am @ 18/10/18

Person Contacted:

Jus

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	81L 8226H -X
	SHA 3948X-CC3/AIG16001595/H/wb3g2 DOA: 24/01/2016
17/10/18 @ 2pm	revised to Eileen Lee by email.
07/11/18 @ 2:32pm	confirmed with Catherine Clark final fig & 3160.88, 3 days.
	LRCA to 7685.93, 46%

Summary

XPR

REF: FCI

69166

ASSIGNMENT

From: Date: 13-10-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SL 8226H

at Workshop m/s Trans Eurokars

of 5 Ubi Close

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Joss

3-30pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SL 8226H Yr Regn: 10 Mar 2017

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: mazda 6 C.C. 1998

Colour: red A/C: Insured / Std / NI / NA

Sp Reading: 30899 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM6GL1071H1067289

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Bm or

Tyre Size: F: 225/55 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 23-10-18

Survey held at w/s 3:50pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 07 DEC 2018

Date/Time. File Pass to?

☐

: Preli. Report

1) 07/12 11:00 AM

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip:

Report Format: TP

Lump Sum / I.B.I: (\$ 3160.88)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS: \$

) Photos:

) Others:

TOTAL

140

50

11

201



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007509MFSH
Our Ref: CS/FCI18018943/Gqd3

Date: 25 October 2018

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLL 8226H

Please be informed that we had conducted the inspection of the abovementioned vehicle on 23/10/2018 at the premises of M/s TRANS EUROKARS and have the following to report:-

Workshop Estimate Amount	: S\$ 5,846.81 .
Revised Estimate Amount	: S\$ 3,160.88 .
"Check" Items Amount	: S\$ 465.93 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

Guo Qiang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	16-10-2018	Our Ref No. D18007509MFSH
Accident Date	12-10-2018	Claim Type. Third Party
Insured Vehicle	SHA3948X	Third Party Vehicle. SLL8226H
Survey Location	5 UBI CLOSE	
Contact Person.	JESS FRANCIS CARLOS	
Contact No.	0/ 81289802	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS EUROKARS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/245100)



PRI Documents



Close X

PRI Header Details

Claim No	D18007509MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & TRANS EL
Workshop Name	TRANS EUROKARS PTE LTD (Contact Person : JESS FRANCIS CARLOS)	Survey Location & Contact Details	5 UBI CLOSE Mobile: 81289802 , Phone: 0 , Fax: 0 EmailId: JESS.FRANCIS@EUROKARS.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA3948X	TP Vehicle No	SLL8226H
PRI Recieved Date	16-10-2018 06:56:22 PM	Surveyor Appointed Date	17-10-2018 04:50:52 PM	Surveyor Accept Date	18-10-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	18-10-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 7 December 2018 2:32 PM
To: catherinechua@eurokars.com.sg
Cc: jess.francis@eurokars.com.sg; SUR
Subject: RE: SLL8226H - FINALISATION OF COR

Dear Catherine,

WITHOUT PREJUDICE

Confirm final fig \$3,160.88 before GST and 3 repair days.

Kindly provide us the before paint photographs.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAUTO)
Sent: Thursday, 6 December 2018 2:42 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Subject: FW: SLL8226H - FINALISATION OF COR

[CS/FCI18018943/Gqd3](#)

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: catherinechua@eurokars.com.sg <catherinechua@eurokars.com.sg>
Sent: Thursday, 6 December, 2018 2:22 PM
To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Cc: jess.francis@eurokars.com.sg; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: SLL8226H - FINALISATION OF COR

Dear Guo Qiang

Our COR computation is attached for your agreement.

COR: \$3160.88 before GST

3 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Kindly confirm the above as soon as possible.

Thanks n Regards
Catherine Chua

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 25 October 2018 2:00 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007509MFSH/1
Attachments: CSFC118018943Gqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SLL 8226H.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 18 October 2018 9:10 AM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18007509MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Wednesday, 17 October 2018 4:51 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D18007509MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	6916G

Vehicle Details

Vehicle No.:	SLL8226H
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	PE20848377
Chassis No.:	JM6GL1071H0107289
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$20,492.00
Original Registration Date:	10 Mar 2017
First Registration Date:	10 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$20,689.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Mar 2027
PARF Rebate Amount:	\$15,516.00

Intended COE Rebate Details

COE Expiry Date:	09 Mar 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,621.00
COE Rebate Amount:	\$42,366.00
Total Rebate Amount:	\$57,882.00

The information contained herein is correct as at 24 Oct 2018

OK

Sketch Plan #3 Pg. 1

Untitled

car: SLL 8226H
Mazda 6 2.0L

At 12 Oct 2018 22.48 I was driving the above car along Sims Avenue entering the KPE tunnel. A car in front of me braked to a very low speed and I braked as well, keep some distance between. A blue comfort taxi SHA 3948X behind me did not stop and hit my car rear end. The damage to my car rear end that I can visually observe includes 2 lost caps and some dents (I will be sending my car for inspection of any further damages). I had no other collisions with other vehicles. I had 2 adult (wife and domestic helper) and 2 child passengers (my children) on my car during the accident. Please refer to video clips. Driver of SHA 3948X is Mr Pang with handphone number 92276112.

DRIVER NRIC & LICENSE Pg. 1

REPUBLIC OF SINGAPORE DRIVING LICENCE

SB336916G

ZHANG KANG'EN

Issued: 12 Nov 1983
Valid till: 22 Dec 2004

001289104F



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. SB336916G



Name
ZHANG KANG'EN

张康恩

Race
CHINESE

Date of birth
12-11-1983

Country/Place of birth
SINGAPORE

Sex
M

SB336916G

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

Class 3 Motor cars <= 3000 kg with <= 7 passengers, exclusive of the driver; and motor tractors / vehicles <= 2500 kg

PASS DATE
22 Dec 2004

NP 428A

Licence No: SB336916G



5572053



NRIC No: SB336916G

9126843

Date of issue
20-10-2014

APT BLK 308A PUNGGOL WALK #08-424
SINGAPORE 621308

NRIC No: SB336916G Date: 04/02/2016



CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2018-00003631 (Comprehensive - Classic Plan)

Car plate number: SLL8226H

Your name (As the policyholder): ZHANG KANG EN

Coverage start date: 10/03/2018

Coverage end date: 09/03/2019

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: Hong Leong Finance Limited

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 11/03/2018

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.

REPUBLIC OF SINGAPORE DRIVING LICENCE

88336916G

ZHANG KANG'EN

Expiry Date: 12 Nov 1983

Issue Date: 22 Dec 2004

001308104F

SUS224

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8336916G

Name
ZHANG KANG'EN

张 康 恩

Race
CHINESE

Date of birth
12-11-1983

Country/Place of birth
SINGAPORE

Sex
M

S8336916G

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor cars <= 3000 kg with <= 7 passengers, exclusive of the driver, and motor tractors / vehicles <= 2500 kg

PASS DATE
22 Dec 2004

NP 428A

Licence No: S8336916G

5372053

NRIC No. S8336916G

47285043

Date of issue
20-10-2014

APT BLK 308A PUNGGOL WALK #0B-424
SINGAPORE 821308

NRIC No. S8336916G Date: 04/02/2016



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



(UB)

FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Zhang Kang'En ADDRESS : Blk 308a Punggol Walk #08-424 Singapore 821308 TEL :		WIP : 31852 EXCESS : DATE :	
VEH NO :	SLL8226H	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6GL1071H0107289	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6	DATE REG.:	10-Mar-17	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO		QTY		REVISED	PRICES
1	REAR BUMPER / <i>OK</i>	1	MGJR9-50-221ABB		\$ 1,172.80
2	BRACKET CENTER, REAR BUMPER ?	1	MKD53-50-251	<i>nn</i>	\$ 5.10
3	TOWING COVER LHS / <i>mm</i>	1	MG4YL-50-EL1 62		\$ 23.70
4	TOWING COVER RHS / <i>mm</i>	1	MG4YL-50-EK1 62		\$ 23.70
5	FASTENER, REAR BUMPER / <i>mm</i>	6	MB45A-56-146A		\$ 16.80
6	GROMMET, REAR BUMPER / <i>mm</i>	4	MH260-50-841		\$ 11.20
7	CLIP, REAR BUMPER / <i>mm</i>	4	MC274-50-133		\$ 14.00
8	GROMMET, REAR BUMPER / <i>mm</i>	2	M9991-00-501		\$ 5.60
9	REAR REINFORCEMENT ?	1	MGHK1-50-260	<i>nn</i>	\$ 512.60
10	GASKET LHS, TAILLAMP / <i>mm</i>	1	MGHK1-51-163		\$ 27.70
11	GASKET RHS, TAILLAMP / <i>mm</i>	1	MGHK1-51-153		\$ 27.70
			TOTAL PARTS		\$ 1,840.90
			LESS 10%		\$ 184.09
			TOTAL PARTS COST		\$ 1,656.81

Labour Description

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	<i>660</i>	\$ 1,320.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	<i>630</i>	\$ 1,260.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	<i>330</i>	\$ 660.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	<i>nn</i> X	\$ 250.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	<i>150</i>	\$ 250.00

6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 100.00
			TOTAL LABOUR	\$ - \$ 4,190.00
			TOTAL PARTS	\$ - \$ 1,656.81
			TOTAL	\$ - \$ 5,846.81
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

3 Days -
before paint photos.
One Q & A.
23/10/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



(UB)

FIRST CAPITAL INS ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Zhang Kang'En ADDRESS : Blk 308a Punggol Walk #08-424 Singapore 821308 TEL :		WIP : 31852 EXCESS : DATE :	
VEH NO :	SLL8226H	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6GL1071H0107289	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6	DATE REG.:	10-Mar-17	POLICY NO. :	

NATURE OF WORKS

Parts Description				
NO	QTY		REVISED	PRICES
1	REAR BUMPER	1	MGJR9-50-221ABB	\$ 1,172.80 \$ 1,172.80
2	BRACKET CENTER, REAR BUMPER	1	MKD53-50-251	\$ 5.10
3	TOWING COVER LHS	1	MG4YL-50-EL1 62	\$ 23.70 \$ 23.70
4	TOWING COVER RHS	1	MG4YL-50-EK1 62	\$ 23.70 \$ 23.70
5	FASTENER, REAR BUMPER	6	MB45A-56-146A	\$ 16.80 \$ 16.80
6	GROMMET, REAR BUMPER	4	MH260-50-841	\$ 11.20 \$ 11.20
7	CLIP, REAR BUMPER	4	MC274-50-133	\$ 14.00 \$ 14.00
8	GROMMET, REAR BUMPER	2	M9991-00-501	\$ 5.60 \$ 5.60
9	REAR REINFORCEMENT	1	MGHK1-50-260	\$ 512.60
10	GASKET LHS, TAILLAMP	1	MGHK1-51-163	\$ 27.70 \$ 27.70
11	GASKET RHS, TAILLAMP	1	MGHK1-51-153	\$ 27.70 \$ 27.70
			TOTAL PARTS	\$ 1,323.20 \$ 1,840.90
			LESS 10%	\$ 132.32 \$ 184.09
			TOTAL PARTS COST	\$ 1,190.88 \$ 1,656.81

Labour Description

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 660.00	\$ 1,320.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	\$ 630.00	\$ 1,260.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	\$ 330.00	\$ 660.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00

7	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
			TOTAL LABOUR	\$ 1,970.00 \$ 4,190.00
			TOTAL PARTS	\$ 1,190.88 \$ 1,656.81
			TOTAL	\$ 3,160.88 \$ 5,846.81
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ 3,160.88
			GST 7%	\$ 221.26 \$ -
			GRAND TOTAL	\$ 3,382.14 \$ -

REMARKS:

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18018943/Gqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3948X	Veh. Inspected	SLL 8226H	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18007509MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	17/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 6	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6GL1071H0107289	Colour	RED	
Odometer	30899	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	TOYO	6 mm	
L/H Front Tyre	225/55 R17	TOYO	6 mm	
R/H Rear Tyre	225/55 R17	TOYO	6 mm	
L/H Rear Tyre	225/55 R17	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/10/2018	Inspection Date	23/10/2018	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 8226H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	1,172.80	1,172.80
1	BRACKET CENTER, REAR BUMPER	NOT NECESSARY	5.10	-
1	TOWING COVER LHS	MISSING	23.70	23.70
1	TOWING COVER RHS	MISSING	23.70	23.70
6	FASTENER, REAR BUMPER	NECESSARY	16.80	16.80
4	GROMMET, REAR BUMPER	NECESSARY	11.20	11.20
4	CLIP, REAR BUMPER	NECESSARY	14.00	14.00
2	GROMMET, REAR BUMPER	NECESSARY	5.60	5.60
1	REAR REINFORCEMENT	NOT NECESSARY	512.60	-
1	GASKET LHS, TAILLAMP	NECESSARY	27.70	27.70
1	GASKET RHS, TAILLAMP	NECESSARY	27.70	27.70
	LESS 10% DISCOUNT		-184.09	-132.32
			1,656.81	1,190.88
SPECIAL NETT ITEMS				
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			100.00	20.00
LABOUR				
	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		1,320.00	660.00
	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.		1,260.00	630.00
	TO TRANSFER REVERSE SENSORS.		660.00	330.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	250.00	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
			4,090.00	1,950.00
GRAND TOTAL			5,846.81	3,160.88
RECOMMENDED COST OF REPAIRS				3,160.88

Report Ref No. CS/FCI18018943/Gqd3n2



Report Ref No. CS/FCI18018943/Gqd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.