

ASS. REC. BY:

REF: CS/FCI18018945/Tlrd3n2/ Special Instruction:

Surveyor: Taufiqh ASSIGNMENT (Office)CWS From (Person): Eileen Lee of FCI Date/Time: 18/10/18 @ 4:54pm

Estimated Cost: Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SMC 1297J Insured: SHC1028Dat Workshop m/s Prime Auto Tel: 68610908of 6 Benoi placePolicy No: Claim No: D18007548 MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 15/10/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (DS) H.O.D. Endorsement:

Date/Time: 5:43pm Person Contacted: pei yee Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SMC1297J - X</u>
	<u>SHC1028D - CS/FCI18006058/Gvde2</u> <u>DVA: 29/03/2018</u>
<u>19/10/18</u>	<u>Email preli revised to FCI</u>
<u>14/11/18</u>	<u>Confirm with Alice \$8347.32 @ 5 days (Red. \$ 3174.16, 28%.)</u>



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18007548MFSH

Our ref: CS/FCI18018945/T1rd3

Date: 19/10/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO SMC 1297J


We thank you for your instruction on 18/10/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18/10/2018 at the premises of M/s PRIME AUTO CLAIMS SERVICE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$10,742.50
Revised Estimate Amount	: S\$7,340.35
"Check" Items Amount	: S\$517.95
Total	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front and rear portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

MOTOR SURVEY ASSIGNMENT

Date	17-10-2018	Our Ref No.	D18007548MFSH
Accident Date	15-10-2018	Claim Type.	Third Party
Insured Vehicle	SHC1028D	Third Party Vehicle.	SMC1297J
Survey Location	6 BENOI PLACE		
Contact Person.	CHRISSY TEO		
Contact No.	68610908/ 0	Fax No.	65152948
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PRIME AUTO CLAIMS SERVICE PTE. LTD.	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	EILEEN LEE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/245150)



PRI Documents



Close X

PRI Header Details

Claim No	D18007548MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PRIME AU LTD.
Workshop Name	PRIME AUTO CLAIMS SERVICE PTE. LTD. (Contact Person : CHRISSY TEO)	Survey Location & Contact Details	6 BENOI PLACE Mobile: 0 , Phone: 68610908 , Fax: 65152948 EmailId: CHRISSY@PRIMEAUTOCLAIMS.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC1028D	TP Vehicle No	SMC1297J
PRI Recieved Date	17-10-2018 06:39:33 PM	Surveyor Appointed Date	17-10-2018 04:53:19 PM	Surveyor Accept Date	18-10-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	18-10-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 19 October 2018 3:40 PM
To: 'CWS Motor Claims'
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007548MFSH/1, SMC 1297J
Attachments: SMC 1297J PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SMC 1297J
Date of survey: 18/10/2018
Number of days : 8 days

Best Regards,

Veron Chen | Case Handler on behalf of Jannice

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 18 October 2018 9:06 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007548MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 17 October 2018 4:53 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007548MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Janice Lee (LKKAUTO)

From: Alice Leong <aliceleong@primeautoclaims.com>
Sent: Wednesday, October 31, 2018 9:49 AM
To: Taufikh (LKKAUTO)
Cc: SUR
Subject: FW: FINALIZE TO VEHICLE SMC1297J
Attachments: AVAN5428.JPG; JMPO7869.JPG; SBYI9126.JPG; TNNE0646.JPG; VQIU2175.JPG; CILM9795.JPG; DVGJ8797.JPG; AGIS7949.JPG; BNIB6142.JPG; BOQO9941.JPG; CFCI0347.JPG; DKSZ4119.JPG; FFNP7198.JPG; LWWH7191.JPG; QTNP1805.JPG; DRVE3700.JPG; LPVY3636.JPG; RMEA6810.JPG; XSPE4082.JPG; img-181031113706.pdf

Importance: High

Hi Taufikh,

See enclosed our amended calculation sheet & supplementary sheet list. Please amend the P & P is \$8,931.64

Thank you

Alice Leong
Manager, Motor Claims

Prime Auto Claims Service Pte Ltd
6 Benoi Place Singapore 629927
T (65): 6861 0908 | F (65) 6515 2948
HP (65) 9818 4304

A member of the Prime Group

Disclaimer

This e-mail (including all attachment) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intend recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Alice Leong [mailto:aliceleong@primeautoclaims.com]
Sent: 29 October, 2018 12:24 PM
To: 'Taufikh (LKKAUTO)' <Taufikh@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>
Subject: FINALIZE TO VEHICLE SMC1297J
Importance: High

Hi Taufikh,

We enclosed our before & after repair photos, supplementary list with purchase invoice & our calculation sheet for your retention. Shall we finalize at part by parts \$8,119.33 and 8 days

Please let us have your confirmation within three days from our e-mail.

Thank you

Alice Leong

Manager, Motor Claims

Prime Auto Claims Service Pte Ltd

6 Benoi Place Singapore 629927

T (65): 6861 0908 | F (65) 6515 2948

HP (65) 9818 4304

A member of the Prime Group

Disclaimer

This e-mail (including all attachment) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intend recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Wednesday, November 14, 2018 3:16 PM
To: 'Alice Leong'; Taufikh (LKKAUTO)
Subject: RE: FINALIZE TO VEHICLE SMC1297J

Ok. Confirm amount \$8,347.32 @ 8 days (as spoken)

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alice Leong [<mailto:aliceleong@primeautoclaims.com>]
Sent: Wednesday, November 14, 2018 3:15 PM
To: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: RE: FINALIZE TO VEHICLE SMC1297J
Importance: High

Hi Janice,

We accepted your below amount and no of days.

Thank you

Alice Leong

Manager, Motor Claims

Prime Auto Claims Service Pte Ltd
6 Benoi Place Singapore 629927
T (65): 6861 0908 | F (65) 6515 2948
HP (65) 9818 4304

A member of the Prime Group

Disclaimer

This e-mail (including all attachment) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intend recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Janice Lee (LKKAUTO) [<mailto:JaniceLee@lkkauto.com>]
Sent: 14 November, 2018 3:10 PM
To: Alice Leong <aliceleong@primeautoclaims.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: RE: FINALIZE TO VEHICLE SMC1297J

Dear Alice,

Kindly confirm

Part : \$6,297.80 = \$4,723.35 (25%)
Sn : \$290.00
Labour : \$2,555.00
Supp Part : \$1,038.63 = \$778.98
Total : \$8,347.33 @ 8 days

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alice Leong [<mailto:aliceleong@primeautoclaims.com>]
Sent: Wednesday, October 31, 2018 9:49 AM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: FW: FINALIZE TO VEHICLE SMC1297J
Importance: High

Hi Taufikh,

See enclosed our amended calculation sheet & supplementary sheet list. Please amend the P & P is \$8,931.64

Thank you

Alice Leong

Manager, Motor Claims

Prime Auto Claims Service Pte Ltd
6 Benoi Place Singapore 629927
T (65): 6861 0908 | F (65) 6515 2948
HP (65) 9818 4304

A member of the Prime Group

Disclaimer

This e-mail (including all attachment) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intend recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Alice Leong [<mailto:aliceleong@primeautoclaims.com>]
Sent: 29 October, 2018 12:24 PM
To: 'Taufikh (LKKAuto)' <Taufikh@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>
Subject: FINALIZE TO VEHICLE SMC1297J
Importance: High

Hi Taufikh,

We enclosed our before & after repair photos, supplementary list with purchase invoice & our calculation sheet for your retention. Shall we finalize at part by parts \$8,119.33 and 8 days

Please let us have your confirmation within three days from our e-mail.

Thank you

Alice Leong

Manager, Motor Claims

Prime Auto Claims Service Pte Ltd

6 Benoi Place Singapore 629927

T (65): 6861 0908 | F (65) 6515 2948

HP (65) 9818 4304

A member of the Prime Group

Disclaimer

This e-mail (including all attachment) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intend recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 17.10.2018

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97415749
- WP
18/10/18 @ 230pm
8 days
sur e lull and to com
Resurvey before paint.
22/10/18.

ESTIMATE COST OF REPAIR TO VEHICLE SMC1297J TOYOTA SIENTA (2018)

To Supply

1) 1pc	front bumper	\$ de 679.10
2) 1pc	front bumper right retainer	\$ X 55.70 X m.
3) 1pc	front bumper sponge	\$ cre 70.30
4) 1pc	front bumper reinforcement	\$ X 347.10 X m
5) 1pc	front radiator top panel	\$ Rx 187.00 X
6) 1pc	hybird cooler	\$? 690.60 X m
7) 1pc	front grille base	\$ cre 55.10
8) 1pc	front grille chrome	\$ mt 455.10
9) 1pc	radiator grille "Toyota" emblem	\$ ner 65.00
10) 1pc	front no plate garnish	\$ mt 40.00
11) 1set	rear bumper	\$ de 687.40
12) 1pc	rear bumper left retainer	\$ ner 71.10
13) 1pc	rear bumper center top garnish (black)	\$ de 357.50
14) 1pc	rear bumper clip	\$ ner 30.00
15) 1pc	rear end panel	\$ bt 604.10
16) 1pc	rear floor panel	\$ Rx 678.10 X
17) 1pc	rear end panel top garnish	\$ de 388.90
18) 1set	rear end panel top garnish clip	\$ ner 15.00
19) 1pc	left rear fender lamp	\$ cre 312.60
20) 1pc	tail gate	\$ bt 1,194.10
21) 1pc	tail gate "Toyota" emblem	\$ ner 55.60
22) 1pc	tail gate "hybrid synergy drive" emblem	\$ ner 50.10

23)	1pc	tail gate weatherstrip		\$	288.90	<i>hi</i>
24)	1pc	tail gate lock		\$	301.60	<i>bf</i>
25)	1pc	tail gate lock catch		\$	60.70	<i>bf</i>
26)	1pc	tail gate trim cover		\$	464.70	<i>x x m</i>
27)	2pcs	tail gate rear glass moulding	@\$257.80	\$	515.60	<i>211.60 ne</i>
28)	1pc	tail pipe with silencer		\$	673.00	<i>x x m</i>

Sub total parts	\$	9,090.00
Less: 25% discount	\$	(2,272.50)
	\$	6,817.50

S.Nett parts

1)	1pc	front no plate with casing	\$	45.00	<i>one</i>
2)	1tube	glass sealant	\$	45.00	<i>net</i>
3)	1set	reverse sensor	\$	250.00	<i>200 net</i>

Sub total S.Nett Parts	\$	340.00
------------------------	----	--------

L/charges

1)	Towing charges (with king trolley)	\$	85.00	<i>✓</i>
2)	To remove front bumper, front grille, radiator top panel, right & left head lamp. To replace front bumper, top panel, front grille, hybrid cooler. To align front bumper & front grille	\$	500.00	<i>300</i>
3)	To putty, respray painting front bumper, top panel	\$	300.00	<i>250</i>
4)	To tuff kote rear portion	\$	100.00	<i>60.</i>
5)	To transfer tail gate cover, glass & mechanism parts	\$	100.00	<i>60.</i>
6)	To remove & refit rear glass	\$	120.00	<i>✓</i>
7)	To remove & replace reverse sensor	\$	60.00	<i>30.</i>
8)	To remove & replace rear exhaust tail pipe & silencer	\$	120.00	<i>x m</i>
9)	To remove rear bumper, tail gate, right & left tail lamp & etc. Cut/welding rear end panel & floor panel. Replace rear bumper, tail gate, end panel & floor panel, adjust & align tail gate & bumper	\$	1,000.00	<i>800</i>

10) To putty, respray painting tail gate inlet & outer, rear bumper, end panel & floor panel. To putty \$ 1,200.00

Sub total L/charges \$ 3,585.00
Estimated total \$ 10,742.50
~~11521.48~~
11749.48



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 17.10.2018

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

RE: SUPPLEMENTARY COST OF REPAIR TO VEHICLE SMC1297J TOYOTA SIENTA (2018

To Supply

- 1) 1pc End panel (outer)
- 2) 1pc rear bumper left side garnish
- 3) 1pc antenna electrical key
- 4) 1pc boot lid door pull, handle (black)
- 5) 1pc tray luggage compartment

\$	378.00	bt ✓
\$	124.00	de ✓
\$	116.40	co ✓
\$	26.90	de ✓
\$	393.33	de ✓

sub total parts	\$	1,038.63
Less 25% discount	\$	(259.65)
	\$	<u>778.98</u>



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 17.10.2018

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

*Tanpin 97415749
- WP
18/10/18 @ 230pm
8 days
sur e lll and so on
Recovery before paint.*

ESTIMATE COST OF REPAIR TO VEHICLE SMC1297J TOYOTA SIENTA (2018)

To Supply

1) 1pc	front bumper	\$ de 679.10
2) 1pc	front bumper right retainer	\$ x 55.70x
3) 1pc	front bumper sponge	\$ crs 70.30
4) 1pc	front bumper reinforcement	\$ R 347.10x
5) 1pc	front radiator top panel	\$ R 187.00x
6) 1pc	hybird cooler	\$? 690.60x
7) 1pc	front grille base	\$ crs 55.10
8) 1pc	front grille chrome	\$ int 455.10
9) 1pc	radiator grille "Toyota" emblem	\$ ne 65.00
10) 1pc	front no plate garnish	\$ int 40.00
11) 1set	rear bumper	\$ de 687.40
12) 1pc	rear bumper left retainer	\$ ne 71.10
13) 1pc	rear bumper center top garnish (black)	\$ de 357.50
14) 1pc	rear bumper clip	\$ ne 30.00
15) 1pc	rear end panel (inner)	\$ bt 604.10
16) 1pc	rear floor panel	\$ R 678.10x
17) 1pc	rear end panel top garnish	\$ de 388.90
18) 1set	rear end panel top garnish clip	\$ ne 15.00
19) 1pc	left rear fender lamp	\$ crs 312.60
20) 1pc	tail gate	\$ bt 1,194.10
21) 1pc	tail gate "Toyota" emblem	\$ ne 55.60
22) 1pc	tail gate "hybrid synergy drive" emblem	\$ ne 50.10

- 23) 1pc tail gate weatherstrip
 24) 1pc tail gate lock
 25) 1pc tail gate lock catch
 26) 1pc tail gate trim cover
 27) 2pcs tail gate rear glass moulding
 28) 1pc tail pipe with silencer

Amend!



@\$257.80

\$ 288.90 *hi*
 \$ 301.60 *bf*
 \$ 60.70 *bf*
 \$ 464.70 *XX*
 \$ 515.60 *211.60 net*
 \$ 673.00 *X*

Sub total parts \$ 9,090.00 *6251.60*
 Less: 25% discount \$ (2,272.50) - *1562.90*
 \$ 6,817.50 *4688.70*

S.Nett parts

- 1) 1pc front no plate with casing
 2) 1tube glass sealant
 3) 1set reverse sensor

\$ *net* 45.00
 \$ 45.00 *net*
 \$ 250.00 *200 net*

Sub total S.Nett Parts \$ 340.00 *290.00*

L/charges

- 1) Towing charges (with king trolley) \$ 85.00 *✓*
 2) To remove front bumper, front grille, radiator top panel, right & left head lamp. To replace front bumper, top panel, front grille, hybrid cooler. To align front bumper & front grille \$ 500.00 *300*
 3) To putty, respray painting front bumper, top panel \$ 300.00 *250*
 4) To tuff kote rear portion \$ 100.00 *60*
 5) To transfer tail gate cover, glass & mechanism parts \$ 100.00 *60*
 6) To remove & refit rear glass \$ 120.00 *✓*
 7) To remove & replace reverse sensor \$ 60.00 *30*
 8) To remove & replace rear exhaust tail pipe & silencer \$ 120.00 *X*
 9) To remove rear bumper, tail gate, right & left tail lamp & etc. Cut/welding rear end panel & floor panel. Replace rear bumper, tail gate, end panel & floor panel, adjust & align tail gate & bumper \$ 1,000.00 *800*

10) To putty, respray painting tail gate inlet & outer, rear bumper, end panel & floor panel. To putty

850
\$ 1,200.00

Sub total L/charges	\$	3,585.00	2555.00
Estimated total	\$	10,742.50	

Parts - \$ 4,688.70
S. rest parts - 4 290.00
L/charges - 4 2555.00
Supplementary - \$ 778.98

4 8312.68



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 17.10.2018

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

RE: SUPPLEMENTARY COST OF REPAIR TO VEHICLE SMC1297J TOYOTA SIENTA (2011

To Supply

1)	1pc	End panel (outer)	\$	378.00
2)	1pc	rear bumper left side garnish	\$	124.00
3)	1pc	antenna electrical key	\$	116.40
4)	1pc	boot lid door pull, handle (black)	\$	26.90
5)	1pc	tray luggage compartment	\$	393.33
sub total parts			\$	1,038.63
Less 25% discount			\$	(259.65)
			\$	<u>778.98</u>



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

PRIME AUTO CLAIMS SERVICE PTE LTD
6 BENOI PLACE (2ND FLOOR)

629926

TEL: 68610908 FAX: 65152948

ATTN: ALICE

WINDSCREEN GLASS
Dept Direct: 6417 8791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 8792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso NGK (Made in Japan)

TAX INVOICE AR201810-10242
DATE: 18/10/2018
CUSTOMER ID: PRI008
VEH REG. NO.: SMC1297J
TERMS: 30 days
PO NO.:
PAGE NO.: Page 1 of 1
CURR.: S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T53101-52460 NSP170-15	FRT GRILLE	U1	1		
2. T58307-52670 NSP170-15	END PANEL (OUTER)	U1	1		
	SUPPLIER				

S-Parts (50%)

Comfort Limousine Service, SMC1297J, 2673

SUB-TOTAL:
ADD GST 7.00 %

E. & O.E

TOTAL AMOUNT S\$

[P] 18/10/2018 15:57:30

[E] 18/10/2018 3:49:53PM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: LAI



* A R 2 0 1 8 1 0 - 1 0 2 4 2 *

This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

PRIME AUTO SERVICE PTE LTD
6 BENOI PLACE (2ND FLOOR)
Tel: 199307741M

629926

TEL : 68610908 FAX : 65152948
ATTN : ALICE

WINDSCREEN GLASS
Dept Direct: 6417 9761 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9704

Dept Direct: 6417 9705

Dept Direct: 6417 9799

Dept Direct: 6417 971

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE AR201810-12205

DATE : 23/10/2018
CUSTOMER ID : PRI008
VEH REG. NO. : SMC1297J
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : S\$

S	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	T52162-52150	RR BUMPER S/GARNISH I.H	U1	1		
	NSP170 15"		L2-C18-A			
2.	T89997-30100	ANTENNA ELECTRICAL KEY	U1	1		
	NSP170 Z/VW50 Z/YX10		L2-S4-F			
3.	T74811-13010-C2	BOOT/ID DOOR PULL HANDLE (BLACK)	U1	1		
	WISH-ZNE10		L2-C20-I			

S-Part (50%)

Comfort Limousine Service, SMC1297J, 2673

SUB-TOTAL :
ADD GST 7.00 %

E & O E

TOTAL AMOUNT S\$

[P] 23/10/2018 11:05:15

[E] 23/10/2018 11:02:55AM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

Goods Received in Good Order

JAE Auto Pte. Ltd.

Sales Executive: LAI



* A R 2 0 1 8 1 0 - 1 2 2 0 5 *

This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

PRIME AUTO CLAIMS SERVICE PTE LTD
BENOI PLACE (2ND FLOOR)

629926

TEL: 68610908 FAX: 65152948

ATTN: ALICE



Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea)
Forch (Made in Germany)

Spark plug: Nippon-Denso, NGK (Made in Japan)

TAX INVOICE AR201810-12586
DATE 23/10/2018
CUSTOMER ID PRI008
VEH REG. NO. SMC1297J
TERMS 30 days
PO NO.
PAGE NO. Page 1 of 1
CURR. S\$

STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 164421-52100-C0	TRAY LUGGAGE COMPARTMENT	U1	1		
NHP170		I3-D1			

S-Parts (50%)

Comfort Liner Service SMC1297J, 2673

SUB-TOTAL :
ADD GST 7.00 %

E. & O.E

TOTAL AMOUNT S\$

[P] 23/10/2018 4:58:22PM

[E] 23/10/2018 4:58:02PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: HAN



AR201810-12586

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18018945/T1rd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1028D	Veh. Inspected	SMC 1297J	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18007548MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	18/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	NHP1707118852	Colour	MAROON	
Odometer	13804	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/10/2018	Inspection Date	18/10/2018	
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 1297J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	679.10	679.10
1	FRONT BUMPER RIGHT RETAINER	NOT NECESSARY	55.70	-
1	FRONT BUMPER SPONGE	CRACKED	70.30	70.30
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	347.10	-
1	FRONT RADIATOR TOP PANEL	TO REPAIR SEE LABOUR	187.00	-
1	HYBRID COOLER	NOT NECESSARY	690.60	-
1	FRONT GRILLE BASE	CRACKED	55.10	55.10
1	FRONT GRILLE CHROME	CUT	455.10	455.10
1	RADIATOR GRILLE "TOYOTA" EMBLEM	NECESSARY	65.00	65.00
1	FRONT NO PLATE GARNISH	CUT	40.00	40.00
1	REAR BUMPER	DEFORMED	687.40	687.40
1	REAR BUMPER LEFT RETAINER	NECESSARY	71.10	71.10
1	REAR BUMPER CENTER TOP GARNISH (BLACK)	DEFORMED	357.50	357.50
1	REAR BUMPER CLIP	NECESSARY	30.00	30.00
1	REAR END PANEL	BENT	604.10	604.10
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	678.10	-
1	REAR END PANEL TOP GARNISH	DEFORMED	388.90	388.90
1	SET REAR END PANEL TOP GARNISH CLIP	NECESSARY	15.00	15.00
1	LEFT REAR FENDER LAMP	CRACKED	312.60	312.60
1	TAIL GATE	BENT	1,194.10	1,194.10
1	TAIL GATE "TOYOTA" EMBLEM	NECESSARY	55.60	55.60
1	TAIL GATE "HYBRID SYNERGY DRIVE" EMBLEM	NECESSARY	50.10	50.10
1	TAIL GATE WEATHERSTRIP	TWISTED	288.90	288.90
1	TAIL GATE LOCK	BENT	301.60	301.60
1	TAIL GATE LOCK CATCH	BENT	60.70	60.70
1	TAIL GATE TRIM COVER	NOT NECESSARY	464.70	-
2	TAIL GATE REAR GLASS MOULDING @\$257.80	NECESSARY	515.60	515.60
1	TAIL PIPE WITH SILENCER	NOT NECESSARY	673.00	-
1	END PANEL (OUTER)(ADDITIONAL)	BENT	378.00	378.00

Report Ref No. CS/FCI18018945/T1rd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER LEFT SIDE GARNISH (ADDITIONAL)	DEFORMED	124.00	124.00
1	ANTENNA ELECTRICAL KEY (ADDITIONAL)	CRACKED	116.40	116.40
1	BOOT LID DOOR PULL,HANDLE (BLACK)(ADDITIONAL)	DEFORMED	26.90	26.90
1	TRAY LUGGAGE COMPARTMENT (ADDITIONAL)	DEFORMED	393.33	393.33
	LESS 25% DISCOUNT		-2,608.15	-1,834.11
			7,824.48	5,502.32
	SPECIAL NETT ITEMS			
1	FRONT NO PLATE WITH CASING (SN)	CRACKED	45.00	45.00
1	TUBE GLASS SEALANT (SN)	NECESSARY	45.00	45.00
1	SET REVERSE SENSOR (SN)	NOT WORKING	250.00	200.00
			340.00	290.00
	LABOUR			
	TOWING CHARGES (WITH KING TROLLEY).		85.00	85.00
	TO REMOVE FRONT BUMPER,FRONT GRILLE,RADIATOR TOP PANEL,RIGHT & LEFT HEAD LAMP.TO REPLACE FRONT BUMPER, TOP PANEL,FRONT GRILLE, HYBRID COOLER.TO ALIGN FRONT BUMPER & FRONT GRILLE.INCLUSIVE OF THE REPAIR OF FRONT RADIATOR TOP PANEL.		500.00	300.00
	TO PUTTY,RESPRAY PAINTING FRONT BUMPER, TOP PANEL.		300.00	250.00
	TO TUFF KOTE REAR PORTION.		100.00	60.00
	TO TRANSFER TAIL GATE COVER,GLASS & MECHANISM PARTS.		100.00	60.00
	TO REMOVE & REFIT REAR GLASS.		120.00	120.00
	TO REMOVE & REPLACE REVERSE SENSOR.		60.00	30.00
	TO REMOVE & REPLACE REAR EXHAUST TAIL PIPE & SILENCER.	NOT NECESSARY	120.00	-
	TO REMOVE REAR BUMPER, TAIL GATE, RIGHT & LEFT TAIL LAMP & ETC.CUT/WELDING REAR END PANEL & FLOOR PANEL.REPLACE REAR BUMPER, TAIL GATE, END PANEL & FLOOR PANEL, ADJUST & ALIGN TAIL GATE & BUMPER.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL.		1,000.00	800.00

Report Ref No. CS/FCI18018945/T1rd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY, RESPRAY PAINTING TAIL GATE INLET & OUTER, REAR BUMPER, END PANEL & FLOOR PANEL TO PUTTY.		1,200.00	850.00
			3,585.00	2,555.00
	GRAND TOTAL		11,749.48	8,347.32
	RECOMMENDED COST OF REPAIRS			8,347.32

Report Ref No. CS/FCI18018945/T1rd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.