

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8006X

MAKE :

MODEL : MERCEDES

DATE 17/10/2018 11:39

Fauzy

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bumper Assy, Frt <i>X repair</i>			\$ 1,890.50
	Bumper Bracket, Frt/LH <i>X su</i>			\$ 95.00
	Head Lamp Assy (LH) <i>/ in</i>			\$ 2,380.00
	<i>Front Fender (LH) X repair</i>		<i>\$ 1380.50</i>	
	<i>Head lamp Control unit - slated</i>			
	SUB TOTAL			\$ 4,365.50
	LESS 20%			\$ 873.10
	DISCOUNTED TOTAL			\$ 3,492.40
	Labour Charge			
	Panel Beating			\$ 400.00 ²⁰⁰
	Spray Painting Charge			\$ 500 ⁴⁰⁰
	<i>programming</i>		<i>\$ 150</i>	
	TOTAL LABOUR			\$ 700.00
	ESTIMATE TOTAL			\$ 4,192.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kahin LKK

17/10/18 1510 hrs.

2 Days.

L/s

After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CHUNNI MOTOR WORK PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Auto point Singapore 568047

Tel: 6542 7162, 6542 5119 Fax: 6542 6039

Company Reg. No. 200923110D

GST Reg. No. 200923110D

QUOTATION

COMFORTDELGRO ENGINEERING PTE LTD
59 LOYANG DRIVE
SINGAPORE 508969

DATE : 24/10/2018

REF NO : 18/033-10

VEH NO : SHC 8006X
MERC E220

DESCRIPTION

AMOUNT

LABOUR CHARGES

PERFORM PROGRAMMING AND ONLINE SCN
CODING FOR FRONT LH HEADLAMP CONTROL UNIT

\$ 580.00 150

\$ 580.00

Add : 7% GST

\$ 40.60

TOTAL AMOUNT

\$ 620.60

