

# SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

LIM SIEW BEE  
c/o 46 Lentor Plain  
Singapore 786548

*Not Authorised*  
*Lim 838006*  
*Resurvey After Paint*  
*5 days*

Date: 16/10/2018

| QUANTITY | PARTICULARS                                                                                           | AMOUNT (\$)                            |
|----------|-------------------------------------------------------------------------------------------------------|----------------------------------------|
|          | RE: SJS3973D / BMW 320i                                                                               |                                        |
| 1 pc     | rear door <i>1815-00</i>                                                                              | <i>Adl/marp</i> 2,176.00 ✓             |
| 1 pc     | front doot                                                                                            | <i>R</i> 2,350.00 X                    |
| 1 pc     | side rocker panel garnish                                                                             | <i>R</i> 1,276.00 X                    |
| 1 pc     | rear bumper <i>1182</i>                                                                               | <i>deep</i> <i>Noted by</i> 1,675.00 ✓ |
|          | sub-total                                                                                             | 7,477.00                               |
|          | less 10%                                                                                              | 747.70                                 |
|          | sub-total                                                                                             | 6,729.30                               |
|          | alloy rim <i>P1: 780-00</i>                                                                           | <i>s.nett</i> <i>P1</i> 900.00 ✓       |
|          | To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas. | <i>5500</i> 900.00                     |
|          | To check wiring system.                                                                               | <i>200</i> 40.00                       |
|          | To apply putty & spray painting on affected areas.                                                    | <i>1000</i> 1,350.00                   |
|          | To transfer doors accessories.                                                                        | <i>600</i> 120.00                      |
|          | To perform 4 wheels computerised alignment.                                                           | <i>600</i> 85.00                       |
|          | Total                                                                                                 | 10,124.30                              |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date: