

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8830H

DATE 17/10/2018 11:30

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille — <i>crs</i>			\$ 1,110.10
	Front Bumper Cover — <i>Paint</i>			\$ 1,052.00
	Front Bumper Sponge <i>X</i>			\$ 99.20
	Front Bumper Reinforcement <i>X</i>			\$ 402.10
	Front Bumper Grille (LH) <i>X</i>			\$ 93.60
	Front Bumper Grille Airduct (LH) <i>X</i>			\$ 26.20
	Headlamp (LH) — <i>cut</i>			\$ 1,388.00
	Front Fender (LH) — <i>Paint</i>			\$ 566.30
	Front Fender Shield (LH) <i>X</i>			\$ 174.90
	Front Door (LH) — <i>Paint</i>			\$ 2,256.40
	Front Door Mirror Assy (LH) — <i>broken</i>			\$ 670.00
	Front Pillar Upper Cover, LH <i>X</i>			\$ 225.00
	Front Wheel Hub Cap (LH) — <i>broken</i>			\$ 107.10
	<i>Front Bumper X repair</i>			
	<i>Front Bumper Emblem — ne</i>			
	SUB TOTAL		\$ 2790 .	\$ 8,171.10
	LESS 20%			\$ 1,634.22
	DISCOUNTED TOTAL			\$ 6,536.88
	Front Fender Advertisement Logo (LH) — <i>ne</i>			\$ 100.00
	Front Door Comfort Logo (LH) — <i>ne</i>			\$ 75.00
	Front Door Advertisement Logo (LH) — <i>ne</i>			\$ 100.00
				\$ 275.00
	Labour Charge			
	Panel Beating-Repair Frt W/S Pillar (LH)			\$ 800.00
	Spray Painting Charge			\$ 1400.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 100.00
	Transfer of Door			\$ 80.00
	FRT Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 2,510.00
	ESTIMATE TOTAL			\$ 9,321.88

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.