

# ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLJ 9135R

Vehicle Model : HONDA VEZEL

Chassis Number : RU31214018

Estimated Repair Cost

| S/N               | Parts Description                               | Qty | List Price   |
|-------------------|-------------------------------------------------|-----|--------------|
| 1                 | FRONT RH DOOR                                   | 1   | 980.00 ✓ DEF |
| 2                 | FRONT RH DOOR HANDLE                            | 1   | 170.00 X SVC |
| 3                 | FRONT RH DOOR LOCK                              | 1   | 262.30 X SVC |
| 4                 | FRONT RH DOOR WINDOW OUTER MOULDING             | 1   | 60.00 / NEC  |
| 5                 | FRONT RH DOOR INNER TRIM BOARD                  | 1   | 650.00 ?     |
| 6                 | FRONT RH DOOR REGULATOR                         | 1   | 382.90 X SVC |
| 7                 | FRONT RH DOOR WINDOW MOTOR                      | 1   |              |
| 8                 | FRONT RH DOOR HINGES                            | 2   | 100.00 ?     |
| 9                 | FRONT RH DOOR WINDOW VERTICAL GARNISH (STICKER) | 1   | 18.50 / NEC  |
| 10                | FRONT RH DOOR WEATHERSTRIP                      | 4   | 202.00 X SVC |
| 11                | FRONT RH DOOR TRIM BOARD CLIPS                  | 20  | 100.00 ?     |
| 12                | RH REAR DOOR                                    | 1   | 930.60 ✓ DEF |
| 13                | RH REAR DOOR WINDOW OUTER MOULDING              | 1   | 65.00 / NEC  |
| 14                | RH REAR DOOR WINDOW VERTICAL GARNISH (STICKER)  | 1   | 18.50 / NEC  |
| 15                | RH REAR DOOR LOCK                               | 1   | 210.00 X SVC |
| 16                | RH REAR DOOR WINDOW MOTOR                       | 1   |              |
| 17                | RH REAR DOOR REGULATOR                          | 1   | 390.00 X SVC |
| 18                | RH REAR DOOR TRIM BOARD                         | 1   | 635.00 ?     |
| 19                | RH REAR DOOR TRIM BOARD CLIPS                   | 20  | 100.00 ?     |
| 20                | RH SIDE SKIRT                                   | 1   | 377.80 / SCR |
| 21                | RH SIDE SKIRT CLIPS                             | 20  | 100.00 ?     |
| 22                | RH REAR WHEEL ARCH                              | 1   | 172.10 / SCR |
| 23                | RH REAR SPLASH SHIELD                           | 1   | 90.40 X SVC  |
| 24                | RH REAR SPLASH SHIELD CLIPS                     | 10  | 50.00 X SVC  |
| 25                | RH REAR WHEEL RIM                               | 1   | 450.00 X R   |
| 26                | RH REAR TYRE                                    | 1   | 350.00 X SVC |
| 27                | RH REAR SHOCK ABSORBER                          | 1   | 330.00 X SVC |
| 28                | RH REAR DOOR WEATHERSTRIP                       | 4   | 202.00 X SVC |
| 29                | RH (FRONT & REAR DOOR) SOUND PROOF              | 2   | 450.00 / NEC |
|                   |                                                 |     | \$ 7847.10   |
| Discount Less 20% |                                                 |     | \$ 1569.42   |
| List Prices Total |                                                 |     | \$ 6,277.68  |

# ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,  
Harvest @ Woodlands Singapore 757322  
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLJ 9135R  
Vehicle Model : HONDA VEZEL  
Chassis Number : RU31214018

| S/N | Labour Descriptions                                                                                                                                                            | Charges                   |
|-----|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------|
| 1   | LABOUR CHARGES TO REMOVE & INSTALL RHS BODY ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO STRAIGHTEN & REPAIR RHS DOOR PILLARS, RHS SILL PANEL, RHS DOORS PILLARS & ARCH PANEL. | \$ <del>1800.00</del> 600 |
| 2   | TO SPRAY PAINTING ON RHS FRONT & REAR DOORS (INNER, OUTER), RHS SILL GARNISH & PANEL, RHS DOOR PILLARS AND ARCH PANEL.                                                         | \$ <del>1800.00</del> 600 |
| 3   | TO REMOVE & TRANSFER RHS FRONT & REAR DOORS TRIM BOARDS, DOORS SCREENS, POWER WINDOW & ELECTRICAL WIRINGS AND SERVICEABLE FITTINGS TO NEW DOORS & TEST FUNCTIONS.              | \$ <del>300.00</del> 120  |
| 4   | TO REMOVE & REPLACE RHS REAR RIM & TYRE,                                                                                                                                       | \$ 50.00 XNN              |
| 5   | TO CHECK & ADJUST WHEEL ALIGNMENT                                                                                                                                              | \$ 160.00 XNN             |
| 6   | TO CHECK, DIAGNOSIS & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.                                                                                                               | \$ <del>180.00</del> 30   |

Labour Total \$ 4290.00

Parts & Labour Total \$ 10567.68

NA2 LKK  
18/10/18 1100  
PL

6 days

- CHECK ITEM PHOTO  
- BEFORE PAINT PHOTO

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: