

CASE OWNER

cc 4, LPE 180 18963, N ja3n2

KK: IDAC:

Surveyor: Naz

ASSIGNMENT  
DOI: 18/10/18

Date / Time: 18/10/18

Pre-assign / CCU / FTE

SPB 529J

Registered in Merimen: 18/10/18 VPOS 021033



Insured Vehicle No. : SPB 529J

Claim No. : 18/10/18 VPOS 021033

Name of Insured : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Insured Tel No. : \_\_\_\_\_ HP: \_\_\_\_\_

Make / Model : \_\_\_\_\_

Excess Sec II :SS \_\_\_\_\_ D.O.A: 16-10-18

Place of Accident : \_\_\_\_\_

Is driver the owner? (YES / NO) Nature of Accident : \_\_\_\_\_

If NO, Driver Name / Age : \_\_\_\_\_

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : \_\_\_\_\_ (V/L: YES / NO)

Insured Liability: % Final? Yes / No

SLQ 53942



INSRS: WSP: World Auto  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_

Date / Time

Date / Time	STAGE	DATE / PIC
<u>18/10/18</u>	Non-Reporting ltr (1st):	
<u>18/10/18</u>	Non-Reporting ltr (2nd):	
<u>18/10/18</u>	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	<u>NA</u>
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

6-6-19 LOD IN FOR MANDATE.

**PRELIMINARY ADVICE** Date/Time: \_\_\_\_\_ Sent By: \_\_\_\_\_

**FINALIZATION** Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Confirm by: \_\_\_\_\_

Repair Cost: \$S \_\_\_\_\_ days) Reduction: % \_\_\_\_\_ Email  Call

**FINAL SETTLEMENT** Date/Time: 3-7-19 Confirm with: GERALDINE Email  Call

Final Liability: % 100 (Assess / Assessed) BOLA S/N No.: 27 If NO or B 28, Ass. Lia: \_\_\_\_\_

Repair Cost: GST \$S 2,877.71

Loss of Rental (LOR): \$S \_\_\_\_\_ ( \_\_\_\_\_ days)

Loss of Use (LOU): \$S 240 (\$ 60 x 4 days)

Loss of Income (LOI): \$S \_\_\_\_\_ (\$ \_\_\_\_\_ x \_\_\_\_\_ days)

LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]

GIA/LTA Search: \$S 2.44

Medical: \$S \_\_\_\_\_

Disbursement: \$S \_\_\_\_\_ (e.g. Tow/ Independent)

Legal Cost: \$S \_\_\_\_\_

Total: \$S 3,119.71 Global Sum \$S: \_\_\_\_\_

**FINAL PAYMENT** Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call

Payee 1: \$S 3,119.71 Name 1: WORLD AUTO PTE LTD

Payee 2: (Strike if N.A.) \$S \_\_\_\_\_ Name 2: X

Payee 3: (Strike if N.A.) \$S \_\_\_\_\_ Name 3: X

**COMPLET**  
17/1/19

PR. 1. 1. 1.

REF:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	XX

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLQ 5394Z Yr Regn: 14 Jul 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: TOYOTA PRINJ HYBRID c.c. 1798

Colour: WHITE A/C: Insur.d / Std / NI / NA

Sp. Reading: 70,580 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDK83Fu203561958

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or PIRELLI P205/60 R15

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 16/10/18 D.O.I. 18/10/18

Survey held at WORLD AUTO

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>IBI \$ 2,689.45</u>
	<u>R (\$ 4,289.27 / 61%)</u>

Date/Time, File Pass to?  : Preli. Report

: Final Report

1) Date/Time, File Return to?

2) \_\_\_\_\_

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_ Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_ S + RS. \$ \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_) Photos

: Interview (\$ \_\_\_\_\_) Others

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

TOTAL



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 18/18/18/VP05/021033  
Our ref: CC4/LPC18018963/Nja3

Date: 22/10/2018

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SLQ 5394Z**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18.10.2018 at the premises of M/s World Auto Pte Ltd have the following to report:-

Workshop Estimate Amount	: S\$	6,978.72
Revised Estimate Amount	: S\$	2,641.53
"Check" Items Amount	: S\$	1,010.65
Total (Including Check Items)	: S\$	3,652.18
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

**Description of Damage:**

The vehicle sustained damages at the  
Rear Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

**MUHAMMAD NAZRIL**  
**Licensed Appraiser**

**WORLD AUTO PTE LTD**

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

**LONPAC INSURANCE BHD**100 BEACH RD #19-00 SHAW TOWER  
S'PORE 189702

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62963767

Estimate : ES180004

Date : 17/10/2018

Vehicle Num. : SLQ 5394Z

Make/Model : TOYOTA PRIUS HYBRID 1.8S

Chassis/Eng# :

Accident Date : 16/10/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
<b>LIST ITEMS :</b>				
1.	1	REAR TAILGATE		922.50 <sup>XR</sup>
2.	1	REAR TAILGATE LOCK		447.40 <sup>XR</sup>
3.	1	REAR TAILGATE OUTER GARNISH		420.00 <sup>XR</sup>
4.	1	REAR TAILGATE PRIUS EMBLEM		68.50 <sup>NBC</sup>
5.	1	REAR TAILGATE HYBRID EMBLEM		52.30 <sup>NBC</sup>
6.	1	REAR BUMPER		423.90 <sup>?</sup>
7.	1	REAR LOWER BUMPER		552.30 <sup>DRG</sup>
8.	1	REAR BUMPER SIDE RETAINER		111.50 <sup>?</sup>
9.	1	REAR BUMPER REINFORCEMENT		318.80 <sup>?</sup>
10.	1	REAR BUMPER LOWER SIDE SPOILER LH		148.40 <sup>XR</sup>
11.	1	REAR BUMPER TAIL LAMP LH		481.90 <sup>SR</sup>
12.	1	REAR TAIL LAMP - LH		433.70 <sup>CRK</sup>
13.	1	REAR WINDSCREEN GLASS MOULDING		29.50 <sup>XNW</sup>
14.	1	REAR TAILGATE LOWER GLASS MOULDING		27.60 <sup>XNW</sup>
List TotalS\$ :				4,438.30
25.00% Discount S\$ :				1,109.58
				3,328.72
<b>SPECIAL NETT ITEMS :</b>				
1.	1SET	REAR TAILGATE INNER TRIM BOARD CLIPS		30.00 <sup>?</sup>
2.	1SET	REAR TAILGATE OUTER GARNISH CLIPS		30.00 <sup>?</sup>
3.	1SET	REAR BUMPER CLIP		30.00 <sup>?</sup>
4.	2	WINDSCREEN SEALANT	80.00	160.00 <sup>XNW</sup>
5.	1SET	REVERSE SENSOR		280.00 <sup>?</sup>
Special Nett Total S\$ :				530.00
<b>LABOUR :</b>				
REMOVE & REFIT REAR WINDSCREEN GLASS (X2 GLASS)				360.00 <sup>XNW</sup>

CONTINUE / ...



# WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03  
 Halcyon 2, S'pore 577200  
 Tel No. : 6451 3933 Fax No. : 6455 7576  
 E-Mail : worldaut@singnet.com.sg  
 Website : www.worldauto.com.sg  
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

Joy

JTDK83FU203561958

LONPAC INSURANCE BHD  
 100 BEACH RD #19-00 SHAW TOWER  
 S'PORE 189702

Estimate : ES180004

Attention : Motor Claim Department  
 Contact : 62507388 Fax No. : 62963767

Date : 17/10/2018  
 Vehicle Num. : SLQ 5394Z  
 Make/Model : TOYOTA PRIUS HYBRID 1.8S  
 Chassis/Eng# :  
 Accident Date : 16/10/2018  
 Claim No. :  
 Reference :  
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

1.	1	REAR TAILGATE		922.50 XR
2.	1	REAR TAILGATE LOCK		447.40 X SVC
3.	1	REAR TAILGATE OUTER GARNISH		420.00 X SVC
4.	1	REAR TAILGATE PRIUS EMBLEM		68.50 X SVC
5.	1	REAR TAILGATE HYBRID EMBLEM		52.30 X SVC
6.	1	REAR BUMPER		423.90 X SVC
7.	1	REAR LOWER BUMPER		552.30 DEF
8.	1	REAR BUMPER SIDE RETAINER		111.50 X HY
9.	1	REAR BUMPER REINFORCEMENT		318.80 X HY
10.	1	REAR BUMPER LOWER SIDE SPOILER LH		148.40 XR
11.	1	REAR BUMPER TAIL LAMP LH		481.90 X CRK
12.	1	REAR TAIL LAMP - LH		433.70 X CRK
13.	1	REAR WINDSCREEN GLASS MOULDING		29.50 X NV
14.	1	REAR TAILGATE LOWER GLASS MOULDING		27.60 X NV

List Total S\$ :  
 25.00% Discount S\$ :

2,012.60 4,438.30  
 503.15 1,109.58  
 1,509.45 3,328.72

SPECIAL NETT ITEMS :

1.	1SET	REAR TAILGATE INNER TRIM BOARD CLIPS		30.00 X HY
2.	1SET	REAR TAILGATE OUTER GARNISH CLIPS		30.00 X HY
3.	1SET	REAR BUMPER CLIP		30.00 X
4.	2	WINDSCREEN SEALANT	80.00	160.00 X NV
5.	1SET	REVERSE SENSOR		280.00 X NV

Special Nett Total S\$ :

30 530.00

LABOUR :  
 REMOVE & REFIT REAR WINDSCREEN GLASS (X2 GLASS)

360.00 X NV

CONTINUE / ...

Finalized  
 - Naz.

# WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03  
 Halcyon 2, S'pore 577200  
 Tel No. : 6451 3933 Fax No. : 6455 7576  
 E-Mail : worldaut@singnet.com.sg  
 Website : www.worldauto.com.sg  
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

LONPAC INSURANCE BHD  
 100 BEACH RD #19-00 SHAW TOWER  
 S'PORE 189702

Attention : Motor Claim Department  
 Contact : 62507388 Fax No. : 62963767

Estimate : ES180004

Date : 17/10/2018  
 Vehicle Num. : SLQ 5394Z  
 Make/Model : TOYOTA PRIUS HYBRID 1.8S  
 Chassis/Eng# :  
 Accident Date : 16/10/2018  
 Claim No. :  
 Reference :  
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

.		TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	180.00	180.00 <i>XUN</i>
.		WIRINGS CHECK AND RECTIFY WHERE NECESSARY	180.00	180.00 <i>50</i>
.		REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN REAR CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	500	1,200.00 <i>700</i>
.		PUTTY AND SPRAY PAINT ALL AFFECTED AREAS	600	1,200.00 <i>700</i>
.		Labour Total S\$ :	1,150	3,120.00

NAZ LKX  
 18/10/18 1130  
 PIP  
 4 DAYS

*Repair before paint*  
*by [Signature]* 19/10/18

- CHECK ITEMS PHOTOS
- BEFORE PAINT PHOTOS

E. & O.E.

Total S\$ : 6,978.72

for WORLD AUTO PTE LTD

CONFIRMED PART BY PART  
 REPAIR \$ 2,689.45 / 4 DAYS.

NAZ LKX  
 Nil

PARTS \$ 2,012.60  
 LESS 25% \$ 1,509.45  
 NETT \$ 30  
 LABOUR \$ 1,150  
 TOTAL \$ 2,689.45 / 4 DAYS

**Nivitha (LKK Auto)**

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Wednesday, 17 October 2018 5:17 PM  
**To:** ainee31@worldauto.com.sg  
**Cc:** MT\_Claim\_SG; Admin-D (LKKAuto)  
**Subject:** RE: Request for Third Party Motor Claim Survey (SLQ5394Z) DOA: 16-10-2018

WITHOUT PREJUDICE

Our Ref : 18/18/18/VP05/021033

Dear Ainee,

We shall appoint LKK Auto Consultants Pte Ltd for the survey.

Our insured has yet to lodge a report and we are making enquiries.

In the meantime, please furnish us a copy of your client's report.

Aside to LKK-Attn :Catherine  
Kindly proceed accordingly.

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** ainee31@worldauto.com.sg [mailto:aine31@worldauto.com.sg]  
**Sent:** Wednesday, 17 October, 2018 4:19 PM  
**To:** MT\_Claim\_SG  
**Cc:** worldautopl@yahoo.com.sg  
**Subject:** Request for Third Party Motor Claim Survey (SLQ5394Z) DOA: 16-10-2018

Good morning/afternoon,

We would like to request for a third party motor claim survey, details as follow;  
Our Vehicle: SLQ5394Z  
Your Insured: SKB5229J  
DOA: 16-10-2018

Our vehicle is currently in the workshop, address as follow;  
World Auto Pte Ltd  
No.1, Kranji Loop  
Singapore 739535

**Ainee**

**Thanks and Rgds,  
World Auto Pte Ltd  
Kranji: 63621776  
Fax: 63631250**

## Mei Kwan (LKKAuto)

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Wednesday, 31 October, 2018 11:15 AM  
**To:** Mei Kwan (LKKAuto)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Request for Third Party Motor Claim Survey (SLQ5394Z) DOA: 16-10-2018  
**Attachments:** 311020181111150.pdf  
  
**Categories:** HMK

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

Please establish liability before proceeding with direct settlement.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]  
**Sent:** Wednesday, 31 October, 2018 10:54 AM  
**To:** GERALD POH WEE BIN  
**Cc:** MT\_Claim\_SG; Admin A; Joy Irene (LKKAuto); CS A Team  
**Subject:** RE: Request for Third Party Motor Claim Survey (SLQ5394Z) DOA: 16-10-2018

### WITHOUT PREJUDICE

**LPC ref: 18/18/18/VP05/021033**  
**LKK REF: CC4/LPC18018963/Nja3**

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SLQ 5394Z

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice
- TP GIA report

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Please take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

*To check availability of the case handler, you may contact the undersigned.*

---

**From:** [aine31@worldauto.com.sg](mailto:aine31@worldauto.com.sg) [mailto:[aine31@worldauto.com.sg](mailto:aine31@worldauto.com.sg)]  
**Sent:** Wednesday, 17 October, 2018 4:19 PM  
**To:** MT\_Claim\_SG  
**Cc:** [worldautopl@yahoo.com.sg](mailto:worldautopl@yahoo.com.sg)  
**Subject:** Request for Third Party Motor Claim Survey (SLQ5394Z) DOA: 16-10-2018

Good morning/afternoon,

We would like to request for a third party motor claim survey, details as follow;  
Our Vehicle: SLQ5394Z  
Your Insured: SKB5229J  
DOA: 16-10-2018

Our vehicle is currently in the workshop, address as follow;  
World Auto Pte Ltd  
No.1, Kranji Loop  
Singapore 739535

**Ainee**  
**Thanks and Rgds,**  
**World Auto Pte Ltd**  
**Kranji: 63621776**  
**Fax: 63631250**



WORLD AUTO PTE LTD

47 JALAN PEMIMPIN #01-02/03

HALCYON 2

SINGAPORE 577200

28/12/2018

Your Ref: *Soy Irene.*  
Our Ref: TP/2295/2018

LONPAC INSURANCE BHD  
300 BEACH RD #17-04/07  
THE CONCOURSE  
SINGAPORE 199555

Attn : Motor Claim Dept - Third Party

Dear Sirs,

**ACCIDENT INVOLVING VEH.NO. SLO5394Z / SKB5229J ON 16/10/2018**

Reference is made to the aforesaid matter (on behalf of our client M/S LCRF PL)

Enclosed herewith are the following documents for your information and necessary actions only :-

- a) Motor Accident Report
- b) Our Final Repair Bill

Please assist in our claims of :

Final Bill	\$ 2689.45 (already surveyed & finalised with your surveyor)
GST 7%	\$ 188.26
Search Fee	\$ 2.00
Loss of Use (\$60 x 4days)	\$ 240.00
	-----
Amount	<u>\$ 3119.71</u>

Kindly let us have your reply and payment as soon as possible.

Thank you for your kind attention and much appreciated assistance.

Yours faithfully,

**WORLD AUTO PTE LTD**

47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG  
 S'PORE 577200  
 Tel No. : 64513933 Fax No. : 64557576  
 E-Mail : worldaut@singnet.com.sg  
 Website : www.worldauto.com.sg  
 Tax Reg. No. : 200006765H Buss. Reg. No. : 200006765H

LONPAC INSURANCE BHD  
 300 BEACH ROAD #17-04/07 THE CONCOURSE  
 S'PORE 199555

Attention : Motor Claim Department  
 Contact : 62507388 Fax No. : 62963767

**Tax Invoice : F189034**

Date : 28/12/2018  
 Vehicle Num. : SLQ 5394Z  
 Make/Model : TOYOTA PRIUS, 1.8 HYBRID  
 Chassis/Eng# :  
 Accident Date : 16/10/2018  
 Claim No. : TP/2295/2018  
 Reference :  
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$	
		LIST ITEMS :			
	1	TAILGATE PRIUS EMBLEM		68.50	
	1	TAILGATE HYBRID EMBLEM		52.30	
2.	1	REAR BUMPER		423.90	
4.	1	REAR LOWER BUMPER		552.30	
5.	1	REAR BUMPER TAILLAMP LH		481.90	
6.	1	TAILLAMP LH		433.70	
		List Total S\$ :		2,012.60	
		25.00% Discount S\$ :		503.15	
				1,509.45	
1.	1SET	SPECIAL NETT ITEMS :			
		REAR BUMPER CLIPS		30.00	
		Special Nett Total S\$ :		30.00	
		LABOUR :			
		REMOVE & INSTALL REAR WINDSCREEN		50.00	
		REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN REAR CHASSIS & REPLACE PARTS		500.00	
		PUTTY & SPRAY PAINT ON ALL AFFECTED AREAS		600.00	
		Labour Total S\$ :		1,150.00	
				<b>Total S\$ :</b>	<b>2,689.45</b>
				<b>GST 7% S\$ :</b>	<b>188.26</b>
				<b>Amount Due S\$ :</b>	<b>2,877.71</b>
				=====	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18018963/Nja3n2

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 15-07-2019



Code : LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SKB 5229J	<b>Veh. Inspected</b>	SLQ 5394Z
<b>Policy No.</b>	Z18VP05018903	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	18/18/18/VP05/021033	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GERALD	<b>Assign Date</b>	17/10/2018

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA PRIUS HYBRID	<b>c.c</b>	1798
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	JTDKB3FU203561958	<b>Colour</b>	WHITE
<b>Odometer</b>	70580	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/65 R15	PIRELLI	5 mm
<b>L/H Front Tyre</b>	195/65 R15	PIRELLI	5 mm
<b>R/H Rear Tyre</b>	195/65 R15	ROVELO	5 mm
<b>L/H Rear Tyre</b>	195/65 R15	ROVELO	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	16/10/2018	<b>Inspection Date</b>	18/10/2018
<b>Survey held at</b>	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 5394Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR TAILGATE	TO REPAIR SEE LABOUR	922.50	-
1	REAR TAILGATE LOCK	SERVICEABLE	447.40	-
1	REAR TAILGATE OUTER GARNISH	SERVICEABLE	420.00	-
1	REAR TAILGATE PRIUS EMBLEM	NECESSARY	68.50	68.50
1	REAR TAILGATE HYBRID EMBLEM	NECESSARY	52.30	52.30
1	REAR BUMPER	CRACKED	423.90	423.90
1	REAR LOWER BUMPER	DEFORMED	552.30	552.30
1	REAR BUMPER SIDE RETAINER	NOT NECESSARY	111.50	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	-
1	REAR BUMPER LOWER SIDE SPOILER LH	TO REPAIR SEE LABOUR	148.40	-
1	REAR BUMPER TAIL LAMP LH	CRACKED	481.90	481.90
1	REAR TAIL LAMP -LH	CRACKED	433.70	433.70
1	REAR WINDSCREEN GLASS MOULDING	NOT NECESSARY	29.50	-
1	REAR TAILGATE LOWER GLASS MOULDING	NOT NECESSARY	27.60	-
	LESS 25% DISCOUNT		-1,109.58	-503.15
			3,328.72	1,509.45
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REAR TAILGATE OUTER GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	30.00	30.00
2	WINDSCREEN SEALANT @\$80.00 (SN)	NOT NECESSARY	160.00	-
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
			530.00	30.00
<b>LABOUR</b>				
	REMOVE & REFIT REAR WINDSCREEN GLASS (X2 GLASS).	NOT NECESSARY	360.00	-
	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES.	NOT NECESSARY	180.00	-
	WIRINGS CHECK AND RECTIFY WHERE NECESSARY.		180.00	50.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT ,STRAIGHTEN REAR CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR TAILGATE AND REAR BUMPER LOWER SIDE SPOILER LH . PUTTY AND SPRAY PAINT ALL AFFECTED AREAS.		1,200.00	500.00
			1,200.00	600.00
			3,120.00	1,150.00
<b>GRAND TOTAL</b>			<b>6,978.72</b>	<b>2,689.45</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,689.45</b>

Report Ref No. CC4/LPC18018963/Nja3n2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.