

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

11/10/18 CLK
11-30

Not Authorized
U/Sump @ ?
Resurvey After Paint
6 days

17, October 2018

China Taiping Insurance (S) PL
105 Cecil Street #18-00
The Octagon
S 069534

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SGD3233X
Accident involving vehicle no: SJN7645B/SGD3233X
DOA: 11/10/2018 AT Bukit Purmei Ave

Dear officer incharge

Re: estimate cost of repair for vehicle no: SJN7645B

To supply--

Photos

Description	Qty	Amount	
Lid	1	1,210.40	✓
Lid-doorboard	1	328.20	X
Hid-handle	1	239.00	X
Lid lock	1	443.50	✓
Lid hinge @55.30	2	110.60	X
End panel	1	441.20	?
End panel top garnish	1	232.90	✓
Spare tyre boot garnish	1	562.90	X
Exhaust tailpipe	1	798.80	X
Taillamp @472	2	944.00	✓
Rear bumper	1	470.70	✓
Rear bumper retainer @56.05	2	112.10	✓
Rear bumper lower skirt	1	423.00	✓
Rear windscreen sealant	1	76.00	✓
Boot weatherstrip @48.50	1	97.60	✓
	Parts	6,490.90	
	Parts less 25%	1,622.72	
		4,868.17	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices to be subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplier/Repairer must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer
Signature
Date

Vehicle no: SJN7645B

To remove/transfer rear windscreen glass

Reverse sensor

To remove damaged parts and attachments.

Cut n weld damaged panel.

Straighten rear chassis where necessary.

Replace/align all parts

To spray paint

180.00 *12cl*
Shot 220.00 *200w*

950.00 *?*
750.00 *70cl*

6,968.17