

*1/ Kasul  
 Hg 900 10068  
 3 days  
 19/10/18 @ 1155*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_

**SERVICE ESTIMATE**

Date: - C00001 SL - SERVICE SALES - PC

Wearnes Automotive Pte Ltd (159-f&L)  
 28 Leng Kee Road

Singapore 159105

Closed by .... : Derek Oh Siong Wee  
 Svc Consultant :  
 Remarks ..... : Wearnes Automotive P

GST Reg.No:M28920628X  
 Inv.No. . : B&P 0 Page 1  
 Inv.date. : 17/10/2018  
 WIP No. . : 33336  
 Veh.In/Out: 17/10/2018  
 \*Tel.No. . : Work: 68765063  
 Reg.No. . : SDJ311C  
 Reg.date .. : 18/01/2017  
 Mileage .. : 0  
 Chassis No: SJKDAAH15U1019577

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR BRACKET, REAR SENSOR, ETC	0	1800.00	0	1,800.00	S	900
800	TO PUTTY SPRAY PAINT ON REAR BUMPER, ETC	0	1000.00	0	1,000.00	S	500
280	TO CHECK WIRING INLCUDE RESETTING OF ALL ELECTRICAL MODULES	0	390.00	0	390.00	S	/
	BUMPER SET-RR Q30	1.0 EA	1440.20		1,440.20	S	DE
	S MLDG RR BMPR	1.0 EA	604.80		604.80	S	scut
	RETAINER LH-RR BUMPE	1.0 EA	50.40		50.40	S	?
	RETAINER-BUMPER Q30	1.0 EA	231.90		231.90	S	?
	REINFORCEMENT-BUMPER	1.0 EA	1021.30		1,021.30	S	?
	BUMPER BRACKET RR LH	1.0 EA	121.00		121.00	S	?
	ADHESIVE SEALER FL2	1.0 EA	549.10		549.10	S	NE

Gross Total. 7,208.70  
 Net..... 7,208.70  
 GST @ 7.0% 504.61  
 Total..... 7,713.30  
 Paid..... 0.00  
 Please Pay.. 7,713.30

Labour Total 3,190.00  
 Parts Total 4,018.70  
 Package Total 0.00

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated