

ASS. REC. BY:

REF: CS/AIG18018 971 / Acd3n2

Special Instruction:

Surveyor
Maximen

Adrian

ASSIGNMENT (Office)

From (Person): Azlan Syazairidina

of

AIG

Date/Time: 18/10/18 @ 2:09pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SU 6157M

Insured:

SLV 2435H

at Workshop m/s

Hiap Hong Motor

Tel:

6745 9633

of

2 kaki Bkt Ave 2 #02-13

Policy No: 1700089301

Claim No:

7969103820SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/08/2018

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time: 2:48pm @ 18/10/18

Person Contacted:

Ah Keong

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SU 6157M - NA/INC18018139/k4

DOA: 7/10/18

SLV 2435H - NA/INC18014054/24

DOA: 1/8/18

REF: AIG

Surveyor

ASSIGNMENT

From: Date: 18/10/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: SJU6157M
at Workshop m/s Hiep Hong Motor
of 2 kaki Bkt Ave 2 #02-13

Insured:

Policy No:


Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{lup}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJU6157M Yr Regn: 2008, Dec

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Fortuner C.C. 2694

Colour: Bronze A/C: Insured / Std / NI / NA

Sp. Reading: 145414 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR02X696100023083

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 265/65R17.

R: 265/65R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 18/10/18

Survey held at Hiep Hong.

Des. of Damages: Frt / Rear / O/S / ☒ N/S / ☒ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP AIG.
29/12	Adrian confirmed LS \$1750 and 4 days with repainer. (Red. 4102.30, 70%)
	MV: 32k
	PV: 17.4k
	Nett: 14.6k
RECEIVED 26 DEC 2018	

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: TP

Lump Sum / I.B.I: (\$ 1750)

250

50

270

- Pre repair inspection request - SJU6157M VS SLV2435H (OI) DOA 01/08/2018

From: Azlan, Syazairdina
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit
Sent: 18/10/2018 2:09:40 PM
Attachments:  tmpF2B0.tif

Hi,

Please refer to the enclosed request from **Tng Soon Chye & Co.**

Claim no : 7969103820SG003
Case Owner : WEI ZHONG BENNIE TAN

If you have any queries/concerns, please let us know.
Kindly assist to assign Adrian Ling as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: tsclcx@singnet.com.sg [mailto:tsclcx@singnet.com.sg]
Sent: Thursday, October 18, 2018 1:03 PM
To: Azlan, Syazairdina
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLV2435H AND SJU6157M ON 01/08/2018

WITHOUT PREJUDICE

Dear Sirs

We refer to your email dated 18th October 2018.

Our client instructs that he agrees to the appointment of Adrian Ling of LKK Auto Consultants Pte Ltd as the Single Joint Expert for the pre repair inspection of SJU6157M at 2 Kaki Bukit Avenue 2 #02-13 Auto Hub Singapore 417921 (Tel: 67459633).

If we do not receive any reply from you within the stipulated timeline, our client shall proceed with the repair without any further to you. Our client's rights are hereby expressly reserved.

Thank You & Best Regards,

Tng Soon Chye & Co
150 South Bridge Road
#02-19
Singapore 058727

From: Azlan, Syazairdina
Sent: Thu, 18 Oct 2018 02:50:23 +0000
To: tsclcx@singnet.com.sg
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLV2435H AND SJU6157M ON 01/08/2018

Without Prejudice

Your Reference : TSC, SJU6157M, Accid.2018(1H)-ak
Our Reference : 7969103820SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

湯 順 才 律 師 樓
TNG SOON CHYE & CO.

ADVOCATES & SOLICITORS
NOTARY PUBLIC
COMMISSIONER FOR OATHS

UEN NO: 53131141D

150 South Bridge Road #02-19 Fook Hai Building Singapore 058727

Tel: 6438 3133 - Fax: 6438 6066
(Service of Court documents via fax is not acceptable)

Our Ref: TSC.SJU6157M.Accid.2018(HH)-ak
Your Ref: SLV2435H

17th Oct 2018

M/s AIG ASIA PACIFIC INSURANCE PTE LTD
Motor Claims Department
78 Shenton Way
#08-16
Singapore 079120
(Insurer of Vehicle No. SLV2435H)

cc. to:

CHEW KENG LEE
208A Compassvale Lane
#10-70
Singapore 541208
(Owner and Driver of vehicle no. SLV2435H)

Dear Sirs,


ACCIDENT ON 1ST AUGUST 2018 @ 14:55 HRS INVOLVING MOTOR-VEHICLES NOS. SJU6157M & SLV2435H ALONG CLEMENCEAU AVE N BEFORE JUNG CAIRNHILL CIRCLE

We are instructed by Mr Ling Wen Hun to notify you of a road traffic accident on 1st August 2018 at about 14:55 hrs along Clemenceau Ave N before Jung Cairnhill Circle involving our client's vehicle registration number SJU6157M and vehicle registration number SLV2435H driven by your insured at the material time. A copy of the Singapore accident statement is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle at 2 Kaki Bukit Avenue 2 #02-13 Auto Hub Singapore 417921.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you. Our client's rights are hereby expressly reserved.

Yours faithfully,


Tng Soon Chye
enc
cc.

client - via fax: 6747 8602 only
(ref: SJU6157M)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3834J
Vehicle Details	
Vehicle No.:	SJU6157M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	19 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	FORTUNER 2.7 2WD AUTO FL
Primary Colour:	Brown
Manufacturing Year:	2009
Engine No.:	2TR6829207
Chassis No.:	MR0ZX69G100023083
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$27,883.00
Original Registration Date:	17 Dec 2009
First Registration Date:	17 Dec 2009
Transfer Count:	2
Actual ARF Paid:	\$27,883.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Dec 2019
PARF Rebate Amount:	\$15,335.00
Intended COE Rebate Details	
COE Expiry Date:	16 Dec 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$18,389.00
COE Rebate Amount:	\$2,127.00
Total Rebate Amount:	\$17,462.00

The information contained herein is correct as at 19 Oct 2018

OK

TF Alb.

STU6157M.

Janice.

Toyota Fortuner 2694CL.

MR02X696100023083.

Front Bumper	torn	591.60	✓
Front Bumper Clips.	new	30.	✓
Front Bumper Side Holder LH.	new	49.70	✓
Front LH Wheel Rim.	new	1913 980(SN)	
Front LH Tyre.	new	550(SN)	X.
Headlamp LH.	new	815.80	X.
Front LH Fender Protector	Repl	330-60	+
Front LH Fender Emblem.	new	75	✓
Front LH Fender Mudflap.	new	96.60	X
List: 746.30		S.N: 980	
Car 25%: 555.72.			

Panel Beating	600	200
Spray Painting.	660	600 350
Wiring.		50 30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

To perform wheel alignment.

total: 2199.72

L/S: 1750. 04 Days

~~180.80~~
\$5852.30

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18018971/ACD3N2

Date: 28/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700089301
 Claimant Vehicle No: SJU6157M Insured Vehicle No: SLV2435H
 Date of Loss: 01/08/2018 Nature of Claim: TP Claim No: 7969103820SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJU6157M
 Make & Model: TOYOTA FORTUNER, 2.7 (A) Engine No: 2TR6829207
 Reg. Date: 17/12/2009 (Man. Year: 2009) Chassis No: MR0ZX69G100023083
 Colour: Bronze Odometer: 145414 km
 Engine Capacity: 2694 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/65R17 Rear Tyre Size: 265/65R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,452.30	1,539.72	2,912.58	65.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	660.00	740.00	52.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,852.30	2,199.72	3,652.58	62.41
Approved Total (Overridden) (S\$)		1,750.00		
Nett Amount (S\$)	5,852.30	1,750.00	4,102.30	70.10

INSPECTION

Date of Assignment: 18/10/2018
 Date Inspected: 18/10/2018 Inspected At: Hiap Hong Motor Repair
 2 Kaki Bykit Avenue 2, #02-13
 Singapore 417921
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	591.60 F	*591.60 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	1		*FRONT BUMPER SIDE HOLDER LH	Necessary	49.70 F	*49.70 FL
4	1		*HEADLAMP LH	Not Necessary	815.80 F	*- FL
5	1		*FRONT LH FENDER PROTECTOR	Repair	330.60 F	*- FL
6	1		*FRONT LH FENDER EMBLEM	Necessary	75.00 F	*75.00 FL
7	1		*FRONT LH FENDER MUDFLAP	Not Necessary	96.60 F	*- FL
8	1		*FRONT LH WHEEL RIM	Cut	1,913.00 FS	*980.00 FS
9	1		*FRONT LH TYRE	Not Necessary	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,452.30	1,726.30
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	186.58
Total Parts (\$\$)	4,452.30	1,539.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	200.00
2	SPRAY PAINTING	New	600.00	350.00
3	WIRING	New	50.00	30.00
4	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (\$\$)			1,400.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >