

**Trans-cab Auto Services Pte Ltd**

AA1810-159

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5904Z**

*Not Authorized*  
*U/Bmp &*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :

**SHC 5904Z**  
VF1ABL15AUC280978  
RENAULT  
LATITUDE  
13.10.2018  
**III**

	<b>PART</b>		<b>LIST</b>	
1	BUMPER COVER FRT	\$	R 1,259.42	} X
1	BUMPER SPOILER FRT	\$	SL 181.75	
1	BUMPER ABSORBER FRT	\$	SL 394.68	
1	BUMPER RETAINER FRT RH	\$	SL 150.77	
1	BUMPER SUPPORT FRT	\$	SL 123.88	
1	BUMPER UNDERTRAY FRT	\$	SL 472.83	
1	BUMPER GRILLE LOWER FRT	\$	SL 266.80	
1	BUMPER FOG LAMP GRILLE RH	\$	SL 207.21	
1	BUMPER BEAM FRT	\$	R 914.08	
1	HEADLAMP RH	\$	SL 1,184.43	
1	HEADLAMP PANEL FRT RH	\$	R 152.15	} ✓
1	HEADLAMP LH	\$	SL 1,184.43	
1	HEADLAMP PANEL FRT LH	\$	R 152.15	} ✓
1	FENDER PANEL FRT RH	\$	R 783.83	
1	WHEELARCH FRT RH	\$	CM 278.84	} X
1	FENDER BRACKET LOWER RH	\$	SL 15.79	
1	FENDER INSULATOR RH	\$	SL 130.84	
1	DOOR PANEL FRT RH	\$	R 2,844.66	
1	RADIATOR GRILLE	\$	SL 1,707.78	
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	SL 225.36	
1	RADIATOR GRILLE FRAME	\$	SL 1,353.75	
1	RADIATOR FAN COWLING	\$	SL 820.54	
1	RADIATOR FAN MOTOR LH	\$	SL 967.36	
1	RADIATOR FAN MOTOR RH	\$	SL 1,479.46	
1	FRAME FULL SUPPORT PANEL	\$	SL 615.90	} X
1	FRAME FULL SUPPORT BRACKET	\$	R 89.79	
1	DOOR MIRROR ASSY RH	\$	SL 1,483.40	
1	DOOR PANEL FRT RH	\$	R 2,844.66	
1	SUBFRAME OUTER FRT	\$	SL 2,652.45	
1	SUBFRAME BRACKET OUTER LH	\$	SL 92.36	

**Trans-cab Auto Services Pte Ltd**

AA1810-159

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5904Z**

1	SUBFRAME BRACKET OUTER RH	\$	92.36	} X
1	ENGINE UNDERTRAY	\$	564.98	
1	A/C CONDENSER	\$	2,020.37	
1	A/C CONDENSER GARNISH LH UPPER	\$	39.67	
1	A/C CONDENSER GARNISH RH UPPER	\$	39.67	
1	A/C CONDENSER GARNISH LH	\$	58.81	
1	A/C CONDENSER GARNISH RH	\$	59.60	
1	LOWER ARM RH	\$	685.76	
1	KUNCKLE ARM RH	\$	846.98	
1	ABSORBER FRT RH	\$	360.54	
1	STABILIZER BAR FRT	\$	604.65	
1	DRIVESHAFT RH	\$	1,747.45	
1	WIPER RESERVOIR	\$	348.25	
1	WIPER RESERVOIR NECK	\$	136.11	
1	WIPER RESERVOIR MOTOR	\$	270.06	

<b>TOTAL</b>	<b>\$</b>	<b>32,906.59</b>
<b>10%</b>	<b>\$</b>	<b>3,290.66</b>
	<b>\$</b>	<b>29,615.93</b>

**Special Nett**

1SET	BUMPER CLIP FRT	\$	66.00	X
1	BUMPER BRACKET CLIP FRT RH	\$	12.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	X
1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	X
1SET	WHEELARCH CLIP FRT RH	\$	30.50	✓
1	WINDSCREEN SEALANT	\$	253.80	} X
1	FRONT WINDSCREEN MOULDING	\$	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	100.00	
1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	\$	80.00	
1	FRONT RIGHT DOOR STICKER '6555-3333'	\$	50.00	
1	FRONT RIGHT TYRE	\$	330.00	
1	FRONT RIGHT TYRE RIM	\$	380.00	

<b>TOTAL</b>	<b>\$</b>	<b>1,621.80</b>
--------------	-----------	-----------------

**Trans-cab Auto Services Pte Ltd**

AA1810-159

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5904Z

**TOTAL PARTS** \$ 31,237.73

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	300
Putty and spray painting of the affected portion.	\$	4,000.00	440
To rust-proofing of the affected areas.	\$	170.00	30
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	nn X
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To Check Electrical Lighting Concerned.	\$	170.00	20
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	nn X
To vacuum, replace, refix and recharge air condenser	\$	380.00	nn X
To replace, refix and top up coolant for radiator	\$	170.00	nn X
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	nn X
To transfer of front windshield fittings and conduct water seepage test	\$	170.00	nn X

**TOTAL** \$ 10,710.00

**Over All Total** \$ 41,947.73

**LUMP SUM (REPAIR DAY)**

**15-DAYS**

*2 days*

To transfer of front windshield fittings and conduct water seepage test

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: