

U2 SPRAY PAINTING PTE LTD

Block 25 Kaki Bukit Road 4, #06-43 Synergy @ KB Singapore 417800
HP: 96583371

WBAVA 76050N/K 66312

TPAXA.

Xiao Tony.

18th OCT 2018

TJAO HUI HAO KARNO WIDJAJA
Bk 25 Kaki Bukit Rd 4
06-43 SYNERGY @KB
Singapore 417800

Accident date: 03rd OCT 2018

Estimated repair cost for vehicle no: SGN7777P BMW 320i '06

S/n	Qty	Items/Nett	U/price	Amount
1	1	Front RH door <i>Repair</i>		\$2,200.00 x
2	1	rear RH door <i>Dented</i>		\$2,200.00 1427
3	1	rear RH rocker panel <i>Repair</i>		\$650.00 x
4	1	Rear R/H fender <i>Repair</i>		\$1,480.00 x
		Front RH Door Weatherstripe. New	187 ✓	
		Rear RH Door Weatherstripe. New	135 x	
			Subtotal :-	\$6,530.00
			1624	
			1542.80	

Labour charges

To Check Wiring System

Tuff kote

Panel beating

Spray painting

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allow.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	\$60.00 30
	\$120.00 x
	\$1,000.00 400
	\$1,000.00 700.
Subtotal :-	\$2,180.00
Total:-	\$8,710.00

total 26728

4/5: 2.11C

04 days