

REF:

CC3 / ALH18018976 / Agbn2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

1700070089

Claims No.

488013661356

Sum Insured:

Excess:

800 20/10/18

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

152K.

IDAC Accident Rpt:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

05 889

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLT16H-

Yr Regn:

2017 Sept.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A5 SB.

C.C. 1984

Colour:

Red.

A/C: Insured / Std / NI / NA

Sp. Reading

21049.

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAU22FS4JA021835

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 245/40R18

R: 245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

18/10/18

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

OD A16.

SLT 16H - X

14/10/18 @ 9.47am revert to Victor via message.

22/10/18 @ 3.10pm Victor informed C/A via message.

22/10/18 @ 3.58pm Informed Premium C/A & ex: \$800 by email.

24/12/18 @ 12.31pm confirmed with Mr BOO final fig \$9205.88, 5 days.
(Red \$14675.77, 61%.)

RECEIVED 23 JAN 2019

Date/Time: File Pass to?

☐

Preli. Report

11/12/18 TURNER

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

) TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

WEEK-07

Lump Sum / I.B.I. (\$

9205.88

300
10

210

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Wui, Shawn-KJ

Date: 19 Oct 2018

Preliminary Advice

Vehicle No	: SLT16H	Accident Date	: 15/10/2018
Make	: AUDI A5	Policy No.	: 1700070089
Assignment Date	: 18/10/2018	Excess	: S\$0.00
Date of Inspection	: 18/10/2018	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,550.00
Revised Amount	:S\$	9,664.00
Check Items (Estimated)	:S\$	1,497.00
Total	:S\$	11,161.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	152,000.00
COE / PARF Rebate	:S\$	77,172.00
Salvage Value	:S\$	
Margin for Repair	:S\$	74,828.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 24 December 2018 12:31 PM
To: Boo seng yak; SUR; Carrine Leong; jiyee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: RE: FINAL REVISION - SLT 16 H - OD AIG - SURVEYED 18 OCT 18

Dear Mr Boo,

WITHOUT PREJUDICE

Confirm final fig \$9,205.88 before excess \$800.00 & GST and 5 repair days.

Kindly expedite discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Saturday, 8 December 2018 4:37 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiyee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SLT 16 H - OD AIG - SURVEYED 18 OCT 18

Hi Adrian and all,

Revised estimate and photographs attached.

Please confirm repair cost of \$9205.88 @ 5 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 22 October 2018 3:58 PM
To: Claims
Cc: SUR
Subject: VEHICLE SLT 16H (DOA: 15/10/2018)

Dear Sir/Madam,

As instructed by our client, please proceed to repair the insured vehicle **SLT 16H. (excess \$800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	15 Oct 2018 18:58	Clim Veh Model Changed			[] Merimen Administrator
2	15 Oct 2018 18:58	Clim Created	Reg No: SLT16H, Policy No: 1700070089-01, Acct Date: 2018/10/15, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification, Created from SAS:MPA118134039		[I] Merimen Administrator
3	17 Oct 2018 08:38	Clim Registration Modified	Pol No:1700070089-01->1700070089, Init.Est.:>5,000 - 6,000.		[I] Mithoo Singh, Aashweenjeet Kaur
4	17 Oct 2018 08:38	Clim Veh Model Changed	(201408) AUDI A5 2.0 TFSI MU (A).		[I] Mithoo Singh, Aashweenjeet Kaur
5	18 Oct 2018 16:07	Clim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.		[] CATHERINE CHONG KAI LING
6	18 Oct 2018 16:07	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)		[] CATHERINE CHONG KAI LING
7	18 Oct 2018 16:07	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] CATHERINE CHONG KAI LING
8	18 Oct 2018 16:07	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/10/29		[A] CATHERINE CHONG KAI LING
9	18 Oct 2018 16:07	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.		[A] CATHERINE CHONG KAI LING
10	18 Oct 2018 16:07	Clim Registration Modified	Rep:1137->200611.		[A] CATHERINE CHONG KAI LING
11	18 Oct 2018 16:07	Clim Veh Model Changed	(201408) -> (205279) AUDI A5 2.0 SPORTBACK (A).		[A] CATHERINE CHONG KAI LING
12	18 Oct 2018 16:07	Adj Adjuster Assigned	[None] -> ADRIAN LING		[A] CATHERINE CHONG KAI LING
13	19 Oct 2018 09:36	Adj Rpt Initiated			[A] SHIAU CHAN
14	19 Oct 2018 09:36	Clim Dtl Modified	JPJ Reg. Date: -> 2017/09/13.		[A] SHIAU CHAN
15	19 Oct 2018 09:36	Clim Details Notified			[A] SHIAU CHAN
16	19 Oct 2018 09:42	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/10/29		[A] SHIAU CHAN
17	19 Oct 2018 09:47	Adj Mandate Request	Cur.Reg:11161.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
18	19 Oct 2018 11:35	Clim Registration Modified	Excess: -> 800.00, 2F Remarks: -> Not Applicable, GST: -> 7.00.		[I] Mohd Zawaye, Norsazani
19	19 Oct 2018 11:35	Label Added	(20226):Coverage Confirmed.		[A] Merimen Administrator
20	22 Oct 2018 15:10	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/10/29, Mandate Remarks: Kindly upload damage photos.		[I] Koh, Victor-CK
21	22 Oct 2018 15:10	Adj Mandate Set	Approved:9664.00:Kindly upload damage photos.Reinsp:Yes.		[I] Koh, Victor-CK

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1950314	19/10/2018 09:36	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLT16H		10.70

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9834M
Vehicle Details	
Vehicle No.:	SLT16H
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Oct 2018
Vehicle Make:	AUDI
Vehicle Model:	A5 SB 2.0 TFSI S TRONIC (DESIGN)
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	CVK044153
Chassis No.:	WAUZZZF54JA021835
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$39,560.00
Original Registration Date:	13 Sep 2017
First Registration Date:	13 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$42,384.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Sep 2027
PARF Rebate Amount:	\$31,788.00
Intended COE Rebate Details	
COE Expiry Date:	12 Sep 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,000.00
COE Rebate Amount:	\$45,384.00
Total Rebate Amount:	\$77,172.00

The information contained herein is correct as at 19 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/10/2018 17:45
Date Of Accident	15/10/2018 12:00
Exact Location Of Accident	YIO CHU KANG RD SLIP ROAD TO AMK AVE 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT16H
Insured/Policyholder	
Name Of Registered Owner	WTG CONSULTANTS PTE LTD
Co Reg No	201109834M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66355570

Vehicle Particulars

Manufacturer	AUDI
Model	A5 SB 2.0 TFS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700070089-01
Cover Note Number	

Driver

Name of Driver	ONG LE YI JOANNE
NRIC No	S7913190C
Date Of Birth	16/05/1979
Occupation	INDOOR
Date Of Driving Pass	25/05/1999
Driving Experience	19 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-94508800
Fax Number	
Contact Number	
Email Address	JOANNEONG@WTG.COM.SG

Address	74 BEGONIA DRIVE
Postcode	809932
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance,	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG YIO CHU KANG ROAD TOWARDS ANG MO KIO AVE 6 AND AT THE SLIP ROAD, I ACCIDENTALLY HIT THE VEHICLE IN FRONT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJV3838X
Vehicle Make/Model/Colour	TOYOTA / ESTIMA / BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TEO HAN CHEONG
NRIC/Passport Number	S8102201A
Contact Number	92218622
Address	BLK 441A FERNVALE RD #20-311
Postcode	791441
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 18/10/18



Reporting Centre Personnel's Signature
Name: Amy Fong
NRIC/FIN No.: 6-2040197A

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ALONG YIO CHU KANG ROAD TOWARDS
LIM MO KIO AVE 6 and AT THE SLIP ROAD,
ACCIDENTALLY HIT THE VEHICLE IN FRONT!

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Tony Fory
NRIC/FIN No.: 620401617A

Accident Photo



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S7913190C**

Name: **ONG LE YI JOANNE**

Birth Date: **16 May 1979**

Issue Date: **19 Feb 2013**

002152025J




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S7913190C**

Name: **ONG LE YI JOANNE**

籍貫: **翁 樂 頤**

Race: **CHINESE**

Date of birth: **16-05-1979**

Sex: **F**

Country of birth: **SINGAPORE**

S7913190C





YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars \leq 3000kg with \leq 7 passengers, exclusive of the driver; and other motor vehicles \leq 2500kg **25 May 1999**

NP 428A

Licence No: S7913190C



4642348

NRIC No. **S7913190C**

Date of issue: **25-10-2010**

74 BEGONIA DRIVE
SINGAPORE 809932

NRIC No: **S7913190C** Date: **01/01/2013** No: **7178967**






CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : WTG CONSULTANTS PTE LTD
Period of Insurance : 13 Sep 2018 To 12 Sep 2019
Engine No. : CVK044153
Chassis No. : WAUZZ2F54JA021835

Vehicle No. : SLT16H
Policy No. : 1700070089-01
Endorsement No. :
Issued Date : 30 Aug 2018

ABOUT THE COVER

Make/Model : AUDI A5 Sportback 2.0TFSI S Tronic (Design)
Engine Capacity/Tonnage : 1,984.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PARF : Yes

Any person who is driving on the Policyholder's order or with their permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125260

PREMIUM LEASING -CHB

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manila

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SSPDSO

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1175/2018/GW
Date : 16-Oct-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : WTG Consultatnts PTE LTD
Address : 74 Begonia Drive
Singapore 809932
Telephone : HP +65 66355570
Type of Claim : Own Damage Claims
Policy No. : 1700070089-01
Vehicle No : **SLT 16 H**
Model Code : Audi A5 SB 2.0 TFSI
Model / Year : Sep-17
Engine No : CVK 044153
Chassis No : WAUZZZF54JA021835
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Oct-18
Place of Accident : Yio Chu Kang Rd Slip Road To AMK Ave 6

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 16 H .

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To dismantle and renew front bumper, bonnet and rhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00 1000 ✓
3	To respray front bumper, bonnet and bonnet hinges.	\$ 1,900.00 1100 ✓
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 4,672.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 16 H.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Rehanded</i>	\$ 1,975.00	✓ 1576
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 349.00	+
3	FRONT BUMPER SECURING STRIP <i>new</i>	2 \$ 60.00	+
4	FRONT BUMPER GRILLE-CENTER <i>Rehanded</i>	\$ 171.00	✓ 136.80
5	FROTN BUMPER CLOSING ELEMENT <i>new</i>	\$ 195.00	+
6	FRONT BUMPER SPOILER <i>Repair</i>	\$ 465.00	+
7	FRONT BUMPER AIR GUIDE-LH/RH <i>new</i>	2 \$ 146.00	+
8	RADIATOR GRILLE <i>Rehanded</i>	\$ 2,022.00	✓ 1617.60
9	ULTRA SOUND SENSOR SUPPORT-LH/RH <i>new</i>	2 \$ 100.00	+
10	RADIATOR GRILLE COVER <i>Not New</i>	\$ 165.00	?
11	FRONT BUMPER AIR GUIDE GRILLE-RH <i>new</i>	\$ 414.00	+
12	FOAM FILLER PIECE <i>Rehanded</i>	\$ 107.00	?
13	FRONT BUMPER CARRIER <i>new</i>	\$ 702.00	?
14	FRONT BUMPER COVER <i>Rehanded</i>	\$ 109.00	✓ 87.70
15	SIGN ' CAUTION ' <i>new</i>	\$ 12.00	✓ 9.28
16	AIR CONDITIONER STICKER <i>new</i>	\$ 7.00	✓ 4.88
17	FRONT BUMPER AIR GUIDE-LH/RH <i>new</i>	2 \$ 62.00	+
18	LOCK CARRIER BRACKET <i>Rehanded</i>	\$ 118.00	?
19	FRONT SENSOR <i>new</i>	2 \$ 421.00	+
20	FRONT SENSOR SEAL RING <i>new</i>	4 \$ 14.00	+
SUB -TOTAL SPARE PARTS		\$ 7,614.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 16 H.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	BONNET <i>Dented</i>	\$ 2,499.00	<i>1999.20</i>
22	BONNET ATTACHMENT PARTS <i>Not Nec</i>	\$ 105.00	<i>X</i>
23	BONNET LID HING-LH/RH <i>Rec</i>	2 \$ 734.00	<i>+</i>
24	BONNET IMPACT PROTECTION-CENTER <i>Rec</i>	\$ 24.00	<i>18.88</i>
25	BONNET IMPACT PROTECTION-LH/RH <i>Rec</i>	2 \$ 48.00	<i>37.76</i>
26	BONNET STOP BUFFER <i>Rec</i>	4 \$ 27.00	<i>+</i>
27	BONNET LID LOCK <i>Rec</i>	\$ 188.00	<i>+</i>
28	BOWDEN CABLE-CENTER <i>Rec</i>	\$ 50.00	<i>+</i>
29	BOWDEN CABLE COVER <i>Rec</i>	\$ 9.00	<i>+</i>
30	BONNET RELEASE CABLE <i>Rec</i>	\$ 50.00	<i>+</i>
31	BONNET RELEASE HANDLE LEVER <i>Rec</i>	\$ 12.00	<i>+</i>
32	LED HEADLIGHT-RH <i>Not Nec</i>	\$ 7,019.00	<i>X</i>
33	LED HEADLIGHT LIFT CYLINDER-RH <i>Rec</i>	\$ 174.00	<i>+</i>
34	FRONT NO. PLATE <i>Bent</i>	S/N \$ 25.00	<i>✓</i>
35	SUNDRIES <i>Rec</i>	\$ 300.00	<i>X</i>
TOTAL SPARE PARTS		:	\$ 18,878.00
TOTAL LABOUR CHARGES		:	\$ 4,672.00
GRAND TOTAL		:	\$ 23,550.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

23881.20

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Wong*
Surveyed Date : *18/10/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 05 Days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1175/2018/GW
Date	:	16-Oct-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
5 days - ok - jb - 8 dec 18

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	WTG Consultatnts PTE LTD
Address	:	74 Begonia Drive Singapore 809932
Telephone	:	HP +65 66355570
Type of Claim	:	Own Damage Claims
Policy No.	:	1700070089-01
Vehicle No	:	SLT 16 H
Model Code	:	Audi A5 SB 2.0 TFSI
Model / Year	:	Sep-17
Engine No	:	CVK 044153
Chassis No	:	WAUZZZF54JA021835
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	15-Oct-18
Place of Accident	:	Yio Chu Kang Rd Slip Road To AMK Ave 6

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 16 H .

S/N	Nature of Jobs	Estimated Charges	
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To dismantle and renew front bumper, bonnet and rhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00	\$ 1,000.00
3	To respray front bumper, bonnet and bonnet hinges.	\$ 1,900.00	\$ 1,100.00
4	To carry out diagnostic checks.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 4,672.00	\$ 2,772.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 16 H.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,975.00	\$ 1,576.00
2	FRONT BUMPER FIXING PARTS	\$ 349.00	
3	FRONT BUMPER SECURING STRIP	2 \$ 60.00	
4	FRONT BUMPER GRILLE-CENTER	\$ 171.00	\$ 136.80
5	FROTN BUMPER CLOSING ELEMENT	\$ 195.00	
6	FRONT BUMPER SPOILER	\$ 465.00	
7	FRONT BUMPER AIR GUIDE-LH/RH	2 \$ 146.00	
8	RADIATOR GRILLE	\$ 2,022.00	\$ 1,617.60
9	ULTRA SOUND SENSOR SUPPORT-LH/RH	2 \$ 100.00	\$ 79.68
10	RADIATOR GRILLE COVER	\$ 165.00	
11	FRONT BUMPER AIR GUIDE GRILLE-RH	\$ 414.00	\$ 331.20
12	FOAM FILLER PIECE	\$ 107.00	\$ 85.20
13	FRONT BUMPER CARRIER	\$ 702.00	
14	FRONT BUMPER COVER	\$ 109.00	\$ 87.20
15	SIGN ' CAUTION '	\$ 12.00	\$ 9.28
16	AIR CONDITIONER STICKER	\$ 7.00	\$ 4.88
17	FRONT BUMPER AIR GUIDE-LH/RH	2 \$ 62.00	
18	LOCK CARRIER BRACKET	\$ 118.00	\$ 94.00
19	FRONT SENSOR	2 \$ 421.00	
20	FRONT SENSOR SEAL RING	4 \$ 14.00	
SUB -TOTAL SPARE PARTS		\$ 7,614.00	\$ 4,021.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 16 H.

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
			\$	4,021.84
21	BONNET		\$ 2,499.00	\$ 1,999.20
22	BONNET ATTACHMENT PARTS		\$ 105.00	
23	BONNET LID HING-LH/RH	2	\$ 734.00	
24	BONNET IMPACT PROTECTION-CENTER		\$ 24.00	\$ 18.88
25	BONNET IMPACT PROTECTION-LH/RH	2	\$ 48.00	\$ 37.76
26	BONNET STOP BUFFER	4	\$ 27.00	
27	BONNET LID LOCK		\$ 188.00	
28	BOWDEN CABLE-CENTER		\$ 50.00	
29	BOWDEN CABLE COVER		\$ 9.00	
30	BONNET RELEASE CABLE		\$ 50.00	
31	BONNET RELEASE HANDLE LEVER		\$ 12.00	
32	LED HEADLIGHT-RH		\$ 7,019.00	
33	LED HEADLIGHT LIFT CYLINDER-RH		\$ 174.00	
34	FRONT NO. PALTE	S/N	\$ 25.00	\$ 25.00
35	<i>Added parts - see attached</i>		\$ 414.00	\$ 331.20
36	SUNDRIES		\$ 300.00	
	TOTAL SPARE PARTS	:	\$ 19,292.00	\$ 6,433.88
	TOTAL LABOUR CHARGES	:	\$ 4,672.00	\$ 2,772.00
	GRAND TOTAL	:	\$ 23,964.00	\$ 9,205.88

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/1175/2018/GW
7-Nov-18
JB
ONE
SLT 16 H
A5 SN 2.0T

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FRONT BUMPER AIR GUIDE GRILL LHS <i>sch</i>	\$ 414.00	\$ 331.20 <i>cm</i>
		<u>\$ 414.00</u>	<u>\$ 331.20</u>
<u>LABORS</u>			
	TOTAL	\$ 414.00	

For Premium Automobiles Pte Ltd

Adrian Ling
SLS

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLT 16 H

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1175/2018/MAS

18 Jan 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SLT 16 H, Audi A5 SB 2.0 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SLT 16 H**, claimant, **WTG Consultants Pte Ltd**, please find the related document per attached.

1. A copy of the Original invoice no. 85013364 – S\$8,994.29
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLT 16 H

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Oct 2018		18 Oct 2018 16:07 Edit Adj Rpt	S\$9,205.88 Edit Estimates	S\$9,205.88 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	WTG CONSULTANTS PTE LTD , Co. Reg. No.: 201109834M		15/10/2018 12:00 - :59 [13 Months and 2 Days From LTA Reg Date (Man Yr)]						
Vehicle Reg. No.:	SLT16H	Date of Loss:							
Claim Type:	OD / 4880136613SG	Policy/Cover Note No.:	1700070089 (Comprehensive)						
		Excess:	S\$800.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 29/10/2018]								
Driver/Custodian:	ONG LE YI JOANNE (39 / Female), NRIC: S7913190C, Tel: +6594508800								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG (22/10/2018): Alert - Adj Mandate Approved (S\$9664.00) - SLT16H - Claim Handler: Mohd Zawaye, ... AIG_SG (19/10/2018): SLT16H / OD / 15/10/2018 / Coverage & Excess update 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT16H (4880136613SG)
OD
Oct 15 2018 12:00PM
[WTG CONSULTANTS PTE LTD]
Premium Automobiles Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		Use Viewer	
Video										1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)								Thumbnail		Print	
1	15/10/18 18:56	Video - Accident [Linked Accident Report Documents]										Load MP4	
Assessment Reports										1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail		Print	
1	19/10/18 09:42	Adjuster Immediate Advice										Load HTM	
Photos/Images										3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail		Print	
1	18/12/18 19:09	General View										Load JPG	
2	18/12/18 19:09	General View										Load JPG	
3	18/12/18 19:09	General View										Load JPG	
4	18/12/18 19:09	General View										Load JPG	
5	18/12/18 19:09	General View										Load JPG	
6	18/12/18 19:09	General View										Load JPG	
7	18/12/18 19:09	General View										Load JPG	
8	18/12/18 19:09	General View										Load JPG	
9	18/12/18 19:09	General View										Load JPG	
10	18/12/18 19:09	General View										Load JPG	
11	18/12/18 19:09	General View										Load JPG	
12	18/12/18 19:09	General View										Load JPG	
13	18/12/18 19:09	General View										Load JPG	
14	18/12/18 19:09	General View										Load JPG	
15	18/12/18 19:09	General View										Load JPG	
16	18/12/18 19:09	General View										Load JPG	
17	18/12/18 19:09	General View										Load JPG	
18	18/12/18 19:09	General View										Load JPG	
19	18/12/18 19:09	General View										Load JPG	
20	18/12/18 19:09	General View										Load JPG	
21	18/12/18 19:09	General View										Load JPG	
22	18/12/18 19:09	General View										Load JPG	
23	18/12/18 19:09	General View										Load JPG	
24	18/12/18 19:09	General View										Load JPG	
25	18/12/18 19:09	General View										Load JPG	
26	18/12/18 19:09	General View										Load JPG	
27	18/12/18 19:09	General View										Load JPG	
28	18/12/18 19:09	General View										Load JPG	
29	18/12/18 19:09	General View										Load JPG	
30	18/12/18 19:09	General View										Load JPG	
31	18/12/18 19:09	General View										Load JPG	
32	18/12/18 19:09	Reinspection Photo										Load JPG	
33	18/12/18 19:09	Reinspection Photo										Load JPG	
34	18/12/18 19:09	Reinspection Photo										Load JPG	
35	18/12/18 19:09	Reinspection Photo										Load JPG	
36	18/12/18 19:09	Reinspection Photo										Load JPG	

37	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
38	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
39	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
40	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
41	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
42	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
43	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
44	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
48	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
49	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
50	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
51	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
52	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
53	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
54	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
55	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
56	18/12/18 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/10/18 09:46	Singapore Accident Statement	1	Load PDF	
2	19/10/18 09:46	Certificate of Insurance	1	Load PDF	
3	19/10/18 09:46	Driver's Driving License	1	Load PDF	
4	19/10/18 09:46	ESTIMATE	1	Load PDF	
5	24/12/18 12:27	SUPPLEMENTARY LIST	1	Load PDF	
6	24/01/19 08:53	WORKSHOP INVOICE	1	Load PDF	
7	24/01/19 08:53	DISCHARGE VOUCHER	1	Load PDF	

Linked Accident Report Documents

			View Use Viewer		
Video			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	15/10/18 18:56	Video - Accident	1	Load MP4	
Assessment Reports			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	15/10/18 18:58	Accident Statement	1	Load HTM	
Photos/Images			3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	15/10/18 17:55	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	15/10/18 17:55	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	15/10/18 17:55	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	15/10/18 17:55	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	15/10/18 17:55	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	15/10/18 17:55	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
7	15/10/18 17:55	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
8	15/10/18 17:55	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
9	15/10/18 17:55	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	15/10/18 17:53	Sketch Plan	1	Load JPG	<input checked="" type="checkbox"/>
2	15/10/18 17:53	Sketch Plan #2	1	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18018976/AQBN2

Date: 24/01/2019

REFERENCE

Insured/Claimant: WTG CONSULTANTS PTE LTD
Date of Loss: 15/10/2018

Policy No: 1700070089
Nature of Claim: OD

Claim No: 4880136613SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT16H	Engine No:	CVK044153
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Chassis No:	WAUZZZF54JA021835
Reg. Date:	13/09/2017 (Man. Year: 2017)	Odometer:	21049 km
Colour:	Red		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$152,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	19,209.20	6,433.88	12,775.32	66.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,672.00	2,772.00	1,900.00	40.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,881.20	9,205.88	14,675.32	61.45
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	23,081.20	8,405.88	14,675.32	63.58
+ GST 7.00/7.00% (S\$)	1,615.68	588.41	1,027.27	63.58
Nett Amount (S\$)	24,696.88	8,994.29	15,702.59	63.58

INSPECTION

Date of Assignment: 18/10/2018

Date Inspected: 18/10/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,975.00 FS	*1,576.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	349.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	60.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTER	Cracked	171.00 FS	*136.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	195.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Repair	465.00 FS	*- FS
7	2		*FRONT BUMPER AIR GUIDE-LH/RH	Not Necessary	146.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cracked	2,022.00 FS	*1,617.60 FS
9	2		*ULTRA SOUND SENSOR SUPPORT-LH/RH	Damaged	100.00 FS	*79.68 FS
10	1		*RADIATOR GRILLE COVER	Not Necessary	165.00 FS	*- FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Damaged	414.00 FS	*331.20 FS
12	1		*FOAM FILLER PIECE	Cracked	107.00 FS	*85.20 FS
13	1		*FRONT BUMPER CARRIER	Not Necessary	702.00 FS	*- FS
14	1		*FRONT BUMPER COVER	Deformed	109.00 FS	*87.20 FS
15	1		*SIGN CAUTION	Necessary	12.00 FS	*9.28 FS
16	1		*AIR CONDITIONER STICKER	Necessary	7.00 FS	*4.88 FS
17	2		*FRONT BUMPER AIR GUIDE-LH/RH	Not Necessary	62.00 FS	*- FS
18	1		*LOCK CARRIER BRACKET	Cracked	118.00 FS	*94.00 FS
19	2		*FRONT SENSOR	Not Necessary	421.00 FS	*- FS
20	4		*FRONT SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
21	1		*BONNET	Dented	2,499.00 FS	*1,999.20 FS
22	1		*BONNET ATTACHMENT PARTS	Not Necessary	105.00 FS	*- FS
23	2		*BONNET LID HINGE-LH/RH	Not Necessary	734.00 FS	*- FS
24	1		*BONNET IMPACT PROTECTION-CENTER	Necessary	24.00 FS	*18.88 FS
25	2		*BONNET IMPACT PROTECTION-LH/RH	Necessary	48.00 FS	*37.76 FS
26	4		*BONNET STOP BUFFER	Not Necessary	27.00 FS	*- FS
27	1		*BONNET LID LOCK	Not Necessary	188.00 FS	*- FS
28	1		*BOWDEN CABLE-CENTER	Not Necessary	50.00 FS	*- FS
29	1		*BOWDEN CABLE COVER	Not Necessary	9.00 FS	*- FS
30	1		*BONNET RELEASE CABLE	Not Necessary	50.00 FS	*- FS
31	1		*BONNET RELEASE HANDLE LEVER	Not Necessary	12.00 FS	*- FS
32	1		*LED HEADLIGHT-RH	Not Necessary	7,019.00 FS	*- FS
33	1		*LED HEADLIGHT LIFT CYLINDER-RH	Not Necessary	174.00 FS	*- FS
34	1		*FRONT NO PLATE	Bent	25.00 FS	*25.00 FS
35	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
36	1		*FRONT BUMPER AIR GUIDE GRILL LHS	Deformed	331.20 FS	*331.20 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	19,209.20	6,433.88
--------------------	-----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND RHS HEADLIGHT.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
3	TO RESPRAY FRONT BUMPER,BONNET AND BONNET HINGES	New	1,900.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			4,672.00	2,772.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >