



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AXA Insured's Veh No : SLB5888U
Date of Accident : 16 October 2018

*Not Allowed
for
d/s =
stdy.
19/10/18
The det. the rep-*

Mr Mak Kam Hung Francis

Date : 17 October 2018

Estimate To Repair SJN5226R - Toyota Vios E Auto
Chassis No : MR053HY9305086825

*Chk - Marcus
19/10/18 0044hrs*

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	bootlid - Vios badge <i>rec</i>	\$ 39.50 ✓
02	1 pc	bootlid - E badge <i>rec</i>	\$ 31.50 ✓
03	1 pc	bootlid centre emblem badge <i>rec</i>	\$ 45.70 ✓
04	1 pc	bootlid lock <i>11</i>	\$ 95.00 X
05	1 pc	bootlid lock striker <i>11</i>	\$ 69.00 X
06	1 pc	bootlid weatherstrip <i>11</i>	\$ 85.00 X
07	1 pc	rear end panel	\$ 668.10 ?
08	1 pc	rear end panel inner trim	\$ 259.60 ?
09	4 ps	rear end panel inner trim clips @ \$4.50 <i>11</i>	\$ 18.00 X
10	1 pc	rear bumper <i>TD</i>	\$ 481.70 ✓
11	2 ps	rear bumper reflectors @ \$97.70	\$ 195.40 ?
12	2 ps	rear bumper side retainers @ \$98.50 <i>set</i>	\$ 197.00 ✓
13	2 ps	rear bumper side holders @ \$33.20	\$ 66.40 ?
14	8 ps	rear bumper clips @ \$4.50 <i>rec</i>	\$ 36.00 ✓
15	2 ps	rear bumper end splashshield cover @ \$87.90	\$ 175.80 ?
16	2 ps	rear lamps @ \$409.90	\$ 819.80 ?
17	4 ps	rear lamp clip holders @ \$25.50 <i>11</i>	\$ 102.00 X
18	1 pc	rear luggage floor side compartment foam <i>11</i>	\$ 951.10 A
19	1 pc	rear luggage floor compartment foam centre <i>11</i>	\$ 225.00 X
		Less 25% <i>50%</i>	\$ 4,561.60
			\$ 1,140.40
			\$ 3,421.20
<u>SPECIAL NETT ITEMS</u>			
20	1 set	rear bumper parking sensor <i>short</i>	\$ 450.00 2005-n
21	1 pc	rear luggage floor insulator <i>11</i>	\$ 280.00 X
			\$ 730.00
<u>LABOUR & MISC. CHARGES</u>			
01		To reinstall of rear bumper parking sensor.	\$ 120.00 50
02		To rust-proofing of the affected areas.	\$ 180.00 30
03		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 150.00 80
04		To check electrical lighting concerned.	\$ 60.00 20
05		To drop rear exhaust box and renew the same.	\$ 11 120.00 X
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00 600



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AXA Insured's Veh No : SLB5888U
Date of Accident : 16 October 2018

Mr Mak Kam Hung Francis

Date : 17 October 2018

Estimate To Repair SJN5226R - Toyota Vios E Auto
Chassis No : MR053HY9305086825

S/No	Quantity	Description	Amount
07		<u>LABOUR & MISC. CHARGES</u> Putty and spray painting of the affected portion.	\$ 850.00
			\$ 2,380.00
		Total	\$ 6,531.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: