

ASS. REC. BY:

REF:

CS/EG18018985/Asd3n2

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGI

Date/Time: 18/10/18 @ 4.16pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC 275T

Insured:

YN 6572G

at Workshop m/s

MG solution

Tel: 6243 1373

of

23 Kaki Bkt Ave 4 # 02-03B

Policy No:

Claim No:

CDMCG18000621/SL/p1

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/10/2018

CA / REV / REP. / REV 24 HRS

1wp

H.O.D. Endorsement:

Date/Time:

4:27pm @ 18/10/18

Person Contacted:

Ms. Hong

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate advise consistency of damages.

obtain estimate

PC 275T-CCG/AXA/4020579/Ksy3w2

DOA: 28/10/2014

YN 6572G-X

22/10/18

@ 14:28 p.m. revert probing estimate from repairer to
Pei Li via email.

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

PC275T.

Yr Regn: 2011

Feb. 2011

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Mini Bus

Make:

Toyota Hiace

C.C. 2982

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

260681

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFST22P900010037

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195 RISC.
R: 195 RISC

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 18/10/18

Survey held at

MG Solution

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S, Front N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

02/11/18

TP Repo.
Confirmed L/S \$6,600/- @ 8 days with Adrian.
(\$11,793.20 Red - 64%)

RECEIVED 02 NOV 2018

Date/Time: File Pass to?

02/11/18



Preli. Report



Final Report

1)

Typist

Date/Time: File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) S + P5 \$

) Photos

) Others:

Add Fee:



Site Insp. (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$ 6,600/- Hs

TOTAL

350

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 22 October 2018 2:28 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: 'SUR'; 'Admin-D (LKKAuto)'; 'assignments'
Subject: RE: YN6572G / TP : PC275T/LKK / DOA : 02/10/2018 (CDMCG18000621)

Dear Pei Li,

Please be informed that we have inspected the vehicle PC 275T on 18/10/2018.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 18 October 2018 4:30 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: YN6572G / TP : PC275T/LKK / DOA : 02/10/2018 (CDMCG18000621)

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Thursday, 18 October 2018 4:16 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>
Subject: OI : YN6572G / TP : PC275T/LKK / DOA : 02/10/2018 (CDMCG18000621)

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Thursday, 18 October 2018 4:16 PM
To: 'admin-d@lkkauto.com'
Cc: 'ASSIGNMENTS@LKKAUTO.COM'
Subject: OI : YN6572G / TP : PC275T/LKK / DOA : 02/10/2018 (CDMCG18000621)
Attachments: YN6572G - SAS.pdf; PC275T - SAS.pdf; PC275T - PRS FORM.pdf; PC275T -(PRE-INSPECTION) ; YOUR RF : YN6572G -DOA ON 02/10/208 (680 KB)

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **MG SOLUTION PTE LTD**,

ADDRESS : 23 KAKI BUKIT AVE 4 (SOUTH WING)
#02-03B VICOM INSPECTION CENTRE
SINGAPORE 415933

PERSON TO CONTACT : MS HONG @ 6243 1373

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel : +65 6829 9199
Fax : +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 18.10.2018
Our Reference: CDMCG18000621/SL/pl
Your Reference: PC 275T

To: MG SOLUTION PTE LTD

Sent via Fax
or
Email

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: PC 275T
Insured's Vehicle: YN 6572G
Date Of Accident: 02.10.2018


We acknowledge receipt of your request for PRS on: 18.10.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input checked="" type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us to date.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.



★ Posted: 12-Oct-2018

Tags: 2010 Hyundai Tucson, 2010 hyundai tucson, Hyundai Tucson, hyundai tucson, Hyundai, Tucson, tucson, Used Hyundai



☐ Hyundai Tucson 2.0A Sunroof \$23,800 \$10,240 /yr 08-Feb-2010 1,998 cc 131,662 km SUV Available

New Arrival, \$2000 Down Payment, Lady Owner, Expat Owned, Cheapest SUV Intown, The Only Fully Agent Service From Day One That Be Trusted, Last Service At Komoco 29/11/17 At 122265km With Agent Receive...

★ Posted: 16-Oct-2018

Tags: 2010 Hyundai Tucson, 2010 hyundai tucson, Hyundai Tucson, hyundai tucson, Hyundai, Tucson, tucson, Used Hyundai



☐ Hyundai Tucson 2.0A Sunroof \$22,500 \$9,960 /yr 09-Feb-2010 1,998 cc - SUV Available

Very Well Maintained Condition, Fuel Efficient And Reliable Model, Very Smooth And Responsive Drive And Also Stable Enough For Long Drives. Car Still Looks Pristine Despite Its Age With Good Exterior ...

★ Posted: 15-Oct-2018

Tags: 2010 Hyundai Tucson, 2010 hyundai tucson, Hyundai Tucson, hyundai tucson, Hyundai, Tucson, tucson, Used Hyundai



☐ Hyundai Tucson 2.0A Sunroof \$24,800 \$10,880 /yr 09-Feb-2010 1,998 cc 100,000 km SUV Available

Up To 95% Loan, Immediate Approval. Twin Panoramic Roof! Excellent And Original Condition, A Practical, Stylish And Comfortable SUV That You Wouldn't Want To Miss! Come View Now You Will Not Regret! T...

★ Posted: 15-Oct-2018

Tags: 2010 Hyundai Tucson, 2010 hyundai tucson, Hyundai Tucson, hyundai tucson, Hyundai, Tucson, tucson, Used Hyundai



Compare your car insurance quotations!

Save 25% on your car insurance, compare your quote from 10 insurers! Make your choice on zero excess and own workshop! Get your cheaper quote now!

Find out more!



☐ Hyundai Tucson 2.0A \$22,800 \$10,310 /yr 18-Feb-2010 1,998 cc 124,500 km SUV Available

Cheapest In Town, Tip Top Condition, Well Groomed And Taken Care, Various Loan Type Provided, Trade In Welcome. Buy With A Piece Of Mind From A Company Accredited With Good Credit. Hurry, Call Us For ...

Benefit Auto Enterprise Pte Ltd

★ Posted: 17-Oct-2018

Tags: 2010 Hyundai Tucson, 2010 hyundai tucson, Hyundai Tucson, hyundai tucson, Hyundai, Tucson, tucson, Used Hyundai



☐ Hyundai Tucson 2.0A \$41,888 \$11,070 /yr 27-Oct-2011 1,998 cc 77,208 km SUV Available

Excellent Condition! View To Believe, Very Low Mileage, Agent Serviced And Maintained, Call Us Now!

★ Posted: 26-Sep-2018

Tags: 2011 Hyundai Tucson, 2011 hyundai tucson, Hyundai Tucson, hyundai tucson, Hyundai, Tucson, tucson, Used Hyundai



☐ Hyundai Tucson 2.0A Sunroof \$72,500 \$9,790 /yr 04-Mar-2015 1,999 cc 30,260 km SUV Available

Agent Maintain And Warranty, Genuine Low Mileage, Stylish Exterior And Interior, Spacious Knockdown Rear Seats And Legroom, Smooth Transmission, Price Negotiable, Trade In Welcome.

★ Posted: 04-Oct-2018

Tags: 2015 Hyundai Tucson, 2015 hyundai tucson, Hyundai Tucson, hyundai tucson, Hyundai, Tucson, tucson, Used Hyundai



☐ Hyundai Tucson 2.0A GLS Sunroof \$77,800 \$9,680 /yr 08-Sep-2015 1,999 cc 50,000 km SUV Available

Full Accessories Equipped And 5 Years Agent Warranty! Condition Like Brand New! An Economical, Stylish And Powerful SUV That Would Appeal To Both Urbanites And Rugged Prospects. Buy It From Us With A P...

Dickson Automobile

★ Posted: 12-Oct-2018

Tags: 2015 Hyundai Tucson, 2015 hyundai tucson, Hyundai Tucson, hyundai tucson, Hyundai, Tucson, tucson, Used Hyundai



☐ Hyundai Tucson 2.0A GLS Sunroof \$78,800 \$9,660 /yr 01-Oct-2015 1,999 cc 59,262 km SUV Available

New Facelifted Tucson 2.0A! High ARF At \$23,320. Original Striking White. Spacious Leg Room. Very Well Kept. Low Mileage Done. In House Loan Available. 100% Accident Free. Price Negotiable. Call Now!

Lake View Credit Pte Ltd

★ Posted: 14-Oct-2018

Tags: 2015 Hyundai Tucson, 2015 hyundai tucson, Hyundai Tucson, hyundai tucson, Hyundai, Tucson, tucson, Used Hyundai



☐ Hyundai Tucson 2.0A GLS \$82,366 \$9,830 /yr 21-Mar-2016 1,999 cc 28,789 km SUV Available

High Loan Available! Pre-Loved By 1 Air-Force Officer Owner, 5 Years Unlimited Mileage Warranty From Agent. Extremely Low Mileage. Incredibly Powerful, Experience, Ultimate Compact SUV With Advanced S...

Creative Auto

★ Posted: 02-Oct-2018

Tags: 2016 Hyundai Tucson, 2016 hyundai tucson, Hyundai Tucson, hyundai tucson, Hyundai, Tucson, tucson, Used Hyundai



☐ Hyundai Tucson 2.0A GLS \$82,000 \$9,690 /yr 20-Apr-2016 1,999 cc 50,000 km SUV Available

Low Mileage Unit! Serviced And Maintained At Agent With Available Records. 5 Years Warranty And 3 Year Servicing With Agent To Go With. Pristine Condition! 80% Loan Available, Trade In Welcome, Contac...

Bavarian Marques Pte Ltd

SHORTLISTED REPORT

Compare

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: ERGO	DATE	: 18/10/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: PC275T		
MODEL	: TOYOTA HIACE COMMUTER		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 2-Oct-18
		TIME	: 10:00HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Replaced</i>	1	\$ 530.00	\$ 530.00
2	FRONT BUMPER SIDE RETAINER LH <i>new</i>	1	\$ 55.80	\$ 55.80
3	FRONT DOOR LH <i>Repair</i>	1	\$ 1,255.30	\$ 1,255.30
4	FRONT DOOR STEP PANEL GARNISH LH <i>cut</i>	1	\$ 187.30	\$ 187.30
5	TAILGATE <i>Replaced</i>	1	\$ 2,366.90	\$ 2,366.90
6	TAILGATE LOGO <i>new</i>	1	\$ 55.20	\$ 55.20
7	TAILGATE LOCK <i>3 new</i>	1	\$ 320.00	\$ 320.00
8	TAILGATE CATCH <i>new</i>	1	\$ 90.20	\$ 90.20
9	TAILGATE INNER BOARD <i>new</i>	1	\$ 533.20	\$ 533.20
10	TAILGATE WEATHERSTRIP <i>cut</i>	1	\$ 422.10	\$ 422.10
11	TAILGATE WINDSCREEN WITH MOULDING <i>new</i>	1	\$ 1,155.60	\$ 1,155.60
12	REAR BUMPER <i>Replaced</i>	1	\$ 560.00	\$ 560.00
13	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 55.40	\$ 110.80
14	REAR AIR VENT RH <i>new</i>	1	\$ 60.90	\$ 60.90
15	TAILLAMP RH <i>cut</i>	1	\$ 322.40	\$ 322.40
16	TAILLAMP LOWER APPRON RH <i>cut</i>	1	\$ 90.30	\$ 90.30
17	TAILLAMP LOWER APPRON SIDE RETAINER RH <i>new</i>	1	\$ 44.60	\$ 44.60
18	TAILLAMP LOWER APPRON STOPPER RH <i>new</i>	1	\$ 55.20	\$ 55.20
19	TAILLAMP PANEL <i>Replaced</i>	1	\$ 630.00	\$ 630.00

20	REAR SIDE PANEL OUTER <i>Buckled</i>	1	\$ 2,055.20	\$ 2,055.20	1750
21	REAR SIDE PANEL INNER <i>Rejis</i>	1	\$ 1,955.20	\$ 1,955.20	x.
22	REAR SIDE PANEL GLASS WITH MOULDING <i>new</i>	1	\$ 1,488.90	\$ 1,488.90	105
23	REAR SAFETY BELT RH <i>Re new</i>	1	\$ 1,288.30	\$ 1,288.30	x
24	REAR SAFETY BELT COVER RH <i>Re new</i>	1	\$ 144.20	\$ 144.20	x

699540
524655

TOTAL PRICE \$ 15,777.60
LESS 25% \$ 3,944.40
SUB TOTAL PRICE \$ 11,833.20

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	x.
2	TAILGATE 70KM/H <i>new</i>	1	\$ 20.00	\$ 20.00	15
3	TAILGATE INNER BOARD CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	+
6	TAILGATE WINDSCREEN SEALANT <i>3m</i>	1	\$ 120.00	\$ 120.00	40
7	TAILGATE WINDSCREEN INNER SEAL	1	\$ 100.00	\$ 100.00	30
8	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
9	TAILLAMP LOWER APRON RIVET <i>new</i>	1	\$ 30.00	\$ 30.00	10
10	REAR SIDE PANEL SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00	+
11	REAR SIDE PANEL QUARTER GLASS SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00	50
14	REAR REVERSE SENSOR <i>Re new</i>	1	\$ 200.00	\$ 200.00	x.

Tailgate protector KH

missing

\$ 200
60.

TOTAL \$ 800.00
800

445

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,400.00	1000	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	800	
3	TUFF COAT	\$ 150.00	60.	
4	WIRING CHECK	\$ 80.00	30	
5	TO REMOVE AND REFIX TAILGATE MECHANISM	\$ 150.00	80	
6	TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN	\$ 180.00	120	
7	TO REMOVE AND REFIX QUARTER GLASS	\$ 150.00	80.	
8	TO REMOVE AND REFIX REVERSE SENSOR	\$ 100.00	60.	
9	TO REMOVE AND REFIX SAFETY BELT INCLUDING REST	\$ 650.00	200	
10	TO REMOVE AND REFIX REAR SEAT TO REPAIR SIDE PANEL	\$ 180.00	150	

11	TO REMOVE AND REFIX SPEAKER TO REPAIR SIDE PANEL	\$ 120.00	X	
----	-----------------------------------------------------	-----------	---	--

TOTAL

\$5,760.00

2580

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,633.20
TOTAL LABOUR COST : \$ 5,760.00
TOTAL REPAIR COST : \$ 18,393.20

18713.20

APPROVED DETAILS

SURVEYOR :
CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
NO OF DAYS :

Adrian Lij total: 8271.55
L/S 18/10/18 L/S: 6.6K
08 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18018985/Asd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 08-11-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 6572G	Veh. Inspected	PC 275T	
Policy No.		Coverage (\$)	0.00	
Claim No.	CDMCG18000621/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	18/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	JTFST22P900010037	Colour	WHITE	
Odometer	260681	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	MICHELIN	6 mm	
L/H Front Tyre	195 R15C	MICHELIN	6 mm	
R/H Rear Tyre	195 R15C	MICHELIN	6 mm	
L/H Rear Tyre	195 R15C	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S AND FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/10/2018	Inspection Date	18/10/2018	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 275T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	530.00	530.00
1	FRONT BUMPER SIDE RETAINER LH	NECESSARY	55.80	55.80
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,255.30	-
1	FRONT DOOR STEP PANEL GARNISH LH	CUT	187.30	187.30
1	TAILGATE	DENTED	2,366.90	2,100.00
1	TAILGATE LOGO	NECESSARY	55.20	55.20
1	TAILGATE LOCK	NOT NECESSARY	320.00	-
1	TAILGATE CATCH	NOT NECESSARY	90.20	-
1	TAILGATE INNER BOARD	NOT NECESSARY	533.20	-
1	TAILGATE WEATHERSTRIP	CUT	422.10	329.00
1	TAILGATE WINDSCREEN WITH MOULDING	NECESSARY	1,155.60	185.00
1	REAR BUMPER	DEFORMED	560.00	560.00
2	REAR BUMPER SIDE RETAINER @\$55.40	NECESSARY	110.80	110.80
1	REAR AIR VENT RH	NOT NECESSARY	60.90	-
1	TAILLAMP RH	CRACKED	322.40	322.40
1	TAILLAMP LOWER APRON RH	CRACKED	90.30	90.30
1	TAILLAMP LOWER APRON SIDE RETAINER RH	NECESSARY	44.60	44.60
1	TAILLAMP LOWER APRON STOPPER RH	NOT NECESSARY	55.20	-
1	TAILLAMP PANEL	DENTED	630.00	630.00
1	REAR SIDE PANEL OUTER	BUCKLED	2,055.20	1,750.00
1	REAR SIDE PANEL INNER	TO REPAIR SEE LABOUR	1,955.20	-
1	REAR SIDE PANEL GLASS WITH MOULDING	NECESSARY	1,488.90	105.00
1	REAR SAFTLY BELT RH	NOT NECESSARY	1,288.30	-
1	REAR SAFTLY BELT COVER RH	NOT NECESSARY	144.20	-
	LESS 25% DISCOUNT		-3,944.40	-1,763.85
			11,833.20	5,291.55
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-

Report Ref No. CS/EGI18018985/Asd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE 70KM/H (SN)	NECESSARY	20.00	15.00
1	SET TAILGATE INNER BOARD CLIPS (SN)	NOT NECESSARY	20.00	-
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	120.00	40.00
1	TAILGATE WINDSCREEN INNER SEAL (SN)	NECESSARY	100.00	30.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
1	TAILLAMP LOWER APRON RIVERT (SN)	NECESSARY	30.00	10.00
1	REAR SIDE PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
1	REAR SIDE PANEL QUARTER GLASS SEALANT (SN)	NECESSARY	120.00	50.00
1	REAR REVERSE SENSOR (SN)	DAMAGED	200.00	200.00
1	TAILLAMP PROTECTOR RH (SN)	MISSING	300.00	60.00
			1,120.00	445.00
	LABOUR			
	PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR LH AND REAR SIDE PANEL INNER.		2,400.00	1,000.00
	TO SPRAY PAINT AFFECTED AREA.		1,600.00	800.00
	TUFF COAT.		150.00	60.00
	WIRING CHECK.		80.00	30.00
	TO REMOVE AND REFIX TAILGATE MECHANISM.		150.00	80.00
	TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN.		180.00	120.00
	TO REMOVE AND REFIX QUARTER GLASS.		150.00	80.00
	TO REMOVE AND REFIX REVERSE SENSOR.		100.00	60.00
	TO REMOVE AND REFIX SAFETY BELT INCLUDING REST.		650.00	200.00
	TO REMOVE AND REFIX REAR SEAT TO REPAIR SIDE PANEL.		180.00	150.00
	TO REMOVE AND REFIX SPEAKER TO REPAIR SIDE PANEL.	NOT NECESSARY	120.00	-
	-		-	-
	-		-	-
	-		-	-
			5,760.00	2,580.00
GRAND TOTAL			18,713.20	8,316.55

Report Ref No. CS/EG118018985/Asd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,600.00
-------------------------------------------------------------------------	--	--	----------

Report Ref No. CS/EGI18018985/Asd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.