

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1190/2018/PH
Date : 19-Oct-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : **SMA 7398 Y**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : HITACHI CAPITAL ASIA PACIFIC PTE LTD
Address :
Singapore
Telephone : HP +65 67341222
Type of Claim : Third Party Claim
Policy No. : VPX/P1929357
Vehicle No : **SLM 5009 H**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : Mar-17
Engine No : CVN 029552
Chassis No : WAUZZZF41HA113633
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Oct-18
Place of Accident : One Shenton (Parking)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLM 5009 H

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 1,800.00	
3	To respray front bumper and rhs front fender.	\$ 1,500.00	
4	To carry out diagnostic check.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 3,852.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 5009 H.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>whd</i>	\$ 1,849.00	✓
2	FIXING PARTS FOR FRONT BUMPER ?	\$ 245.00	x
3	SECURING STRIP	\$ 30.00	x
4	GRILLE SATIN BLACK	\$ 171.00	x
5	CLOSING ELEMENT	\$ 180.00	x
6	AIR GUIDE - RH	\$ 73.00	x
7	AIR GUIDE GRILLE - RH	\$ 118.00	x
8	FOAM FILLER PIECE ?	\$ 107.00	?
9	FRONT BUMPER CARRIER ?	\$ 702.00	?
10	GUIDE SECTION - RH <i>new</i>	\$ 32.00	x
11	BRACKET LOCK CARRIER <i>new</i>	\$ 118.00	x
12	FRONT FENDER - RH <i>Painted</i>	\$ 665.00	✓
13	ATTACHMENT PARTS FOR FENDER ?	\$ 45.00	?
14	CLOSING ELEMENT - RH <i>new</i>	\$ 44.00	x
15	BRACKET FOR FENDER - RH	\$ 31.00	?
16	BRACKET FOR DEFORMATION - RH ?	\$ 43.00	?
17	FRONT FENDER BRACE - RH ?	\$ 103.00	?
18	WHEEL HOUSING LINER - RH <i>new</i>	\$ 209.00	x
19	ATTACHMENT PARTS FOR WHEEL HOUSING LINER <i>new</i>	\$ 78.00	x
20	WHEEL SPOILER - RH <i>new</i>	\$ 63.00	x
SUB TOTAL SPARE PARTS		\$ 4,906.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 5009 H.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	SPOILER <i>new</i>	\$ 31.00	*
22	STONE CHIP GUARD - SATIN BLACK <i>new</i>	\$ 44.00	✓
23	COVER <i>new</i>	\$ 27.00	✓
24	COVER - RH	\$ 20.00	✓
25	LED HEADLIGHT - RH <i>new</i>	\$ 6,973.00	✓
26	POWER MODULE FOR MAIN LIGHT <i>new</i>	\$ 695.00	*
27	CONTROL UNIT FOR LIGHT CONTROL UNIT <i>new</i>	\$ 657.00	*
28	HEADLIGHT LIFT CYLINDER - RH ?	\$ 184.00	?
29	RADIATOR GRILLE <i>new</i>	\$ 972.00	*
30	FRONT NUMBER PLATE <i>new</i>	S/N \$ 25.00	*
31	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 14,834.00
TOTAL LABOUR CHARGES		:	\$ 3,852.00
GRAND TOTAL		:	\$ 18,686.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 19/10/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days.

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant