

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKP9832S
Accident Date : 16-Oct-2018

No. : 05868

Date : 18-Oct-2018

Our Ref : 218173 (AXA) / CHAN

PAGE : 1

BOON TONG KEE PTE LTD
52 WOODLANDS TERRACE
Singapore 738462

Not Notarized
Henry Bk paint

ESTIMATED COST OF REPAIR FOR NISSAN NV200 ACENTA GBH4636Z

1 pc N/s rear door
1 pc N/s rear door "NV200" emblem
1 pc N/s rear door nissan logo
1 pc O/s rear door
1 pc Rear bumper fascia
1 pc Rear bumper sponge
1 pc Rear end panel-inner
1 pc Rear end panel -outer

R 1,281.00 n *—*
me 87.00 n *—*
me 145.60 n *—*
me 1,130.90 n *—*
Bu 740.00 n *—*
R 84.00 n *7*
R 598.40 n *x*
182.40 n *?*

4,249.30
Less 10% : 424.93

1 pc N/s rear door 70/km sticker
1 pc N/s rear door glass sealant
1 pc O/s rear door glass sealant

3,824.37
me 15.00 sn *✓*
me 60.00 sn *60sn*
me 60.00 sn *40sn*

To remove & refix rear windscreen glass and conduct water leak test.

120.00 *1001*

To apply undersealing

80.00 *602*

To putty and spray replaced parts

900.00 *6001*

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

800.00 *5001*

Total : S\$ 5,859.37

Singapore Dollars Five Thousand Eight Hundred and Fifty Nine and Cents Thirty Seven Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: