

ASS. REC. BY:

REF: CS/SMO18018995/ Kv d3 | 02

Special Instruction:

Surveyor:

manman

ASSIGNMENT (Office)

From (Person): Chan Shu hui Agnes of SMO

Date/Time: 18/10/18 @ 4:48pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGH 1578T

Insured:

at Workshop m/s Lai Huiat (Meng Kee)

Tel: 64538110

of 160 Sin Ming Drive # 04-01

Policy No: D18MTPV01009173

Claim No: CNTD1804543

Sum Insured:

Excess: 1BA

Make of Veh:

D.O.A. 17/10/2018

(Client's Record)

Further advised upon survey
CA / REV / REP. / REV 24 HRS

19/10/18

H.O.D. Endorsement:

Date/Time: 5:13pm @ 18/10/18

Person Contacted: Jenny

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SGH 1578T - CS/SMO18018940/Ktd3 DOA: 17/10/2018
7/4	1/1 Ly @ 2800 Carbur to eno1 (Red 1444.70, 3490)

REF: SMO

ASSIGNMENT

From:

Date: 19/10/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SGH 1578T

at Workshop m/s

Lei Huat (Meng Kee)

of

160 Sin Ming Drive # 04-01

Insured:

Policy No.

Claims No.

Sum Insured:

Excess: TBA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

817k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

upon survey
CA / REV / REP. / 24 HRS

Date:

5/21

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGH 1578T Yr Regn: 05, 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

N/S

Sylphy

C.C

1498

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading:

29P 779

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1BAAG 118 0100450

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Yoko

195/65R15

R: Felixa

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

3

mm

L/Bal.

7

mm

L/Bal.

3

mm

D.O.A.

17/10/18

D.O.I.

19/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

02/10 PM pass to Corrine

RECEIVED 07 NOV 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 7/11 - typist

Days Of Repair:

6

Resurvey No. of Trip:

2

Report Format :

merimen

Lump Sum / I.B.I: (\$

2800/-)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

250
10

260

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Inc Auth'd	Status
Main	18 Oct 2018 14:56 Sendback Est	18 Oct 2018 15:16 S\$4,244.70	18 Oct 2018 16:48 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	IN THE ESTATE OF MELIANA KOHAR WIJAYA, ID: --		
Vehicle Reg. No.:	SGH1578T	Date of Loss:	17/10/2018 09:00 - :59 [148 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / CMTD1804543	Policy/Cover Note No.:	D18MTPV01009173 (Comprehensive)
		Excess:	
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/10/2018]		
Driver/Custodian:	YEO IOK SEK JOSEPH (36 / Male), NRIC: S8206003J, Tel: +6596635541		
Adj Asg. Remarks:	Excess : to be advise Authorisation will be further advised upon survey.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 5828Z

Vehicle Details

Vehicle No.: SGH1578T
Vehicle to be Exported: Yes
Intended Deregistration Date: 17 Oct 2018
Vehicle Make: NISSAN
Vehicle Model: SYLPHY 1.5 4AT
Primary Colour: Purple
Manufacturing Year: 2006
Engine No.: HR15353424
Chassis No.: JN1BAAG11Z0100450
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$18,494.00
Original Registration Date: 31 May 2006
First Registration Date: 31 May 2006
Transfer Count: 0
Actual ARF Paid: \$20,344.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 May 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$22,789.00
COE Rebate Amount: \$11,933.00
Total Rebate Amount: \$11,933.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 17 Oct 2018

OK

REPUBLIC OF SINGAPORE DRIVING LICENCE

000058860K

YEO IOK SEK JOSEPH

Birth Date: 09 Mar 1982
Issue Date: 23 Dec 2002

000058860K

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8206003J

Name
YEO IOK SEK JOSEPH

杨 约 瑟

Race
CHINESE

Date of birth
09-03-1982

Sex
M

Country of birth
SINGAPORE

S8206003J

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	12 Dec 2001

NP 428A

Licence No: S8206003J

4887243

NRIC No: S8206003J

Date of issue
21-09-2012

APT BLK 110 LENGKONG TIGA #06-227
SINGAPORE 410110

NRIC No: S8206003J Date: 21/03/2018 (R)

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

INSURER: Sompoo Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	69920
Policy No:	D18MTPV01009173	Date of Loss:	17/10/2018
Vehicle Reg. No.:	SGH1578T	Driveable?	
Driver Age/Info:	36 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	IN THE ESTATE OF MELIANA KOHAR WIJAYA		
Driver:	YEO IOK SEK JOSEPH		
Make/Model:	NISSAN SYLPHY, 1.5 4AT (A)	Vehicle Reg. Date:	31/05/2006
Vehicle Colour:	Purple		
Engine No:	HR15353424	Chassis No:	JN1BAAG11Z0100450
Odometer:	299779 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6 days		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) / VICTAN FAN		

COST OF CLAIMS	Amount
Parts	2,924.70
Miscellaneous Items	0.00
Labour	620.00
Paintwork Labour	700.00
Towing	0.00
Gross Total (S\$)	4,244.70
+ GST 7.00% (S\$)	297.13
Nett Amount (S\$)	4,541.83

This claim is handled by: VICTOR FAN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Oct 2018)
Parts: 143 NISSAN SYLPHY 1.5 4AT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SGH1578T/18/10/2018 15:16
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet	Bu 0.00	0.00	*320.00 F
2	1		*Bonnet lock	0.00	0.00	*45.00 F
3	1		*Bonnet hinge LH	0.00	0.00	*35.00 F
4	1		*Bonnet hinge RH	0.00	0.00	*35.00 F
5	1		*Bonnet chrome moulding	0.00	0.00	*75.00 F
6	1		*Front bumper	Bu 0.00	0.00	*250.00 F
7	1		*Headlamp LH	Mg CM 0.00	0.00	*290.00 F
8	1		*Headlamp RH	Mg CM 0.00	0.00	*290.00 F
9	1		*Front top panel	Bu 0.00	0.00	*130.00 F
10	1		*Front bumper sponge	CM 0.00	0.00	*75.00 F
11	1		*Front bumper reinforcement	0.00	0.00	*150.00 F
12	1		*Air con condenser	Sm 0.00	0.00	*280.00 F
13	1		*Front brace panel	Bu 0.00	0.00	*20.00 F
14	1		*Radiator	0.00	0.00	*250.00 F
15	1		*Radiator grille	CM 0.00	0.00	*160.00 F
16	1		*Radiator grille logo emblem	Nu 0.00	0.00	*30.00 F
17	10		*Front bumper clips	Nu 0.00	0.00	*20.00 F
18	1		*Front bumper side holder LH	Dit 0.00	0.00	*12.00 F
19	1		*Front bumper side chrome moulding LH	Nu 0.00	0.00	*35.00 F
20	1		*Front bumper side chrome moulding RH	Nu 0.00	0.00	*35.00 F
21	1		*Front end panel top cover	Dit 0.00	0.00	*90.00 F
22	1		*Front number plate	Bu 0	0.00	*35.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$) **2,662.00**
 + Margin on L,N Items 10.00% (S\$) **262.70**
Total Parts (S\$) 2,924.70

Lai Huat (Meng Kee) Motor Pte Ltd/SGH1578T/18/10/2018 15:16. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer:
 Signature:
 Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To spray paint	New	700.00 <i>650</i>
<u>Labour Items</u>			
2	To remove + renew air con condenser and refill gas	New	120.00 <i>100</i>
3	To straighten front body, to knock dents on front fender LH, headlamp panel LH & RH and renew of parts	New	500.00 ✓
Gross Labour Cost (S\$)			1,320.00

Lai Huat (Meng Kee) Motor Pte Ltd/SGH1578T/18/10/2018 15:16. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO18018995/KVD3N2

Date: 12/11/2018

REFERENCE

Insured/Claimant: IN THE ESTATE OF MELIANA KOHAR
WIJAYA

Policy No: D18MTPV01009173

Date of Loss: 17/10/2018

Nature of
Claim:

OD

Claim
No:

CMTD1804543

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGH1578T

Make & Model: NISSAN SYLPHY, 1.5 4AT (A)

Reg. Date: 31/05/2006 (Man. Year: 2006)

Colour: Metallic Grey

Engine Capacity: 1498 cc

Market Value/New Car Price: S\$17,000.00

Sum Insured (S\$): Market Value/New Car Price

Engine No: HR15353424

Chassis No: JN1BAAG11Z0100450

Odometer: 299779 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 65 R15

Front Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm

Rear Tyre Size:

195 65 R15

Rear Left Side:

Falken 3 mm

Rear Right Side:

Falken 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,924.70	2,264.70	660.00	22.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	620.00	600.00	20.00	3.23
Paintwork Labour	700.00	650.00	50.00	7.14
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,244.70	3,514.70	730.00	17.20
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	4,244.70	2,800.00	1,444.70	34.04
+ GST 7.00/7.00% (S\$)	297.13	196.00	101.13	34.04
Nett Amount (S\$)	4,541.83	2,996.00	1,545.83	34.04

INSPECTION

Date of Assignment: 18/10/2018 Present Location:

Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

Date Inspected: 19/10/2018 Inspected At:

Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #04-01, Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Nov 2018)
Parts: 143	NISSAN SYLPHY 1.5 4AT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGH1578T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Bonnet	Buckled	320.00 F	*320.00 F
2	1		*Bonnet lock	Distorted	45.00 F	*45.00 F
3	1		*Bonnet hinge LH	Repair	35.00 F	*- F
4	1		*Bonnet hinge RH	Repair	35.00 F	*- F
5	1		*Bonnet chrome moulding	Cracked	75.00 F	*75.00 F
6	1		*Front bumper	Buckled	250.00 F	*250.00 F
7	1		*Headlamp LH	Mtg Cracked	290.00 F	*290.00 F
8	1		*Headlamp RH	Mtg Cracked	290.00 F	*290.00 F
9	1		*Front top panel	Buckled	130.00 F	*130.00 F
10	1		*Front bumper sponge	Cracked	75.00 F	*75.00 F
11	1		*Front bumper reinforcement	Bent	150.00 F	*150.00 F
12	1		*Air con condenser	Serviceable	280.00 F	*- F
13	1		*Front brace panel	Bent	20.00 F	*20.00 F
14	1		*Radiator	Serviceable	250.00 F	*- F
15	1		*Radiator grille	Cracked	160.00 F	*160.00 F
16	1		*Radiator grille logo emblem	Necessary	30.00 F	*30.00 F
17	10		*Front bumper clips	Necessary	20.00 F	*20.00 F
18	1		*Front bumper side holder LH	Distorted	12.00 F	*12.00 F
19	1		*Front bumper side chrome moulding LH	Necessary	35.00 F	*35.00 F
20	1		*Front bumper side chrome moulding RH	Necessary	35.00 F	*35.00 F
21	1		*Front end panel top cover	Dented	90.00 F	*90.00 F
22	1		*Front number plate	Bent	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	2,662.00	2,062.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	262.70	202.70
Total Parts (\$\$)	2,924.70	2,264.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To spray paint	New	700.00	650.00
<u>Labour Items</u>				
2	To remove + renew air con condenser and refill gas	New	120.00	100.00
3	To straighten front body, to knock dents on front fender LH, headlamp panel LH & RH and renew of parts	New	500.00	500.00
Gross Labour Cost (S\$)			1,320.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >