

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1192/2018/GW
Date	:	19-Oct-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Ng Kok Wah
Address	:	9 Tampines Street 86
	:	#12-27
	:	Singapore 528587
Telephone	:	HP +65 96190345
Type of Claim	:	Third Party Claims
Policy No.	:	1800061529
Vehicle No	:	SFV 2818 H
Model Code	:	Audi A4 Sedan 2.0 TFSI
Model / Year	:	Jun-18
Engine No	:	CVK 060539
Chassis No	:	WAUZZZF40HA159718
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	18-Oct-18
Place of Accident	:	SERANGOON GARDEN MARKET CAR PARK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFV 2818 H .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Rehd</i>	\$ 1,902.00	✓
2	FRONT BUMPER FIXING PARTS	\$ 245.00	X
3	FRONT BUMPER SECURING STRIP <i>ne a</i>	\$ 30.00	X
4	FRONT BUMPER GRILLE-CENTRE	\$ 171.00	X
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>ne a</i>	\$ 180.00	X
6	FRONT BUMPER AIR GUIDE-RH <i>ne a</i>	\$ 73.00	X
7	RADIATOR GRILLE <i>ne a</i>	\$ 1,155.00	X
8	FRONT BUMPER AIR GUDIE GRILLE-RH <i>ne a</i>	\$ 118.00	X
9	FRONT BUMPER GUIDE SECTION-RH	\$ 32.00	X
10	FOAM FILLER PIECE <i>ne a</i>	\$ 107.00	X
11	FRONT BUMPER CARRIER	\$ 702.00	X
12	FRONT SENSOR <i>ne a</i>	2 \$ 421.00	X
13	FRONT SENSOR SEAL RING	4 \$ 14.00	X
14	FRONT FENDER <i>Repair</i>	\$ 665.00	X
15	FRONT FENDER ATTACHEMENT PARTS <i>ne a</i>	\$ 45.00	X
16	FRONT FENDER CLOSING ELEMENT-RH <i>ne a</i>	\$ 44.00	X
17	FRONT FENDER BRACKET-RH	\$ 31.00	X
18	FRONT FENDER BRACKET DEFORMANTON-RH <i>ne a</i>	\$ 43.00	X
19	FRONT FENDER BRACE-RH <i>ne a</i>	\$ 103.00	X
20	FRONT WHEEL HOUSING LINER-RH	\$ 209.00	X
SUB-TOTAL SPARE PARTS		\$ 6,290.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFV 2818 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 78.00	x
22	FRONT WHEEL SPOILE-RH	\$ 63.00	x
23	FRONT WHEEL SPOILER END PLATE-RH	\$ 31.00	x
24	STONE CHIP GUARD -RH	\$ 44.00	y
25	FRONT FENDER LEDGE-RH	\$ 27.00	x
26	FRONT FENDER LEDGE TOP COVER-RH	\$ 20.00	x
27	LED HEADLIGHT-RH	\$ 6,973.00	x
28	LED HEADLIGHT LIFT CYLINDER-RH	\$ 184.00	f
29	FRONT NO. PLATE	S/N \$ 25.00	x
30	SUNDRIES	\$ 300.00	.
TOTAL SPARE PARTS		: \$ 14,035.00	
TOTAL LABOUR CHARGES		: \$ 3,972.00	
GRAND TOTAL		: \$ 18,007.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 23/10/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 days.

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant