

2009/2009

ASS REC BY:

REF: C33 / SMO18012634 / Uq627

Special Instruction:

MVA/DA

ASSIGNMENT (Office)

From (Person): Bernard Han. of SMO Date/Time: 18-10-2018

Estimated Cost: _____ Bill to: _____

OD / (IP) / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKR 8602K Insured: SJH 6084Hat Workshop m/s: Boon Siong Tel: 6746 5426of Bk 1 Kaki Bukit Ave 6 #01-103Policy No: _____ Claim No: CMTD1802910/HCY

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A: 07072018
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement

Date/Time: 11072018 1056am Person Contacted: Boon Siong Vehicle: (IN) OUTDate/Time: _____ Action/Instruction: (X) 1. Change2. 21/10/183. 11/10/18Dismanlle: 13/11/2018\$ 20,00019/10/18 Sumat 2/5 9000 14h (Red. #4000, 95%).[Signature]19/10/2018

URGENT

(08/11/13) wef

ASS. REC. BY: Marius

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKR8602Kat Workshop m/s Beaury

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$ 21k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: 2 Consistent?: Yes or NoEst. Repairs: 8 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

3.17/2021

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKR8602K Yr Regn: 10 06Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: M. F. Colt Plus c.c. 1499Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 213910 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM/LT223W52000698

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/50 R15
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FAUden

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 7/7/18

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 11/7/18 @ 11am

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Reen

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

no settlmt. 3yrs. LTA 15/08 with S812

RECEIVED 17 JUL 2018

81C-9K8 days

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS, \$ SI

Photos

Others

TOTAL

Report Format: PRE

Lump Sum / I.B.I. (\$) _____

100
60
160

Catherine Chong (LKK Auto)

From: Han, Bernard <Bernard.han@sompo.com.sg>
Sent: Thursday, 18 October, 2018 3:38 PM
To: Celine Fong (LKKAuto)
Cc: Admin-D (LKKAuto); assignments; KKLau; LKK Valuation
Subject: RE: SUV(LKK)/ ACCIDENT INVOLVING SJH6084H & SKR8602K ON 07.07.2018, LKK ref : CS3/SMO18012634/Uz4be2, Sompo ref : CMTD1802910/HCY

Importance: High

Dear Ms Celine

We refer to our emails on 1/9 and 8/10 asking for your paper survey report, till date we do not seems to have receive a copy of it.

We attached below the email reminder from the claimant's solicitors this morning.

As we have been asking for your report more than 1.5 months ago, if the solicitors proceed on with the next stage of proceedings, we have no other alternatives but to look to you to be responsible for the increase in legal costs and disbursements.

Please let us have your report by tomorrow noon time so that we can revert back to the solicitors before the weekend.

If you have already forward us a copy earlier, please send us a softcopy of it.

Thank you.

--

From: Igene Lim <igene.lim@mneduco.com.sg>
Sent: Thursday, October 18, 2018 10:21 AM
To: Han, Bernard <Bernard.han@sompo.com.sg>
Subject: RE: ACCIDENT INVOLVING SJH6084H AND SKR8602K ON 7/7/2018, Your ref : MN.IG.B2.1812525.st, Our ref : CMTD18025

WITHOUT PREJUDICE

Our Ref : MN.IG.B2.1812525

Hi Bernard,

As we have been instructed to expedite matter, please let us hear from you on our proposal as soon as possible.

With thanks & regards,
Igene Lim (Ms)
M NEDUMARAN & CO
Advocates & Solicitors
Commissioner for Oaths

Best Regards

Bernard Han

Claims Division

D: 6322 4659 | T: 6221 2211 | F: 6221 3147

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Han, Bernard

Sent: Monday, October 08, 2018 06:28 PM

To: 'Celine Fong (LKKAUTO)' <celinefong@lkkauto.com>

Cc: 'Admin-D (LKKAUTO)' <admin-d@lkkauto.com>; 'assignments' <assignments@lkkauto.com>; 'KKLau' <kklau@lkkauto.com>; 'LKK Valuation' <valuation@lkkauto.com>

Subject: FW: SUV(LKK)/ ACCIDENT INVOLVING SJH6084H & SKR8602K ON 07.07.2018, LKK ref : CS3/SMO18012634/Uz4be2, Sompo ref : CMTD1802910/HCY

Importance: High

Dear Ms Celine

We refer to our email on 1/9.

The solicitors representing SKR8602K has sent us a reminder.

It is more than a month since our email to you with third party documents, requesting your surveyor to prepared a paper re-inspection report for the repairs to SKR8602K.

We will have no alternative but to seek reimbursements from you if the solicitors issue a Writ of Summons against our insured due to this delay.

We definitely hope that we will not reach such a stage, kindly revert on an urgent basis.

Thank you.

Best Regards

Bernard Han

Claims Division

D: 6322 4659 | T: 6221 2211 | F: 6221 3147

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Han, Bernard

Sent: Saturday, September 01, 2018 11:43 AM

To: 'Celine Fong (LKKAUTO)' <celinefong@lkkauto.com>

Cc: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>; KKLau <kklau@lkkauto.com>; LKK Valuation <valuation@lkkauto.com>

Subject: SUV(LKK)/ ACCIDENT INVOLVING SJH6084H & SKR8602K ON 07.07.2018, LKK ref : CS3/SMO18012634/Uz4be2, Sompo ref : CMTD1802910/HCY

Dear Ms Celine

We refer to the above pre-repair inspection conducted by your surveyor, Mr Chua Kang Seng.

Please request Mr Chua to do a paper re-inspection of SKR8602K, attached are the survey report and photographs from the claimant.

Kindly send us your re-inspection report on an urgent basis, so that we can continue to negotiate with the claimant's solicitors.

Thank you.

Best Regards

Bernard Han

Claims Division

D: 6322 4659 | T: 6221 2211 | F: 6221 3147

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Celine Fong (LKKAuto) [<mailto:celinefong@lkkauto.com>]

Sent: 23 July 2018 12:55 PM

To: Han, Bernard <Bernard.han@sompo.com.sg>

Cc: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>; KKLau <kklau@lkkauto.com>; LKK Valuation <valuation@lkkauto.com>

Subject: RE: CMTD1802910/HCY - SUV(LKK)/ ACCIDENT INVOLVING SJH6084H & SKR8602K ON 07.07.2018

Dear Bernard,

The net loss of vehicle SKR 8602K is as below:

Market Value	: \$21,000.00 (Est)
LTA Rebate	: \$15,108.00
Nett Value	: \$ 5,892.00

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: KKLau

Sent: Saturday, 21 July 2018 2:14 PM

To: Han, Bernard <Bernard.han@sompo.com.sg>; LKK Valuation <valuation@lkkauto.com>; Celine Fong (LKKAuto) <celinefong@lkkauto.com>

Cc: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: Re: CMTD1802910/HCY - SUV(LKK)/ ACCIDENT INVOLVING SJH6084H & SKR8602K ON 07.07.2018

Hi Bernard,

Thank you for the email.

Hi Celine team, please ASAP.

Regards,

K K Lau

LKK Auto Consultants P L.

Sent from my iPad

On 21 Jul 2018, at 1:07 PM, Han, Bernard <Bernard.han@sompo.com.sg> wrote:

Dear Ms Catherine

We receive your pre-repair inspection report for SKR8602K which states that the vehicle was registered in 2006.

We require your advice for the following.

1. The market value and scrap value of the vehicle, SKR8602K.
2. What is the net loss if the vehicle is to be considered under constructive total loss.

Please let us have your reply of the above 2 questions as soon as possible, so that we can reply to the claimant's solicitors when we receive their claim.

Thank you.

Best Regards

Bernard Han

Claims Division

D: 6322 4659 | T: 6221 2211 | F: 6221 3147

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @ <image001.png> or <image002.png>

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.
Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]

Sent: 11 July 2018 11:01 AM

To: 'Serene Tan' <serene.tan@mneduco.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>; assignments@lkkauto.com

Cc: Han, Bernard <Bernard.han@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: RE: CMTD1802910/HCY - SUV(LKK)/ ACCIDENT INVOLVING SJH6084H & SKR8602K ON 07.07.2018

Dear Serene,

Noted with thanks.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Serene Tan [mailto:serene.tan@mneduco.com.sg]
Sent: Tuesday, 10 July, 2018 3:11 PM
To: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>; 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments@lkkauto.com
Cc: 'Han, Bernard' <Bernard.han@sompo.com.sg>; 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>
Subject: RE: CMTD1802910/HCY - SUV(LKK)/ ACCIDENT INVOLVING SJH6084H & SKR8602K ON 07.07.2018

OUR REF: MN.IG.B2.1812525

Dear Catherine,

The vehicle is in the workshop now. Venue at 1 Kaki Bukit Avenue 6, #01-103 AutoBay@ Kaki Bukit, Singapore 417883

Thanks & Best Regards,
(For and on behalf of Mr Nedumaran Muthukrishnan)

Serene Tan (Ms)
M NEDUMARAN & CO
Advocates & Solicitors
Commissioner for Oaths

Branch Office:

11 Sin Ming Road
#B2-09 (Unit 2), Thomson V Two
Singapore 575629
Tel: 6509-8480 / 6509-8481
Fax: 6509-8482

Email : serene.tan@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509 8480, if you have received this message in error. Thank you.

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, July 10, 2018 9:43 AM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; Serene Tan <serene.tan@mneduco.com.sg>; assignments@lkkauto.com
Cc: 'Han, Bernard' <Bernard.han@sompo.com.sg>; 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>
Subject: RE: CMTD1802910/HCY - SUV(LKK)/ ACCIDENT INVOLVING SJH6084H & SKR8602K ON 07.07.2018

Dear Grace,

Thank you for the assignment.

Dear Serene,

Kindly provide us the workshop detail.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]

Sent: Monday, 9 July, 2018 4:36 PM

To: Serene Tan <serene.tan@mneduco.com.sg>; admin-d@lkkauto.com; assignments@lkkauto.com

Cc: Han, Bernard <Bernard.han@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: CMTD1802910/HCY - SUV(LKK)/ ACCIDENT INVOLVING SJH6084H & SKR8602K ON 07.07.2018

Our Reference : CMTD1802910/HCY

Your Reference: MN/IG/B2/1812525/st

Date: 9th July 2018

Without Prejudice
EMAIL ONLY

Attention:

M/S M NEDUMARAN & CO

Dear Sir/ Madam,

ACCIDENT INVOLVING SJH6084H & SKR8602K ON 07.07.2018

We refer to your email reply of today.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

<image009.jpg>

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @ <image010.png> or <image011.png>

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Serene Tan [<mailto:serene.tan@mneduco.com.sg>]

Sent: Monday, July 09, 2018 4:03 PM

To: Teo, Grace

Cc: Han, Bernard; Ye, Yong Kang Melvin

Subject: RE: CMTD1802910/HCY - PRI/ ACCIDENT INVOLVING SJH6084H & SKR8602K ON 07.07.2018

Our Ref : [MN.IG.B2.1812525.st](#)

WITHOUT PREJUDICE
SAVE AS TO COSTS

NOTICE TO INSURERS OBJECTING TO THE LIST OF MOTOR SURVEYORS PROVIDED WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2.6 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)

Hi Grace,

1. We refer to your email below.
2. We are instructed by **SGM HARDWARE PTE LTD**, the claimant and/or **BOON SIONG VEHICLE SERVICE**, the motor workshop for **SKR 8602K** that they are not agreeable to the appointment of the motor surveyors as stated in your said email.
3. In compliance with The State Courts Practice Directions (Amendment No. 1 of 2016), we propose to use one of the below mentioned motor surveyor to conduct the joint pre-repair survey ("hereinafter referred to as PRS") as a Single Joint Expert ("hereinafter referred to as a SJE").

1.	NICKY SEAH (Absolute Appraisal Services)	6.	ANDREW HOW (Prominent Appraiser Services)
2.	MICHAEL YAP TECK CHYE (MC-COY Appraiser Pte Ltd)	7.	NG KONG BENG PATRICK (Carlink Consultancy)
3.	DIXON YEO (Treasure Appraisal Services)	8.	ANANDA KUMAR BISWAS S/O B N BISWAS (United Appraisal & Management Pte Ltd)
4.	LOI BOON JUAN	9.	DENNIS YAP TECK WEE

	(Par Automotive Consultancy)		(PAL's Appraiser Pte Ltd)
5.	AMAS ONG AEON Auto Consultants LLP)	10.	ANDY YAP TECK LEE (LCW Appraiser Pte Ltd)

4. Please let us know **within two (2) working days** whether you agree to the appointment of any of the above motor surveyors as proposed by the claimant and/or the motor workshop as a Single Joint Expert ("hereinafter referred to as "SJE").

Thanks & Best Regards,
(For and on behalf of Mr Nedumaran Muthukrishnan)

Serene Tan (Ms)
M NEDUMARAN & CO
Advocates & Solicitors
Commissioner for Oaths

Branch Office:

11 Sin Ming Road
#B2-09 (Unit 2), Thomson V Two
Singapore 575629
Tel: 6509-8480 / 6509-8481
Fax: 6509-8482

Email : serene.tan@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509 8480, if you have received this message in error. Thank you.

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]

Sent: Monday, July 9, 2018 3:39 PM

To: Serene Tan <serene.tan@mneduco.com.sg>; Igene Lim <igene.lim@mneduco.com.sg>

Cc: Han, Bernard <Bernard.han@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: CMTD1802910/HCY - PRI/ ACCIDENT INVOLVING SJH6084H & SKR8602K ON 07.07.2018

Our Reference : CMTD1802910/HCY

Your Reference: MN/IG/B2/1812525/st

Date: 9th July 2018

Without Prejudice
EMAIL ONLY

Attention:
M/S M NEDUMARAN & CO

Dear Sir/ Madam,

ACCIDENT INVOLVING SJH6084H & SKR8602K ON 07.07.2018

We refer to your Notice of Accident dated 09/07/2018 via fax.

Kindly re-direct your future motor claims survey request to motorsurvey@sompo.com.sg

Please be informed that Lorriance Wong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

<image009.jpg>

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @ <image012.png> or <image011.png>

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies,

credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

MC-COY

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Billing Name & Address

SGM Hardware Pte Ltd
C/o No. 1 Kaki Bukit Avenue 6
#01-103 AutoBay @ Kaki Bukit
Singapore 417883

Invoice No 18018-07/AY

Date 2 Aug 2018

Vehicle No : SKR 8602 K

Model : Mitsubishi Colt Plus

Item	Descriptions	Amount S\$
1	Date of inspection : <u>11 Jul 2018</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Develop photographs - Storage of digital photographs - Submission of photographs <u>223</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 1098.00</u>
	SDLS : ONE THOUSAND AND NINETY-EIGHT ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Mc-Coy Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Report Reference : **TP / 18018-07/AY / 2018**
Date of Report : **2 Aug 2018**

SGM Hardware Pte Ltd
c/o No. 1 Kaki Bukit Avenue 6
#01-103 AutoBay @ Kaki Bukit
Singapore 417883

THIRD PARTY SURVEY
ACCIDENT HAPPENED ON 7 Jul 2018

Workshop Address : Boon Siong Vehicles Service
No.1 Kaki Bukit Avenue 6
#01-103 Auto Bay@Kaki Bukit
Singapore 417883

As per your instruction dated **11 Jul 2018** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SKR 8602 K**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No	: SKR 8602 K	Engine No	: 4A910015994
Model	: Mitsubishi Colt Plus	Mileage	: 213910
Year / Capacity	: 2006/1499	Colour	: Silver
Chassis No	: JMYLTZ23W5Z000698		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S	: 195/50R15	Falken	4.00 mm	Sport
REAR O/S	: 195/50R15	Falken	4.00 mm	Sport
FRONT N/S	: 195/50R15	Falken	4.00 mm	Sport
REAR N/S	: 195/50R15	Falken	4.00 mm	Sport



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 14 working days to complete.
5. Enclosed number of photograph : 223 copies.
6. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SKR 8602 K**
Report No: **TP/ 18018-07/AY / 2018**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>Nett Items</u>				
1	Rear windscreen moulding	Necessary	\$ 118.00	\$ — 118.00 NEC
1	Rear tailgate	Damage	\$ 855.00	\$ — 855.00 BUC
2	Rear tailgate dampers	Damage	\$ 292.00	\$ x 292.00 XNN
1	Rear tailgate inner trim board	Damage	\$ 245.00	\$ — 245.00 CRA
2	Rear tailgate lamps	Damage	\$ 378.00	\$ — 378.00 CRA
1	Rear tailgate lock	Damage	\$ 339.00	\$ — 339.00 BT
1	Rear tailgate logo	Necessary	\$ 40.00	\$ — 40.00 NEC
1	Rear tailgate outer handle	Damage	\$ 129.00	\$ — 129.00 CRA
1	Rear tailgate rubber	Necessary	\$ 145.00	\$ — 145.00 BT
1	Rear tailgate 'COLT' emblem	Necessary	\$ 28.00	\$ — 28.00 NEC
1	Rear tailgate 'PLUS' emblem	Necessary	\$ 26.00	\$ — 26.00 CRA
1	Rear tailgate 'C&C' emblem	Necessary	\$ 40.00	\$ — 40.00 DIS
1	Rear tailgate auto motor	Intact	\$ 296.00	\$ 11 x
1	Rear tailgate inner 'AUTO LOCK' switch	Damage	\$ 125.00	\$ — 125.00 Short
1	Rear tailgate lower moulding	Necessary	\$ 315.00	\$ — 315.00 BT
2	Rear taillamps	Damage	\$ 554.00	\$ — 554.00 CRA
1	Rear end panel outer	Damage	\$ 327.00	\$ — 327.00 BUC
1	Rear end panel inner garnish	Damage	\$ 179.00	\$ — 179.00 CRA
1	Rear end panel inner	Damage	\$ 245.00	\$ — 245.00 BUC
1	Rear bumper	Damage	\$ 586.00	\$ — 586.00 DD
2	Rear bumper reflectors RH-CRA, LH-NN	Damage	\$ 76.00	\$ 38 76.00 MC
2	Rear bumper side retainers	Damage	\$ 76.00	\$ — 76.00 DIS
1	Rear spare tyre board	Damage	\$ 175.00	\$ — 175.00 DIS
2	Rear spare tyre side boards	Damage	\$ 148.00	\$ x 148.00 XSVC
1	Rear spare tyre panel	Damage	\$ 856.00	\$ — 856.00 BUC
1	Rear spare tyre panel tray	Damage	\$ 182.00	\$ — 182.00 CRA
1	Rear n/s chassis	Damage	\$ 645.00	\$ R 645.00 XR
1	Rear exhaust silencer	Damage	\$ 410.00	\$ R 410.00 XR
2	Rear exhaust silencer mountings	Damage	\$ 56.00	\$ 11 56.00 DIS x
2	Rear fenders	Damage	\$ 1528.00	\$ — 1528.00 BUC
2	Rear fender inner garnishes	Damage	\$ 828.00	\$ 11 828.00 —
2	Rear fender quarter glass mouldings	Damage	\$ 620.00	\$ 11 620.00 XNN
2	Rear fender corner garnishes	Necessary	\$ 126.00	\$ 11 126.00 XSVC
2	Rear fender inner shields	Damage	\$ 76.00	\$ — 76.00 CRA
1	Rear seat (top)	Damage	\$ 880.00	\$ R 880.00 x
2	Rear doors	Repair	\$ 1376.00	\$
2	Rear door locks	Damage	\$ 548.00	\$ 11 548.00 XSVC

Nett Items Sub Total \$ 13868.00 \$ 12196.00

10%

Vehicle No: **SKR 8602 K**
 Report No: **TP/ 18018-07/AY / 2018**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
-----	-------------------	-----------	-----------------------	------------------------

Nett Items Total c/f \$ 13868.00 \$ 12196.00

Nett Items

\$ 13868.00 \$ 12196.00

Special Nett Items

1	Rear windscreen sealant	Necessary	\$ 60.00	\$ 40 60.00 NEC
1	Rear bumper clip (1 set)	Damage	\$ 28.00	\$ - 28.00 NEC
1	Rear number plate	Damage	\$ 60.00	\$ - 40 60.00 BT
1	Rear reverse sensor (1 set)	Damage	\$ 280.00	\$ 280 280.00 200
2	Rear fender quarter glass sealants	Damage	\$ 120.00	\$ - 80 120.00 NEC
			\$ 548.00	\$ 548.00

3768

Spare Parts Total \$ 14416.00 \$ 12744.00

Vehicle No: **SKR 8602 K**
 Report No: **TP/ 18018-07/AY / 2018**


LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 14416.00	\$ 12744.00
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 50.00	\$ 40.00 30
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 150.00	\$ 100.00 60
3	To remove and refit rear bumper sensor.	\$ 150.00	\$ 80.00 50
4	To remove and refit rear windscreen glass.	\$ 200.00	\$ 120.00 —
5	To remove and refit, straighten and re-adjust exhaust pipe and replace rear exhaust silencer and mountings.	\$ 150.00	\$ 80.00 70
6	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 2500.00	\$ 2200.00 1600
7	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 2500.00	\$ 1760.00 1300
8	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 350.00	\$ 210.00 150
Total		\$ 20466.00	\$ 17334.00

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 13900.00

SDLS: THIRTEEN THOUSAND NINE HUNDRED ONLY



 Qualified Appraiser

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref : CS3/SMO18012634/Uqbe2-1	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623			Date : 19-10-2018	
			Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJH 6084H		Veh. Inspected	SKR 8602K
Policy No.			Coverage (\$)	0.00
Claim No.	CMTD1802910/HCY		Excess (\$)	0.00
Assign From	BERNARD HAN		Assign Date	18/10/2018
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI COLTPLUS (A)		c.c	1499
Engine No.	HIDDEN		Year of Reg.	2006
Chassis No.	JMYLTZ23W5Z000698		Colour	SILVER
Odometer	213910		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R15	FALKEN	6 mm	
L/H Front Tyre	195/50 R15	FALKEN	6 mm	
R/H Rear Tyre	195/50 R15	FALKEN	6 mm	
L/H Rear Tyre	195/50 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/07/2018		Inspection Date	11/07/2018
Survey held at	BOON SIONG VEHICLE SERVICE BLK 1 KAKI BUKIT AVE 6 #01-103 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			14 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 8602K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING	NECESSARY	118.00	118.00
1	REAR TAILGATE	BUCKLED	855.00	855.00
2	REAR TAILGATE DAMPERS	NOT NECESSARY	292.00	-
1	REAR TAILGATE INNER TRIM BOARD	CRACKED	245.00	245.00
2	REAR TAILGATE LAMPS	CRACKED	378.00	378.00
1	REAR TAILGATE LOCK	BENT	339.00	339.00
1	REAR TAILGATE LOGO	NECESSARY	40.00	40.00
1	REAR TAILGATE OUTER HANDLE	CRACKED	129.00	129.00
1	REAR TAILGATE RUBBER	BENT	145.00	145.00
1	REAR TAILGATE 'COLT' EMBLEM	NECESSARY	28.00	28.00
1	REAR TAILGATE 'PLUS' EMBLEM	CRACKED	26.00	26.00
1	REAR TAILGATE 'C&C' EMBLEM	DISTORTED	40.00	40.00
1	REAR TAILGATE AUTO MOTOR	NOT NECESSARY	296.00	-
1	REAR TAILGATE INNER 'AUTO LOCK' SWITCH	SHORTED	125.00	125.00
1	REAR TAILGATE LOWER MOULDING	BENT	315.00	315.00
2	REAR TAILLAMPS	CRACKED	554.00	554.00
1	REAR END PANEL OUTER	BUCKLED	327.00	327.00
1	REAR END PANEL INNER GARNISH	CRACKED	179.00	179.00
1	REAR END PANEL INNER	BUCKLED	245.00	245.00
1	REAR BUMPER	DENTED	586.00	586.00
2	REAR BUMPER REFLECTORS	O/S CRACKED / N/S NOT NECESSARY	76.00	38.00
2	REAR BUMPER SIDE RETAINERS	DISTORTED	76.00	76.00
1	REAR SPARE TYRE BOARD	DISTORTED	175.00	175.00
2	REAR SPARE TYRE SIDE BOARDS	SERVICEABLE	148.00	-
1	REAR SPARE TYRE PANEL	BUCKLED	856.00	856.00
1	REAR SPARE TYRE PANEL TRAY	CRACKED	182.00	182.00
1	REAR N/S CHASSIS	TO REPAIR SEE LABOUR	645.00	-
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	410.00	-
2	REAR EXHAUST SILENCER MOUNTINGS	NOT NECESSARY	56.00	-
2	REAR FENDERS	BUCKLED	1,528.00	1,528.00
2	REAR FENDER INNER GARNISHES	TORN	828.00	828.00
2	REAR FENDER QUARTER GLASS MOULDINGS	NOT NECESSARY	620.00	-

Report Ref No. CS3/SMO18012634/Uqbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER CORNER GARNISHES	SERVICEABLE	126.00	-
2	REAR FENDER INNER SHIELDS	CRACKED	76.00	76.00
1	REAR SEAT (TOP)	TO REPAIR SEE LABOUR	880.00	-
2	REAR DOORS	TO REPAIR SEE LABOUR	1,376.00	-
2	REAR DOOR LOCKS	NOT NECESSARY	548.00	-
	LESS 10% DISCOUNT		-	-843.30
			13,868.00	7,589.70
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	28.00	28.00
1	REAR NUMBER PLATE (SN)	BENT	60.00	40.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
2	REAR FENDER QUARTER GLASS SEALANTS (SN)	NECESSARY	120.00	80.00
			548.00	388.00
	<u>LABOUR</u>			
	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.		50.00	30.00
	TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS.		150.00	60.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		150.00	50.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		200.00	120.00
	TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXHAUST SILENCER AND MOUNTINGS.		150.00	70.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF REAR N/S CHASSIS, REAR EXHAUST SILENCER, REAR SEAT (TOP) AND REAR DOORS.		2,500.00	1,600.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		2,500.00	1,300.00

Report Ref No. CS3/SMO18012634/Uqbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		350.00	150.00
			6,050.00	3,380.00
GRAND TOTAL			20,466.00	11,357.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,000.00

Report Ref No. CS3/SMO18012634/Uqbe2-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.