

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
computers@chinmeng.com.sg

Your Ref: TP claim against SMA9675J

18-Oct-18

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16
Singapore 409179

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimated cost of repair to Mazda 3 no: SLN2297G

Date of accident: 16-10-2018

Parts supply:

1 pc Headlamp R/h *lit*
1 pc Headlamp lower bracket R/h *new*
1 pc Headlamp panel R/h (front) *new*
1 pc Headlamp clips R/h *new*
1 pc Bonnet rubber (front) *new*
1 pc Bonnet rubber (centre) *new*
16pcs Bonnet rubber clips @\$3.50 *new*
1 pc Front R/h fender *new*
1 pc Front R/h fender inner shield *new*
8 pcs Front R/h fender inner shield clips @\$3.50 *new*
1 pc Front bumper *new*
2 pcs Front bumper retainers @\$38.60 *new*
2 pcs Front bumper brackets @\$65.90 *new*
1 pc Front bumper fog lamp R/h *new*
1 pc Front bumper fog lamp cover R/h *new*
1 pc Front bumper signal lamp R/h *new*
1 pc Front bumper inner garnish *new*
1 pc Front bumper reinforcement *new*
1 pc Front bumper lower grille *new*
12 pcs Front bumper clips @\$3.50 *new*
1 pc Front bumper nozzle unit R/h *new*
1 pc Front bumper nozzle cover R/h *new*
1 pc Front grille *new*
1 pc Front grille emblem *new*
10 pcs Front grille clips @\$3.50 *new*
2 pcs Front grille garnish (chrome) @\$351.80 *new*
1 pc Front support panel top garnish *new*
1 pc Front support panel (top) *new*

S/Nett Items

1 pc Front no. plate with cover (S/Nett) *new*

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.

To respray affected part.

To check wirings.

ESTIMATE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SS 2,357.50
35.80
186.30
10.00
50.70
52.70
56.00
350.60
102.80
28.00
1,084.30
77.20
131.80
369.80
48.80
165.20
98.40
564.20
89.50
42.00
255.60
89.30
610.70
46.50
35.00
703.60
351.80
130.20
8,124.10
Less 20%: (1,624.82)
45.00
1230

Supplementary: 151.60

total: 5764.32

L/S: 4-6K

05 days

Adrian King

L/S 18/10/18

05 days

900.00
1,000.00
30.00
SS 8,474.28

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Our Ref: EST321A/18/TP

Your Ref: TP claim against SMA9675J

ESTIMATE

18-Oct-18

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16
Singapore 409179

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Supplementary cost of repair to Mazda 3 no: SLN2297G

Date of accident: 16-10-2018

Parts supply:

1 pc Washer tank bracket *new*
1 pc Washer tank assy *del*

SS	98.50
	<u>189.50</u>
	288.00
Less 20%:	<u>(37.90)</u>
	<u>250.10</u>

189.5
151.60

Adrian
19/10/18.
sls