

REF: CS/CTU18019026 / 68bez

Special Instruction:

ASSIGNMENT (Office)

From (Person): Irene Tay of CTL Date/Time: 19.10.08
Estimated Cost: _____ Bill to: _____

4s: \$9000.00

Third Parties:

Claimant:

Surveyor: Autumn Survey

Workshop: Eng Soon Painting

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: FBH 905Z Insured: SLL 1736H

at Workshop m/s Eng Soon Painting Tel: 3937
of 81k & Yew Tee Ind Est

Policy No: _____ Claim No: 9M18D0132602

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 09-03-2018
(Client's Record)

(Client's Record)

22.10.2018 (Monday) @ 2pm

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 22/11 Confirmed with 25 Final Fig 24 days (Red \$ 1 / 1 %; Original 5 days)

Date/Time: 22/10 Submit Final Fig 2500, 4 days (Red \$6.500/172%; Original 5 days)

[illegible]

RECEIVED 24 OCT 2010

Para(1) : Parts found not replaced	(To highlight <i>R</i> or <i>UB</i> , <i>LR</i> , <i>Etc</i>)
------------------------------------	--

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)
--

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

<i>Fee Charged:</i>

Date: _____

Basic & Add

Transport

Photos

Others

Total

1) Date/Time _____ File Pass to _____

2) Date/Time

File Return to

3) Date/Time _____ File Pass to _____

4) Date/Time

File Return to

5) Date/Time _____ File Pass to _____

6) Date/Time

File Return to

Summary

REF:

CS/CTI/8019026/Gsb

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value:

\$4800

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

BBH9058

Yr Regn:

2012

Type: M/Car / M/Truck / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha FZ16

C.C.

153

Colour:

Red

A/C.

Insured / Std / NI / NA

Sp. Reading:

6406

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ME12 / COD102020589

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

100 / 80-17

R:

140 / 70 R 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

(Rear)

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

mm

D.O.A.

D.O.I.

22-10-18

Survey held at

w/s

2pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

and

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/10

No GIA

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Catherine Chong (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Friday, 19 October, 2018 9:34 AM
To: admin-d@lkkauto.com
Cc: bonnie kwok
Subject: CTP REF NO. SNM18D01326C02 & CO3 BK REF NO. BK.18613.18.ST - ACCIDENT INVOLVING SLL4726H AND FBH905Z ON 09 MARCH 2018
Attachments: 19102018093228.pdf

URGENT

Dear LKK (Catherine),

Please assist to get your surveyor to arrange with Bonnie Kwok on the Re-inspection.

Thank you.

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: bonnie kwok [mailto:litigation@bonniekwok.com]
Sent: Monday, 15 October, 2018 2:48 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Re-inspection: CTP REF NO. SNM18D04049C02 & CO3 BK REF NO. BK.18613.18.ST - ACCIDENT INVOLVING SLL4726H AND FBH905Z ON 09 MARCH 2018

Dear Irene,

We refer to our email dated 28 September 2018.

We notice that you did not reply to our said email.

Kindly have your surveyor attend at Blk 4 Yew Tee Ind Est 393-J Woodlands Road Singapore 677978 on **22 October 2018 at 2.00 p.m.** for the re-survey of our client's vehicle.

Kindly ensure that your surveyor attends punctually.

Kindly let us know which surveyor you have appointed so that we may inform our client accordingly.

Please let us have your offer of settlement as soon as possible.

Regards,
June

On Fri, 28 Sep 2018 at 17:27, bonnie kwok <litigation@bonniekwok.com> wrote:

Dear Irene,

We refer to your email dated 28 September 2018.

Kindly have your surveyor attend at Blk 4 Yew Tee Ind Est 393-J Woodlands Road Singapore 677978 on 15 October 2018 at 2.00 p.m. for the re-survey of our client's vehicle.

Kindly ensure that your surveyor attends punctually.

Kindly let us know which surveyor you have appointed so that we may inform our client accordingly.

Please let us have your offer of settlement as soon as possible.

Regards,
June

On Fri, 28 Sep 2018 at 11:37, Irene Tay <irene.tay@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above captioned matter and your letter dated 18 September 2018.

We are prepare to offer up to **10%** to resolve your client's injury claim and as for the property damage, we will wish to conduct a resurvey on your client's vehicle.

Kindly please revert.

Regards,

Irene Tay

Executive

Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6192

Fax (65) 62247478/62247175

Email: claimsdept@sg.cntaiping.com

www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

--

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Report Ref : TP18030021

Date: 14 June 2018

*Muhammad Azroy Bin Abdul Hamid
c/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969*

THIRD PARTY SURVEY
ACCIDENT OCCURED ON 09 March 2018

Workshop Name and Address

Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

As per your instruction dated 09 April 2018
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

with regard to the above matter.
FBH 905 Z

1. VEHICLE PARTICULARS

Registration No : FBH 905 Z
Model : YAMAHA FZ 16
Year / Capacity : 2012 / 153 cc
Chassis No : ME121C0D1D2020589

Engine No : 21CD020625
Mileage : n.a km
Colour : Multi colour

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT :	70/90/R17	Preilli	9.00 mm	Sport
REAR :	70/90/R17	Preilli	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the ALL portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 05 working days to complete

5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : FBH 905 Z

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
-----	-------------------	-----------	---------------------------------	------------------------------------

List Items

1 pc	Grip throttle	grazed/deformed	\$ 36.80	\$ 36.80 /
1 pc	Grip handle	bent/distorted	\$ 13.80	\$ 13.80 /
1 pc	Brake master cylinder assy	distorted	\$ 483.00	\$ 483.00 X NV
1 pc	Steering handle lever	bent/distorted	\$ 26.60	\$ 26.60 /
1 pc	Steering stem complete	dent/deformed	\$ 368.00	\$ 368.00 135
1 set	Front wheel fender	grazed/deformed	\$ 155.50	\$ 155.50 /
2 pcs	Front shock absorber assy	twisted/distorted	\$ 744.90	\$ 744.90 560
1 pc	Front brake caliper assy	malfunction	\$ 389.90	\$ 389.90 X NV
1 pc	Front rim	wrapped	\$ 424.30	\$ 424.30 300 (SV)
1 pc	Front brake disc	wrapped/distorted	\$ 109.25	\$ 109.25 /
1 pc	Fuel tank assy	dent/distorted	\$ 199.80	\$ 199.80 X Repair
1 pc	Seat assy (double)	grazed/deformed	\$ 332.50	\$ 332.50 X NV
1 set	Cover set inner front body	cracked/deformed	\$ 64.50	\$ 64.50 /
1 pc	Kick start arm assy	bent/distorted	\$ 111.15	\$ 111.15 X
1 pc	Brake pedal complete	bent/distorted	\$ 77.00	\$ 77.00 X
1 pc	Step bar complete	dent/deformed	\$ 115.50	\$ 115.50 X NV
2 pcs	Front rubber step	torn/deformed	\$ 33.80	\$ 33.80 X
1 pc	Headlamp complete	malfunction	\$ 378.65	\$ 378.65 250

Vehicle Number : FBH 905 Z

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
-----	-------------------	-----------	--------------------------	-----------------------------

List Items

1 pc	Ignition key set	malfunction	\$ 158.50	\$ 158.50 X NN
1 pc	Body frame assy	deformed - repair	\$ 1,559.40	\$ -
1 pc	Speedometer assy complete	malfunction	\$ 306.60	\$ 306.60 /
1 pc	Steering handle pipe complete	bent/distorted	\$ 155.80	\$ 155.80 /
1 set	Complete steering cover handle	grazed/deformed	\$ 386.90	\$ 386.90 200
1 pc	Switch starter	malfunction	\$ 25.20	\$ 25.20 X
1 pc	Switch dimer	malfunction	\$ 35.50	\$ 35.50 X NN
1 pc	Switch horn	malfunction	\$ 35.50	\$ 35.50 X
1 pc	Switch winker	malfunction	\$ 35.50	\$ 35.50 X
2 pcs	Side mirror assy	grazed/deformed	\$ 110.80	\$ 110.80 /
2 pcs	Winker assy	grazed/deformed	\$ 284.85	\$ 284.85 X NN
1 pc	Front top cover assy with windshield	distorted/deformed	\$ 457.80	\$ 457.80 155
2 pcs	Front headlamp outer cover	distorted/deformed	\$ 135.20	\$ 135.20 X NN
Parts Sub-Total			\$ 7,752.50	\$ 6,193.10 279.65
Discount 10.00%			\$ 775.25	\$ 619.31
			\$ 6,977.25	\$ 5,573.79 2051.68

Vehicle Number : FBH 905 Z

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
-----	-------------------	-----------	--------------------------	-----------------------------

Special Nett Items

2 pcs	Number plate	distorted	\$ 90.00	\$ 90.00 15
2 blts	Fork oil	Necessary	\$ 45.00	\$ 45.00 /
1 pc	Meter cable	grazed/cut	\$ 50.00	\$ 50.00 X
1 pc	Throttle cable	grazed/cut	\$ 50.00	\$ 50.00 X
2 pcs	Hose/Pipe	deformed	\$ 82.00	\$ 82.00 X
1 pc	Horn assy	dent/ open circuit	\$ 35.00	\$ 35.00 X
1 pc	Tyre	deformed	\$ 200.00	\$ 200.00 X NN
1 pc	Gasket	Necessary	\$ 32.00	\$ 32.00 X
1 pc	Spark plug	electronically shocked	\$ 19.50	\$ 19.50 X
1 pc	Brake pad	damaged	\$ 24.00	\$ 224.00 X
1 pc	Exhaust assy	distorted	\$ 1,850.00	\$ 1,850.00 X
Special Nett Sub-Total			\$ 2,477.50	\$ 2,677.50
Spare Parts Total			\$ 9,454.75	\$ 8,251.29 60


LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
------	------------------	---------------------------------	------------------------------------

	Spare Parts	Total c/f	\$ 9,454.75	\$ 8,251.29
1	Labour charges to repair and panel beat body frame structure cutting/welding and replacing the above mentioned parts.	\$ 1,800.00	\$ 1,600.00	250
2	Transport	\$ 120.00	\$ 120.00	80
3	To replace wiring harness system incl checking	\$ 180.00	\$ 150.00	X } NN
4	To tuff coat affected areas	\$ 150.00	\$ 120.00	X } NN
5	To respray affected areas	\$ 1,400.00	\$ 1,200.00	400
6	Bleed brake system	\$ 100.00	\$ 120.00	X NN
	Total	\$ 13,204.75	\$ 11,561.29	730

The repairer has agreed to undertake the repair under a Sum Basis. We have further adjusted the amount to Sum Repair of

\$ 9,000.00


Fong Kok Heng
Qualified Appraiser



3141.68

20% : 2500

ENG SOON PAINTING SERVICES

Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677978
Tel: 6760 6271 Fax: 6764 6676

MUHAMMAD AZROY BIN ABDUL HAMID
BLK 613 CHOA CHU KANG STREET 62
#07-225
SINGAPORE 680613

DATE: 14/06/18

DEAR SIRs

ACCIDENT DATE: 09/03/18
FINAL REPAIR BILL TO FBH 905 Z

LUMP SUM REPAIRS RECOMMENDED
BY THE SURVEYOR-----\$ 9,000.00

DOLLARS: NINE THOUSAND ONLY



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18019026/Gsbe2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 25-10-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SLL 4726H	Veh. Inspected	FBH 905Z
Policy No.		Coverage (\$)	0.00
Claim No.	SNM18D01326C02	Excess (\$)	0.00
Assign From	IRENE TAY	Assign Date	19/10/2018

2. Vehicle Particulars & Condition

Make & Model	YAMAHA FZ 16	c.c	153
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	ME121C0D1D2020589	Colour	RED
Odometer	6406	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	100/80-17	DUNLOP	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70 R17	MICHELIN	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.
REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	09/03/2018	Inspection Date	22/10/2018
Survey held at	ENG SOON PAINTING SVC BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 905Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	GRIP THROTTLE	REPLACED	36.80	36.80
1	GRIP HANDLE	REPLACED	13.80	13.80
1	BRAKE MASTER CYLINDER ASSY	NOT NECESSARY	483.00	-
1	STEERING HANDLE LEVER	REPLACED	26.60	26.60
1	STEERING STEM COMPLETE	REPLACED	368.00	135.00
1	SET FRONT WHEEL FENDER	REPLACED	155.50	155.50
2	FRONT SHOCK ABSORBER ASSY	REPLACED	744.90	560.00
1	FRONT BRAKE CALIPER ASSY	NOT NECESSARY	389.90	-
1	FRONT BRAKE DISC	REPLACED	109.25	109.25
1	FUEL TANK ASSY	REPAIRED SEE LABOUR	199.80	-
1	SEAT ASSY (DOUBLE)	NOT NECESSARY	332.50	-
1	SET COVER SET INNER FRONT BODY	REPLACED	64.50	64.50
1	KICK START ARM ASSY	NOT NECESSARY	111.15	-
1	BRAKE PEDAL COMPLETE	NOT NECESSARY	77.00	-
1	STEP BAR COMPLETE	NOT NECESSARY	115.50	-
2	FRONT RUBBER STEP	NOT NECESSARY	33.80	-
1	HEADLAMP COMPLETE	REPLACED	378.65	250.00
1	SET IGNITION KEY	NOT NECESSARY	158.50	-
1	BODY FRAME ASSY	REPAIRED SEE LABOUR	1,559.40	-
1	SPEEDMETER ASSY COMPLETE	REPLACED	306.60	306.60
1	STEERING HANDLE PIPE COMPLETE	REPLACED	155.80	155.80
1	SET COMPLETE STEERING COVER HANDLE	REPLACED	386.90	200.00
1	SWITCH STARTER	NOT NECESSARY	25.20	-
1	SWITCH DIMER	NOT NECESSARY	35.50	-
1	SWITCH HORN	NOT NECESSARY	35.50	-
1	SWITCH WINKER	NOT NECESSARY	35.50	-
2	SIDE MIRROR ASSY	REPLACED	110.80	110.80
2	WINKER ASSY	NOT NECESSARY	284.85	-
1	FRONT TOP COVER ASSY WITH WINDSHIELD	REPLACED	457.80	155.00

Report Ref No. CS/CT18019026/Gsbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT HEADLAMP OUTER COVER	NOT NECESSARY	135.20	-
	LESS 10% DISCOUNT		-732.82	-227.97
			6,595.38	2,051.68
1	FRONT RIM (SN)	REPLACED	424.30	300.00
	LESS 10% DISCOUNT		-42.43	-
			381.87	300.00
	<u>SPECIAL NETT ITEMS</u>			
2	NUMBER PLATE (SN)	REPLACED	90.00	15.00
2	BLTS FORK OIL (SN)	REPLACED	45.00	45.00
1	METER CABLE (SN)	NOT NECESSARY	50.00	-
1	THROTTLE CABLE (SN)	NOT NECESSARY	50.00	-
2	HOSE / PIPE (SN)	NOT NECESSARY	82.00	-
1	HORN ASSY (SN)	NOT NECESSARY	35.00	-
1	TYRE (SN)	NOT NECESSARY	200.00	-
1	GASKET (SN)	NOT NECESSARY	32.00	-
1	SPARK PLUG (SN)	NOT NECESSARY	19.50	-
1	BRAKE PAD (SN)	NOT NECESSARY	24.00	-
1	EXHAUST ASSY (SN)	NOT NECESSARY	1,850.00	-
			2,477.50	60.00
	<u>LABOUR</u>			
	LABOUR CHARGES TO REPAIR AND PANEL BEAT BODY FRAME STRUCTURE CUTTING / WELDING AND REPLACING THE ABOVE MENTIONED PARTS. INCLUSIVE OF THE REPAIR OF FUEL TANK ASSY AND BODY FRAME ASSY.		1,800.00	250.00
	TRANSPORT.		120.00	80.00
	TO REPLACE WIRING HARNESS SYSTEM INCL CHECKING.	NOT NECESSARY	180.00	-
	TO TUFF COAT AFFECTED AREAS.	NOT NECESSARY	150.00	-
	TO RESPRAY AFFECTED AREAS.		1,400.00	400.00
	BLEED BRAKE SYSTEM.	NOT NECESSARY	100.00	-
			3,750.00	730.00

Report Ref No. CS/CT118019026/Gsbe2



GRAND TOTAL		13,204.75	3,141.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,500.00

Report Ref No. CS/CT118019026/Gsbe2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.