

PDI TUAS

PDI TUAS

SIAH TENG SIA
17 WOODLANDS AVENUE 6
#08-17
Singapore, 738997
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV041327
Quote No. SER/QUO/1801750
QuoteDate 18/10/18
Salesperson Delsie Ong
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Golf 1.0 TSI 81 kW Trendline	0	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SJM3611E	WVWZZZAUZJW257999	26/07/18	Delsie Ong
Engine Code	Labor Type	Engine No.	Model Code
	1T	CHZ 474272	BQ12AZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P MACP LABOUR	LABOUR	5	UNIT		1680 4,200.00
P B&P MACP PAINT	SPRAY PAINT	4	UNIT		1600 3,200.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		480.00
P B&P MECH	CHECK WIRE HARNESS, ECU, S Nett	1	Time Un		280.00
P B&P MECH	R&R RIM & BALANCE Nett	1	Time Un		50.00
P B&P WHEEL ALIGNMENT	B&P WHEEL ALIGNMENT NETT Sum Labor	1	Time Un		360.00 8,570.00
P 311601361	RUBBER VALVE <i>nee</i> Use Predecessor 281601361	1	Pieces		2.29
P 5G0073146B 8Z8	ALLOY WHEEL 16" HITA <i>scr</i>	1	Pieces		1,044.23
P 5G0807049B	LHF BUMPER BRACKET <i>X</i>	1	Pieces		24.70
P 5G0807050B	RHF BUMPER BRACKET <i>nee</i>	1	Pieces		24.70
P 5G0807217FNGRU	FRT BUMPER <i>scr</i>	1	Pieces		1,041.59
P 5G0807723F	LHF BUMPER INNER BRACKET <i>3X</i>	1	Pieces		58.70
P 5G0807724F	RHF BUMPER INNER BRACKET <i>?</i>	1	Pieces		62.28
P 5G0821106B	RHF FENDER <i>BT</i>	1	Pieces		626.55
P 5G0821136C	RHF FENDER BRACKET <i>nee</i>	1	Pieces		35.44
P 5G0853211G 9B9	LHF VENT GRILLE <i>?</i>	1	Pieces		35.68
P 5G0853665L 9B9	LHF VENT GRILLE MOULDING <i>?</i>	1	Pieces		82.09
P 5G0853665N 9B9	LHF VENT GRILLE MOULDING <i>?</i>	1	Pieces		82.09
P N 90817302	NUT <i>?</i>	4	Pieces		6.20
Sum carried forward					11,696.54

Payments to:

- BBN: - Acc.-No...:

PDI TUAS

PDI TUAS

SIAH TENG SIA
17 WOODLANDS AVENUE 6
#08-17
Singapore, 738997
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV041327
Quote No. SER/QUO/1801750
QuoteDate 18/10/18
Salesperson Delsie Ong
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Golf 1.0 TSI 81 kW Trendline	0	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SJM3611E	WVWZZZAUZJW257999	26/07/18	Delsie Ong
Engine Code	Labor Type	Engine No.	Model Code
	1T	CHZ 474272	BQ12AZ
Continued			11,696.54
Sum Item			3,126.54
Sum Labor			8,570.00
Sum Item			3,126.54
Total SGD			11,696.54
7% GST			11,696.54 818.76
Total SGD Incl. GST			12,515.30

Explanations

P = Proportionately Charged

Payment Terms No Credit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Payments to: - BBN: - Acc.-No...:

Paul
Hp 90010068
5 days
23/10/18 @ 1630
Resurvey by part