



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6881 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg No. 198003963G

Page 1 / 2

ESTIMATE

Date	: 18/10/2018	Reg No	: YN6750J
To	: INDIA INTERNATIONAL INSURANCE PTE LTD	Model	: FM65FM2RDEB C/C
Attn.	:	Chassis No	: FM65FMA10118
Office / Mobile	:	Engine No	: 6M60194440
Email Address	:	Quotation No.	: 73977
		Ref. No.	: GBE/SVC/SALES-4708/181018
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 13/06/2018
Attn.	: LILEWEI	Policy No.	: M496479
Office / Mobile	: +65 6864 0637	Claim Type	: TP CLAIM - III
Email / Fax No.	: LiLewei@goldbell.com.sg	Workshop	: 29 TANJONG PENJURU

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1	MX915944	LAMP, LICENSE PLATE <i>1pc</i>	2	66.98	-25	50.24	100.47
PARTS TOTAL :							100.47

SPECIAL NETT ITEMS

1	REAR BUMPER	1	600	950.00	/
2	REAR BUMPER BRACKET LHS	1		250.00	X
3	REAR NUMBER PLATE	1	10	20.00	/
PARTS TOTAL:				1220.00	

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	600	1200.00
2	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTIC CHECK	180	280.00
3	TO PUTTY, CLEAN, SPRAY PAINT, ETC.	250	400.00
4	SUNDRIES	1040	30.00
LABOUR TOTAL :			1,910.00

SUB-TOTAL : 3,230.47
GST @ 7% for \$ 3,230.47 226.13
GRAND TOTAL (S\$) : 3,456.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2 Days. 1700.28
part by part.
Before paint photos.
After paint photos.
23/10/18

