PMINEAUL.	HUMAN.		ASSIGNM	ENT (Office)	
From (Person	: Frankie T	Λαγ	of	SPF	Date/Time: 9.10.2018
Estimated Cos	st:	_		Bill to:	
To Inspect Ve	S / TP RES / OD I	SK	ik 6089s	es.	Insured: Ablic Hability
at Workshop i	m/s	SM	Automotive		Tel:
of		BK 1	Kaki Bukit	Ave 6 #01	-43
Policy No:				Claim No:	AEMO/105/009/2018/146
Sum Insured:				Excess:	
Make of Veh: (Client's Record	the same of the sa				D.O.A. 01-102018
CA / REV .	/ REP. / REV 24 1.107018 942am	HRS'W	rson Contacted:	Sukyi	H.O.D. Endorsement:
Date/Time: 1	1.102018 942am	1Pe	rson Contacted:	2	Vehicle (N) OUT
Date/Time: 1	Action/Instruction	1 Pe	rson Contacted:	2	H.O.D. Endorsement: Vehicle IN OUT
Date/Time: 1	Action/Instruction SKK U893 -	1 Pe	rson Contacted:	2	Vehicle (N) OUT
CA / REV / Date/Time: Date/Time	Action/Instruction SKK U893 -	1 Pe	rson Contacted:	2	Vehicle (N) OUT
Date/Time: 1	Action/Instruction SKK U895 - Public Liubility	1 Pe	rson Contacted:) Estimate	2	Vehicle (N) OUT

ASSIGNMENT

13.503	I
From. Date	Veh No. SKK 60895 . Yr Regn. 2013 August.
Estimated Cost	Type M.Cap/ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make. Hyundui Tucson a.c 1988
at Workshop m/s	Make Hyundui Tucson at 1888 Golour Silver. A/C: Insured/Std/NI/NA
of	Sp.Reading 13060 / T/Radio: Insured / Std / NI / NA
Insured	Eng/No:
Policy No.	C/No: KMH JU818MDU 7.76997
Claims No.	Gen. Cond. Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Lorder / Jammed / Leaked / Burnt or
Make of Veh	Modi Nil /S/Rim / STD A/Rim or
	Tyre Size: F: 225/55 R18 -
(Policy Condition)	R: 225/55 R18.
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Continental.
Bal. or Market Value.	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 06 mm R/Bal. 06 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 96 mm L/Bal. 06 mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 19/10/18
Lum Sum: % 3 Val.: Yes or No	Survey held at SM -
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN/OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction TP SPF MV 1 56 K. RECE Nett : 10.2 K.	WED 1 1 DEC 2018
Preli. Report : Preli. Report : Final Report : Cate/Time, File Return to? : Add Fee	Interview (\$) Photos Tech Invs (\$) Others
Lump Sum / I.B.I: (\$ 8571.444	Weekend (\$)
	TOTAL



Your Ref

: SKK6089S

Our Ref

: AEMD/105/009/2018/146

Tel: 64784841

Fax: 64784848

Date

: 19 Oct 2018

LKK Auto Consultants Pte Ltd Paya Ubi Industrial Park 51 Ubi Avenue 1 # 01/02-25 Singapore 408933

Via Fax only: 62564315

SPF Accidents Claims Section

Police Logistics Department No. 1 Mount Pleasant Road Block 8 Old Police Academy #02-12 Singapore 298333

Automotive Engg & Mgmt Div

Dear Sir,

2

3

ACCIDENT INVOLVING GOVENMENT ANTI-CRASH BARRIER AND MOTOR VEHICLE SKK6089S ON 01 OCTOBER 2018

We refer to the above matter.

Kindly arrange for a Pre-Repair Inspection for Vehicle SKK6089S at M/s SM Automotive, 1 kaki Bukit Ave 6, #01-43 Blk C @ Autobay, Singapore 417833.

Please contact Reena/Sukyi at 67479241 for appointment.

Thank you.

Yours faithfully,

3/

Frankie Thay
Safe Driving Manager
for ASSISTANT DIRECTOR

A FORCE FOR THE NATION

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

7100F

Vehicle Details

Vehicle No.:

SKK6089S

Vehicle to be Exported:

No

Intended Deregistration Date:

18 Oct 2018

Vehicle Make:

HYUNDAI

Vehicle Model:

LM TUCSON 2.0L AUTO ABS

D/AB SR

Primary Colour:

Grey

Manufacturing Year:

2013

Engine No.:

G4KDDU124803

Chassis No.:

KMHJU81BMDU776997

Maximum Power Output: Open Market Value: 122.0 kW (163 bhp) \$19,500.00

Original Registration Date:

04 4 - 2012

Original Registration Date:

06 Aug 2013

First Registration Date:

06 Aug 2013

Transfer Count:

0

Actual ARF Paid:

\$19,500.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

05 Aug 2023

PARF Rebate Amount:

\$13,650.00

Intended COE Rebate Details

COE Expiry Date:

05 Aug 2023

COE Category:

B - Car (1601cc & above)

COE Period(Years):

10

QP Paid:

\$67,010.00

COE Rebate Amount:

\$32,153.00

Total Rebate Amount:

\$45,803.00

The information contained herein is correct as at 18 Oct 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars Owner ID Type:	Singapore NRIC
Owner ID:	7100F
Vehicle Details	/100F
Vehicle No.:	SKK6089S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	19 Oct 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	LM TUCSON 2.0L AUTO ABS D/AB SR
Primary Colour:	Grey
Manufacturing Year:	2013
Engine No.:	G4KDDU124803
Chassis No.:	KMHJU81BMDU776997
Maximum Power Output:	122.0 kW (163 bhp)
Open Market Value:	\$19,500.00
Original Registration Date:	
First Registration Date:	06 Aug 2013
Transfer Count:	06 Aug 2013 0
Actual ARF Paid:	T
Intended PARF Rebate Details	\$19,500.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Aug 2023
PARF Rebate Amount:	\$13,650.00
Intended COE Rebate Details	\$15,550.00
COE Expiry Date:	05 Aug 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$67,010.00
COE Rebate Amount:	\$32,135.00
Total Rebate Amount:	\$45,785.00
information contained herein is correct as at 19 Oct 2018	

Veron Chen (LKKAuto)

From:

Sent:		October 2018 5:40 PM
To:	Admin-D (LK	
Subject: Attachments:		S CLAIMING AGAINST ANTI-CRASH BARRIER (SPF) DOA:01.10.18 MENDED GIA.pdf
Attachments:	3KK00033 AI	VIENDED GIA.pui
Best Regards,		
Shu Pei Admin		
LKK Auto Consultants Pte Ltd		
Phone: 6366-0055 email: shupei@lkka	uto.com fax: 67	41-4108
Blk 51, Paya Ubi Industrial Park, Ubi Aver	nue 1, #02-25 S	(408933)
From: Admin nht <admin@nhtm< th=""><td></td><td></td></admin@nhtm<>		
Sent: Thursday, 25 October 2018 To: Admin A <admin-a@lkkauto.< th=""><td></td><td></td></admin-a@lkkauto.<>		
Cc: Chloe <chloe@nhtmotor.com< th=""><td></td><td></td></chloe@nhtmotor.com<>		
Subject: SKK6089S CLAIMING AG	AINST ANTI-C	RASH BARRIER (SPF) DOA:01.10.18
Without Prejudice		
Hi all		
Enclosed amended GIA for your r	reference.	
Please ignore previously GIA, the	re was amend	led of the action to be taken,thanks.
		x
Best Regards,		
Sukyi		
NEW HOCK TECK MOTOR P 1 Kaki Bukit Ave 6 Blk C #01-43 Autobay@Kal Tel: 6747 9241 Fax: 6741 7276	TE. LTD. ki Bukit S(417883)	
×		
×		
	11	

Shu Pei (LKKAuto)

MNII18128233-01 / NTUC Income Insurance Co-operative Ltd - HQ ENTRY DATE & TIME: 03/10/2018 13:01 SUBMITTED BY: Joreen Ang

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Fax Number

Contact Number EMail Address

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	03/10/2018 13:01
Date Of Accident	01/10/2018 13:55
Exact Location Of Accident	ENTRANCE OF WOODLANDS DIVISION NO1 WOODLANDS ST 12
Country/State of Loss	SINGAPORE
D	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKK6089S
Insured/Policyholder	
Name Of Registered Owner	SAJALI BIN SATARI
NRIC No	S1447100F
Email Address	SAJALI_SATARI@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91000279
Alternative Phone No	OTHERS-91000279
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	TUCSON
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5061148182-05
Cover Note Number	
Driver	
Name of Driver	SAJALI BIN SATARI
NRIC No	S1447100F
Date Of Birth	04/06/1960
Occupation	INDOOR
Date Of Driving Pass	11/03/1978
Driving Experience	40 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91000279

OTHERS-91000279

SAJALI_SATARI@HOTMAIL.COM

Address

BLK 865 #03-311

WOODLANDS STREET 83

Postcode

730865

OWNER

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLIDED INTO PROPERTY

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

NO

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

JURONG POLICE DIVISIONAL HQ ('J' DIVISION)

Police Station Address

ROAD: NO. 2 JURONG WEST AVENUE 5, POSTCODE: 649482,

COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-7910000 - FAX NO: 68965649

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

On 1 Oct 2018 at about 1.55 pm. I drove slowly my car SKK6089S, Hyundai/ Tucson/ Grey into the main entrance of Woodlands Division to unload my boxes of belongings from NPPK. I am in the midst of carrying my belongings from NPPK to our new Division. Prior to this, I have sought permission from Mr Omar to enter the premise. I then turned left and was stopped by SC Nuriman, along the said driveway, 5 to 6 metres from the anti-crash barrier which is lowered for the vehicle to pass through. After checking, Mr Nuriman, signalled and permitted me to drive through. Shortly, when I was near the anti-crash barrier my car had onto something. I stopped and realized that anti-barrier was in raised position and my car was in contact with the said barrier. SC Nuriman then told me that his colleague had wrongly pressed the button caused the said barrier to raise. The front bonnet and bumper were considerably damaged. The left front headlight broken.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

Sketch Plan

No Sketch Available



1.012

Report No J/2018100177008

Status Duny No.

Publice Statum Of Origin Jurang Police Divisional HG 2 Jurang West Avenue 5 SINGAPORE 649492 Tel No.1800-7910089 Departme Report Made

Data/Time Report Made
01/10/2018 20:41
Name Of Informent Appress
Appress
Appress

SAJALI BIN SATARI SING
IO Type / IO No. Conte
NRIC NO / \$1447100F Home

Nationally
SINGAPORE CITIZEN
Occupation
Division Losistic Officer I. Div
Institution/School Name

Date/Time Of Incident 01/10/2018 13:55 - 01/10/2018 14:00 Aptress
APT BLK 865 WOODLANDS STREET 83 #03-313
SINGAPORE 730965
Conted No.
Homo/Office: Mobile:
91060279

Sex Age Date of Birth Race

Male 58 04/08/1960 Malay

Language

English
Lecallor Of Incident
APT BLK 865 WOODLANDS STREET 83 #03-311
SINGAPORE 730865

Brief details.

On 1 October 2018 at about 1.55pm, I drove slowly my car SKKB0895, Hyundet Tucson! Grey into the main entrance of Woodland's Division (No. 1 Woodlands Street 12) to unload my boxes of belongings from NPPK. I am in the midst of carrying my belongings from NPPK to que new division. Prior to this, I have sought concurrence form OC Security, Mr Omar, to enter the premise. I then tuned left and was slopped by SC Numan, along the said driveway, about 5 to 6 metres away from the anti-crash barrier which is lowered for the vehicle to pass through.

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:
Not applicable

Signature Of Informant.
The identity of the person making this report has been authenticated by SingPass. No signature is required.


Date/Time: 01/10/2018 20:41

Classification Of Case:

Authentication Stamp

Officer In-Charge Of Case:





2 613

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20181001/7066

After checking, SC Nuriman, signalled and permitted me to drive through. Shortly, when I was somewhere near the anti-crash barrier, the front part of my car had collided onto something. Immediately, I stopped and realised that the anti-crash barrier which was planted across the road was in a raised position and my car was in contact with it.

SC Nuriman, then told me that his colleague, SC Chan, had wrongly pressed the button that caused the anti-crash barrier to raise into my path.

At the time of incident, the weather was fine, road surface was dry and visibility was clear. No one was injured at the time of socident.

The front bonnet and bumper were considerably damaged. The left front headlight broken.

Subjects Involve	ed		
Suspect			
Person Name	Chan Zi Hao		
Gender	Male		
	10 10 10 10 10 10 10 10 10 10 10 10 10 1	Mark Balletin	7/12 3 1 1 1
Victim	THE REPORT OF THE PARTY OF THE		
Person Name	SAJALI BIN SATARI		
ID Type	NRIC NO	ID No	S1447100F
Gender	Male	Age	58
Race	Malay	Language	English
Occupation	Division Logistic Officer L Div	Address Type	
ddress	APT BLK 865 WOODLANDS	Mobile No	91000279
	STREET 83 #03-311		
	SINGAPORE 730865		


Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 01/10/2018 20:41
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp

le bitorna	ank A Yes		
Vertru?	eme (SAJALI BIN SATARI (Informant)		
Not spi	re Of Officer Recording The Report: bicable re Of Interpreter: bicable	Signature Of Informant: The Identity of the person tricking this report has been aumorbitalish by SingPeas. No eignature is required. Date/Time: U1(10)2018 20:41	
Not sp Signate Not sp		Signature Of Informant: The Identity of the person tracking this report has been a menticaled by SingPrass. No eignature is required. Date/Time: U1(10)2018 20:41 Classification Of Case:	














Character.	COMPAN. SECRETAR STANDARD OF AS CONCRETE MERCHANISM WAS CONCRETE SECRETAR WAS CONTRACT LAND OF CONCRETAR AS CONCRETAR MERCHANISM WAS CONTRACT. THE WAS CONTRACT OF THE WAS CONTRACT. THE WAS CONTRACT OF THE WAS CONTRACT.
MEDITALISTIC P	Percentilist the supported Advances from the Same April 1990 System of Carties and Same Appropriate System of Carties and Same Same Same Same Same Same Same Same
	ACCINDUM
Grand Approximation	Portugated of the good of the
Linguist margin is may have the forese	CHANADON/ANGRACONIS
junal of	They have
- Asi	Total Section

SM &UTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883 Email: SM_AUTOMOTIVE@HOTMAIL.COM Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6 # 01-43 Singapore 417883 19/10/2018

KMI+J481BMD4776897

Accident date: 01/10/2018

Estimated repair cost for vehicle no: SKK6089S HYUNDAI TUCSON 2.0 A '13

CHASSIS: KMHJU81BMDU776997

		CHASSIS. KIVIHJUOI BIVIDU / / 033/		
S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Front Bonnet Dewled		\$1,430.80
2	2	Front Bonnet Hinge Bent	\$70.60	\$141.20
3	1	Front Bonnet Insulator 2		\$153.80
4	10	Front Bonnet Insulator Clip	\$6.50	\$65.00 🖟
5	1	Front Bonnet Inner Rubber		\$42.00
6	1	Front Bonnet Top Lock Dod.		\$65.80
7	1	Front Bonnet Lock Cover 2 M		\$35.60 +
8	4	Front Bonnet Lock Cover Clip	\$6.50	\$26.00
9	2	Front Head Lamp Cauleed -	\$854.80	\$1,709.60
10	2	Front Head Lamp Lower Bracket Bend	\$45.20	\$90.40
11	1	Front Bumper Deland		\$765.80
12	10	Front Bumper Clip / /	\$6.50	\$65.00 3 2
13	2	Front Bumper Side Retainer	\$42.00	\$84.00
14	2	Fornt Bumper Fog Lamp He M	\$183.00	\$366.00 ×
15	1	Front Bumper Number Plate		\$50.00
16	1	Front Bumper Towing Cover >H M		\$35.00 ×
17	1	Front Bumper Inner Sponge		\$65.80
18	1	Front Bumper Reinforcement		\$528.60
19	1	Front Bumper Lower Spoiler (Black)		\$280.00
20	1	Front Grille Could		\$193.80
21	1	Front Grille Emblem Logo		\$35.80
22	1	Front Grille Emblem Top Cover (Black)		\$65.00
23	1	Front Grille Chrome and		\$184.80
24	2	Front Grille Side Chrome	\$95.00	\$190.00
25	1	Front Grille Lower (Black) De Lo		\$184.80
26	2	Front Fender LIT Buelcled	\$491.80	\$983.60-48/-80
27	2	Front Fender Cowling 7 M	\$85.80	\$171.60
28	16	Front Fender Cowling Clip	\$6.50	\$104.00
29	1	Front Support Panel Crulica		\$885.00

30	1	Front Support Panel Lock	2		\$145.00
31	2	Front Support Panel Side Air Duct Cover	10	\$45.00	\$90.00
32	8	Front Support Panel Side Air Duct Cover Clip		\$6.50	\$52.00
33	1	Front Support Panel Air Cleaner Air Duct			\$78.60
34	2	Front Horn		\$72.00	\$144.00
35	1	Front Air-Con Condenser Bent			\$853.80
36	1	Front Radiator 7 hl sh	_		\$1,815.80
37	1	Front Radiator Fan Motor Assy			\$455.80

662144

Subtotal:- \$12,633.80

Labour charges

To remove & refit air-con condenser, radiator, fan motor & top up gas

\$380.00 120

Tuff kote

To check wiring

Panel beating

Spray painting

1950

\$150.00 🛧

\$100:00 30

\$1,400.00

\$1,400.00

Subtotal:-

\$3,430.00

Total:- \$16,063.80

LKK Asia Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged partis) during resurvey
- Pans prices are subject to confirmation
- Third party survey is on a "Wift" on added basis
- No illegal modification(s) is a:
- Surplementary items i must be result eyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

total: 8571.44 (P/A)

OT Days.
Range: 8:516-516



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale	Des Experts En Automobile
---	---------------------------

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref: CS/SPF18019034/Avbe2

ACCIDENT CLAIM SECTION(SINGAPORE POLICE

FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD

POLICE ACADEMYSINGAPORE 298333

Accident Date

01/10/2018

ESTIMATED NORMAL PERIOD FOR REPAIR:

Survey held at SM AUTOMOTIVE

Date: 11-12-2018

1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SKK 6089S	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	AEMD/105/009/2018/146	Excess (\$)	0.00	
	Assign From	FRANKIE THAY	Assign Date	19/10/2018	
2.		Vehicle Pa	rticulars & Condition		
	Make & Model	HYUNDAI TUCSON	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	KMHJU81BMDU776997	Colour	SILVER	
	Odometer	130601	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.		Con	ditions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	225/55 R18	CONTINENTAL	6 mm	
	L/H Front Tyre	225/55 R18	CONTINENTAL	6 mm	
	R/H Rear Tyre	225/55 R18	CONTINENTAL	6 mm	
	L/H Rear Tyre	225/55 R18	CONTINENTAL	6 mm	
4.		Descri	ption of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE	FRONT PORTION.		
	DAMAGES SEE DETAILS.				
5.		Gene	eral Information		

	BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		
5a.	Remarks		
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b.	Estimate Days of Repair		

Inspection Date

7 Working Days

19/10/2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 6089S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	DENTED	1,430.80	1,430.80
2	FRONT BONNET HINGE @\$70.60	BENT	141.20	141.20
1	FRONT BONNET INSULATOR	NOT NECESSARY	153.80	-
10	FRONT BONNET INSULATOR CLIP @\$6.50	NOT NECESSARY	65.00	-
1	FRONT BONNET INNER RUBBER	NOT NECESSARY	42.00	
1	FRONT BONNET TOP LOCK	DAMAGED	65.80	65.80
1	FRONT BONNET LOCK COVER	NOT NECESSARY	35.60	4
4	FRONT BONNET LOCK COVER CLIP @\$6.50	NOT NECESSARY	26.00	-
2	FRONT HEAD LAMP @\$854.80	CRACKED	1,709.60	1,709.60
2	FRONT HEAD LAMP LOWER BRACKET @\$45.20	BENT	90.40	90.40
1	FRONT BUMPER	DEFORMED	765.80	765.80
10	FRONT BUMPER CLIP @\$6.50	NECESSARY	65.00	30.00
2	FRONT BUMPER SIDE RETAINER @\$42.00	NECESSARY	84.00	84.00
2	FRONT BUMPER FOG LAMP @\$183.00	NOT NECESSARY	366.00	-
1	FRONT BUMPER NUMBER PLATE	NOT NECESSARY	50.00	-
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	35.00	-
1	FRONT BUMPER INNER SPONGE	CRACKED	65.80	65.80
1	FRONT BUMPER REINFORCEMENT	BENT	528.60	528.60
1	FRONT BUMPER LOWER SPOILER (BLACK)	DAMAGED	280.00	280.00
1	FRONT GRILLE	CRACKED	193.80	193.80
1	FRONT GRILLE EMBLEM LOGO	NECESSARY	35.80	35.80
1	FRONT GRILLE EMBLEM TOP COVER (BLACK)	DAMAGED	65.00	65.00
1	FRONT GRILLE CHROME	CRACKED	184.80	184.80
2	FRONT GRILLE SIDE CHROME @\$95.00	NECESSARY	190.00	190.00
1	FRONT GRILLE LOWER (BLACK)	DEFORMED	184.80	184.80
2	FRONT FENDER @\$491.80	N/S BUCKLED	983.60	491.80
2	FRONT FENDER COWLING @\$85.80	NOT NECESSARY	171.60	±
16	FRONT FENDER COWLING CLIP @\$6.50	NOT NECESSARY	104.00	75
1	FRONT SUPPORT PANEL	CRACKED	885.00	885.00
1	FRONT SUPPORT PANEL LOCK	NOT NECESSARY	145.00	-
2	FRONT SUPPORT PANEL SIDE AIR DUCT COVER @\$45.00	NOT NECESSARY	90.00	-
8	FRONT SUPPORT PANEL SIDE AIR DUCT COVER CLIP @\$6.50	NOT NECESSARY	52.00	-

Report Ref No. CS/SPF18019034/Avbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SUPPORT PANEL AIR CLEANER AIR DUCT	NOT NECESSARY	78.60	
2	FRONT HORN @\$72.00	NOT NECESSARY	144.00	,
1	FRONT AIR-CON CONDENSER	BENT	853.80	853.80
1	FRONT RADIATOR	NOT NECESSARY	1,815.80	
1	FRONT RADIATOR FAN MOTOR ASSY	NOT NECESSARY	455.80	
	LESS 20% DISCOUNT		-	-1,655.36
			12,633.80	6,621.44
	LABOUR			
	TO REMOVE & REFIT AIR-CON CONDENSER, RADIATOR, FAN MOTOR & TOP UP GAS.		380.00	120.00
	TUFF KOTE.	NOT NECESSARY	150.00	
	TO CHECK WIRING.		100.00	30.00
	PANEL BEATING.		1,400.00	900.00
	SPRAY PAINTING.		1,400.00	900.00
			3,430.00	1,950.00
	GRAND TOTAL		16,063.80	8,571.44

RECOMMENDED COST OF REPAIRS	8.571.44

Report Ref No. CS/SPF18019034/Avbe2

NOTES: THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,500-\$9,000

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.