



# CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

18/10/2018

TP AXA  
vic.

Accident date: 18/10/2018

Estimated repair cost for vehicle no: SMA9403C HYUNDAI ACCENT 1.4 A '18

CHASSIS: KMHCU41BTKU431373

| S/n | Qty | Items                                       | U/price | Amount     |    |
|-----|-----|---------------------------------------------|---------|------------|----|
| 1   | 1   | Rear Boot Lid <i>Deke</i>                   |         | \$1,223.80 | ✓  |
| 2   | 2   | Rear Boot Lid Hinge <i>new</i>              | \$75.00 | \$150.00   | +  |
| 3   | 1   | Rear Boot Lid Emblem Logo <i>green</i>      |         | \$30.00    | +  |
| 4   | 1   | Rear Boot Lid Accent Logo                   |         | \$38.00    | +  |
| 5   | 1   | Rear Boot Lid Centre Moulding <i>lit</i>    |         | \$60.00    | ✓  |
| 6   | 1   | Rear R/H Tail Lamp <i>Cracked</i>           |         | \$365.00   | ✓  |
| 7   | 2   | Rear R/H Tail Lamp Clip <i>in</i>           | \$6.50  | \$13.00    | ✓  |
| 8   | 1   | Rear R/H Tail Lamp Lower Bracket <i>new</i> |         |            | +  |
| 9   | 1   | Rear Bumper <i>torn</i>                     |         | \$643.80   | ✓  |
| 10  | 8   | Rear Bumper Clip <i>in</i>                  | \$6.80  | \$54.40    | 30 |
| 11  | 1   | Rear R/H Bumper Side Retainer <i>new</i>    |         | \$38.00    | +  |
| 12  | 1   | Rear R/H Bumper Side Reflector <i>lit</i>   |         | \$44.00    | ✓  |
| 13  | 1   | Rear R/H Fender <i>Repair</i>               |         | \$1,218.60 | +  |
| 14  | 1   | Rear Windscreen Seal <i>green</i>           |         | \$50.00    | +  |
| 15  | 1   | Rear Windscreen Moulding                    |         | \$85.80    | +  |

2379.7

1903.76

Subtotal :- **\$3,891.40**

## Labour charges

To remove & refit cushion & trim board

~~\$280.00~~ 60

To remove & refit roof lining

\$380.00 +

To remove & refit reverse sensor

~~\$100.00~~ 40

To remove & refit rear camera

~~\$180.00~~ 50

To remove & refit rear windscreen

\$120.00 +

Gum

\$50.00 ~~x~~

To check wiring

\$100.00 ~~30~~

Tuff kote

1460

\$150.00 ~~x~~

Panel beating

\$1,000.00 ~~500~~

Spray painting

\$1,000.00 ~~600~~

7. transfer bottle fittings

~~180~~ 80.

Subtotal :- \$3,360.00

Total:- \$7,251.40

total. 3363.76

h/s: 2.7K.

Adrian Lij  
h/s 22/10/18

04 Days.

LKK Auto Consultants hereby notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2.7K

05 Days