

ASS. REC. BY:

REF: CS/LPC/18019060/ Rlvds

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Gerald Poh of LPC

Date/Time: 19/10/18 3:57pm

Estimated Cost: Bill to:

☒ OD ☐ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐ CS

To Inspect Vehicle No: SJA 668B Insured:

at Workshop n/a: Cycle & Carriage Ind.

Tel: 8332 0062 / 5771 4401

of 188 Pandan Loop

Policy No: Claim No: 18/18/18/VP05/021039

Sum Insured: Excess: TBA NIL

Make of Veh: D.O.A. 19/10/2018
(Client's Record)CA / ☒ REV / REP. / REV 24 HRS22/10/2018
H.O.D. Endorsement:

Date/Time: 4:19pm 19/10/18 Person Contacted: Vincent

Vehicle: ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SJA 668B - MBA/LPC/18019007/K4 JON: 19/10/18
23/10/18	Revert to Gerald by email
24/10/18	Rece authorize repair from Gerald by email ex NIL
24/10/18	Informed Vincent CIA ex NIL by email
28/11/18	Send supplementary to Longpac to get approval

REF: LPC

89103

ASSIGNMENT

From: Date: 22.10.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLA 668B

at Workshop n/s: Cycle & Carriage

of 188 Pardon Loop.

Insured:

Policy No:

Claims No:

Sum Insured: Excess: TBA

(Client's Record)

Make of Veh: Vincent

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 168k

IDAC Accident Rpt: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLA 668B Yr Regn: 2016 / Jun

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES Benz E200 Sedan c.c. 1991

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 27241 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD 2120 34 2B 314417

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size F: 245/40ZR18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 19/10/18

Survey held at

C8C (PL)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

28/11/18 @230pm Gerald Said C/A

28/11/18 final fig \$ 27,113.89 confirmed by email (Ref 3755-17, 12/9)

RECEIVED 28 NOV 2018

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 28/11- typist

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Report Format: OD

Lump Sum / I.B.I: (\$ 27,113.89)

Survey Fee:

Transportation:

50

50

127

Other:

580

580

28/11/18

20x15=

170+300

50

50

127

697

Veron Chen (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 28 November 2018 2:31 PM
To: Veron Chen (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: SLA668B- OD CLAIM - SURVEY

Our Ref : 18/18/18/VP05/021039

Dear Veron,

Kindly proceed to authorize repair as adjusted

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, 28 November, 2018 12:05 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; SUR
Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Gerald,

Enclosed revised include supplementary.

For your approval please.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 24 October 2018 8:39 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Veron,

Kindly proceed to authorize repair as adjusted.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Wednesday, 24 October, 2018 8:36 AM
To: GERALD POH WEE BIN; SUR
Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Gerald,

Enclosed with photos.

Kindly let us have your approval and policy excess.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 23 October 2018 1:55 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: SLA668B- OD CLAIM - SURVEY

18/18/18/VP05/021039

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Tuesday, 23 October, 2018 1:44 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; SUR
Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Gerald,

Enclosed preliminary revised of vehicle SLA 668B
Date of survey: 22/10/2018

Number of days : 6 days

We have Not authorise repair.

Kindly let us have your approval please.

Please provides us the claim number.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto)
Sent: Friday, 19 October 2018 4:19 PM
To: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>; assignments <assignments@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; SUR <sur@lkkauto.com>
Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Gerald,

Thank you for the assignment.

BEST REGARDS,
G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]
Sent: Friday, 19 October 2018 3:57 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: FW: SLA668B- OD CLAIM - SURVEY

Our Ref : To be advised

Dear Catherine,

For your necessary action.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

-----Original Message-----

From: Vincent Seah [mailto:vincent.seah@cyclecarriage.com.sg]
Sent: Friday, 19 October, 2018 3:51 PM

To: MT_Claim_SG
Subject: SLA668B- OD CLAIM - SURVEY

Hi

Kindly arrange survey on Monday 22.10.18

Vehicle in our premises

Tks

Vincent Seah
Cycle & Carriage Ind. Pte Limited
Body Care & Repair - Pandan Loop Service Center
188 Pandan Loop Singapore 128378
Tel : 83320062 (H/P) DID: 6771 4401
Fax.: 6872 1272

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

This email has been checked for viruses by AVG.
<https://www.avg.com>

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 28 November 2018 12:55 PM
To: 'GERALD POH WEE BIN'
Cc: MT_Claim_SG; SUR
Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Gerald,

Case not registered in mermen.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 28 November 2018 12:24 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Veron,

Please revert in Merimen.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]
Sent: Wednesday, 28 November, 2018 12:05 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; SUR
Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Gerald,

Enclosed revised include supplementary.

For your approval please.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>

Sent: Wednesday, 24 October 2018 8:39 AM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Veron,

Kindly proceed to authorize repair as adjusted.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Wednesday, 24 October, 2018 8:36 AM

To: GERALD POH WEE BIN; SUR

Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Gerald,

Enclosed with photos.

Kindly let us have your approval and policy excess.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>

Sent: Tuesday, 23 October 2018 1:55 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: RE: SLA668B- OD CLAIM - SURVEY

18/18/18/VP05/021039

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, 23 October, 2018 1:44 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; SUR
Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Gerald,

Enclosed preliminary revised of vehicle SLA 668B
Date of survey: 22/10/2018
Number of days : 6 days

We have Not authorise repair.

Kindly let us have your approval please.

Please provides us the claim number.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto)
Sent: Friday, 19 October 2018 4:19 PM
To: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>; assignments <assignments@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; SUR <sur@lkkauto.com>
Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Gerald,

Thank you for the assignment.

BEST REGARDS,
G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]
Sent: Friday, 19 October 2018 3:57 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: FW: SLA668B- OD CLAIM - SURVEY

Our Ref : To be advised

Dear Catherine,

For your necessary action.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

-----Original Message-----

From: Vincent Seah [mailto:vincent.seah@cyclecarriage.com.sg]
Sent: Friday, 19 October, 2018 3:51 PM
To: MT_Claim_SG
Subject: SLA668B- OD CLAIM - SURVEY

Hi

Kindly arrange survey on Monday 22.10.18

Vehicle in our premises

Tks

Vincent Seah

Cycle & Carriage Ind. Pte Limited
Body Care & Repair - Pandan Loop Service Center
188 Pandan Loop Singapore 128378
Tel : 83320062 (H/P) DID: 6771 4401
Fax.: 6872 1272

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

This email has been checked for viruses by AVG.
<https://www.avg.com>



Auto
Consultants
Pte Ltd

Company Registration No. 1996071

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564

Your ref: 18/18/18/VP05/021039

Our ref: CS/LPC18019060/R1vd3

Date: 28/11/2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir

PRELIMINARY ADVICE OF VEHICLE NO. SLA 668B


We thank for your instruction on 19/10/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22/10/2018 at the premises of M/s CYCLE & CARRIAGE INDUSTRIES PTE LTD and have the following to report:-

Workshop Estimate Amount	:S\$30,869.06 (incl.supplementary \$6751.54)
Revised Estimate Amount	:S\$27,113.89 (incl.supplementary \$6751.54)
"Check" Items Amount	:S\$
Total	:S\$
Market Value	:S\$168,000.00
LTA Reimbursement Value	:S\$91,933.00
Nett Value	:S\$76,067.00

Description of Damage:

The vehicle sustained damages at the front o/s portion.



Comments/Present Status:

Damages Consistent

Repair Cost Economical

Yours faithfully,

MOHAMMED RASUL (HP 9001 0068)

Automotive Assessor

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 24 October 2018 9:30 AM
To: 'Vincent Seah'; SUR
Subject: SLA 668B-DOA: 19/10/2018 (LONPAC OD)

Dear Vincent,

As instructed by our client, please proceed to repair the **insured vehicle SLA 668B (Excess NIL)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 24 October 2018 8:46 AM
To: Veron Chen (LKKAUTO)
Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Veron,

There is no excess applicable.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, 24 October, 2018 8:36 AM
To: GERALD POH WEE BIN; SUR
Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Gerald,

Enclosed with photos.

Kindly let us have your approval and policy excess.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 23 October 2018 1:55 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: RE: SLA668B- OD CLAIM - SURVEY

18/18/18/VP05/021039

Best Regards
Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, 23 October, 2018 1:44 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; SUR
Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Gerald,

Enclosed preliminary revised of vehicle SLA 668B
Date of survey: 22/10/2018
Number of days : 6 days

We have Not authorise repair.

Kindly let us have your approval please.

Please provides us the claim number.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto)
Sent: Friday, 19 October 2018 4:19 PM
To: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>; assignments <assignments@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; SUR <sur@lkkauto.com>
Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Gerald,

Thank you for the assignment.

BEST REGARDS,
G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]
Sent: Friday, 19 October 2018 3:57 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: FW: SLA668B- OD CLAIM - SURVEY

Our Ref : To be advised

Dear Catherine,

For your necessary action.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

-----Original Message-----

From: Vincent Seah [mailto:vincent.seah@cyclecarriage.com.sg]

Sent: Friday, 19 October, 2018 3:51 PM

To: MT_Claim_SG

Subject: SLA668B- OD CLAIM - SURVEY

Hi

Kindly arrange survey on Monday 22.10.18

Vehicle in our premises

Tks

Vincent Seah

Cycle & Carriage Ind. Pte Limited

Body Care & Repair - Pandan Loop Service Center

188 Pandan Loop Singapore 128378

Tel : 83320062 (H/P) DID: 6771 4401

Fax.: 6872 1272

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

This email has been checked for viruses by AVG.
<https://www.avg.com>

Veron Chen (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 24 October 2018 8:39 AM
To: Veron Chen (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Veron,

Kindly proceed to authorize repair as adjusted.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, 24 October, 2018 8:36 AM
To: GERALD POH WEE BIN; SUR
Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Gerald,

Enclosed with photos.

Kindly let us have your approval and policy excess.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 23 October 2018 1:55 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: RE: SLA668B- OD CLAIM - SURVEY

18/18/18/VP05/021039

Best Regards
Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, 23 October, 2018 1:44 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; SUR
Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Gerald,

Enclosed preliminary revised of vehicle SLA 668B
Date of survey: 22/10/2018
Number of days : 6 days

We have Not authorise repair.

Kindly let us have your approval please.

Please provides us the claim number.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto)
Sent: Friday, 19 October 2018 4:19 PM
To: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>; assignments <assignments@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; SUR <sur@lkkauto.com>
Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Gerald,

Thank you for the assignment.

BEST REGARDS,
G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]
Sent: Friday, 19 October 2018 3:57 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: FW: SLA668B- OD CLAIM - SURVEY

Our Ref : To be advised

Dear Catherine,

For your necessary action.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

-----Original Message-----

From: Vincent Seah [mailto:vincent.seah@cyclecarriage.com.sg]

Sent: Friday, 19 October, 2018 3:51 PM

To: MT_Claim_SG

Subject: SLA668B- OD CLAIM - SURVEY

Hi

Kindly arrange survey on Monday 22.10.18

Vehicle in our premises

Tks

Vincent Seah

Cycle & Carriage Ind. Pte Limited

Body Care & Repair - Pandan Loop Service Center

188 Pandan Loop Singapore 128378

Tel : 83320062 (H/P) DID: 6771 4401

Fax.: 6872 1272

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

This email has been checked for viruses by AVG.
<https://www.avg.com>

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 23 October 2018 1:44 PM
To: 'GERALD POH WEE BIN'
Cc: 'MT_Claim_SG'; SUR
Subject: RE: SLA668B- OD CLAIM - SURVEY
Attachments: MARK EST.pdf; PRELI ADVISED.pdf

Dear Gerald,

Enclosed preliminary revised of vehicle SLA 668B
Date of survey: 22/10/2018
Number of days : 6 days

We have Not authorise repair.

Kindly let us have your approval please.

Please provides us the claim number.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO)
Sent: Friday, 19 October 2018 4:19 PM
To: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>; assignments <assignments@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; SUR <sur@lkkauto.com>
Subject: RE: SLA668B- OD CLAIM - SURVEY

Dear Gerald,

Thank you for the assignment.

BEST REGARDS,
G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]
Sent: Friday, 19 October 2018 3:57 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: FW: SLA668B- OD CLAIM - SURVEY

Our Ref : To be advised

Dear Catherine,

For your necessary action.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

-----Original Message-----

From: Vincent Seah [mailto:vincent.seah@cyclecarriage.com.sg]
Sent: Friday, 19 October, 2018 3:51 PM
To: MT_Claim_SG
Subject: SLA668B- OD CLAIM - SURVEY

Hi

Kindly arrange survey on Monday 22.10.18

Vehicle in our premises

Tks

Vincent Seah
Cycle & Carriage Ind. Pte Limited
Body Care & Repair - Pandan Loop Service Center
188 Pandan Loop Singapore 128378
Tel : 83320062 (H/P) DID: 6771 4401
Fax.: 6872 1272

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

This email has been checked for viruses by AVG.
<https://www.avg.com>

Your ref: PLEASE ADVISED
Our ref: CS/LPC18019060/R1vd3

Date: 23/10/2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir

PRELIMINARY ADVICE OF VEHICLE NO. SLA 668B


We thank for your instruction on 19/10/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22/10/2018 at the premises of M/s CYCLE & CARRIAGE INDUSTRIES PTE LTD and have the following to report:-

Workshop Estimate Amount	:S\$24,117.52
Revised Estimate Amount	:S\$17,651.61
"Check" Items Amount	:S\$3,840.66
Total	:S\$21,492.27
Market Value	:S\$168,000.00
LTA Reimbursement Value	:S\$91,933.00
Nett Value	:S\$76,067.00

Description of Damage:

The vehicle sustained damages at the front o/s portion.



Comments/Present Status:

Damages Consistent
Repair Cost Economical

Yours faithfully,

MOHAMMED RASUL (HP 9001 0068)
Automotive Assessor

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Friday, 19 October 2018 3:57 PM
To: Admin-D (LKKAuto)
Cc: MT_Claim_SG
Subject: FW: SLA668B- OD CLAIM - SURVEY
Attachments: img-X19154732-0001.pdf; SLA668B_19102018.PDF

Our Ref : To be advised

Dear Catherine,

For your necessary action.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

-----Original Message-----

From: Vincent Seah [mailto:vincent.seah@cyclecarriage.com.sg]
Sent: Friday, 19 October, 2018 3:51 PM
To: MT_Claim_SG
Subject: SLA668B- OD CLAIM - SURVEY

Hi

Kindly arrange survey on Monday 22.10.18

Vehicle in our premises

Tks

Vincent Seah
Cycle & Carriage Ind. Pte Limited
Body Care & Repair - Pandan Loop Service Center
188 Pandan Loop Singapore 128378
Tel : 83320062 (H/P) DID: 6771 4401
Fax.: 6872 1272

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8910J
Vehicle Details	
Vehicle No.:	SLA668B
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Oct 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200 SEDAN EDITION E (R18 LED SR)
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	27492030585527
Chassis No.:	WDD21203428314417
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$52,377.00
Original Registration Date:	22 Jun 2016
First Registration Date:	22 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$66,279.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jun 2026
PARF Rebate Amount:	\$49,709.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jun 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$55,100.00
COE Rebate Amount:	\$42,224.00
Total Rebate Amount:	\$91,933.00

The information contained herein is correct as at 23 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/10/2018 10:55
Date Of Accident	19/10/2018 07:45
Exact Location Of Accident	CLEMENCEAU AVE NORTH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA668B
Insured/Policyholder	
Name Of Registered Owner	CHAN WOEI SHYONG
NRIC No	S7018910J
Email Address	CWSHYONG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90121230
Alternative Phone No	OTHERS-90121230

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	-
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z18VP05018850
Cover Note Number	

Driver

Name of Driver	CHAN WOEI SHYONG
NRIC No	S7018910J
Date Of Birth	06/06/1970
Occupation	INDOOR
Date Of Driving Pass	25/09/1992
Driving Experience	26 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90121230
Fax Number	
Contact Number	OTHERS-90121230
EMail Address	CWSHYONG@GMAIL.COM

Address	71 JALAN CHENGAM
Postcode	578354
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH9329B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	GOH KWEE SENG
NRIC/Passport Number	S0362898A
Contact Number	90056615
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

II. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Car A was driving along Cleveland Ave North towards Carroll
Car B came out from Vinstreet Road
Car A did not manage to stop down in time and
hit into rear side of Car B.
Car A has damage on front right bumper
Car B has damage on back-right wheels

DECLARATION

i/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: _____
NR/C/TIN No: _____



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLA668B

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

WIP No

27720

Reg No/Reg Date

SLA668B / 22/06/2016

Date In/Mileage

/ 27241

Chassis No

WDD2120342B314417

Engine No

27492030585527

Make/Model

MB/MB E 200 2.0 SEDAN (W212) "EDITION E"

Colour/Trim

029 992 Selenite Gr/ 042 241 Leather Blk

Vehicle & Document Information

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	19/10/2018/ 12:28	V5	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : Z18P05018850 // 19.10.18 DRIVE IN/EXCESS : 19.10.18 // DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	✓ 380.00
S BPNSUB SUPPLY 1PCS NUMBER PLATE WITH HOUSING.NETT FRONT				✓ 60.00
A BPILAB TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT				✓ 120.00
A BPILAB DISASSEMBLE AND REPLACE ON FRONT BUMPER , BONNET, RHF FENDER , FRONT SUPPORT PANEL				✓ 2880 4800.00
A BPIRES RESPRAY ON FRONT BUMPER, RHF FENDER, BONNET				✓ 1800 2400.00
A BPILAB REMOVE AND REPLACE RADIATOR COOLING SYSTEM , CONDENSER WITH VACCUM AND RECHARGE REFRIGERANT. NETT				✓ ? 960.00 LAB
M RIGHT HEADLAMP UNIT bro	1.00	5023.11	00.00	5023.11 ✓
M RIGHT FRONT FENDER bt	1.00	1030.82	00.00	1030.82 ✓
M RIGHT FRONT FENDER LINER FF DE	1.00	193.30	00.00	193.30 ✓
M RHF INTERMEDIATE LAYER CRA	1.00	6.71	00.00	✓ 6.71 X
M FRONT BUMPER TORN	1.00	1628.37	00.00	1628.37 ✓
M RIGHT FRONT BUMPER ORNAMENTAL MOLDING DE	1.00	226.84	00.00	226.84 ✓
M CENTRAL FRONT BUMPER ORNAMENTAL MOLDING ad	1.00	302.49	00.00	302.49 ✓
M AIR INLET FRONT BUMPER DE ? X	1.00	104.84	00.00	✓ 104.84 X
M LICENSE PLATE MOLDING CRA ? X	1.00	168.51	00.00	✓ 168.51 X
M BOTTOM BASIC MOUNTING FOR BUMPER ? CR	1.00	76.07	00.00	76.07 ✓
M CT/F REINFORCEMENT CRA	1.00	126.74	00.00	126.74 ✓
M CT/F IMPACT ABSORBER CRA	1.00	126.74	00.00	126.74 ✓

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLA668B

LONPAC INSURANCE BHD
MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information
WIP No 27720
Reg No/Reg Date SLA668B / 22/06/2016
Date In/Mileage / 27241
Chassis No WDD2120342B314417
Engine No 27492030585527
Make/Model MB/MB E 200 2.0 SEDAN (W212) "EDITION E"
Colour/Trim 029 992 Selenite Gr/ 042 241 Leather Blk

Account No	Terms	Date/Time Printed	CSE	Operator	
WL001605	Credit	19/10/2018/ 12:28	VS	356 / Vincent Seah	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	RIGHT FOGLAMP COVER <i>De</i>	1.00	51.27	00.00	51.27
M	RIGHT FOGLAMP INNER COVER <i>De</i>	1.00	55.41	00.00	55.41
M	CT/F BOTTOM REINFORCEMENT <i>De</i>	1.00	123.15	00.00	123.15
M	RIVET <i>new x</i>	2.00	3.27	00.00	<i>AA</i> 6.54
M	ELECTRICAL WIRING HARNESS <i>cat</i>	1.00	147.91	00.00	147.91
M	DISTANCE SENSOR <i>new</i>	2.00	172.07	00.00	344.14
M	SPACER RING <i>new</i>	2.00	6.42	00.00	12.84
M	BONNET HOOK <i>De</i>	2.00	29.91	00.00	<i>SVC</i> 59.82
M	BONNET <i>De</i>	1.00	2385.66	00.00	2385.66
M	COMPANY SIGN <i>new</i>	1.00	78.83	00.00	78.83
M	BONNET CATCH <i>De</i>	2.00	32.77	00.00	<i>AA</i> 65.54
M	BAFFLE-STOPPER <i>new</i>	2.00	3.62	00.00	7.24
M	BONNET STOP BUFFER <i>new</i>	2.00	9.57	00.00	19.14
M	BEAM- FRONT RADIATOR SUPPORT <i>De</i>	1.00	256.66	00.00	<i>SVC</i> 256.66
M	RAD. GRILLE <i>CR</i>	1.00	179.54	00.00	179.54
M	RADIATOR ORNAMENTAL MOLDING <i>CR</i>	1.00	344.87	00.00	344.87
M	RADIATOR STAR HOUSING FRAME <i>CR</i>	1.00	177.95	00.00	177.95
M	TOP LEFT CHROME MOULDING <i>CR</i>	1.00	35.19	00.00	35.19
M	TOP RIGHT CHROME MOULDING <i>CR</i>	1.00	35.19	00.00	35.19
M	BOTTOM LEFT CHROME MOULDING <i>CR</i>	1.00	35.19	00.00	35.19
M	BOTTOM RIGHT CHROME MOULDING <i>CR</i>	1.00	35.19	00.00	35.19
M	LEFT RAD. BRACKET <i>De</i>	1.00	12.17	00.00	<i>AA</i> 12.17
M	RIGHT RAD. BRACKET <i>De</i>	1.00	12.17	00.00	12.17
M	RHF FENDER SYMBOL PLATE <i>new</i>	1.00	105.25	00.00	105.25
M	FRONT CROSS MEMBER <i>De</i>	1.00	530.19	00.00	530.19
M	RIGHT STRUT <i>De</i>	1.00	51.50	00.00	51.50
M	FRAME FOR HEADLAMP UNIT <i>CR</i>	1.00	256.69	00.00	256.69
M	U-SHAPED STRIKER <i>De</i>	1.00	40.66	00.00	<i>AA</i> 40.66
M	RIGHT ABSORBER <i>De</i>	1.00	284.15	00.00	<i>SVC</i> 284.15
M	SUPPORT ABSORBER <i>De</i>	2.00	28.70	00.00	<i>AA</i> 57.40
M	FRT CTR STIFFENING <i>De</i>	1.00	150.99	00.00	150.99
M	RIGHT ENG. COVER BRACKET <i>De</i>	1.00	37.83	00.00	37.83
M	LEFT ENG. COVER BRACKET <i>De</i>	1.00	37.83	00.00	<i>SVC</i> 37.83

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLA668B

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information
WIP No 27720
Reg No/Reg Date SLA668B / 22/06/2016
Date In/Mileage / 27241
Chassis No WDD2120342B314417
Engine No 27492030585527
Make/Model MB/MB E 200 2.0 SEDAN (W212) "EDITION E"
Colour/Trim 029 992 Selenite Gr/ 042 241 Leather Blk

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	19/10/2018/ 12:28	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M COVER F ENGINE COMP. BM	1.00	225.57	00.00	225.57
M FRONT BUMPER LOWER GRILLE	1.00	123.31	00.00	123.31

Rasul
Hp 90010068
6 days

22/10/18 @ 1610

EXCESS TBA

REPAIR

Resurvey bK paint

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

30,869.06

Confirmed & accepted by

Nett 24,117.52
7% GST on 24117.52 1688.23
Total Payable 25,805.75

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 19640367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SLA668B

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information
WIP No 27720
Reg No/Reg Date SLA668B / 22/06/2016
Date In/Mileage 24/10/2018/ 27244
Chassis No WDD2120342B314417
Engine No 27492030585527
Make/Model MB/MB E 200 2.0 SEDAN (W212) "EDITION E"
Colour/Trim 029 992 Selenite Gr/ 042 241 Leather Blä

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WL001605	Credit	27/11/2018/ 17:37	VS	356 / Vincent Seah					
M BPKSUN									
POLICY NO/ACQ DATE : 218905018850 19.10.18									
DRIVE IN/EXCESS : 19110.48 // NA									
DATE IN/DATE SURVEY: 19.10.18 // 22.10.18 RASUL-LKK 16:10PM									
BY/AUTHORIZED ON : VVERON CHEN- LKK // 24.10.18									
A BPILAB									
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT									
S BPNSUB									
SUPPLY ONE PC NO PLATE									
A BPILAB									
TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT									
A BPILAB									
DISASSEMBLE AND REPLACE ON FRONT BUMPER, BONNET, RHE FENDER, FRONT SUPPORT PANEL									
A BPIRES									
RESPRAY ON FRONT BUMPER, RHE FENDER, BONNET									
A BPILAB									
REMOVE AND REPLACE RADIATOR COOLING SYSTEM, CONDENSER WITH VACCUM AND RECAHRGE REFRIGERANT. NETT									
X RIGHT HEADLAMP UNIT									
X RIGHT FRONT FENDER									
X FRONT BUMPER									
X RIGHT FRONT BUMPER ORNAMENTAL MOLDING									
X CENTRAL FRONT BUMPER ORNAMENTAL MOLDING									
X LICENSE PLATE MOLDING									
X BOTTOM BASIC MOUNTING FOR BUMPER									
X CT/F REINFORCEMENT									
X CT/F IMPACT ABSORBER									
X RIGHT FOGLAMP COVER									
X RIGHT FOGLAMP INNER COVER									
X CT/F BOTTOM REINFORCEMENT									
X ELECTRICAL WIRING HARNESS									

0.10 380.00

60.00

120.00

2880.00

1800.00

960.00

1.00 5023.11 00.00 5023.11

1.00 1030.82 00.00 1030.82

1.00 1628.37 00.00 1628.37

1.00 226.84 00.00 226.84

1.00 302.49 00.00 302.49

1.00 168.51 00.00 168.51

1.00 76.07 00.00 76.07

1.00 126.74 00.00 126.74

1.00 126.74 00.00 126.74

1.00 51.27 00.00 51.27

1.00 55.41 00.00 55.41

1.00 123.15 00.00 123.15

1.00 147.91 00.00 147.91

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 195400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLA668B

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

WIP No

27720

Reg No/Reg Date

SLA668B / 22/06/2016

Date In/Mileage

24/10/2018 / 27241

Chassis No

WDD2120342B314417

Engine No

27492030585527

Make/Model

MB/MB E 200 2.0 SEDAN (W212) "EDITION E"

Colour/Trim

029 992 Selenite Gr/ 042 241 Leather Bls

Account No	Terms	Date/Time Printed	CSE	Operator				
WL001605	Credit	27/11/2018/ 17:37	VS	356 / Vincent Seah				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X DISTANCE SENSOR					2.00	172.07	00.00	344.14
X SPACER RING					2.00	6.42	00.00	12.84
X BONNET					1.00	2385.66	00.00	2385.66
X COMPANY SIGN					1.00	78.83	00.00	78.83
X BAFFLE-STOPPER					2.00	3.62	00.00	7.24
X BONNET STOP BUFFER					2.00	9.57	00.00	19.14
X RADIATOR ORNAMENTAL MOLDING					1.00	344.87	00.00	344.87
X RADIATOR STAR HOUSING FRAME					1.00	177.95	00.00	177.95
X TOP LEFT CHROME MOULDING					1.00	35.19	00.00	35.19
X TOP RIGHT CHROME MOULDING					1.00	35.19	00.00	35.19
X BOTTOM LEFT CHROME MOULDING					1.00	35.19	00.00	35.19
X BOTTOM RIGHT CHROME MOULDING					1.00	35.19	00.00	35.19
X RIGHT RAD. BRACKET					1.00	12.17	00.00	12.17
X RH FENDER SYMBOL PLATE					1.00	105.25	00.00	105.25
X FRONT CROSS MEMBER					1.00	530.19	00.00	530.19
X FRAME FOR HEADLAMP UNIT					1.00	256.69	00.00	256.69
X FRT CTR STIFFENING					1.00	150.99	00.00	150.99
X RIGHT ENG. COVER BRACKET					1.00	37.83	00.00	37.83
X COVER F ENGINE COMP. BM					1.00	225.57	00.00	225.57
X RADIATOR					1.00	1374.00	00.00	1374.00
X RADIATOR ANTIFREEZE					2.00	46.49	00.00	92.98
X BEAM					1.00	72.06	00.00	72.06
X MERCEDES STAR					1.00	130.65	00.00	130.65
X AIR DUCT					1.00	81.15	00.00	81.15
X RIGHT STRUT					1.00	51.50	00.00	51.50
X COVER BUMPER AREA					1.00	179.54	00.00	179.54
X RIGHT HEADLIGHT VOLTAGE CONVERTER					1.00	1143.32	00.00	1143.32
X RIGHT HEADLIGHT CONTROL UNIT					1.00	836.85	00.00	836.85
X FANFARE HORN					1.00	180.78	00.00	180.78
X EXPANSION RIVET					2.00	1.65	00.00	3.30
X TOP AIR BAFFLE					1.00	38.72	00.00	38.72
X RIGHT FRONT FENDER LINER FF					1.00	193.30	00.00	193.30
X CAMERA					1.00	1433.42	00.00	1433.42

Finalization

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz, and associated trademarks of Daimler AG are registered trademarks of Daimler AG.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLA668B

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

WIP No 27720
Reg No/Reg Date SLA668B / 22/06/2016
Date In/Mileage 24/10/2018/ 27241
Chassis No WDD2120342B314417
Engine No 27492030585527
Make/Model MB/MB E 200 2.0 SEDAN (W212) "EDITION E"
Colour/Trim 029 992 Selenite Gr/ 042 241 Leather Blk

Vehicle & Document Information

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	27/11/2018/ 17:37	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X RADAR SENSOR	1.00	1157.08	00.00	1157.08
X RADAR SENSOR BRACKET	1.00	27.69	00.00	27.69

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Initialization

Confirmed & accepted by

Nett 27,113.89
7% GST on 27113.89 1897.97
Total Payable 29,011.86

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of removing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz is a registered trademark of Daimler AG. Mercedes-Benz is a registered trademark of Daimler AG.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLA668B

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No 27720
Reg No/Reg Date SLA668B / 22/06/2016
Date In/Mileage 24/10/2018/ 27241
Chassis No WDD2120342B314417
Engine No 27492030585527
Make/Model MB/MB E 200 2.0 SEDAN (W212) "EDITION E"
Colour/Trim 029 992 Selenite Gr/ 042 241 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	27/11/2018/ 17:36	V5	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
THIS IS NOT AN OFFICIAL TAX INVOICE				
M. BPHSUN POLICY NO/ACC DATE : 218905018850 19.10.18 DRIVE IN/EXCESS : 19.10.18 // NA DATE IN/DATE SURVEY: 19.10.18 // 22.10.18 RASUL-LKK 16:10PM BY/AUTHORIZED ON : VVERON CHEN- LKK // 24.10.18				
X RADIATOR <i>BT</i>	1.00	1374.00	00.00	1374.00
X RADIATOR ANTIFREEZE <i>Am</i>	2.00	46.49	00.00	92.98
X BEAM <i>BT</i>	1.00	72.06	00.00	72.06
X MERCEDES STAR <i>Am</i>	1.00	130.65	00.00	130.65
X AIR DUCT <i>CR</i>	1.00	81.15	00.00	81.15
X COVER BUMPER AREA <i>CR</i>	1.00	179.54	00.00	179.54
X RIGHT HEADLIGHT VOLTAGE CONVERTER <i>Am</i>	1.00	1143.32	00.00	1143.32
X RIGHT HEADLIGHT CONTROL UNIT <i>Am</i>	1.00	836.85	00.00	836.85
X FANFARE HORN <i>CR</i>	1.00	180.78	00.00	180.78
X EXPANSION RIVET <i>Am</i>	2.00	1.65	00.00	3.30
X TOP AIR BAFFLE <i>CR</i>	1.00	38.72	00.00	38.72
X CAMERA <i>Am</i>	1.00	1433.42	00.00	1433.42
X RADAR SENSOR <i>Am</i>	1.00	1157.08	00.00	1157.08
X RADAR SENSOR BRACKET <i>CR</i>	1.00	27.69	00.00	27.69

SUPPLEMENTARY

Confirmed & accepted by

7% GST on **Nett 6,751.54**
472.61
Total Payable 7,224.15

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 28 November 2018 2:39 PM
To: Vincent Seah; SUR
Subject: RE: SLA 668B-DOA: 19/10/2018 (LONPAC OD)

Dear Vincent,

Confirmed amount \$27,113.89 before GST @ 6 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vincent Seah <vincent.seah@cyclecarriage.com.sg>
Sent: Tuesday, 27 November 2018 5:41 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: SLA 668B-DOA: 19/10/2018 (LONPAC OD)

Afternoon

Finalise

Vincent Seah
Cycle & Carriage Ind. Pte Limited
Body Care & Repair - Pandan Loop Service Center
188 Pandan Loop Singapore 128378
Tel : 83320062 (H/P) DID: 6771 4401
Fax.: 6872 1272

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]
Sent: Tuesday, 27 November 2018 5:02 PM
To: Vincent Seah <vincent.seah@cyclecarriage.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SLA 668B-DOA: 19/10/2018 (LONPAC OD)

Dear Vincent,

Kindly advise vehicle status.

If vehicle has been repaired, please forward us finalize.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Wednesday, 24 October 2018 9:30 AM

To: 'Vincent Seah' <vincent.seah@cyclecarriage.com.sg>; SUR <sur@lkkauto.com>

Subject: SLA 668B-DOA: 19/10/2018 (LONPAC OD)

Dear Vincent,

As instructed by our client, please proceed to repair the **insured vehicle SLA 668B (Excess NIL)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS/LPC18019060/R1vd3e2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 10-12-2018



Code : LPC2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLA 668B
Policy No.	Z18VP05018850	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/021039	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	19/10/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E200 SEDAN	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD2120342B314417	Colour	GREY
Odometer	27241	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40Z R18	MICHELIN	6 mm
L/H Front Tyre	245/40Z R18	MICHELIN	6 mm
R/H Rear Tyre	245/40Z R18	MICHELIN	6 mm
L/H Rear Tyre	245/40Z R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/10/2018	Inspection Date	22/10/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A)THE MARKET VALUE IS S\$168,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 668B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	NUMBER PLATE WITH HOUSING (SN)	BENT	60.00	60.00
1	RIGHT HEADLAMP UNIT (SN)	BROKEN	5,023.11	5,023.11
1	RIGHT FRONT FENDER (SN)	BENT	1,030.82	1,030.82
1	RIGHT FRONT FENDER LINER FF (SN)	DEFORMED	193.30	193.30
1	RHF INTERMEDIATE LAYER (SN)	NOT NECESSARY	6.71	-
1	FRONT BUMPER (SN)	TORN	1,628.37	1,628.37
1	RIGHT FRONT BUMPER ORNAMENTAL MOLDING (SN)	DEFORMED	226.84	226.84
1	CENTRAL FRONT BUMPER ORNAMENTAL MOLDING (SN)	CUT	302.49	302.49
1	AIR INLET FRONT BUMPER (SN)	SERVICEABLE	104.84	-
1	LICENSE PLATE MOLDING (SN)	CRACKED	168.51	168.51
1	BOTTOM BASIC MOUNTING FOR BUMPER (SN)	CRACKED	76.07	76.07
1	CT/F REINFORCEMENT (SN)	CRACKED	126.74	126.74
1	CT/F IMPACT ABSORBER (SN)	CRACKED	126.74	126.74
1	RIGHT FOGLAMP COVER (SN)	DEFORMED	51.27	51.27
1	RIGHT FOGLAMP INNER COVER (SN)	CRACKED	55.41	55.41
1	CT/F BOTTOM REINFORCEMENT (SN)	BENT	123.15	123.15
2	RIVET (SN)	NOT NECESSARY	6.54	-
1	ELECTRICAL WIRING HARNESS (SN)	CUT	147.91	147.91
2	DISTANCE SENSOR (SN)	NECESSARY	344.14	344.14
2	SPACER RING (SN)	NECESSARY	12.84	12.84
2	BONNET HOOK (SN)	SERVICEABLE	59.82	-
1	BONNET (SN)	BENT	2,385.66	2,385.66
1	COMPANY SIGN (SN)	NECESSARY	78.83	78.83
2	BONNET CATCH (SN)	NOT NECESSARY	65.54	-
2	BAFFLE-STOPPER (SN)	NECESSARY	7.24	7.24
2	BONNET STOP BUFFER (SN)	NECESSARY	19.14	19.14
1	BEAM-FRONT RADIATOR SUPPORT (SN)	SERVICEABLE	256.66	-
1	RAD. GRILLE (SN)	SERVICEABLE	179.54	-
1	RADIATOR GRILLE ORNAMENTAL MOLDING (SN)	CRACKED	344.87	344.87
1	RADITOR STAR HOUSING FRAME (SN)	CRACKED	177.95	177.95
1	TOP LEFT CHROME MOULDING (SN)	CRACKED	35.19	35.19
1	TOP RIGHT CHROME MOULDING (SN)	CRACKED	35.19	35.19
1	BOTTOM LEFT CHROME MOULDING (SN)	CRACKED	35.19	35.19
1	BOTTOM RIGHT CHROME MOULDING (SN)	NECESSARY	35.19	35.19

Report Ref No. CS/LPC18019060/R1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LEFT RAD. BRACKET (SN)	NOT NECESSARY	12.17	-
1	RIGHT RAD. BRACKET (SN)	NECESSARY	12.17	12.17
1	RHF FENDER SYMBOL PLATE (SN)	NECESSARY	105.25	105.25
1	FRONT CROSS MEMBER (SN)	BENT	530.19	530.19
1	RIGHT STRUT (SN)	BENT	51.50	51.50
1	FRAME FOR HEADLAMP UNIT (SN)	CRACKED	256.69	256.69
1	U-SHAPED STRIKER (SN)	NOT NECESSARY	40.66	-
1	RIGHT ABSORBER (SN)	SERVICEABLE	284.15	-
2	SUPPORT ABSORBER (SN)	NOT NECESSARY	57.40	-
1	FRT CTR STIFFENING (SN)	BENT	150.99	150.99
1	RIGHT ENG. COVER BRACKET (SN)	CRACKED	37.83	37.83
1	LEFT ENG. COVER BRACKET (SN)	SERVICEABLE	37.83	-
1	COVER F ENGINE COMP. BM (SN)	CRACKED	225.57	225.57
1	FRONT BUMPER LOWER GRILLE (SN)	SERVICEABLE	123.31	-
1	RADIATOR (SN) (ADDITIONAL)	BENT	1,374.00	1,374.00
2	RADIATOR ANTIFREEZE (SN) (ADDITIONAL)	NECESSARY	92.98	92.98
1	BEAM (SN) (ADDITIONAL)	BENT	72.06	72.06
1	MERCEDES STAR (SN) (ADDITIONAL)	NECESSARY	130.65	130.65
1	AIR DUCT (SN) (ADDITIONAL)	CRACKED	81.15	81.15
1	COVER BUMPER AREA (SN) (ADDITIONAL)	CRACKED	179.54	179.54
1	RIGHT HEADLIGHT VOLTAGE CONVERTER (SN) (ADDITIONAL)	NOT WORKING	1,143.32	1,143.32
1	RIGHT HEADLIGHT CONTROL UNIT (SN) (ADDITIONAL)	NOT WORKING	836.85	836.85
1	FANFARE HORN (SN) (ADDITIONAL)	CRACKED	180.78	180.78
2	EXPANSION RIVET (SN) (ADDITIONAL)	NECESSARY	3.30	3.30
1	TOP AIR BAFFLE (SN) (ADDITIONAL)	CRACKED	38.72	38.72
1	CAMERA (SN) (ADDITIONAL)	NOT WORKING	1,433.42	1,433.42
1	RADAR SENSOR (SN) (ADDITIONAL)	NOT WORKING	1,157.08	1,157.08
1	RADAR SENSOR BRACKET (SN) (ADDITIONAL)	NECESSARY	27.69	27.69
			22,209.06	20,973.89
	LABOUR			
	USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.		380.00	380.00
	TO REMOVE, REPLACE HEADLAMP WITH FOCUS.		120.00	120.00
	DISASSEMBLE AND REPLACE ON FRONT BUMPER, BONNET, RHF FENDER, FRONT SUPPORT PANEL.		4,800.00	2,880.00
	RESPRAY ON FRONT BUMPER, RHF FENDER, BONNET.		2,400.00	1,800.00

Report Ref No. CS/LPC18019060/R1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REPLACE RADIATOR COOLING SYSTEM, CONDENSER WITH VACUUM AND RECAHRGE REFRIGERANT.		960.00	960.00
			8,660.00	6,140.00
GRAND TOTAL			30,869.06	27,113.89
RECOMMENDED COST OF REPAIRS				27,113.89

Report Ref No. CS/LPC18019060/R1vd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.