



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLA668B

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No **27720**
Reg No/Reg Date **SLA668B / 22/06/2016**
Date In/Mileage **24/10/2018/ 27241**
Chassis No **WDD2120342B314417**
Engine No **27492030585527**
Make/Model **MB/MB E 200 2.0 SEDAN (W212) "EDITION E"**
Colour/Trim **029 992 Selenite Gr/ 042 241 Leather Bla**

| Account No | Terms | Date/Time Printed | CSE | Operator | Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|---|---|-------------------|---------|--------------------|---------------------------------|-----|------------|-------|---------|
| WL001605 | Credit | 27/11/2018/ 17:37 | VS | 356 / Vincent Seah | | | | | |
| M BPNSUN | | | | | | | | | |
| POLICY NO/ACC DATE : Z18P05018850 // 19.10.18 | | | | | | | | | |
| DRIVE IN/EXCESS : 19.10.18 // NA | | | | | | | | | |
| DATE IN/DATE SURVEY: 19.10.18 // 22.10.18 RASUL-LKK 16:10PM | | | | | | | | | |
| BY/AUTHORIZED ON : VVERON CHEN- LKK // 24.10.18 | | | | | | | | | |
| A BPILAB | | | | | | | | | |
| USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT | | | | | | | | 0.10 | 380.00 |
| S BPNSUB | | | | | | | | | |
| SUPPLY ONE PC NO PLATE | | | | | | | | | 60.00 |
| A BPILAB | | | | | | | | | |
| TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT | | | | | | | | | 120.00 |
| A BPILAB | | | | | | | | | |
| DISASSEMBLE AND REPLACE ON FRONT BUMPER , BONNET, RHF FENDER , FRONT SUPPORT PANEL | | | | | | | | | 2880.00 |
| A BPIRES | | | | | | | | | |
| RESPRAY ON FRONT BUMPER, RHF FENDER, BONNET | | | | | | | | | 1800.00 |
| A BPILAB | | | | | | | | | |
| REMOVE AND REPLACE RADIATOR COOLING SYSTEM , CONDENSER WITH VACUUM AND RECHARGE REFRIGERANT. NETT | | | | | | | | | 960.00 |
| X | RIGHT HEADLAMP UNIT | 1.00 | 5023.11 | 00.00 | | | | | 5023.11 |
| X | RIGHT FRONT FENDER | 1.00 | 1030.82 | 00.00 | | | | | 1030.82 |
| X | FRONT BUMPER | 1.00 | 1628.37 | 00.00 | | | | | 1628.37 |
| X | RIGHT FRONT BUMPER ORNAMENTAL MOLDING | 1.00 | 226.84 | 00.00 | | | | | 226.84 |
| X | CENTRAL FRONT BUMPER ORNAMENTAL MOLDING | 1.00 | 302.49 | 00.00 | | | | | 302.49 |
| X | LICENSE PLATE MOLDING | 1.00 | 168.51 | 00.00 | | | | | 168.51 |
| X | BOTTOM BASIC MOUNTING FOR BUMPER | 1.00 | 76.07 | 00.00 | | | | | 76.07 |
| X | CT/F REINFORCEMENT | 1.00 | 126.74 | 00.00 | | | | | 126.74 |
| X | CT/F IMPACT ABSORBER | 1.00 | 126.74 | 00.00 | | | | | 126.74 |
| X | RIGHT FOGLAMP COVER | 1.00 | 51.27 | 00.00 | | | | | 51.27 |
| X | RIGHT FOGLAMP INNER COVER | 1.00 | 55.41 | 00.00 | | | | | 55.41 |
| X | CT/F BOTTOM REINFORCEMENT | 1.00 | 123.15 | 00.00 | | | | | 123.15 |
| X | ELECTRICAL WIRING HARNESS | 1.00 | 147.91 | 00.00 | | | | | 147.91 |

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLA668B

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No **27720**
Reg No/Reg Date **SLA668B / 22/06/2016**
Date In/Mileage **24/10/2018/ 27241**
Chassis No **WDD2120342B314417**
Engine No **27492030585527**
Make/Model **MB/MB E 200 2.0 SEDAN (W212) "EDITION E"**
Colour/Trim **029 992 Selenite Gr/ 042 241 Leather Bla**

| Account No | Terms | Date/Time Printed | CSE | Operator | Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|------------|--------|-------------------|-----|--------------------|-----------------------------------|------|------------|-------|---------|
| WL001605 | Credit | 27/11/2018/ 17:37 | VS | 356 / Vincent Seah | | | | | |
| X | | | | | DISTANCE SENSOR | 2.00 | 172.07 | 00.00 | 344.14 |
| X | | | | | SPACER RING | 2.00 | 6.42 | 00.00 | 12.84 |
| X | | | | | BONNET | 1.00 | 2385.66 | 00.00 | 2385.66 |
| X | | | | | COMPANY SIGN | 1.00 | 78.83 | 00.00 | 78.83 |
| X | | | | | BAFFLE-STOPPER | 2.00 | 3.62 | 00.00 | 7.24 |
| X | | | | | BONNET STOP BUFFER | 2.00 | 9.57 | 00.00 | 19.14 |
| X | | | | | RADIATOR ORNAMENTAL MOLDING | 1.00 | 344.87 | 00.00 | 344.87 |
| X | | | | | RADITOR STAR HOUSING FRAME | 1.00 | 177.95 | 00.00 | 177.95 |
| X | | | | | TOP LEFT CHROME MOULDING | 1.00 | 35.19 | 00.00 | 35.19 |
| X | | | | | TOP RIGHT CHROME MOULDING | 1.00 | 35.19 | 00.00 | 35.19 |
| X | | | | | BOTTOM LEFT CHROME MOULDING | 1.00 | 35.19 | 00.00 | 35.19 |
| X | | | | | BOTTOM RIGHT CHROME MOULDING | 1.00 | 35.19 | 00.00 | 35.19 |
| X | | | | | RIGHT RAD. BRACKET | 1.00 | 12.17 | 00.00 | 12.17 |
| X | | | | | RHF FENDER SYMBOL PLATE | 1.00 | 105.25 | 00.00 | 105.25 |
| X | | | | | FRONT CROSS MEMBER | 1.00 | 530.19 | 00.00 | 530.19 |
| X | | | | | FRAME FOR HEADLAMP UNIT | 1.00 | 256.69 | 00.00 | 256.69 |
| X | | | | | FRT CTR STIFFENING | 1.00 | 150.99 | 00.00 | 150.99 |
| X | | | | | RIGHT ENG. COVER BRACKET | 1.00 | 37.83 | 00.00 | 37.83 |
| X | | | | | COVER F ENGINE COMP. BM | 1.00 | 225.57 | 00.00 | 225.57 |
| X | | | | | RADIATOR | 1.00 | 1374.00 | 00.00 | 1374.00 |
| X | | | | | RADIATOR ANTIFREEZE | 2.00 | 46.49 | 00.00 | 92.98 |
| X | | | | | BEAM | 1.00 | 72.06 | 00.00 | 72.06 |
| X | | | | | MERCEDES STAR | 1.00 | 130.65 | 00.00 | 130.65 |
| X | | | | | AIR DUCT | 1.00 | 81.15 | 00.00 | 81.15 |
| X | | | | | RIGHT STRUT | 1.00 | 51.50 | 00.00 | 51.50 |
| X | | | | | COVER BUMPER AREA | 1.00 | 179.54 | 00.00 | 179.54 |
| X | | | | | RIGHT HEADLIGHT VOLTAGE CONVERTER | 1.00 | 1143.32 | 00.00 | 1143.32 |
| X | | | | | RIGHT HEADLIGHT CONTROL UNIT | 1.00 | 836.85 | 00.00 | 836.85 |
| X | | | | | FANFARE HORN | 1.00 | 180.78 | 00.00 | 180.78 |
| X | | | | | EXPANSION RIVET | 2.00 | 1.65 | 00.00 | 3.30 |
| X | | | | | TOP AIR BAFFLE | 1.00 | 38.72 | 00.00 | 38.72 |
| X | | | | | RIGHT FRONT FENDER LINER FF | 1.00 | 193.30 | 00.00 | 193.30 |
| X | | | | | CAMERA | 1.00 | 1433.42 | 00.00 | 1433.42 |

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz are registered trademarks of Daimler Stuttgart Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLA668B

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No 27720
Reg No/Reg Date SLA668B / 22/06/2016
Date In/Mileage 24/10/2018/ 27241
Chassis No WDD2120342B314417
Engine No 27492030585527
Make/Model MB/MB E 200 2.0 SEDAN (W212) "EDITION E"
Colour/Trim 029 992 Selenite Gr/ 042 241 Leather Bla

| Account No | Terms | Date/Time Printed | CSE | Operator | | | |
|---------------------------------|--------|-------------------|-----|--------------------|------------|-------|---------|
| WL001605 | Credit | 27/11/2018/ 17:37 | VS | 356 / Vincent Seah | | | |
| Description of Goods / Services | | | | Qty | Unit Price | Disc% | Amount |
| X | RADAR | SENSOR | | 1.00 | 1157.08 | 00.00 | 1157.08 |
| X | RADAR | SENSOR BRACKET | | 1.00 | 27.69 | 00.00 | 27.69 |

ESTIMATE

Initialization

Confirmed & accepted by

Nett 27,113.89
7% GST on 27113.89 1897.97

Authorized signatory and company stamp

Total Payable 29,011.86

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLA668B

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No **27720**
Reg No/Reg Date **SLA668B / 22/06/2016**
Date In/Mileage **24/10/2018/ 27241**
Chassis No **WDD2120342B314417**
Engine No **27492030585527**
Make/Model **MB/MB E 200 2.0 SEDAN (W212) "EDITION E"**
Colour/Trim **029 992 Selenite Gr/ 042 241 Leather Bla**

| Account No | Terms | Date/Time Printed | CSE | Operator |
|------------|--------|-------------------|-----|--------------------|
| WL001605 | Credit | 27/11/2018/ 17:36 | VS | 356 / Vincent Seah |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|---|------|------------|-------|---------|
| M BPNSUN | | | | |
| POLICY NO/ACC DATE : Z18P05018850 / 19.10.18 | | | | |
| DRIVE IN/EXCESS : 19.10.18 // NA | | | | |
| DATE IN/DATE SURVEY: 19.10.18 // 22.10.18 RASUL-LKK 16:10PM | | | | |
| BY/AUTHORIZED ON : VVERON CHEN- LKK // 24.10.18 | | | | |
| X RADIATOR | 1.00 | 1374.00 | 00.00 | 1374.00 |
| X RADIATOR ANTIFREEZE | 2.00 | 46.49 | 00.00 | 92.98 |
| X BEAM | 1.00 | 72.06 | 00.00 | 72.06 |
| X MERCEDES STAR | 1.00 | 130.65 | 00.00 | 130.65 |
| X AIR DUCT | 1.00 | 81.15 | 00.00 | 81.15 |
| X COVER BUMPER AREA | 1.00 | 179.54 | 00.00 | 179.54 |
| X RIGHT HEADLIGHT VOLTAGE CONVERTER | 1.00 | 1143.32 | 00.00 | 1143.32 |
| X RIGHT HEADLIGHT CONTROL UNIT | 1.00 | 836.85 | 00.00 | 836.85 |
| X FANFARE HORN | 1.00 | 180.78 | 00.00 | 180.78 |
| X EXPANSION RIVET | 2.00 | 1.65 | 00.00 | 3.30 |
| X TOP AIR BAFFLE | 1.00 | 38.72 | 00.00 | 38.72 |
| X CAMERA | 1.00 | 1433.42 | 00.00 | 1433.42 |
| X RADAR SENSOR | 1.00 | 1157.08 | 00.00 | 1157.08 |
| X RADAR SENSOR BRACKET | 1.00 | 27.69 | 00.00 | 27.69 |

SUPPLEMENTARY

Confirmed & accepted by

Nett **6,751.54**
7% GST on **6751.54** **472.61**

Authorized signatory and company stamp

Total Payable **7,224.15**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler Stuttgart Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg