



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SLA668B

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555  
62507388

### Vehicle & Document Information

WIP No 27720  
Reg No/Reg Date SLA668B / 22/06/2016  
Date In/Mileage 24/10/2018 / 27241  
Chassis No WDD2120342B314417  
Engine No 27492030585527  
Make/Model MB/MB E 200 2.0 SEDAN (W212) "EDITION E"  
Colour/Trim 029 992 Selenite Gr/ 042 241 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator		
WL001605	Credit	27/11/2018/ 17:36	VS	356 / Vincent Seah		
		Description of Goods / Services	Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : 218P05018850 / 19.10.18  
DRIVE IN/EXCESS : 19.10.18 // NA  
DATE IN/DATE SURVEY: 19.10.18 // 22.10.18 RASUL-LKK 16:10PM  
BY/AUTHORIZED ON : VVERON CHEN- LKK // 24.10.18

X RADIATOR	1.00	1374.00	00.00	1374.00
X RADIATOR ANTIFREEZE	2.00	46.49	00.00	92.98
X BEAM	1.00	72.06	00.00	72.06
X MERCEDES STAR	1.00	130.65	00.00	130.65
X AIR DUCT	1.00	81.15	00.00	81.15
X COVER BUMPER AREA	1.00	179.54	00.00	179.54
X RIGHT HEADLIGHT VOLTAGE CONVERTER	1.00	1143.32	00.00	1143.32
X RIGHT HEADLIGHT CONTROL UNIT	1.00	836.85	00.00	836.85
X FANFARE HORN	1.00	180.78	00.00	180.78
X EXPANSION RIVET	2.00	1.65	00.00	3.30
X TOP AIR BAFFLE	1.00	38.72	00.00	38.72
X CAMERA	1.00	1433.42	00.00	1433.42
X RADAR SENSOR	1.00	1157.08	00.00	1157.08
X RADAR SENSOR BRACKET	1.00	27.69	00.00	27.69

SUPPLEMENTARY

Confirmed & accepted by

7% GST on **Nett** 6,751.54  
472.61

**Total Payable** 7,224.15

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler Stuttgart Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg