



Auto  
Consultants  
Pte Ltd

STUBIAVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408934 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: FY18/19/0027  
Our Ref: CC2/MIDA18019071 /j

15 May 2019

HQ-Transport Command  
Kranji Camp 3  
151 Chua Chu Kang Way  
Singapore 688248

**ATTENTION : IWO RAVEEN/CAPT. MERLIN**

Dear Sirs,

**ACCIDENT INVOLVING MID 21253 & PA 6104A ON 21/09/2018**

We refer to the above matter.

Based on our report, we not at fault.

The action now is for our recovery claim of our COR at \$43.72.

Considering the minimal COR. It would be cost efficient if we will not file or process recovery claim.

In view of this, we seek your approval to close file.

Kindly advise if we may proceed.

Thank you.

Yours faithfully,

Joy Irene Bascao  
Claims Section  
DID: 6749 5792  
Fax: 6741 4108  
E-mail: joyirene@lkkauto.com

51842144E  
IWO RAVEENDRAN  
TA INVESTIGATION WS  
HQ TRANSPORT

*16/5*  
**APPROVED**



RESTRICTED

FIGURE H-2 – STATEMENT OF VEHICLE COMMANDER (MID 21253)

**SINGAPORE ARMED FORCES  
STATEMENT OF TRANSPORT OPERATOR AND VEHICLE  
COMMANDER**

**SINGAPORE ARMED FORCES  
STATEMENT OF DRIVER/WITNESS**

STATEMENT OF	LTA NEO MENG HIANG BRANDON			ALIASES	
NRIC NO.	S9828932A	AGE	20	MALE/FEMALE	MALE
EMPLOYMENT	NSF	DRIVING LICENSE NO	NIL	NATIONALITY	SINGAPOREAN
DIALECT	NIL	LANGUAGE SPOKEN	CHINESE, ENGLISH	TEL NO	96306212
ADDRESS					
INTERPRETED BY	NIL	RANK		TIME	
				DATE	
SIGN					
RECORDED BY	NIL	RANK		TIME	
				DATE	
SIGN					
<p>I, S9828932A, LTA NEO MENG HIAN BRANDON, was the vehicle commander for MID 21253, a troop lift ARF tonner. On 210918, at around 0701hrs, a van scrapped past the tonner and filtered left to stop at the road shoulder. The TO slowed down after the incident and came to a stop behind the van. There were no injuries sustained from the incident while the civilian van had scratches, dents and window smashed. The tonner had visible scratches to the rim of the front right tyre.</p>					
DATE	210918	SIGNATURE OF DRIVER/WITNESS			

All statements and further statements are to timed and dated. Witness will be re-warned immediately prior to the recording of further statements. Statements and further statements will be signed by the Recording Officer and Interpreter.  
Statements of witness must be signed by the Witness.

SAP 1201





**SINGAPORE  
POLICE FORCE**



T/20180921/2089

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

2 of 3

Report No. T/20180921/2089

CONTINUATION OF REPORT

<b>Driver</b>			
Name	MUHAMMAD NJR HAKIM BIN MOHD YUSOFF	ID No.	S9541952F
Related Vehicle	MID21253	Contact No.	83993270
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	Rosli Samsuri Bin Mardi	ID No.	S7370471E
Related Vehicle	PA6104A	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

I, S9541952F, PTE MUHAMMAD NJR HAKIM, was travelling along, PIE(Tuas) on the leftmost lane(Lane 3) after passing jurong town hall exit (Exit 31), a white civilian van (PA6104A) Driven by S7370471E, who was travelling along lane 2 and hit onto my 5 ton (MID21253) Near Lamppost 1535F

The White van's left side grazed onto the right side of my vehicle. That portion of the expressway was a right bend. The driver informed me that he could have understeers his vehicle causing it to deviate off his lane and grazed onto the right side of my vehicle, MID21253.

The vehicle I was driving suffered some scratches and dents on the right side while the white van suffered some dents and scratches on his left side. The front left side door handle of the van is also damage as it collided with a metal piece on the vehicle I was driving.

That's all.



**SINGAPORE  
POLICE FORCE**



T/20180921/2089

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

3 of 3

Report No. T/20180921/2089

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: D / ASP TEOH TENG CHOON <i>TC</i>	Signature Of Informant: <i>Yis</i>
Signature Of Interpreter: Not applicable	Date/Time: 21/09/2018 13:41
Officer In Charge Of Case: TP / AEIT / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:  <div style="border: 1px solid black; padding: 2px; display: inline-block;">SN 37</div>
Authentication Stamp NP168 <div style="border: 1px solid black; padding: 5px; text-align: center;">           SIGNATURE       </div>	



RESTRICTED

### COMPLETED COST OF REPAIR

(To be completed for only one type of item)

To:	CLEMENTI NODE	From:	Ref	MID21253
CLEMENTI NODE Unit		92FMD/CLEMENTI IWF Base/LEO Area Office		

Description of Item:	MAN STEER	SAF 1222:	-
Part/Reg No:	-	Original Value:	-
Quantity:	-	CE/Non CE:	-
Description of Damages and Costs of Repairs:		Workshop Job No:	8202172180
		Date:	24 September 2018

#### ACCIDENT INSPECTION

- 1) RH Front Rim Cover graze with scratch mark

#### Base/LEO Area Office's Assessment of Damages

Labour Charges @ \$43.72 per hour x 1 hrs = \$43.72  
Total Cost of Parts / Materials Used = -  
Sub-contractor = -  
Towing Service = -  
Total = \$43.72

#### Estimated Time for Repair:

#### Base/LEO Area Office's comment on the Damages:

1. Damage due to Accident: RH Front Rim Cover graze with scratch mark
2. The item is Repairable / Beyond Economical Repair
3. Additional Comments and Recommendations: NIL

SIGNATURE:

UNIT STAMP:



RANK & NAME:

M2 Mhd Firdaus  
S8521263Z

24/09/18

\*Delete whichever is not applicable  
SAF 1223/90

RESTRICTED