

22/03/2002

ASS. SEC. BY:

REF: CS/SPF18019101/Koboz

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Frankie Tay of SPF Date/Time: 22-10-2018

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKT8924X Insured: Qx 590K

at Workshop n/s Tan Chong Motor Tel: 63570757

of 17 Lorong 8 Toa Payoh

Policy No: Claim No: AEMD / 105 / 10A / 2018 / 148

Sum Insured: Excess:

Make of Veh: D.O.A. 15.10.2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' 23.10.2018 @ 10am - 12pm H.O.D. Endorsement:

Date/Time: 22.10.2018 149pm Person Contacted: Affendi Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKT 8924X - x
	Qx 590K - x
3/1	Vehicle has not send in for repair. Pending for liability.
4/1	Submit preli report. (Repair range \$3K-\$5K) Final fig \$2,030.24 ; 4 days (Red. 5143.44, 71%)
3/4	Reopen file to submit final report.

REF: SPF

ASSIGNMENT

From: _____ Date: 23-10-2018

Veh No: SKT 8924X Yr Regn: 06/15

Estimated Cost: _____

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____

To Inspect Vehicle No: SKT 8924X
at Workshop m/s: Tan Chong
of: 17 Lorong 8 Tou Payoh

Make: NIS ^{A)} Q99999 c.c. 1197

Colour: M. Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 85175 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STNFEAJ11U1405401

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD/Rim or

Tyre Size: F: 215/60R17


R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

(Policy Condition)

10am - 12pm



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

Front

Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal. 9 mm

R/Bal. 9 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 9 mm

L/Bal. 9 mm

Est. Repairs: 4-5 days Res.: Yes or No

D.O.A. 15/10/18

D.O.I. 23/10/18

Lum Sum: 1.31 % 3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Do not finalize

24/10 File pass to Catherine (3-9K)

Date/Time, File Pass to?

: Preli. Report
 : Final Report

Days Of Repair: 5

1) _____

Resurvey No. of Trip: -

Survey Fee: 280

Date/Time, File Return to?

Transportation: _____

2) _____

Add Fee: : Site Insp (\$) \$ + RS, SI

: Interview (\$) Photos

: Tech. Invs (\$) Others

: Weekend (\$)

Report Format: TP

Lump Sum / I.B.I: (\$)

TOTAL

280

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : 225/1C/TC/HO/2018

DATE : 18-OCT-2018

SPP ACCIDENT CLAIMS SECTION
POLICE LOGISTICS DEPARTMENT
NO.1 MOUNT PLEASANT ROAD
BLK 8 OLD POLICE ACADEMY S(298333)
TEL : 64784840
FAX : 64784848
MR QUEK SWEE CHOON

OWNER'S NAME : MR CHEW CHYE GUAN
ADDRESS : 145 LENTOR STREET

S(786840)
TELEPHONE NO : 83838812/98311218

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : SINGAPORE POLICE FORCE 3RD PAR
VEHICLE NO : SKT8924X
MODEL CODE : FRLARB2J11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2152137A
CHASSIS NO : SJNFEAJ11U1405401
MILEAGE : 1 KM
DATE IN : 18/10/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HO YUE MENG
ACCIDENT DATE : 15/10/2018

TC AUTOCLINIC PTE LTD
 1 SIXTH LOK YANG ROAD
 SINGAPORE 628099

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGH NO SKT89242

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	NP1	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS-REAR	60.00	X
2	NP1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	X nn
3	RS1	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	601 110
4	SEAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X nn
5	ZZ/001	REMOVE/INSTALL REAR BUMPER, END PANEL AND AFFECTED PORTION. REPAIR BACK DOOR, LHR FENDER & RHR FENDER	1560.00	7801
6	ZZ/002	RESPRAY PAINT REAR BUMPER, END PANEL, BACK DOOR, LH REAR FENDER AND RH REAR FENDER	1500.00	5001
7	ZZ/003	REMOVE/INSTALL REAR SEAT AND CARPETS TO FACILITATE THE REPAIR	240.00	X nn
8	ZZ/004	CHECK REAR LIGHTINGS AND WIRING SYSTEM	20.00	✓
TOTAL LABOUR CHARGES			3710.00	

TC AUTOCLINIC PTE LTD
 1 SIXTH LOK YANG ROAD
 SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REG NO SKTB924X

DAMAGED PARTS & PRICES					
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1	CLIP-LH REAR OVER FENDER @\$2.50EACH X3PCS	76847-3G00A	<i>me</i> 7.50	<input checked="" type="checkbox"/>	
2	CLIP-LH REAR OVER FENDER @\$2.50EACH X3PCS	76847-4EA0A	<i>me</i> 7.50	<input checked="" type="checkbox"/>	
3	OVER FENDER-REAR, LH	93829-4EA0A	<i>R</i> 483.00	<input checked="" type="checkbox"/>	
4	CLIP-REAR LUGGAGE PLATE @\$1.20EACH X4PCS	01554-001B1	<i>me</i> 4.80	<input checked="" type="checkbox"/>	
5	PLATE-LUGGAGE, REAR	01992-4EA0A	<i>me</i> 63.50	<input checked="" type="checkbox"/>	
6	DRAFTER-AIR @\$62.30EACH X2PCS	76804-JD00A	<i>Sm</i> 124.60	<input checked="" type="checkbox"/>	
7	WEATHER STRIP-BACK DOOR	90830-4EA00	<i>Sm</i> 158.70	<input checked="" type="checkbox"/>	
8	EMBLEM-REAR	90892-4EA0A	<i>me</i> 87.00	<input checked="" type="checkbox"/>	
9	EMBLEM-REAR	90890-4EA0A	<i>me</i> 59.70	<input checked="" type="checkbox"/>	
10	LH REAR BUMPER STAY	H5211-4EANA	<i>R</i> 126.00	<input checked="" type="checkbox"/>	
11	RH REAR BUMPER STAY	H5210-4EANA	<i>R</i> 126.00	<input checked="" type="checkbox"/>	
12	REAR BUMPER REINFORCEMENT	H5030-4EANA	<i>R</i> 619.20	<input checked="" type="checkbox"/>	
13	REAR BUMPER ENERGY ABSORBER	85090-4EA00	<i>Sm</i> 126.40	<input checked="" type="checkbox"/>	
14	RH REAR BUMPER SIDE BRACKET	85220-4EA0A	<i>R</i> 35.90	<input checked="" type="checkbox"/>	
15	LH REAR BUMPER SIDE BRACKET	85221-4EA0A	<i>R</i> 35.90	<input checked="" type="checkbox"/>	
16	RETAINER-REAR BUMPER SIDE, LH	79185-4EA0A	<i>Di</i> 23.80	<input checked="" type="checkbox"/>	
17	RETAINER-REAR BUMPER SIDE, RH	79184-4EA0A	<i>Sm</i> 23.80	<input checked="" type="checkbox"/>	
18	REAR BUMPER UPPER CLIP @\$7.40EACH X3PCS	85284-JD00A	<i>me</i> 22.20	<input checked="" type="checkbox"/>	
19	CANOE RIVET-REAR BUMPER @\$6.50EACH X2PCS	76882-0M000	<i>Di</i> 13.00	<input checked="" type="checkbox"/>	
20	REAR BUMPER LOWER CLIP @\$1.20EACH X4PCS	01553-05933	<i>me</i> 4.80	<input checked="" type="checkbox"/>	
21	FINISHER-REAR BUMPER	85071-4EA0A	<i>Sm</i> 16.80	<input checked="" type="checkbox"/>	
22	REVERSE SENSOR (4EYE)	SENSOR-4-FUM			SVC 250.00 <input checked="" type="checkbox"/>
23	REAR BUMPER FASCIA	85022-4EA0H	<i>me</i> 717.00	<input checked="" type="checkbox"/>	
24	REAR END PANEL	G9110-4EANA	<i>R</i> 482.60	<input checked="" type="checkbox"/>	
25	LAMP ASSY-REAR COMBI, RH	26550-4EA0A	<i>Sm</i> 323.70	<input checked="" type="checkbox"/>	

TC AUTOCLINIC PTE LTD
 1 SIXTH LOR YANG ROAD
 SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGH ID SET8924X

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
26	LAMP ASSY-REAR COMBI, LH	26555-4RA0A	323.70		X
SUB TOTAL			4017.10	0.00	250.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			803.42	0.00	0.00
GRAND TOTAL			3213.68	0.00	250.00
OVERALL TOTAL			3463.68		

LEGEND: REMARKS [OK] = APPROVED, REMARKS [X] = NOT APPROVED

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To spray damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : 225/1C/TC/HO/2018
DATE : 18-OCT-2018

SPF ACCIDENT CLAIMS SECTION
POLICE LOGISTICS DEPARTMENT
NO.1 MOUNT PLEASANT ROAD
BLK 8 OLD POLICE ACADEMY S(298333)
TEL : 64784840
FAX : 64784848
MR QUEK SWEE CHOON

OWNER'S NAME : MR CHEW CHYE GUAN
ADDRESS : 145 LENTOR STREET

S(786840)
TELEPHONE NO : 83838812/98311218

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : SINGAPORE POLICE FORCE 3RD PAR
VEHICLE NO : SKT8924X
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2152137A
CHASSIS NO : SJNFEAJ11U1405401
MILEAGE : 90357 KM
DATE IN : 18/10/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HO YUE MENG
ACCIDENT DATE : 15/10/2018

"Finalised Bill"

To: LKIC

Att: Mr Kenneth

4 days

Best regards
YMD

TC AUTOCLINIC PTE LTD
 1 SIXTH LOK YANG ROAD
 SINGAPORE 628099

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKT8924X

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	BY01W	**COMPLETE WAXING OF VEHICLE		
2	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS-REAR	60.00	.00
3	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	<i>na</i> 120.00	.00 X
4	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	110.00 ✓
5	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00 <i>na</i>	.00 X
6	ZZ/001	REMOVE/INSTALL REAR BUMPER AND AFFECTED PORTION. REPAIR END PANEL	1560.00	780.00
7	ZZ/002	RESPRAY PAINT REAR BUMPER AND END PANEL	1500.00	500.00
8	ZZ/003	REMOVE/INSTALL REAR SEAT AND CARPETS TO FACILITATE TEH REPAIR	240.00 <i>na</i>	.00 X
9	ZZ/004	CHECK REAR LIGHTINGS AND WIRING SYSTEM	20.00	20.00
TOTAL LABOUR CHARGES			3710.00	1410.00

TC AUTOCLINIC PTE LTD
 1 SIXTH LOK YANG ROAD
 SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKTB924X

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	CLIP-LH REAR OVER FENDER @\$2.50EACH X3PCS	76847-JG00A	7.50			OK
2	CLIP-LH REAR OVER FENDER @\$2.50EACH X3PCS	76847-4EA0A	7.50			X
3	OVER FENDER-REAR, LH	93829-4EA0A	483.00			X
4	CLIP-REAR LUGGAGE PLATE @\$1.20EACH X4PCS	01554-00101	4.80			X
5	PLATE-LUGGAGE, REAR	84992-4EA0A	63.50			X
6	DRAFTER-AIR @\$62.30EACH X2PCS	76804-JD00A	124.60			X
7	WEATHER STRIP-BACK DOOR	90830-4EA0B	158.70			X
8	EMBLEM-REAR	90892-4EA0A	87.00			X
9	EMBLEM-REAR	90890-4EA0A	59.70			X
10	LH REAR BUMPER STAY	H5211-4EAMA	126.00			X
11	RH REAR BUMPER STAY	H5210-4EAMA	126.00			X
12	REAR BUMPER REINFORCEMENT	H5030-4EAMA	619.20			X
13	REAR BUMPER ENERGY ABSORBER	85090-4EA0B	126.40			X
14	RH REAR BUMPER SIDE BRACKET	85220-4EA0A	35.90			X
15	REAR BUMPER UPPER CLIP @\$7.40EACH X3PCS	85284-JD00A	22.20			OK
16	CANOE RIVET-REAR BUMPER @\$6.50EACH X2PCS	76882-0M000	13.00			X
17	REAR BUMPER LOWER CLIP @\$1.20EACH X4PCS	01553-05933	4.80			OK
18	FINISHER-REAR BUMPER	85071-4EA0A	16.80			X
19	REVERSE SENSOR(4EYE)	SENSOR-4-FUM			250.00	X
20	REAR BUMPER FASCIA	85022-4EA0H	717.00			OK
21	REAR END PANEL	G9110-4EAMA	482.60			X
22	LAMP ASSY-REAR COMBI, RH	26550-4EA0A	323.70			X
23	LAMP ASSY-REAR COMBI, LH	26555-4EA0A	323.70			X
24	LH REAR BUMPER SIDE BRACKET	85221-4EA0A	35.90			X
25	RETAINER-REAR BUMPER SIDE, LH	79185-4EA0A	23.80			OK

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKT8924X

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
26	RETAINER-REAR BUMPER SIDE, RH	79184-4EA0A	23.80		X
SUB TOTAL			775.30	0.00	0.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			155.06	0.00	0.00
GRAND TOTAL			620.24	0.00	0.00
OVERALL TOTAL			620.24		

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SKT8924X

NETT ITEM	775.30
LESS 20.00%)	-155.06
NETT AMOUNT	620.24
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	0.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	0.00
TOTAL LABOUR CHARGES	1410.00
TOTAL SPARE PARTS CHARGES	620.24
TOTAL CHARGES	2030.24
ADD 7 % GST	142.12
GRAND TOTAL	2172.36



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18019101/Kcbe2	
ACCIDENT CLAIM SECTION(SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 07-01-2019	
ATTN : FRANKIE THAY		Code : SPF	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 590K	Veh. Inspected	SKT 8924X
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/09/2018/148	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	22/10/2018
2. Vehicle Particulars & Condition			
Make & Model	NISSAN QASHQAI (A)	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	SJNFEAJ11U1405401	Colour	METALLIC MAROON
Odometer	85175	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R17	BRIDGESTONE	9 mm
L/H Front Tyre	215/60 R17	BRIDGESTONE	9 mm
R/H Rear Tyre	215/60 R17	BRIDGESTONE	9 mm
L/H Rear Tyre	215/60 R17	BRIDGESTONE	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/10/2018	Inspection Date	23/10/2018
Survey held at	TAN CHONG MOTOR SALES PTE LTD 17 LORONG 8 TOA PAYOH SINGAPORE 319254		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 8924X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
3	CLIP-LH REAR OVER FENDER @\$2.50 (N)	NECESSARY	7.50	7.50
3	CLIP-LH REAR OVER FENDER @\$2.50 (N)	NOT NECESSARY	7.50	-
1	OVER FENDER-REAR, LH (N)	TO REPAIR SEE LABOUR	483.00	-
4	CLIP-REAR LUGGAGE PLATE @\$1.20 (N)	NOT NECESSARY	4.80	-
1	PLATE-LUGGAGE, REAR (N)	NOT NECESSARY	63.50	-
2	DRAFTER-AIR @\$62.30 (N)	SERVICEABLE	124.60	-
1	WEATHER STRIP-BACK DOOR (N)	SERVICEABLE	158.70	-
1	EMBLEM-REAR (N)	NOT NECESSARY	87.00	-
1	EMBLEM-REAR (N)	NOT NECESSARY	59.70	-
1	LH REAR BUMPER STAY (N)	TO REPAIR SEE LABOUR	126.00	-
1	RH REAR BUMPER STAY (N)	TO REPAIR SEE LABOUR	126.00	-
1	REAR BUMPER REINFORCEMENT (N)	TO REPAIR SEE LABOUR	619.20	-
1	REAR BUMPER ENERGY ABSORBER (N)	SERVICEABLE	126.40	-
1	RH REAR BUMPER SIDE BRACKET (N)	TO REPAIR SEE LABOUR	35.90	-
1	LH REAR BUMPER SIDE BRACKET (N)	TO REPAIR SEE LABOUR	35.90	-
1	RETAINER-REAR BUMPER SIDE, LH (N)	DISTORTED	23.80	23.80
1	RETAINER-REAR BUMPER SIDE, RH (N)	SERVICEABLE	23.80	-
3	REAR BUMPER UPPER CLIP @\$7.40 (N)	NECESSARY	22.20	22.20
2	CANOE RIVET-REAR BUMPER @\$6.50 (N)	SERVICEABLE	13.00	-
4	REAR BUMPER LOWER CLIP @\$1.20 (N)	NECESSARY	4.80	4.80
1	FINISHER-REAR BUMPER (N)	SERVICEABLE	16.80	-
1	REAR BUMPER FASCIA (N)	DENTED	717.00	717.00
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	482.60	-
1	LAMP ASSY-REAR COMBI, RH (N)	SERVICEABLE	323.70	-
1	LAMP ASSY-REAR COMBI, LH (N)	SERVICEABLE	323.70	-

Report Ref No. CS/SPF18019101/Kcbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-803.42	-155.06
			3,213.68	620.24
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (4EYE) (SN)	SERVICEABLE	250.00	-
			250.00	-
	<u>LABOUR</u>			
	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS - REAR.	NOT NECESSARY	60.00	-
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.	NOT NECESSARY	120.00	-
	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST.		110.00	110.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.	NOT NECESSARY	100.00	-
	REMOVE / INSTALL REAR BUMPER, END PANEL AND AFFECTED PORTION, REPAIR BACK DOOR, LHR FENDER & RHR FENDER. INCLUSIVE OF THE REPAIR OF OVER FENDER-REAR, LH, LH REAR BUMPER STAY, RH REAR BUMPER STAY, REAR BUMPER REINFORCEMENT, RH REAR BUMPER SIDE BRACKET, LH REAR BUMPER SIDE BRACKET AND REAR END PANEL.		1,560.00	780.00
	RESPRAY PAINT REAR BUMPER, END PANEL, BACK DOOR, LH REAR FENDER AND RH REAR FENDER.		1,500.00	500.00
	REMOVE / INSTALL REAR SEAT AND CARPETS TO FACILITATE TEH REPAIR.	NOT NECESSARY	240.00	-
	CHECK REAR LIGHTINGS AND WIRING SYSTEM.		20.00	20.00
			3,710.00	1,410.00
	GRAND TOTAL		7,173.68	2,030.24
RECOMMENDED COST OF REPAIRS				2,030.24

Report Ref No. CS/SPF18019101/Kcbe2

NOTES : THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$5,000

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.