

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1201/2018/GW
Date : 21-Oct-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

13 days exclude 2 Sundays 1 PH

jb 8 Dec 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Chan Yuen Mun
Address : Blk 23 Yishun St 51
#04-07
Singapore 768086
Telephone : HP +65 81271358
Type of Claim : Own Damage Claims
Policy No. : 1700055222-01
Vehicle No : **SLS 4422 Y**
Model Code : Audi A3 Sedan 1.0 TFSI
Model / Year : Sep-18
Engine No : CHZ 528845
Chassis No : WAUZZZ8V91013081
Mileage : 36044 KM
Date In : 19-Oct-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 18-Oct-18
Place of Accident : Junction of Bay Front Ave & Marina BLVD

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 4422 Y.

S/n	Nature of Jobs	Estimated Charges			
1	To tow and recover vehicle from scene of accident.	S/N	AIG		
2	To remove and reinstall rear parking aid. Check function.	S/N	280.00	\$	280.00
3	To renew rear windscreen and lhs 1/4 glass for fender renewal.	S/N	\$	600.00	\$ 600.00
4	To remove and transfer lhs front door and lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N	\$	560.00	\$ 280.00
5	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$	1,400.00	\$ 1,400.00
6	To remove and reinstall lhs front seat assy, lhs rear seat assy, back rest, ACBD pillar, trims. Disengage curtain airbags, safety belts, carpets, roof liner, carpets, sill trims, etc.	S/N	\$	1,800.00	\$ 1,800.00
SUB- TOTAL LABOUR CHARGES		:	\$	4,640.00	\$ 4,360.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 4422 Y.

S/n	Nature of Jobs	Estimated Charges	
		c/f	\$
			4,360.00
7	To dismantle lhs front door, lhs rear door, rear bumper and rear lid. Cut out and reweld lhs rear fender, lhs sill panel and lhs B- pillar.to renew rear bumper, lhs front door and lhs rear door. re-organize crash management components. Reinstall all parts removed.	9,000.00	\$ 3,500.00
8	To respray rear bumper, lhs front door, lhs rear door, lhs rear fender, lhs sill panel, lhs B-pillar, door entrances, door hinges, roof channel, drain channel and end panelling. To carry out join sealant work and stone chip treatment.	\$ 6,200.00	\$ 2,750.00
9	To renew lhs rear rim and carry out wheel alignment.	\$ 280.00	
10	To carry out diagnostic check.	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		\$ 20,312.00	\$ 10,802.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 4422 Y

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	REAR BUMPER	\$ 1,697.00	
2	REAR BUMPER STICKY PAD	TBC	
3	REAR BUMPER FIXING PARTS	\$ 166.00	
4	REAR WHEEL HOUSING LINER ADAPTER-LH	\$ 32.00	
5	REAR BUMPER UPPER GUIDE SECTION-LH	\$ 14.00	
6	REAR BUMPER LOCKING MECHANISM	\$ 25.00	
7	REAR BUMPER SEAL RING	4 \$ 14.00	
8	REAR SIDE PANEL-LH	\$ 3,190.00	\$ 2,552.00
9	REAR WINDOW	\$ 704.00	\$ 563.20
10	PRIMER	\$ 37.00	\$ 29.12
11	REAR SIDE WINDOW-LH	\$ 502.00	\$ 401.20
12	REAR SIDE WINDOW TRIM STRIP-LH	\$ 388.00	
13	REAR DOOR-LH	\$ 2,190.00	\$ 1,752.00
14	REAR DOOR OUTER SEAL-LH	\$ 139.00	\$ 111.20
15	BONDING AGENT	\$ 43.00	
16	CLEANING SOLUTION	\$ 64.00	
17	REAR DOOR INNER SEAL-LH	\$ 165.00	
18	REAR DOOR CATCH-LH	\$ 82.00	
19	REAR DOOR CATCH COVER-LH	\$ 14.00	
20	REAR DOOR UPPER HINGE HALF-LH	\$ 72.00	
SUB- TOTAL SPARE PARTS CHARGES		\$ 9,538.00	\$ 5,408.72

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 4422 Y

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
			\$	5,408.72
21	REAR DOOR LOWER HINGE HALF-LH		\$ 44.00	
22	REAR DOOR UPPER HINGE LALF-LH LOWER		\$ 108.00	
23	REAR DOOR LOWER HINGE HALF-LH LOWER		\$ 72.00	
24	REAR EXTERIOR HANDLE-LH		\$ 207.00	\$ 165.60
25	SLIDE VALVE-LH		\$ 11.00	
26	REAR EXTERIOR HANDLE HOUSING-LH		\$ 26.00	
27	REAR DOOR MOUNTING BAR		\$ 143.00	
28	REAR DOOR WINDOW GUIDE-LH		\$ 365.00	
29	TRIM FOR PILLAR C/B -LH	2	\$ 202.00	
30	REAR WINDOW GUIDE TRIM STRIP-LH		\$ 193.00	
32	REAR WINDOW APERTURE SEAL-LH		\$ 97.00	
33	REAR WINDOW REAR SLOT SEAL WITH TRIM STRIP-LH		\$ 256.00	\$ 204.40
34	REAR WINDOW FRONT SLOT SEAL WITH TRIM STRIP-LH		\$ 268.00	
35	REAR WINDOW GUIEDE TRIM STRIP-LH		\$ 222.00	
36	REAR WINDOW REGULATOR WITHOUT MOTOR-LH		\$ 220.00	
37	REAR GUIDE RAIL-LH		\$ 45.00	
38	REAR DOOR CONTROL UNIT -LH		\$ 438.00	
39	REAR DOOR POWER MODULE-LH		\$ 363.00	
40	REAR DOOR PANEL-LH		\$ 1,430.00	
SUB-TOTAL SPARE PARTS CHARGES			\$ 4,710.00	\$ 5,778.72

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 4422 Y

S/N	Parts Description	c/f	Damaged Parts & Prices		Remark
			S/Nett	\$	
					5,778.72
41	REAR DOOR WINDOW -LH		\$	204.00	\$ 162.80
42	FRONT DOOR-LH		\$	2,190.00	
43	FRONT OUTER DOOR SEAL-LH		\$	139.00	
44	BONDING AGENT		\$	43.00	
45	CLEANING SOLUTION		\$	64.00	
46	APPLICATOR		\$	7.00	
47	FRONT DOOR ATTACHEMNT PARTS-LH		\$	206.00	
48	FRONT DOOR CATCH-LH		\$	92.00	
49	FRONT DOOR CATCH COVER-LH		\$	13.00	
50	FRONT WHEEL HOUSING LINER-LH		\$	215.00	
51	WHEEL HOUSING LINER ATTACHMENT PARTS		\$	77.00	
52	FRONT WHEEL SPOILER-LH		\$	30.00	
53	B-PILLAR TRIM		\$	102.00	
54	SILL TRIM STRIP-LH		\$	183.00	
55	B-PILLAT TRIM		\$	190.00	
56	FRONT ALUMINIUM RIM		\$	659.00	
57	RUBBER VALVE	4	\$	12.00	
58	ACRYLIC SEALANT	S/N	\$	180.00	\$ 180.00
59	CAVITY WAX	S/N	\$	140.00	\$ 140.00
60	STONE CHIP	S/N	\$	180.00	\$ 180.00
SUB-TOTAL SPARE PARTS CHARGES			\$	4,926.00	\$ 6,441.52

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 4422 Y

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
			\$	6,441.52
61	METAL FILLER POWDER	S/N	\$ 280.00	\$ 280.00
62	REAR WINDSCREEN SEALNT	S/N	\$ 200.00	\$ 200.00
63	1/4 GLASS SEALANT	S/N	\$ 100.00	\$ 100.00
64	SUNDRIES		\$ 500.00	\$ 75.44
	TOTAL SPARE PARTS CHARGES	:	\$ 20,254.00	\$ 7,096.96
	TOTAL LABOUR CHARGES	:	\$ 20,312.00	\$ 10,802.00
	GRAND TOTAL	:	\$ 40,566.00	\$ 17,898.96

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLS 4422 Y

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1201/2018/MAS

18 Jan 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLS 4422 Y, Audi A3 Sedan 1.0 TFSI

With reference to the above-mentioned vehicle, no. **SLS 4422 Y**, claimant, **Mr. Chan Yuen Mun**, please find the related document per attached.

1. A copy of the Original invoice no. 85013366 – S\$18,830.89
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLS 4422 Y

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408629
Telephone: 6388 2223

Customer Service
Service Appointment
72-hour Breakdown Service
Tel: 6366 2323
Fax: 9828 1233
Email: customer.care@premiumauto.com.sg

Page 1 17:02

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013366
Date: 08/01/2019
Order: SLS4422Y
Term: 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLS4422Y (V 35185)

Regn Date: 22/09/2017

Mileage: 36050

WIP No.: 28993

Model: A3 SEDAN 1.0 TFSI 8VMANG

Chassis: WAUZZZ8V9J1013001

Engine: CHZ 528845

Dept: U

USB No.:

You have been assisted by :- UB-Jiayee

(33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-300.00	1.00	-300.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION	280.00	1.00	280.00
S	BODYWORK	M: TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS FOR FENDER RENEWAL	600.00	1.00	600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	280.00	1.00	280.00
S	BODYWORK	M: TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	1400.00	1.00	1,400.00
S	BODYWORK	M: TO REMOVE AND REINSTALL LHS FRONT SEAT	1800.00	1.00	1,800.00
Sub-Total					
7% GST					
Grand Total					

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408600
Telephone 6388 2223

Customer Service
Service Appointment 6366 2223
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 2 17:02

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013366 Date : 08/01/2019 Order : SLS4422Y Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLS4422Y (V 35185) Regn Date: 22/09/2017 Mileage: 36050 WIP No.: 28993
Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V9J1013081 Engine: CHZ 528845 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	ASSY,LHS REAR SEAT ASSY,BACK REST,ABCD PILLAR TRIMS,DISENGAGE CURTAIN AIRBAG,SAFETY BELTS, CARPETS,ROOF LINER,SILL TRIMS,ETC M:	3500.00	1.00	3,500.00
S	BODYWORK	TO DISMANTLE LHS FRONT DOOR,LHS REAR DOOR, REAR BUMPER AND REAR LID.CUT OUT AND REWELD LHS REAR FENDER,LHS SILL PANEL AND LHS B PILLAR. TO RENEW LHS REAR DOOR.REORANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED M:	2750.00	1.00	2,750.00
S	BODYWORK	TO RESPRAY REAR BUMPER,LHS REAR DOOR,LHS REAR FENDER,LHS SILL PANEL AND END PANELLING.TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT M:	192.00	1.00	192.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK M:	1080.00	1.00	1,080.00
		TO SUPPLY ACRYLIC SEALANT,CAVITY WAX,STONE			
Sub-Total					
7% GST					
Grand Total					

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408600
Telephone 6388 2223

Customer Service
Service Appointment 6366 2323
Hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

Page 3 17:02

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013366
Date : 08/01/2019
Order : SLS4422Y
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLS4422Y (V 35185) Regn Date: 22/03/2017 Mileage: 36050 WIP No.: 28993
Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V9J1013081 Engine: CHZ 528845 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount	
		CHIP, METAL FILLER POWDER, REAR WINDSCREEN SEALANT AND 1/4 GLASS SEALANT				
X	A8V5810075TA	(A) (GER) SIDE PANEL (2	Less 020%	1.00	3190.00	2,552.00
X	A8V5845297K NVB	SIDE WINDO	Less 020%	1.00	501.50	401.20
X	A8V5845205	(SK) WINDOW (23/10/201	Less 020%	1.00	203.50	162.80
X	A8V5833051C	(SK) DOOR (23/10/2018)	Less 020%	1.00	2190.00	1,752.00
X	A8V5845501E NVB	REAR WINDOW	Less 020%	1.00	704.00	563.20
X	A8V5837901B SFO	TRIM	Less 020%	1.00	84.30	67.44
X	A8V5839911C	(SK) SEAL (23/10/2018)	Less 020%	1.00	139.00	111.20
X	A8V0837205A GRU	HANDLE	Less 020%	1.00	207.00	165.60
X	AD 00920002	PRIMER (D6)	Less 020%	2.00	18.20	29.12
X	AN 91233601	NUT	Less 020%	10.00	1.00	8.00
X	A8V5853763C 2ZZ	WINDOW SLO	Less 020%	1.00	255.50	204.40
				Sub-Total	17,598.96	
Parts 6,016.96				7% GST	1,231.93	
Labour 0.00						
Sublet 11,882.00						
Menus 0.00						
Lubricant 0.00				Grand Total	18,830.89	

Parts 6,016.96
Labour 0.00
Sublet 11,882.00
Menus 0.00
Lubricant 0.00

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Your Ref: SLS4422Y

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1201/2018/TF
9 Nov 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SEDAN 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V9J1013081
Vehicle Regn No. : **SLS4422Y**
Vehicle Mileage : 36050KM
Vehicle Owner : Mr. Chan Yuen Mun
Certificate No : 1700055222 -01
Policy Excess : \$321.00 (Inclusive GST)
Accident Date : 18th October 2018
Place : Junc of Bay Front Ave & Marina Blvd
Repair Cost : \$ 18,830.89
WIP No. : 28993
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

Date :

10/11/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Oct 2018		22 Oct 2018 14:05 Edit Adj Rpt	S\$17,898.96 Edit Estimates	S\$17,898.96 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHAN YUEN MUN, ID: S8581178I, Tel: +6581271358, Email: YUENMUN_CHAN@YAHOO.COM		
Vehicle Reg. No.:	SLS4422Y	Date of Loss:	18/10/2018 18:00 - :59 [12 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 8562174718SG	Policy/Cover Note No.:	1700055222 (Comprehensive)
		Excess:	S\$300.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 31/10/2018]		
Driver/Custodian:	CHAN YUEN MUN (32 / Male), NRIC: S8581178I, Tel: +6581271358		

[View All](#)[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

- AIG_SG (23/10/2018): Alert - Adj Mandate Approved (S\$19579.00) - SLS4422Y - Claim Handler: Dally Amri...
- AIG_SG (23/10/2018): SLS4422Y / OD / 18/10/2018 / Coverage & Excess update

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLS4422Y (8562174718SG)**
OD
Oct 18 2018 6:00PM
[CHAN YUEN MUN]
Premium Automobiles Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#)

1 per page
☒

Video

No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	19/10/18 15:10	Video - Accident [Linked Accident Report Documents]	Load MP4	☒

1 per page
☒

Assessment Reports

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/10/18 10:39	Adjuster Immediate Advice	Load HTM	☒

3 per page
☒

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/10/18 10:32	General View	Load JPG	☒
2	23/10/18 10:32	Chassis Number	Load JPG	☒
3	23/10/18 10:32	General View	Load JPG	☒
4	23/10/18 10:32	General View	Load JPG	☒
5	23/10/18 10:32	General View	Load JPG	☒
6	23/10/18 10:32	General View	Load JPG	☒
7	23/10/18 10:32	General View	Load JPG	☒
8	23/10/18 10:32	General View	Load JPG	☒
9	23/10/18 10:32	General View	Load JPG	☒
10	23/10/18 10:32	General View	Load JPG	☒
11	23/10/18 10:32	General View	Load JPG	☒
12	23/10/18 10:32	General View	Load JPG	☒
13	23/10/18 10:32	General View	Load JPG	☒
14	23/10/18 10:33	General View	Load JPG	☒
15	23/10/18 10:33	General View	Load JPG	☒
16	23/10/18 10:33	General View	Load JPG	☒
17	23/10/18 10:33	General View	Load JPG	☒
18	23/10/18 10:33	General View	Load JPG	☒
19	23/10/18 10:33	General View	Load JPG	☒
20	23/10/18 10:33	General View	Load JPG	☒
21	23/10/18 10:33	General View	Load JPG	☒
22	23/10/18 10:33	General View	Load JPG	☒
23	23/10/18 10:33	General View	Load JPG	☒
24	23/10/18 10:33	General View	Load JPG	☒
25	23/10/18 10:33	General View	Load JPG	☒
26	23/10/18 10:33	General View	Load JPG	☒
27	23/10/18 10:33	General View	Load JPG	☒

1 per page
☒

Documentation

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
----	-----------------	-----------------------------------	-----------	-------

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	23/10/18 10:32	Singapore Accident Statement	Load PDF	☐
2	23/10/18 10:32	Certificate of Insurance	Load PDF	☐
3	23/10/18 10:32	Driver's Driving License	Load PDF	☐
4	23/10/18 10:32	ESTIMATE	Load PDF	☐
5	24/01/19 10:26	DISCHARGE VOUCHER	Load PDF	☐
6	24/01/19 10:26	WORKSHOP INVOICE	Load PDF	☐

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	19/10/18 15:10	Video - Accident	Load MP4	☐

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	19/10/18 15:13	Accident Statement	Load HTM	☐

Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	19/10/18 14:44	Accident Photo	Load JPG	☒
2	19/10/18 14:44	Accident Photo	Load JPG	☒
3	19/10/18 14:44	Accident Photo	Load JPG	☒
4	19/10/18 14:44	Accident Photo	Load JPG	☒
5	19/10/18 14:44	Accident Photo	Load JPG	☒
6	19/10/18 14:44	Accident Photo	Load JPG	☒
7	19/10/18 14:44	Accident Photo	Load JPG	☒
8	19/10/18 14:44	Accident Photo	Load JPG	☒
9	19/10/18 14:44	Accident Photo	Load JPG	☒
10	19/10/18 14:44	Accident Photo	Load JPG	☒
11	19/10/18 14:44	Accident Photo	Load JPG	☒
12	19/10/18 14:44	Accident Photo	Load JPG	☒
13	19/10/18 14:44	Accident Photo	Load JPG	☒
14	19/10/18 14:44	Accident Photo	Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	19/10/18 14:25	Sketch Plan	Load JPG	☒
2	19/10/18 14:25	Sketch Plan #2	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18019102/AQBS2**Date:** 24/01/2019REFERENCE

Insured/Claimant: CHAN YUEN MUN Policy No: 1700055222
Date of Loss: 18/10/2018 Nature of Claim: OD Claim No: 8562174718SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS4422Y**
Make & Model: AUDI A3, 999cc TFSI (A) Engine No: CHZ528845
Reg. Date: 22/09/2017 (Man. Year: 2017) Chassis No: WAUZZZ8V9J1013081
Colour: Blue Odometer: 36044 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$98,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,254.00	7,096.96	13,157.04	64.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,312.00	10,802.00	9,510.00	46.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	40,566.00	17,898.96	22,667.04	55.88
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	40,266.00	17,598.96	22,667.04	56.29
+ GST 7.00/7.00% (S\$)	2,818.62	1,231.93	1,586.69	56.29
Nett Amount (S\$)	43,084.62	18,830.89	24,253.73	56.29

INSPECTION

Date of Assignment: 22/10/2018
Date Inspected: 22/10/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 13.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,697.00 FS	*- FS
2	1		*REAR BUMPER STICKY PAD (NPA)	Not Necessary	0.00 FS	*- FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	166.00 FS	*- FS
4	1		*REAR WHEEL HOUSING LINER ADAPTER - LH	Not Necessary	32.00 FS	*- FS
5	1		*REAR BUMPER UPPER GUIDE SECTION - LH	Not Necessary	14.00 FS	*- FS
6	1		*REAR BUMPER LOCKING MECHANISM	Not Necessary	25.00 FS	*- FS
7	4		*REAR BUMPER SEAL RING	Not Necessary	14.00 FS	*- FS
8	1		*REAR SIDE PANEL - LH	Distorted	3,190.00 FS	*2,552.00 FS
9	1		*REAR WINDOW	Necessary	704.00 FS	*563.20 FS
10	1		*PRIMER	Necessary	37.00 FS	*29.12 FS
11	1		*REAR SIDE WINDOW - LH	Necessary	502.00 FS	*401.20 FS
12	1		*REAR SIDE WINDOW TRIM STRIP - LH	Not Necessary	388.00 FS	*- FS
13	1		*REAR DOOR - LH	Distorted	2,190.00 FS	*1,752.00 FS
14	1		*REAR DOOR OUTER SEAL - LH	Necessary	139.00 FS	*111.20 FS
15	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
16	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
17	1		*REAR DOOR INNER SEAL - LH	Not Necessary	165.00 FS	*- FS
18	1		*REAR DOOR CATCH - LH	Not Necessary	82.00 FS	*- FS
19	1		*REAR DOOR CATCH COVER - LH	Not Necessary	14.00 FS	*- FS
20	1		*REAR DOOR UPPER HINGE HALF - LH	Not Necessary	72.00 FS	*- FS
21	1		*REAR DOOR LOWER HINGE HALF - LH	Not Necessary	44.00 FS	*- FS
22	1		*REAR DOOR UPPER HINGE HALF - LH LOWER	Not Necessary	108.00 FS	*- FS
23	1		*REAR DOOR LOWER HINGE HALF - LH LOWER	Not Necessary	72.00 FS	*- FS
24	1		*REAR EXTERIOR HANDLE - LH	Cut	207.00 FS	*165.60 FS
25	1		*SLIDE VALVE - LH	Not Necessary	11.00 FS	*- FS
26	1		*REAR EXTERIOR HANDLE HOUSING - LH	Not Necessary	26.00 FS	*- FS
27	1		*REAR DOOR MOUNTING BAR	Not Necessary	143.00 FS	*- FS
28	1		*REAR DOOR WINDOW GUIDE - LH	Not Necessary	365.00 FS	*- FS
29	2		*TRIM FOR PILLAR C/B - LH	Not Necessary	202.00 FS	*- FS
30	1		*REAR WINDOW GUIDE TRIM STRIP - LH	Not Necessary	193.00 FS	*- FS
31	1		*REAR WINDOW APERTURE SEAL - LH	Not Necessary	97.00 FS	*- FS
32	1		*REAR WINDOW REAR SLOT SEAL WITH TRIM STRIP - LH	Bent	256.00 FS	*204.40 FS
33	1		*FRONT WINDOW FRONT SLOT SEAL WITH TRIM STRIP - LH	Not Necessary	268.00 FS	*- FS
34	1		*REAR WINDOW GUIDE TRIM STRIP - LH	Not Necessary	222.00 FS	*- FS
35	1		*REAR WINDOW REGULATOR WITHOUT MOTOR - LH	Not Necessary	220.00 FS	*- FS
36	1		*REAR GUIDE RAIL - LH	Not Necessary	45.00 FS	*- FS
37	1		*REAR DOOR CONTROL UNIT - LH	Not Necessary	438.00 FS	*- FS
38	1		*REAR DOOR POWER MODULE - LH	Not Necessary	363.00 FS	*- FS
39	1		*REAR DOOR PANEL - LH	Not Necessary	1,430.00 FS	*- FS
40	1		*REAR DOOR WINDOW - LH	Shattered	204.00 FS	*162.80 FS
41	1		*FRONT DOOR - LH	Not Necessary	2,190.00 FS	*- FS
42	1		*FRONT OUTER DOOR SEAL - LH	Not Necessary	139.00 FS	*- FS
43	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
44	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
45	1		*APPLICATOR	Not Necessary	7.00 FS	*- FS
46	1		*FRONT DOOR ATTACHMENT PARTS - LH	Not Necessary	206.00 FS	*- FS
47	1		*FRONT DOOR CATCH - LH	Not Necessary	92.00 FS	*- FS
48	1		*FRONT DOOR CATCH COVER - LH	Not Necessary	13.00 FS	*- FS
49	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	215.00 FS	*- FS
50	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	77.00 FS	*- FS
51	1		*FRONT WHEEL SPOILER - LH	Not Necessary	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*B-PILLAR TRIM	Not Necessary	102.00 FS	*- FS
53	1		*SILL TRIM STRIP - LH	Not Necessary	183.00 FS	*- FS
54	1		*B-PILLAR TRIM	Not Necessary	190.00 FS	*- FS
55	1		*FRONT ALUMINIUM RIM	Not Necessary	659.00 FS	*- FS
56	4		*RUBBER VALVE	Not Necessary	12.00 FS	*- FS
57	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
58	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
59	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
60	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
61	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
62	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
63	1		*SUNDRIES	Necessary	500.00 FS	*75.44 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					20,254.00	7,096.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT. (NPA)	New	0.00	0.00
2	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION.	New	280.00	280.00
3	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS FOR FENDER RENEWAL.	New	600.00	600.00
4	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	New	560.00	280.00
5	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	New	1,400.00	1,400.00
6	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, LHS REAR SEAT ASSY, BACK REST, ABCD PILLAR, TRIMS, DISENGAGE CURTAIN AIRBAGS, SAFETY BELTS, CARPETS, ROOF LINER, CARPETS, SILL, TRIMS, ETC.	New	1,800.00	1,800.00
7	TO DISMANTLE LHS FRONT DOOR, LHS REAR DOOR, REAR BUMPER AND REAR LID. CUT OUT AND REWELD LHS REAR FENDER, LHS SILL PANEL AND LHS B-PILLAR. TO RENEW REAR BUMPER, LHS FRONT DOOR AND LHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	9,000.00	3,500.00
8	TO RESPRAY REAR BUMPER, LHS FRONT DOOR. LHS REAR DOOR, LHS REAR FENDER, LHS SILL PANEL, LHS B-PILAR, DOOR ENTRANCES; DOOR HINGES, ROOF CHANNEL, DRAIN CHANNEL AND END PANELLING. TO CARRY OUT JOIN SEALANT WORK AND STONE CHIP TREATMENT.	New	6,200.00	2,750.00
9	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	New	280.00	0.00
10	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			20,312.00	10,802.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >