

REF:

003 / A1118019103 / A9607

ASSIGNMENT

From

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No

at Workshop m/s

of

Insured:

Policy No.

Claims No

Sum Insured:

Excess

\$300/-

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

21/88

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLR3073H.

Yr Regn:

2017

August
JulyType: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A3 Sedan.

c.c. 999

Colour

Black.

A/C: Insured / Std / NI / NA

Sp. Reading

18162.

T/Radio: Insured / Std / NI / NA

Engi No:

C/No:

WAU2228V1J100392

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size

F: 205/55R16

R: 205/55R16.

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

22/10/18.

Survey held at

Premium.

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD AIG.

Current Market Value: 97K.

New Car Price: 136K

SLR 3073H - X

RECEIVED 1-2 SEP 2019

23/10/18 @ 16:14 p.m. revised IA to AIG via merimer.

23/10/18 @ 16:22 p.m. mandate requested authorise repair to AIG via merimer.

24/10/18 @ 14:47 p.m. mandate approved by Andy Fong via merimer.

24/10/18 @ 15:19 p.m. revert authorise repair to James (Gopar) via email.

Date/Time, File Pass to?

12/09/19



: Prel. Report



: Final Report

Days Of Repair:

21

Resurvey No. of Trip:

2

Survey Fee

Transportation

) S - PE \$

) Photos

) Other

Add Fee:



Site Insp \$



Interview \$



Tech. Invs \$



Weekend \$

Report Format:

Lump Sum (I.B.) (\$) 54,935.64 P/A

300

11

211

30/08/19 Confirmed P/P \$ 54,935.64 @ 21 days
with Adrian
(\$ 24,414.36 Red - 31%)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 6499C

Vehicle Details

Vehicle No.: SLR3073H
Vehicle to be Exported: No
Intended Deregistration Date: 23 Oct 2018
Vehicle Make: AUDI
Vehicle Model: A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour: Black
Manufacturing Year: 2017
Engine No.: CHZ399301
Chassis No.: WAUZZZ8V1J1003192
Maximum Power Output: 85.0 kW (113 bhp)
Open Market Value: \$24,469.00
Original Registration Date: 08 Aug 2017
First Registration Date: 08 Aug 2017
Transfer Count: 0
Actual ARF Paid: \$16,257.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 07 Aug 2027
PARF Rebate Amount: \$12,192.00

Intended COE Rebate Details

COE Expiry Date: 07 Aug 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$42,801.00
COE Rebate Amount: \$37,623.00
Total Rebate Amount: \$49,815.00

The information contained herein is correct as at 23 Oct 2018

OK

IS YOUR CAR DUE FOR SCRAP OR EXPORT?

Use Our **FREE** Service To Get The Best Selling Price!




[SEARCH](#)

 to

[Advanced Search](#)

Home > New Cars > Audi A3 Sedan Search Results

Audi A3 Sedan Search Results (1 vehicles)

Sort by: Model (Ascending)

15 results/page

Car Model	Price	Dealer	Built in	User Rating
Audi A3 Sedan  ☐ 1.0 TFSI S tronic (A) FACELIFT + Road facelift article ☐ 1.4 TFSI S tronic (A)	\$136,440 \$13,400 /yr	Premium Automobiles • 21.3km/h 114bhp 7-speed (A) S tronic	Hungary	★★★★★ (12) 14 User Reviews Promotion Editor's Review

Car Model	Price	Dealer	Built in	User Rating
-----------	-------	--------	----------	-------------

15 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one site for buying Singapore cars, including new cars, pre-owned cars & used cars. View all new cars, such as Toyota, Honda, Nissan, Volkswagen, Mitsubishi & more. We have new car dealers representing popular agencies, authorised car distributors, and used car dealers. Find new car models, new car launches, new car promotions, new car reviews, latest car news & car advice. Also join our car discussion and forum to engage for car reviews, feedback, news & buying guides. Visit our partner sites and have full coverage for Singapore cars, Singapore car news, market and car value perspective for you.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are followed by sgCarMart.com. It is not intended to be used for any other purpose. We warrant that the information is accurate, complete and correct. sgCarMart.com does not assume any responsibility for errors or omissions or for any loss or damage caused by the use of the information.

Follow sgCarMart.com



[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

SELL YOUR CAR YOURSELF

Get listed until it's sold + we will handle all the paperwork!

POST AN AD NOW!



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Toyota Vios 1.5A G Model (New COE).



High Specs G Model, Low
Mileage, Fuel Fuel Consumption,
Well Maintained,
Direct Owner, SunAd



PRIME MOTOR & LEASING

SHENYONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES

With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.



Browse by Category

[Save Search](#)

[Print](#)

Sort by Date Posted

20 results/page

7 vehicles

Search

Audi A3

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Audi A3

Any

Any

2017

Any

Any

Any

Available



☐ Audi A3 Sedan 1.0A TFSI S-tronic

\$88,888

\$9,780 /yr

20-Jan-2017

999 cc

--

Luxury

Available

New Arrival, Audi A3 Sedan With The Latest Technology For A Better Efficiency, Fully Serviced And Maintained By Premium Automobiles With 5 Years Agent Warranty, High Loan Available, Please Arrange For...

[Posted: 21-Oct-2018](#) [Tags: 2017 Audi A3, 2017 Audi A3, 2017 Audi A3, 2017 Audi A3, 2017 Audi A3, 2017 Audi A3](#)



☐ Audi A3 Sedan 1.0A TFSI S-tronic

\$98,999

\$10,980 /yr

26-Jan-2017

999 cc

27,000 km

Luxury

Available

Newly Arrived, Beautiful Midnight Blue On Brown Leather, Good Boot Space, Certified Premium Preworn 110 Points Check, Flexible Financing And Trade In Are Available, Special 2.46% Bank Rates, Why Risk...

Premium Automobiles

[Posted: 09-Oct-2018](#) [Tags: 2017 Audi A3, 2017 Audi A3, 2017 Audi A3, 2017 Audi A3, 2017 Audi A3, 2017 Audi A3](#)



☐ Audi A3 Sedan 1.0A TFSI S-tronic

\$94,000

\$10,270 /yr

27-Feb-2017

999 cc

20,100 km

Luxury

Available

1.99% Loan Interest Rate Available! Well Maintained By The Previous Owner, Factory Fitted Interior, Accident Free, No Repairs Needed, Best Deal In Town, Buy With A Peace Of Mind, 6 Months Gearbox And ...

Carro

[Posted: 27-Oct-2018](#) [Tags: 2017 Audi A3, 2017 Audi A3, 2017 Audi A3, 2017 Audi A3, 2017 Audi A3, 2017 Audi A3](#)



☐ Audi A3 Cabriolet 1.4A TFSI S-tronic

\$132,800

\$13,860 /yr

28-Feb-2017

1,395 cc

35,500 km

Sports

Available

1 Lady Owner, Full Servicing & History Records With Premium Automobile, Lively Red Exterior With Well Kept Black Interior, Black Canvas Soft-Top, Excellent Condition For Daily Usage! Call Our Sales Co...

Orchard Credit Pte Ltd

[Posted: 12-Oct-2018](#) [Tags: 2017 Audi A3, 2017 Audi A3, 2017 Audi A3, 2017 Audi A3, 2017 Audi A3, 2017 Audi A3](#)



Latest generation of Audi A3 series

At the top of the range is the Audi S3, which packs more power, torque and a seven-speed S-tronic transmission, which comes with a coasting function.

[Read this article](#)



☐ Audi A3 Sedan 1.0A TFSI S-tronic

\$97,000

\$10,190 /yr

12-Jul-2017

999 cc

8,700 km

Luxury

Available

Lowest Depre With Low Mileage Of 8000km, Ultra Low Usage, Fully Serviced By Audi Agent, Agent Warranty In Place, Buy A Like New Car At Huge Discount From New, Selling Purely Due To Under Usage, Don't ...

[Posted: 06-Oct-2018](#) [Tags: 2017 Audi A3, 2017 Audi A3, 2017 Audi A3, 2017 Audi A3, 2017 Audi A3, 2017 Audi A3](#)



☐ Audi A3 Sportback 1.0A TFSI S-tronic

\$99,800

\$10,420 /yr

21-Aug-2017

999 cc

9,000 km

Hatchback

Available

1.98% Loan Interest Is Available Now! AA Trust Certified Quality Pre-Owned Vehicle! Extremely Well Maintained By Previous Owner! Fully Serviced And Maintained By Agent! A3 In Hatchback Guise With Knoc...

AA Trust Automotive

[Posted: 25-Sep-2018](#) [Tags: 2017 Audi A3, 2017 Audi A3, 2017 Audi A3, 2017 Audi A3, 2017 Audi A3, 2017 Audi A3](#)

SHORTLISTED

Compare

☐ Audi A3 Sedan 1.0A TFSI S-tronic

\$103,999

\$10,600 /yr

06-Nov-2017

999 cc

11,700 km

Luxury

Available



300 Points Check, Fully Serviced And Maintained By Premium Automobiles. Warranty Up To 5 Years From Date Of Registration. For Selected Unit. Please Arrange For Appointment For Viewing. Thank You!

Premium Automobiles

Posted: 29-Sep-2018 | Type: 2017 Audi A3, 2017 Audi A3, Audi A3, Audi A3, Audi A3, Audi A3, Audi A3, Audi A3, Audi A3, Audi A3

PREMIUM 300

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classified for pre-owned import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from alloy wheels, custom cars, luxury cars, sports cars or station wagons, SUV, MPV, Jeeps, etc. to CNG cars & CNG cars. They also have a lot of cars for sale from a car auction, but you can find low mileage cars, car brands, car parts & car accessories. Find new used Audi A3, Audi A3 Singapore, used Audi A3 Singapore, used Audi A3, used vehicles Singapore or even just used Audi A3 Singapore. We have new car dealers comprising pre-owned imports, registered car dealers, and used car dealers on our site. Find new car good ads, new car searches and new car promotions. Visit our website for job openings for Singapore jobs, real estate properties for sale, power car performance parts, car depreciation, forum discussions, commercial vehicle leasing & CNG results.

All prices and other information displayed on sgCarMart.com are generated from sources and based on algorithms that are followed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or for any loss or damage caused by the use of this information.

Follow sgCarMart.com



About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2018 sgCarMart. All rights reserved.

RETAIL PRICE LIST

Effective as of 6 Oct 2018



MODEL	Power (hp)	Torque (Nm)	Combined Fuel Consumption L/100km	VES (Band)	Retail Price	VES (rebate / surcharge)	Nett Price after VES
AUDI A3 Sportback							
A3 1.0 TFSI S tronic	116	200	4.8	C1	\$134,240	\$10,000	\$134,240
A3 1.4 TFSI S tronic	150	250	5.0	B	\$140,280	\$0	\$140,280
S3 2.0 TFSI qu S tronic	290	380	6.6	C2	\$219,580	\$20,000	\$239,580
RS 3 2.5 TFSI qu S tronic	400	480	8.4	C2	\$278,680	\$20,000	\$298,680
AUDI A3 Sedan							
A3 1.0 TFSI S tronic	116	200	4.7	C1	\$126,440	\$10,000	\$136,440
A3 1.4 TFSI S tronic	150	250	4.9	B	\$142,480	\$0	\$142,480
S3 2.0 TFSI qu S tronic	290	380	6.5	C2	\$221,780	\$20,000	\$241,780
RS 3 2.5 TFSI qu S tronic	400	480	8.4	C2	\$286,380	\$20,000	\$306,380
AUDI A3 Cabriolet							
A3 1.4 TFSI S tronic	150	250	5.1	B	\$178,719	\$0	\$178,719
AUDI A4 Sedan							
A4 2.0 TFSI S tronic	190	320	5.2	B	\$166,980	\$0	\$166,980
A4 2.0 TFSI qu S tronic (Design)	252	370	6.2	C2	\$221,080	\$20,000	\$243,080
S4 3.0 TFSI qu tiptronic	354	500	7.7	C1	\$284,680	\$10,000	\$294,680
AUDI A4 Avant							
A4 2.0 TFSI S tronic	190	320	5.4	B	\$176,480	\$0	\$176,480
A4 2.0 TFSI qu S tronic (Design)	252	370	6.5	C2	\$232,680	\$20,000	\$252,680
S4 3.0 TFSI qu tiptronic	354	500	7.8	C1	\$294,180	\$10,000	\$304,180
RS 4 2.9 TFSI qu tiptronic	450	600	8.9	C2	\$362,380	\$20,000	\$382,380
AUDI A5 Sportback							
A5 2.0 TFSI S tronic (Design)	190	320	5.6	B	\$191,980	\$0	\$191,980
A5 2.0 TFSI qu S tronic (Sport)	252	370	6.4	C2	\$236,930	\$20,000	\$256,930
S5 3.0 TFSI qu tiptronic	354	500	7.9	C1	\$289,580	\$10,000	\$299,580
AUDI A5 Coupe							
A5 2.0 TFSI S tronic (Design)	190	320	5.5	B	\$196,580	\$0	\$196,580
A5 2.0 TFSI qu S tronic (Sport)	252	370	6.4	C2	\$242,030	\$20,000	\$262,030
S5 3.0 TFSI qu tiptronic	354	500	7.6	C1	\$296,880	\$10,000	\$306,880
RS 5 2.9 TFSI qu tiptronic	450	600	8.8	C2	\$359,080	\$20,000	\$379,080
AUDI A5 Cabriolet							
A5 2.0 TFSI S tronic (Design)	190	320	5.9	B	\$235,701	\$0	\$235,701
A5 2.0 TFSI qu S tronic (Sport)	252	370	6.7	B	\$274,280	\$0	\$274,280
S5 3.0 TFSI qu tiptronic	354	500	8.1	C1	\$334,780	\$10,000	\$344,780
AUDI A7 Sportback							
A7 2.0 TFSI S tronic	252	370	5.9	C1	\$290,080	\$10,000	\$300,080
A7 3.0 TFSI qu S tronic (New)	340	500	7.3	C1	\$360,500	\$10,000	\$370,500
AUDI A8							
A8 L 3.0 TFSI qu tip	310	440	7.9	C1	\$402,580	\$10,000	\$412,580
A8 L 3.0 TFSI qu tip (New)	340	500	8.2	C2	\$417,479	\$20,000	\$437,479
AUDI Q2							
Q2 1.0 TFSI S tronic	116	200	5.2	C1	\$130,906	\$10,000	\$140,906
Q2 1.4 TFSI COD S tronic	150	250	5.3	B	\$150,406	\$0	\$150,406
Q2 1.4 TFSI COD S tronic (Sport)	150	250	5.3	B	\$160,380	\$0	\$160,380
AUDI Q3							
Q3 1.4 TFSI S tronic	150	250	6.0	C1	\$158,395	\$10,000	\$168,395
AUDI Q5							
Q5 2.0 TFSI qu S tronic (Sport)	252	370	7.4	C1	\$219,080	\$10,000	\$229,080
SQ5 3.0 TFSI qu tiptronic	354	500	8.7	C2	\$286,080	\$20,000	\$306,080
AUDI Q7							
Q7 2.0 TFSI qu tip	252	370	7.4	C1	\$283,780	\$10,000	\$293,780
Q7 3.0 TFSI qu tip	333	440	7.9	C2	\$343,402	\$20,000	\$363,402
AUDI Q8							
Q8 3.0 TFSI qu tip	340	500	8.9	C2	\$349,300	\$20,000	\$369,300
AUDI TT Roadster							
TT 1.8 TFSI S tronic	180	250	6.1	B	\$209,980	\$0	\$209,980
AUDI R8 Coupe							
R8 5.2 FSI qu S tronic	540	540	11.4	C2	\$763,380	\$20,000	\$783,380
AUDI R8 Spyder							
R8 5.2 FSI qu S tronic	540	540	11.7	C2	\$837,080	\$20,000	\$857,080

Terms and Conditions:

- ✓ Retail price is subject to in-house Financing and Insurance. Price includes 12-months road tax, registration fee and GST but without insurance.
 - ✓ COE is non guaranteed and subject to 8-bids, failing which new terms and conditions shall apply.
 - ✓ Booking deposit for all models is \$520,000/-. Minimum booking deposit for indent order is \$525,000/-. with the exception of RS/RB is \$75,000/-.
 - ✓ All deposits are non-refundable upon cancellation.
 - ✓ In-house utilization of PARF/COE Rebates for new car registration is within Premium Automobile's discretion.
- All prices and promotions are subject to change without any prior notice.

Re: FINAL REVISION - SLR3073H - OD AIG - SURVEYED 22 OCT 18

Shirley Hiew (LKK Auto)

Mon 2/9/2019 4:47 PM

To: Boo seng yak <boojohnny@gmail.com>; Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>;
Carrine Leong <carrine.leong@premiumauto.com.sg>; jiyee.yap@premiumauto.com.sg
<jiyee.yap@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>

Dear Mr Boo,

Confirmed final fig \$ 54,935.64 @ 21 days of repairs before excess \$ 300/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>**Sent:** Wednesday, 21 August 2019 3:23 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>;
SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>;
jiyee.yap@premiumauto.com.sg <jiyee.yap@premiumauto.com.sg>; Chang Chee Sing
<claims@premiumauto.com.sg>

Subject: FINAL REVISION - SLR3073H - OD AIG - SURVEYED 22 OCT 18

Hi Adrian and all,

Revised estimate is attached. Photo file is obtainable from our Ubi Centre. Vehicle re-inspected by Rasul on 30 Oct 18.

Please confirm repair cost of \$54,935.64 @ 21 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 24 October 2018 3:48 PM
To: 'Claims'
Cc: SUR; 'Nora Khai'
Subject: RE: OWN DAMAGE CLAIM FOR SLR 3073 H

Dear James,

As spoken, insurance approved \$ 63,381.00 inclusive of check items.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Wednesday, 24 October 2018 3:23 PM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>; 'Nora Khai' <nora.khai@premiumauto.com.sg>; 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OWN DAMAGE CLAIM FOR SLR 3073 H

Dear Shirley,

Noted.

And also kindly advise limit repair for the above mentioned vehicle.

Thanks.

Best Regards,

James Tan

Claims Advisor

Premium Automobiles Pte Ltd (Reg No: 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sq/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

Sent: Wednesday, 24 October 2018 3:19 PM

To: 'Claims'

Cc: SUR; 'Nora Khai'

Subject: RE: OWN DAMAGE CLAIM FOR SLR 3073 H

Dear James,

As instructed by our client, please proceed to repair the insured vehicle **SLR 3073H**. According to our surveyor's estimate marking (Excess \$ 300/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

Sent: Wednesday, 24 October 2018 9:15 AM

To: 'Claims' <claims@premiumauto.com.sg>

Cc: SUR <sur@lkkauto.com>; 'Nora Khai' <nora.khai@premiumauto.com.sg>

Subject: RE: OWN DAMAGE CLAIM FOR SLR 3073 H

Hi James,

We are still pending approval from insurance.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]

Sent: Wednesday, 24 October 2018 8:38 AM

To: 'Claims' <claims@premiumauto.com.sg>; 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>

Cc: 'SUR' <sur@lkkauto.com>; 'Nora Khai' <nora.khai@premiumauto.com.sg>

Subject: RE: OWN DAMAGE CLAIM FOR SLR 3073 H

Dear Shirley,

Kindly assist any update?

Thanks.

Best Regards,

James Tan

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 10000271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims [<mailto:claims@premiumauto.com.sg>]

Sent: Tuesday, 23 October 2018 3:22 PM

To: 'Shirley Hiew (LKK Auto)'

Cc: 'SUR'; 'Nora Khai'

Subject: RE: OWN DAMAGE CLAIM FOR SLR 3073 H

Dear Shirley,

We are unable to accept the repair cost within \$47,000.

We propose total loss.

Kindly advice.

Thanks.

Best Regards,
James Tan
Claims Advisor

Premium Automobiles Pte Ltd (Reg No: 199802271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

Sent: Tuesday, 23 October 2018 2:09 PM

To: 'Claims'

Cc: SUR; 'Nora Khai'

Subject: RE: OWN DAMAGE CLAIM FOR SLR 3073 H

Dear James/Nora,

Kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 47,000.00 on part by part basis?

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]

Sent: Monday, 22 October 2018 2:23 PM

To: SUR <sur@lkkauto.com>

Cc: 'Claims Dept' <claims@premiumauto.com.sg>

Subject: OWN DAMAGE CLAIM FOR SLR 3073 H

Dear All,

Kindly assist approval for the above mentioned case.

Survey was done earlier this morning.

Thanks.

Best Regards,
James Tan
Claims Advisor

Premium Automobiles Pte Ltd (Reg No: 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

View Received Message

This mail is associated with :

***SLR3073H (3158783675SG)**

OD

Oct 18 2018 6:00PM

[LI ZUOWEI]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 02/11/2018 13:01 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$67207.00) - SLR3073H - Claim Handler: Mohd Zawaye, Norsazani

Approved:67207.00.

DOCUMENTS SUMMARY

There are no documents.



View Received Message

This mail is associated with :

***SLR3073H (31587836755G)**

OD

Oct 18 2018 6:00PM

[LI ZUOWEI]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 24/10/2018 14:47 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$63381.00) - SLR3073H - Claim Handler: Mohd Zawaye, Norsazani

Approved:63381.00:To commence repairs based on new car value. All awarded, check, supplementary items to be quantified with clear damage photos

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Zawaye, Norsazani

Date: 31 Oct 2018

Preliminary Advice

Vehicle No	: SLR3073H	Accident Date	: 18/10/2018
Make	: AUDI A3	Policy No.	: 1700037426
Assignment Date	: 22/10/2018	Excess	: S\$300.00
Date of Inspection	: 22/10/2018	Est. Duration of Repair	: 21 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	79,350.00 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	60,720.00 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	6,487.00
Total	:S\$	67,207.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	136,440.00
Pre-Accident Value	:S\$	97,000.00
COE / PARF Rebate	:S\$	49,815.00
Salvage Value	:S\$	
Margin for Repair (New f	:S\$	86,625.00
	:S\$	47,185.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : SUPPLEMENTARY AMOUNT \$ 3,704.00

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Zawaye, Norsazani

Date: 30 Oct 2018

Preliminary Advice

Vehicle No	: SLR3073H	Accident Date	: 18/10/2018
Make	: AUDI A3	Policy No.	: 1700037426
Assignment Date	: 22/10/2018	Excess	: S\$300.00
Date of Inspection	: 22/10/2018	Est. Duration of Repair	: 21 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	78,052.00 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	59,721.00 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	6,365.00
Total	:S\$	66,086.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	136,440.00
Pre-Accident Value	:S\$	97,000.00
COE / PARF Rebate	:S\$	49,815.00
Salvage Value	:S\$	
Margin for Repair (New For Old Value)	:S\$	86,625.00
	:S\$	47,185.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : SUPPLEMENTARY AMOUNT IS \$ 2,705.00

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 23 Oct 2018

Preliminary Advice

Vehicle No	: SLR3073H	Accident Date	: 18/10/2018
Make	: AUDI A3	Policy No.	: 1700037426-01
Assignment Date	: 22/10/2018	Excess	: S\$0.00
Date of Inspection	: 22/10/2018	Est. Duration of Repair	: 21 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	75,347.00
Revised Amount	:S\$	57,016.00
Check Items (Estimated)	:S\$	6,365.00
Total	:S\$	63,381.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	136,440.00	
Pre-Accident Value	:S\$	97,000.00	
COE / PARF Rebate	:S\$	49,815.00	
Salvage Value	:S\$		
Margin for Repair	:S\$	86,625.00	(NEW CAR VALUE MINUS RESIDUAL VALUE)
	:S\$	47,185.00	(MARKET VALUE MINUS RESIDUAL VALUE)

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/10/2018 11:15
Date Of Accident	18/10/2018 18:20
Exact Location Of Accident	WOODLANDS AVE 12 EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR3073H
Insured/Policyholder	
Name Of Registered Owner	LI ZUOWEI
NRIC No	S7366499C
Email Address	DAVIDLIZUOWEI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97849510
Alternative Phone No	OTHERS-97849510

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.0 TFSI 8V
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700037426-01
Cover Note Number	

Driver

Name of Driver	LI ZUOWEI
NRIC No	S7366499C
Date Of Birth	22/09/1973
Occupation	INDOOR
Date Of Driving Pass	07/06/2008
Driving Experience	10 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97849510
Fax Number	
Contact Number	OTHERS-97849510
EMail Address	DAVIDLIZUOWEI@GMAIL.COM

Address	BLK 491 ADMIRALTY LINK #21-205
Postcode	750491
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING HOME FROM SLE TOWARDS CTE EXIT AT WOODLANDS AVE 12. THERE WAS A LORRY IN FRONT OF ME, LATER KNOW PLATE NO: GBE1579R, THE LORRY SUDDEN STOPPED. I WAS UNABLE TO STOP IN TIME. TO AVOID THE ACCIDENT, MY CAR HIT THE BACK OF THE LORRY AND STOPPED. THE AIRBAGS CAME OUT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE1579R
Vehicle Make/Model/Colour	TOYOTA / LORRY / SILVER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SARKER RASEL
NRIC/Passport Number	G2781551R
Contact Number	84915521
Address	NGOI & NGOI ENGINEERING
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: JAMES TAN
NRIC/Fin No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving home from SLE towards CTE Exit at Woodland Ave 12, there was a lorry in front me, later plate no. GBE 1579R, the lorry suddenly stopped, I was unable to stop in time, to avoid the accident, my car hit the back of the lorry and stopped, the airbags came out

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature

Date & Time:

[Signature]
Driver's Signature
(If driver is not the policyholder)

Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name: *[Signature]*
NRIC/FIN No.:

Accident Photo



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S7366499C**

Name **LI ZUOWEI**

Birth Date **22 Sep 1973**

Issue Date **07 Jun 2008**

0016105358




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7366499C**

Name
LI ZUOWEI

李 作为

Race
CHINESE

Date of birth **22-09-1973** Sex **M**

Country of birth
CHINA

S7366499C




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES!

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles <= 2500kg

PASS DATE **07 Jun 2008**

Licence No: **S7366499C**

NP 428A



8910213

S7366499C

NRIC No. **S7366499C**

Nationality
CHINESE

Date of issue
19-02-2008

APT BLK 491 ADMIRALTY LINK #21-205
SINGAPORE 750491

NRIC No: **S7366499C** Date: **09/07/2008** No: **6180972**






CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LI ZUOWEI
Period of Insurance : 08 Aug 2018 To 07 Aug 2019
Engine No. : CHZ 399301
Chassis No. : WAUZZZ8V1J1003192

Vehicle No. : SLR3073H
Policy No. : 1700037426-01
Endorsement No. :
Issued Date : 26 Jun 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PAFF : Yes

Person or Classes of Persons Entitled to Drive*

- a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

ZUOWEI LI - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125259

PREMIUM LEASING -PSHS

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Monik

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1200/2018/GW
Date	:	20-Oct-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Li ZouWei
Address	:	Blk 491 Admiralty link #21-205 Singapore 750491
Telephone	:	HP +65 97849510
Type of Claim	:	Own Damage Claims
Policy No.	:	1700037426-01
Vehicle No	:	SLR 3073 H
Model Code	:	Audi A3 Sedan 1.0 TFSI
Model / Year	:	Aug-17
Engine No	:	CHZ 339301
Chassis No	:	WAUZZZ8V1J1003192
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	18-Oct-18
Place of Accident	:	Woodlands Ave 12 Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 3073 H

S/N	Nature of Jobs	Estimated Charges
1	To tow and recover vehicle from scene of accident.	S/N AIG ✕
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
3	To remove and renew aircon condenser, radiator, additional radiator, electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,000.00 ✓
4	To remove center console, instrument panels and clusters. Renew dashboard, both frontal air bags, slip ring . Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain bags and knee airbag.	S/N \$ 3,600.00 ✓
5	To renew front windscreen.	S/N \$ 480.00 ✓
SUB- TOTAL LABOUR CHARGES		: \$ 5,440.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 3073 H

S/N	Nature of Jobs	Estimated Charges
6	To dismantle and renew front bumper, bonnet, both front fenders and both headlights. Renew front lock carrier and align to position. Re-organise front crash management components. reinstall all parts removed.	\$ 6,000.00 4000
7	To respray front bumper, bonnet, hinges, both front fenders and both A-pillar.	2800 3000 S/N \$ 4,700.00 4x550 = 2200 2x300 = 600 2x100 = 200
8	To carry out wheel alignment.	S/N \$ 240.00 x
9	To carry out diagnostic check.	S/N \$ 384.00 ✓
TOTAL LABOUR CHARGES		: \$ 16,764.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLR 3073 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$ 1,739.00 ✓	1391.20
2	FIXING PARTS FOR FRONT BUMPER	\$ 161.00 ✗	
3	FRONT BUMPER GUIDE SECTION-LH/RH <i>2</i>	2 \$ 66.00 ✗	
4	FRONT BUMPER GRILLE -CENTER	\$ 140.00 ✗	
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$ 460.00 ✗	
6	FRONT BUMPER CLOSING ELEMENT-LH/RH <i>2</i>	2 \$ 508.00 ✗	
7	FRONT BUMPER COVER TRIM-LH/RH <i>2</i>	2 \$ 280.00 ✗	
8	FRONT WHEEL HOSUING LINER ADAPTER -LH/RH <i>2</i>	2 \$ 64.00 ✗	
9	RADIAOTOR GRILLE <i>crushed</i>	\$ 1,239.00 ✓	991.20
10	RADIAOTOR CLOSING LEMENT <i>Distorted</i>	\$ 167.00 ✓	133.20
11	FRONT BUMPER AIR GUIDE GRILLE-LH/RH <i>new</i>	2 \$ 328.00 ✗	
12	FOAM FILLER PIECE <i>Rehnd</i>	\$ 162.00 ✓	129.60
14	FRONT BUMPER SIDE REINFORCEMENT <i>Best</i>	\$ 633.00 ✓	506
15	FRONT BUMPER COVER <i>crushed</i>	\$ 105.00 ✓	83.60
16	STICKER FOR AIR CONDITTIONER <i>free</i>	\$ 7.00 ✓	4.88
17	SIGN' CUATION'	\$ 12.00 ✓	9.28
18	FRONT FENDER-RH <i>Distorted</i>	\$ 746.00 ✓	596.80
19	FENDER ATTACHEMENT PARTS <i>2</i>	\$ 62.00 ✗	
20	FRONT FEENDER BRACKET-RH <i>2</i>	2 \$ 34.00 ✗	26.64
SUB -TOTAL SPARE PARTS		\$ 6,913.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLR 3073 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT FENDER BRACE-RH <i>damaged</i>	\$ 84.00	* ✓ 62.04
22	BONNET <i>Distorted</i>	\$ 2,755.00	✓ 2204
23	BONNET ATTACHEMENT PARTS <i>not nec</i>	\$ 141.00	✓ X
24	BONNET LID HINGE-LH/RH <i>But</i>	2 \$ 106.00	✓ 84.64
25	BONNET STOP BUFFER <i>not nec</i>	2 \$ 9.00	* ✓
26	GAS FILLED STRUT <i>not nec</i>	\$ 105.00	* ✓
27	BONNET CATCH HOOK <i>But</i>	\$ 78.00	✓ 62.24
28	BONNET STRIKER-LH/RH <i>But</i>	2 \$ 192.00	✓ 152.96
29	EDGE PROTECTION <i>not</i>	\$ 24.00	✓ 18.88
30	BONNET CATCH HOOK <i>But</i>	\$ 55.00	✓ 43.84
31	BONNET LID LOCK WITH MIRCRO <i>Damaged</i>	2 \$ 353.00	✓ 282.40
32	BONNET BOWDEN CABLE <i>? Damaged</i>	\$ 50.00	✓ 40.00
33	BONNET LID LOCK CABLE	\$ 64.00	✓ 51.12
34	BONNET COVER <i>not</i>	\$ 9.00	✓ 6.88
35	BONNET LOCK LATCH COVER <i>Damaged not nec</i>	2 \$ 7.00	- X
36	SIGNAL HORN-HIGH TONE <i>? not</i>	\$ 177.00	* ✓
37	SIGNAL HORN-LOW TONE <i>not</i>	\$ 177.00	* ✓
38	LED HEADLIGHT-LH/RH <i>cracked</i>	2 \$ 9,776.00	✓ 7820.80
39	LED HEADLIGHT POWER MODULE <i>not nec</i>	2 \$ 1,329.00	* ✓
40	LED HEADLIGHT CONTROL UNIT <i>not nec</i>	2 \$ 972.00	* ✓
SUB-TOTAL SPARE PARTS		\$ 16,463.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLR 3073 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	LED WITH HEAT SINK-LH/RH <i>not nee</i>	2 \$	1,250.00 x
42	HEADLIGHT CYLINDER-LH/RH <i>Not nee</i>	2 \$	246.00 ? X
43	HEADLIGHT WASHER HOSE <i>not nee</i>	\$	57.00 x
44	WASH WATER RESERVOIR <i>Not nee</i>	\$	177.00 ? X
45	LOCK CARRIER <i>Distorted</i>	\$	638.00 ✓ 510
46	A/C CONDENSER <i>Dented</i>	\$	468.00 ✓ 374
47	REFRIGERANT LINE FOR A/C CONDENSER <i>Not nee</i>	\$	582.00 ? X
48	REFRIGERANT LINE FOR A/C COMPRESSOR <i>Not nee</i>	\$	447.00 ? X
49	COOLER FOR COOLANT <i>Bent</i>	\$	828.00 ✓ 6240
50	ADDITIONAL COOLER FOR COOLANT <i>Bent.</i>		TBC ? 639.20
51	COOLANT CONCENTRATE 1.5 LTR <i>nee</i>	4 \$	133.00 ✓ 65.28
52	RADIATOR FAN <i>Distorted</i>	\$	1,425.00 ✓ 1140
53	AIR GUDIE-LH/RH <i>cracked</i>	2 \$	40.00 ✓ 31.84
54	RADIATOR CORE SUPPORT SEAL-RH OUTER <i>nee</i>	\$	7.00 ✓ 5.12
55	RADIATOR CORE SUPPORT AIR DUCT-UPPER CENTRE <i>Dmgd</i>	\$	10.00 ✓ 7.68
56	RADIATOR CORE SUPPORT AIR DUCT <i>Dmgd</i>	\$	59.00 ✓ 46.80
57	AIR FILTER <i>cracked</i>	\$	242.00 ✓ 193.60
58	SPRING BAND CLAMP <i>not nee</i>	\$	18.00 ✓ X
59	<i>Front</i> REAR WINDSCREEN <i>cracked.</i>	\$	953.00 ✓ 762.00
60	GEL FOIL FOR RAIN SENSOR <i>nee</i>	\$	127.00 ✓ 101.20
SUB-TOTAL SPARE PARTS		\$	7,707.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLR 3073 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	MIRROR INSIDE CLAMP <i>Not Nec</i>	\$	19.00 ? X
62	WATER DEFLECTOR STRIP-LH /RH <i>not in</i>	2 \$	160.00 +
63	FRONT FENDER-LH <i>Buckled</i>	\$	746.00 ✓ 5076.80
64	FENDER ATTACHEMENT PARTS <i>Not Nec</i>	\$	62.00 ? X
65	FRONT FENDER BRACKET-LH ? <i>foreign damaged.</i>	\$	34.00 + ✓ 26.64
66	FRONT FENDER BRACE-LH <i>foreign not in</i>	\$	84.00 + X
67	PLEUM CHAMBER COVER <i>new demand</i>	\$	156.00 + ✓ 124.88
68	BONNET SIDE SEAL-LH/RH <i>Not Nec</i>	2 \$	72.00 - X
69	INTAKE MANIFOLD <i>new cracked.</i>	\$	551.00 + ✓ 444.80
70	INTERCOOLER SEAL <i>Not Nec</i>	3 \$	39.00 ? X
71	CHARGE AIR COOLER <i>Dented</i>	\$	658.00 ? ✓ 536
72	THROTTLE VALVE CONTROL ELEMENT <i>Not Nec</i>	\$	953.00 ? X
73	THROTTLE VALVE SEAL <i>Not Nec</i>	\$	16.00 ? X
74	RETAINING BAR <i>Not Nec</i>	\$	14.00 ? X
75	FRONT W/S SEALANT <i>new</i>	\$	200.00 ✓
76	FRONT NO. PLATE <i>Best</i>	S/N \$	25.00 ✓
77	AIR BAG UNIT FOR STEERING WHEEL	\$	3,111.00 ✓ 2438.80
78	AIRBAG UNIT	\$	4,060.00 ✓ 3248.00
79	HEAD AIRBAG UNIT-LH/RH	2 \$	3,384.00 ✓ 2707.20
80	KNEE AIRBAG UNIT	\$	1,692.00 ✓ 1353.60
SUB-TOTAL SPARE PARTS		:	\$ 16,036.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLR 3073 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
81	DASH BOARD LOWER BOTTOM TRIM <i>Not seen</i>	\$ 397.00	? X
82	AIR BAG CONTROL UNIT <i>? Activated</i>	\$ 1,538.00	✓ 1230.40
83	CRASH SENSOR AIR BAG	\$ 716.00	✓ 572.40
84	THREE POINT AUTOMATIC SEAT-LH/RH <i>Activated</i>	2 \$ 1,912.00	? ✓ 1529.60
85	SEAT BELT HEIGHT ADJUSTER <i>Bond</i>	2 \$ 343.00	? ✓ 137.20
86	DASH BOARD WITH AIR DUCT <i>torn</i>	\$ 3,729.00	✓ 2993.20
87	MOULDED HEADLINER <i>crumpled</i>	\$ 1,551.00	✓ 1240.80
88	FRONT GAB HANDLE FOLDING	\$ 248.00	+
89	REAR GAB HANDLE FOLDING-LH/RH <i>? not seen</i>	2 \$ 248.00	+ ✓ 99.20
90	A PILLAR TRIM-LH/RH <i>Not seen</i>	2 \$ 282.00	X ✓ 224.80
91	SUNDRIES <i>Nec.</i>	\$ 500.00	? ✓ 105.52
TOTAL SPARE PARTS		:	\$ 58,583.00
TOTAL LABOUR CHARGES		:	\$ 16,764.00
GRAND TOTAL		:	\$ 75,347.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

79/87 76

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 22/10/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorized, 21 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/1200/2018/GW

30-Oct-18

Kee Siang

1 of 1

SLR 3073 H

Audi A3 Sedan 1.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	COOLANT HOSE WITH QUICK RELEASE COUPLING <i>cut</i>	\$ 229.00	132.80
2	WIRING CONNETOR FOR ALTERNATOR <i>CR</i>	\$ 8.00	6.24
3	NON RETURN VALVE <i>2</i>	\$ 50.00	✓ 40.16
4	WATER RESERVOIR <i>replaced</i>	\$ 177.00	✓ 141.60
5	WATER RESERVOIR END CAP <i>new</i>	\$ 18.00	✓ 14.24
6	WATER RESERVOIR STRAINER <i>new</i>	\$ 18.00	✓ 14.00
7	RADIATOR MOUNT BRACKET <i>new</i>	\$ 75.00	✓ 59.36
8	RADIATOR BUSH LOWER <i>new</i>	\$ 17.00	✓ 13.44
9	RADIATOR SEALING STRIP <i>cut</i>	\$ 14.00	✓ 11.04
10	INTAKE AIR DUCT <i>CR</i>	\$ 26.00	✓ 20.52
11	AIR GUIDE <i>CR</i>	\$ 50.00	✓ 39.76
12	VACUUM HOSE WITH NON-RETURN VALVE <i>CR</i>	\$ 348.00	✓ 278.40
13	BONNET INSULATOR <i>DE</i>	\$ 193.00	✓ 153.20
14	BONNET INSULATOR SCREW <i>new</i>	\$ 3.00	✓ 2.36
15	FENDER COVER <i>new</i>	\$ 36.00	✓ 28.16
16	FENDER COVER <i>new</i>	\$ 36.00	✓ 28.16
TOTAL		\$ 1,298.00	

For Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.	PA/OD/1200/2018/GW
Date	26-Oct-18
Service Advisor	Kee Siang
Pages	1-Jan
Regn No	SLR 3073 H
Model No	Audi A3 Sedan 1.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	STEERING WHEEL <i>cat</i>	S 2,084.00	✓ 1667.20
2	HEAD REST <i>cat</i>	S 621.00	✓ 496.80
TOTAL		S 2,705.00	

For Premium Automobiles Pte Ltd

Adrian Ling.
88/8
30/10/18.

Authorised Signature

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1200/2018/GW
Date	:	20-Oct-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

21 days - ok - jb 21 Aug 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Li ZouWei
Address	:	Blk 491 Admiralty link #21-205 Singapore 750491
Telephone	:	HP +65 97849510
Type of Claim	:	Own Damage Claims
Policy No.	:	1700037426-01
Vehicle No	:	SLR 3073 H
Model Code	:	Audi A3 Sedan 1.0 TFSI
Model / Year	:	Aug-17
Engine No	:	CHZ 339301
Chassis No	:	WAUZZZ8V1J1003192
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	18-Oct-18
Place of Accident	:	Woodlands Ave 12 Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 3073 H

S/N	Nature of Jobs	Estimated Charges			
1	To tow and recover vehicle from scene of accident.	S/N	AIG		
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$	360.00	\$ 360.00
3	To remove and renew aircon condenser, radiator, additional radiator, electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$	1,000.00	\$ 1,000.00
4	To remove center console, instrument panels and clusters. Renew dashboard, both frontal air bags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain bags and knee airbag.	S/N	\$	3,600.00	\$ 3,600.00
5	To renew front windscreen.	S/N	\$	480.00	\$ 480.00
SUB- TOTAL LABOUR CHARGES		:	\$	5,440.00	\$ 5,440.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 3073 H

S/N	Nature of Jobs	Estimated Charges	
		<i>c/f</i>	
			\$ 5,440.00
6	To dismantle and renew front bumper, bonnet, rhs front fender and both headlights. Renew front lock carrier and align to position. Re-organise front crash management components.reinstall all parts removed. (Add 1 day for 1 more frt fender replaced and added parts)	\$ 5,400.00	\$ 4,000.00
7	To respray front bumper, bonnet, hinges, lhs front fender and both A-pillar.	S/N \$ 4,000.00	\$ 2,800.00
8	To carry out wheel alignment.	S/N \$ 240.00	
9	To carry out diagnostic check.	S/N \$ 384.00	\$ 384.00
TOTAL LABOUR CHARGES		: \$ 15,464.00	\$ 12,624.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLR 3073 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,739.00	\$ 1,391.20
2	FIXING PARTS FOR FRONT BUMPER	\$ 161.00	
3	FRONT BUMPER GUIDE SECTION-LH/RH	2 \$ 66.00	
4	FRONT BUMPER GRILLE -CENTER	\$ 140.00	
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$ 460.00	
6	FRONT BUMPER CLOSING ELEMENT-LH/RH	2 \$ 508.00	
7	FRONT BUMPER COVER TRIM-LH/RH	2 \$ 280.00	
8	FRONT WHEEL HOSUING LINER ADAPTER -LH/RH	2 \$ 64.00	
9	RADIAOTOR GRILLE	\$ 1,239.00	\$ 991.20
10	RADIAOTOR CLOSING LEMENT	\$ 167.00	\$ 133.20
11	FRONT BUMPER AIR GUIDE GRILLE-LH/RH	2 \$ 328.00	
12	FOAM FILLER PIECE	\$ 162.00	\$ 129.60
14	FRONT BUMPER SIDE REINFORCEMENT	\$ 633.00	\$ 506.00
15	FRONT BUMPER COVER	\$ 105.00	\$ 83.60
16	STICKER FOR AIR CONDITTIONER	\$ 7.00	\$ 4.88
17	SIGN 'CUATION'	\$ 12.00	\$ 9.28
18	FRONT FENDER-RH	\$ 746.00	\$ 596.80
19	FENDER ATTACHEMENT PARTS	\$ 62.00	
20	FRONT FEENDER BRACKET-RH	\$ 34.00	\$ 26.64
SUB -TOTAL SPARE PARTS		\$ 6,913.00	\$ 3,872.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLR 3073 H

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 3,872.40
21	FRONT FENDER BRACE-RH	\$	84.00	\$ 67.04
22	BONNET	\$	2,755.00	\$ 2,204.00
23	BONNET ATTACHEMENT PARTS	\$	141.00	
24	BONNET LID HINGE-LH/RH	2 \$	106.00	\$ 84.64
25	BONNET STOP BUFFER	2 \$	9.00	
26	GAS FILLED STRUT	\$	105.00	
27	BONNET CATCH HOOK	\$	78.00	\$ 62.24
28	BONNET STRIKER-LH/RH	2 \$	192.00	\$ 152.96
29	EDGE PROTECTION	\$	24.00	\$ 18.88
30	BONNET CATCH HOOK	\$	55.00	\$ 43.84
31	BONNET LID LOCK WITH MIRCRO	2 \$	353.00	\$ 282.40
32	BONNET BOWDEN CABLE	\$	50.00	\$ 40.00
33	BONNET LID LOCK CABLE	\$	64.00	\$ 51.12
34	BONNET COVER	\$	9.00	\$ 6.88
35	BONNET LOCK LATCH COVER	2 \$	7.00	
36	SIGNAL HORN-HIGH TONE	\$	177.00	
37	SIGNAL HORN-LOW TONE	\$	177.00	
38	LED HEADLIGHT-LH/RH	\$	9,776.00	\$ 7,820.80
39	LED HEADLIGHT POWER MODULE	2 \$	1,329.00	
40	LED HEADLIGHT CONTROL UNIT	2 \$	972.00	
SUB-TOTAL SPARE PARTS		:	\$ 16,463.00	\$ 14,707.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLR 3073 H

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		<i>c/f</i>	\$	14,707.20
41	LED WITH HEAT SINK-LH/RH	2 \$	1,250.00	
42	HEADLIGHT CYLINDER-LH/RH	2 \$	246.00	
43	HEADLIGHT WASHER HOSE	\$	57.00	
44	WASH WATER RESERVOIR	\$	177.00	
45	LOCK CARRIER	\$	638.00	\$ 510.00
46	A/C CONDENSER	\$	468.00	\$ 374.00
47	REFRIGERANT LINE FOR A/C CONDENSER	\$	582.00	
48	REFRIGERANT LINE FOR A/C COMPRESSOR	\$	447.00	
49	COOLER FOR COOLANT	\$	828.00	\$ 662.40
50	ADDITIONAL COOLER FOR COOLANT		TBC	\$ 639.20
51	COOLANT CONCENTRATE 1.5 LTR	4 \$	133.00	\$ 65.28
52	RADIATOR FAN	\$	1,425.00	\$ 1,140.00
53	AIR GUDIE-LH/RH	2 \$	40.00	\$ 31.84
54	RADIATOR CORE SUPPORT SEAL-RH OUTER	\$	7.00	\$ 5.12
55	RADIATOR CORE SUPPORT AIR DUCT-UPPER CENTRE	\$	10.00	\$ 7.68
56	RADIATOR CORE SUPPORT AIR DUCT	\$	59.00	\$ 46.80
57	AIR FILTER	\$	242.00	\$ 193.60
58	SPRING BAND CLAMP	\$	18.00	
59	REAR WINDSCREEN	\$	953.00	\$ 762.00
60	GEL FOIL FOR RAIN SENSOR	\$	127.00	\$ 101.20
SUB-TOTAL SPARE PARTS			\$ 7,707.00	\$ 19,246.32

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLR 3073 H

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		<i>c/f</i>	\$	19,246.32
61	MIRROR INSIDE CLAMP	\$	19.00	
62	WATER DEFLECTOR STRIP-LH /RH	2 \$	160.00	
63	FRONT FENDER-LH	\$	746.00	\$ 596.80
64	FENDER ATTACHEMENT PARTS	\$	62.00	
65	FRONT FENDER BRACKET-LH	\$	34.00	\$ 26.64
66	FRONT FENDER BRACE-LH	\$	84.00	
67	PLEUM CHAMBER COVER	\$	156.00	\$ 124.80
68	BONNET SIDE SEAL-LH/RH	2 \$	72.00	
69	INTAKE MANIFOLD	\$	551.00	\$ 444.80
70	INTERCOOLER SEAL	3 \$	39.00	
71	CHARGE AIR COOLER	\$	658.00	\$ 530.00
72	THROTTLE VALVE CONTROL ELEMENT	\$	953.00	
73	THROTTLE VALVE SEAL	\$	16.00	
74	RETAINING BAR	\$	14.00	
75	FRONT W/S SEALANT	\$	200.00	\$ 200.00
76	FRONT NO. PLATE	S/N \$	25.00	\$ 25.00
77	AIR BAG UNIT FOR STEERING WHEEL	\$	3,111.00	\$ 2,488.80
78	AIRBAG UNIT	\$	4,060.00	\$ 3,248.00
79	HEAD AIRBAG UNIT-LH/RH	2 \$	3,384.00	\$ 2,707.20
80	KNEE AIRBAG UNIT	\$	1,692.00	\$ 1,353.60
SUB-TOTAL SPARE PARTS		:	\$ 16,036.00	\$ 30,991.96

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

\$ 596.80

\$ 26.64

\$ 124.80

\$ 444.80

\$ 530.00

\$ 200.00

\$ 25.00

\$ 2,488.80

\$ 3,248.00

\$ 2,707.20

\$ 1,353.60

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLR 3073 H

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		<i>c/f</i>	\$	30,991.96
81	DASH BOARD LOWER BOTTOM TRIM		\$ 397.00	
82	AIR BAG CONTROL UNIT		\$ 1,538.00	\$ 1,230.40
83	CRASH SENSOR AIR BAG		\$ 716.00	\$ 572.40
84	THREE POINT AUTOMATIC SEAT-LH/RH	2	\$ 1,912.00	\$ 1,529.60
85	SEAT BELT HEIGHT ADJUSTER	2	\$ 343.00	\$ 137.20
86	DASH BOARD WITH AIR DUCT		\$ 3,729.00	\$ 2,983.20
87	MOULDED HEADLINER		\$ 1,551.00	\$ 1,240.80
88	FRONT GAB HANDLE FOLDING		\$ 248.00	
89	REAR GAB HANDLE FOLDING-LH/RH	2	\$ 248.00	\$ 99.20
90	A PILLAR TRIM-LH/RH	2	\$ 282.00	\$ 224.80
91	Added parts		\$ 1,298.00	\$ 1,032.56
92	Added parts		\$ 2,705.00	\$ 2,164.00
93	SUNDRIES		\$ 500.00	\$ 105.52
TOTAL SPARE PARTS		:	\$ 62,586.00	\$ 42,311.64
TOTAL LABOUR CHARGES		:	\$ 15,464.00	\$ 12,624.00
GRAND TOTAL		:	\$ 78,050.00	\$ 54,935.64

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/1200/2018/GW

26-Oct-18

Kee Siang

1 of 1

SLR 3073 H

Audi A3 Sedan 1.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	STEERING WHEEL	\$ 2,084.00	\$ 1,667.20
2	HEAD REST	\$ 621.00	\$ 496.80
TOTAL		\$ 2,705.00	\$ 2,164.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315	Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1200/2018/GW 30-Oct-18 Kee Siang 1 of 1 SLR 3073 H Audi A3 Sedan 1.0 TFSI
--	---	--

Quantity	Description	Unit Price	Amount
Parts			
1	COOLANT HOSE WITH QUICK RELEASE COUPLING	\$ 229.00	\$ 182.80
2	WIRING CONNETOR FOR ALTERNATOR	\$ 8.00	\$ 6.24
3	NON RETURN VALVE	\$ 50.00	\$ 40.16
4	WATER RESERVOIR	\$ 177.00	\$ 141.60
5	WATER RESERVOIR END CAP	\$ 18.00	\$ 14.24
6	WATER RESERVOIR STRAINER	\$ 18.00	\$ 14.00
7	RADIATOR MOUNT BRACKET	\$ 75.00	\$ 59.36
8	RADIATOR BUSH LOWER	\$ 17.00	\$ 13.44
9	RADIATOR SEALING STRIP	\$ 14.00	\$ 11.04
10	INTAKE AIR DUCT	\$ 26.00	\$ 20.32
11	AIR GUIDE	\$ 50.00	\$ 39.76
12	VACUUM HOSE WITH NON-RETURN VALVE	\$ 348.00	\$ 278.40
13	BONNET INSULATOR	\$ 193.00	\$ 153.20
14	BONNET INSULATOR SCREW	\$ 3.00	\$ 1.68
15	FENDER COVER	\$ 36.00	\$ 28.16
16	FENDER COVER	\$ 36.00	\$ 28.16
TOTAL		\$ 1,298.00	\$ 1,032.56

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. PA/OD/1200/2018/GW Date 25-Feb-19 Service Advisor Kee Siang Pages 1 of 1 Regn No SLR 3073 H Model No Audi A3 Sedan 1.0 TFSI	
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Instrument Cluster (Owner not persuing)	\$ 3,937.00	AX
TOTAL		: \$ 3,937.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLR 3073 H

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1200/2018/KK

4 Sep 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

1

total pages

RE: INSURANCE CLAIM FOR SLR 3073 H, Audi A3 SEDAN 1.0 TFSI.

With reference to the above-mentioned vehicle, no. **SLR 3073 H**, claimant, **Mr Li Zuowei**, please find the related document per attached.

1. A copy of the Original invoice no. 85014192 – S\$ 58,460.13.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLR 3073 H

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408998
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 1 15:18

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice: 85014192 Date : 03/09/2019 Order : SLR3073H Term : 30	Account: A0006 (T) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120		
Regn No: SLR3073H (V 34580)		Regn Date: 08/08/2017	Mileage: 28343	WIP No.: 29000	
Model: A3 SEDAN 1.0 TFSI 8VMANG		Chassis: WAUZZZ8V1J1003192	Engine: CH2 399301	Dept: U	
You have been assisted by :- UB-Tony Foong (33)					
		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-300.00	1.00	-300.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNES FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND RENEW AIRCON CONDENSER,RADIATOR, ADDITIONAL RADIATOR,ELECTRICAL FAN AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	1000.00	1.00	1,000.00
S	BODYWORK	M: TO REMOVE CENTER CONSOLE,INSTRUMENT PANELS AND CLUSTERS.RENEW DASHBOARD,BOTH FRONTAL AIR BAGS AND SLIP RING.TRANSFER OLD FITTING. RENEW SEAT BELTS AND CONTROL UNIT,PILLAR TRIM, ROOF LININF,BOTH CURTAIN AIRBAG AND KNEE AIRBAG	3600.00	1.00	3,600.00
S	BODYWORK	M: TO RENEW FRONT WINDSCREEN	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,BONNET, RHS FRONT FENDER AND BOTH HEADLIGHTS.RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	4000.00	1.00	4,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,BONNET,HINGES,LHS FRONT FENDER AND BOTH A PILLAR	2800.00	1.00	2,800.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	384.00	1.00	384.00
S	BODYWORK	M: TO SUPPLY FRONT WINDSCREEN SEALANT	200.00	1.00	200.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6366 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6366 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408698
Main Telephone 6368 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 2 15:18

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice: 85014192 Date : 03/09/2019 Order : SLR3073H Term : 30	Account: A0006 (T) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120			
Regn No: SLR3073H (V 34580)		Regn Date: 08/08/2017	Mileage: 28343	WIP No.: 29000		
Model: A3 SEDAN 1.0 TFSI 8VMANG		Chassis: WAUZZZ8V1J1003192	Engine: CHZ 399301	Dept: U		
You have been assisted by :- UB-Tony Foong (33)						
		Details	Qty	Unit Price	Amount	
X	A8V0880201DN6PS	(A) (GER) AIRBAG (TECH)	Less 020%	1.00	3111.00	2,488.80
X	A8V5880741D	(A) (GER) AIRBAG (TECH)	Less 020%	1.00	1692.00	1,353.60
X	A8V5880742D	(A) (SK) AIRBAG (TECH)	Less 020%	1.00	1692.00	1,353.60
X	A8V2880841D	(A) (SK) AIRBAG (TECH)	Less 020%	1.00	1692.00	1,353.60
X	A5Q0959655BJ	(A) (SK) MODULE (TECH)	Less 020%	1.00	1538.00	1,230.40
X	A8V5867505S YX7	(A) (GER) ROOFLINING (T	Less 020%	1.00	1551.00	1,240.80
X	A8V5867233A VU6	(V) (GER) LINING (TECH)	Less 020%	1.00	140.50	112.40
X	A8V5867234A VU6	(V) (GER) LINING (TECH)	Less 020%	1.00	140.50	112.40
X	A04C129601G	(V) (GER) AIRCLEANER	Less 020%	1.00	242.00	193.60
X	A04C129709E	(A) (SK) MANIFOLD	Less 020%	1.00	556.00	444.80
X	A04C145749A	(A) (SK) COOLER	Less 020%	1.00	662.50	530.00
X	A5Q0121049CB	(V) (G) WATER HOSE	Less 020%	1.00	228.50	182.80
X	A04E103175M	(A) (SK) VALVE	Less 020%	1.00	50.20	40.16
X	A8V0121331	(A) (SK) SEAL STRIP	Less 020%	1.00	13.80	11.04
X	A8V0419091CHINU	(V) (GER) STEERINGWH	Less 020%	1.00	2084.00	1,667.20
X	A8V3853651AA3FZ	GRILLE	Less 020%	1.00	1239.00	991.20
X	A8V0880204G	(A) (SK) AIRBAG (TECH)	Less 020%	1.00	4060.00	3,248.00
X	A8V0941773D	HEADLIGHT	Less 020%	1.00	4888.00	3,910.40
X	A8V0941774D	HEADLIGHT	Less 020%	1.00	4888.00	3,910.40
X	A8V5821105A	FENDER	Less 020%	1.00	746.00	596.80
X	A8V0863825	(A) (SK) SILENCER	Less 020%	1.00	191.50	153.20
X	A8V5821106A	FENDER	Less 020%	1.00	746.00	596.80
X	A5Q0816411AS	(V) (GER) CONDENSER	Less 020%	1.00	467.50	374.00
X	A5Q0121251GD	RADIATOR	Less 020%	1.00	828.00	662.40
X	A5Q0121251GB	RADIATOR	Less 020%	1.00	799.00	639.20
X	A8V5819401A 9B9	COVER	Less 020%	1.00	156.00	124.80
X	A8V0805588A	CARRIER	Less 020%	1.00	637.50	510.00
X	A5Q0121203DA	ELECTRIC F	Less 020%	1.00	1425.00	1,140.00
X	A8V0807550A	FOAM INSER	Less 020%	1.00	162.00	129.60
X	A8V4807109E	BEAM	Less 020%	1.00	632.50	506.00
X	AG A13040M2	PREMIX-COOLANT	Less 020%	4.00	20.40	65.28
X	A8V5845099G HVB	GLASS	Less 020%	1.00	952.50	762.00
X	A8V5823029A	HOOD	Less 020%	1.00	2755.00	2,204.00
X	A8V5807065R GRU	COVER	Less 020%	1.00	1739.00	1,391.20

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6386 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 3 15:18

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85014192 Date : 03/09/2019 Order : SLR3073H Term : 30	Account: A0006 (T) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SLR3073H (V 34580) Regn Date: 08/08/2017 Mileage: 28343 WIP No.: 29000
Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V1J1003192 Engine: CHZ 399301 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details		Qty	Unit Price	Amount
X	ABV2857001J 24N	(A) (SK) DASHBOARD (TEC	Less 020%	1.00	3729.00	2,983.20
X	A431955465A	GASKET	Less 020%	1.00	6.40	5.12
X	A1K0955455	COVER	Less 020%	1.00	17.80	14.24
X	A04E145757	GASKET	Less 020%	1.00	12.30	9.84
X	A5Q0121367F	BRACKET	Less 020%	2.00	37.10	59.36
X	ABV0121285A	AIR DUCT	Less 020%	1.00	9.60	7.68
X	ABV0823126B	EDGING	Less 020%	1.00	23.60	18.88
X	ABV0807217A	COVER	Less 020%	1.00	104.50	83.60
X	ABV5821468B	BRACKET	Less 020%	1.00	33.30	26.64
X	ABV0823301G	HINGE	Less 020%	1.00	52.90	42.32
X	ABV0823302G	HINGE	Less 020%	1.00	52.90	42.32
X	ABV0821136C	SUPPORT	Less 020%	1.00	83.80	67.04
X	ABV5821467B	BRACKET	Less 020%	1.00	33.30	26.64
X	A5Q0129621B	AIR DUCT	Less 020%	1.00	17.20	13.76
X	ABV0121230	SEAL	Less 020%	1.00	6.80	5.44
X	A5Q0129618J	AIR DUCT	Less 020%	1.00	58.50	46.80
X	A1K0121367F	MOUNTING	Less 020%	2.00	8.40	13.44
X	ABV0823185C	CATCH	Less 020%	1.00	95.60	76.48
X	ABV0857819	(A) (SK) ADJUSTER (TECH	Less 020%	1.00	171.50	137.20
X	ABV0823186C	CATCH	Less 020%	1.00	95.60	76.48
X	A4H0823543	COVER	Less 020%	1.00	8.60	6.88
X	ABV0821169E	(A) (SK) COVER	Less 020%	1.00	35.20	28.16
X	ABV4823485C	HOOK	Less 020%	1.00	54.80	43.84
X	A4D0260749B	WASHER	Less 020%	1.00	2.90	2.32
X	A3D0260749C	WASHER	Less 020%	1.00	3.80	3.04
X	A5Q0612041BD	(V) (G) HOSE	Less 020%	1.00	348.00	278.40
X	ABV0823480A	HOOK	Less 020%	1.00	77.80	62.24
X	A4H0823188	(V) (GER) COVER	Less 020%	1.00	3.10	2.48
X	ABV0823509A	LOCK	Less 020%	2.00	176.50	282.40
X	ABV5857705E V04	(A) (SK) SEAT BELT (TEC	Less 020%	1.00	956.00	764.80
X	ABV5857706E V04	(A) (SK) SEAT BELT (TEC	Less 020%	1.00	956.00	764.80
X	ABV0857607 MGE	(V) (GER) HANDLE (TECH	Less 020%	1.00	124.00	99.20
X	ABV2823535B	(V) (GER) CABLE	Less 020%	1.00	63.90	51.12
X	ABV0823531A	BOWD CABLE	Less 020%	1.00	50.00	40.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6366 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6366 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6366 2323
Main Telefax 6541 1153

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 4 15:18

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice: 85014192 Date : 03/09/2019 Order : SLR3073H Term : 30	Account: A0006 (T) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120			
Regn No: SLR3073H (V 34580)		Regn Date: 08/08/2017	Mileage: 28343	WIP No.: 29000		
Model: A3 SEDAN 1.0 TFSI 8VMANG		Chassis: WAUZZZ8V1J1003192	Engine: CHZ 399301	Dept: U		
You have been assisted by :- UB-Tony Feong (33)						
		Details	Qty	Unit Price	Amount	
X	ABV0821170E	COVER	Less 020%	1.00	35.20	28.16
X	A4A0955485	STRAINER	Less 020%	1.00	17.50	14.00
X	ABV0885901AN3RM	(V) (GER) HEADREST	Less 020%	1.00	621.00	496.80
X	ABU0955609	FILM	Less 020%	1.00	126.50	101.20
X	A5Q0959651B	(A) (SK) SENSOR (TECH)	Less 020%	3.00	238.50	572.40
X	A1K0973751	HOUSING	Less 020%	1.00	13.40	10.72
X	A443955465	GASKET	Less 020%	1.00	2.80	2.24
X	A4H0973712	HOUSING	Less 020%	1.00	7.80	6.24
X	A8K0010520A	PLATE	Less 020%	1.00	11.60	9.28
X	A8V0010515A	STICKER	Less 020%	1.00	6.10	4.88
X	A5Q0129254B	AIR DUCT	Less 020%	1.00	49.70	39.76
X	A8V0121284K	AIR DUCT	Less 020%	1.00	19.90	15.92
X	A8V0121283K	AIR DUCT	Less 020%	1.00	19.90	15.92
X	A8V3853949	PLATE	Less 020%	1.00	166.50	133.20
X	A5Q0955453R	WATER RES.	Less 020%	1.00	177.00	141.60
X	AN 0161857	POP-RIVET	Less 020%	10.00	2.90	23.20
X	AN 91022001	NUT	Less 020%	4.00	1.40	4.48
X	AN 90656201	CLIP	Less 020%	1.00	17.20	13.76
X	AWHT005551A	BOLT	Less 020%	8.00	1.10	7.04
X	AN 91097201	SCREW	Less 020%	5.00	1.80	7.20
X	AN 91141501	RIVET	Less 020%	1.00	2.10	1.68
X	A5Q0129954	COVER	Less 020%	1.00	25.40	20.32

Parts 42,086.64
Labour 0.00
Sublet 12,849.00
Menus 0.00
Lubricant 0.00



Sub-Total 54,635.64

7% GST 3,824.49

Grand Total 58,460.13

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Your Ref: SLR 3073 H

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1200/2018/JW
14 Nov 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER


Make & Model : Audi A3 SEDAN 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V1J1003192
Vehicle Regn No. : SLR 3073 H
Vehicle Mileage : 18167 KM
Vehicle Owner : Mr. Li Zuowei
Certificate No : 1700037426-01
Policy Excess : \$321.00
Accident Date : 18th October 2018
Place : Along Woodlands Ave 12 Exit
Repair Cost : \$ 58,460.13
WIP No. : 29000
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

11:00

Date :

16/11/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Oct 2018		22 Oct 2018 14:09 Edit Adj Rpt	S\$54,935.64 Edit Estimates	S\$54,935.64 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LI ZUOWEI , ID: S7366499C, Tel: +6597849510, Email: DAVIDLIZUOWEI@GMAIL.COM									
Vehicle Reg. No.: SLR3073H		Date of Loss: 18/10/2018 18:00 - :59 [14 Months and 10 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 315878367SSG		Policy/Cover Note No.: 1700037426 (Comprehensive)							
		Excess: S\$300.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 31/10/2018]									
Driver/Custodian: LI ZUOWEI (45 / Male) , NRIC: S7366499C, Tel: +6597849510 Email: DAVIDLIZUOWEI@GMAIL.COM									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (02/11/2018): Alert - Adj Mandate Approved (S\$67207.00) - SLR3073H - Claim Handler: Mohd Zaway... - AIG_SG (24/10/2018): Alert - Adj Mandate Approved (S\$63381.00) - SLR3073H - Claim Handler: Mohd Zaway... - AIG_SG (24/10/2018): SLR3073H / OD / 18/10/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR3073H (31587836755G)

OD

Oct 18 2018 6:00PM

[LI ZUOWEI]

Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Video						1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print		
1	19/10/18 11:36	Video - Accident [Linked Accident Report Documents]		Load AVI			
Assessment Reports						1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	23/10/18 16:14	Adjuster Immediate Advice		Load HTM			
2	30/10/18 17:43	Adjuster Immediate Advice		Load HTM			
3	30/10/18 17:49	Adjuster Immediate Advice		Load HTM			
4	31/10/18 17:50	Adjuster Immediate Advice		Load HTM			
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	23/10/18 16:20	General View		Load JPG	☒		
2	23/10/18 16:20	General View		Load JPG	☒		
3	23/10/18 16:20	General View		Load JPG	☒		
4	23/10/18 16:20	General View		Load JPG	☒		
5	23/10/18 16:20	General View		Load JPG	☒		
6	23/10/18 16:20	General View		Load JPG	☒		
7	23/10/18 16:20	General View		Load JPG	☒		
8	23/10/18 16:20	General View		Load JPG	☒		
9	23/10/18 16:20	General View		Load JPG	☒		
10	23/10/18 16:20	General View		Load JPG	☒		
11	23/10/18 16:20	General View		Load JPG	☒		
12	23/10/18 16:20	General View		Load JPG	☒		
13	23/10/18 16:20	General View		Load JPG	☒		
14	23/10/18 16:20	General View		Load JPG	☒		
15	23/10/18 16:20	General View		Load JPG	☒		
16	23/10/18 16:20	General View		Load JPG	☒		
17	23/10/18 16:20	General View		Load JPG	☒		
18	23/10/18 16:20	General View		Load JPG	☒		
19	23/10/18 16:20	General View		Load JPG	☒		
20	23/10/18 16:20	General View		Load JPG	☒		
21	23/10/18 16:20	General View		Load JPG	☒		
22	23/10/18 16:20	General View		Load JPG	☒		
23	23/10/18 16:20	General View		Load JPG	☒		
24	23/10/18 16:20	General View		Load JPG	☒		
25	23/10/18 16:20	General View		Load JPG	☒		
26	23/10/18 16:20	General View		Load JPG	☒		
27	23/10/18 16:20	General View		Load JPG	☒		
28	23/10/18 16:20	General View		Load JPG	☒		
29	23/10/18 16:20	General View		Load JPG	☒		
30	23/10/18 16:20	General View		Load JPG	☒		
31	23/10/18 16:20	General View		Load JPG	☒		
32	23/10/18 16:20	General View		Load JPG	☒		
33	23/10/18 16:20	General View		Load JPG	☒		
34	23/10/18 16:20	General View		Load JPG	☒		
35	23/10/18 16:20	General View		Load JPG	☒		

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
36	23/10/18 16:20	General View	 Load JPG	☒
37	23/10/18 16:20	General View	 Load JPG	☒
38	23/10/18 16:20	General View	 Load JPG	☒
39	23/10/18 16:20	General View	 Load JPG	☒
40	23/10/18 16:20	General View	 Load JPG	☒
41	23/10/18 16:20	General View	 Load JPG	☒
42	23/10/18 16:20	General View	 Load JPG	☒
43	23/10/18 16:20	General View	 Load JPG	☒
44	23/10/18 16:20	General View	 Load JPG	☒
45	23/10/18 16:20	General View	 Load JPG	☒
46	23/10/18 16:20	General View	 Load JPG	☒
47	23/10/18 16:20	General View	 Load JPG	☒
48	23/10/18 16:20	General View	 Load JPG	☒
49	23/10/18 16:20	General View	 Load JPG	☒
50	23/10/18 16:20	General View	 Load JPG	☒
51	23/10/18 16:20	General View	 Load JPG	☒
52	23/10/18 16:20	General View	 Load JPG	☒
53	23/10/18 16:20	General View	 Load JPG	☒
54	23/10/18 16:20	General View	 Load JPG	☒
55	23/10/18 16:20	General View	 Load JPG	☒
56	23/10/18 16:20	General View	 Load JPG	☒
57	23/10/18 16:20	General View	 Load JPG	☒
58	23/10/18 16:20	General View	 Load JPG	☒
59	23/10/18 16:20	General View	 Load JPG	☒
60	23/10/18 16:20	General View	 Load JPG	☒
61	23/10/18 16:20	General View	 Load JPG	☒
62	23/10/18 16:20	General View	 Load JPG	☒
63	23/10/18 16:20	General View	 Load JPG	☒
64	23/10/18 16:20	Chassis Number	 Load JPG	☒
65	23/10/18 16:20	General View	 Load JPG	☒
66	23/10/18 16:20	General View	 Load JPG	☒
67	23/10/18 16:20	General View	 Load JPG	☒
68	23/10/18 16:20	General View	 Load JPG	☒
69	23/10/18 16:20	General View	 Load JPG	☒
70	23/10/18 16:20	General View	 Load JPG	☒
71	23/10/18 16:20	General View	 Load JPG	☒
72	23/10/18 16:20	General View	 Load JPG	☒
73	23/10/18 16:20	General View	 Load JPG	☒
74	23/10/18 16:20	General View	 Load JPG	☒
75	23/10/18 16:20	General View	 Load JPG	☒
76	23/10/18 16:20	General View	 Load JPG	☒
77	23/10/18 16:20	General View	 Load JPG	☒
78	23/10/18 16:20	General View	 Load JPG	☒
79	23/10/18 16:20	General View	 Load JPG	☒
80	23/10/18 16:20	General View	 Load JPG	☒
81	30/10/18 17:38	Reinspection Photo	 Load JPG	☒
82	30/10/18 17:38	Reinspection Photo	 Load JPG	☒
83	30/10/18 17:38	Reinspection Photo	 Load JPG	☒
84	30/10/18 17:38	Reinspection Photo	 Load JPG	☒
85	30/10/18 17:38	Reinspection Photo	 Load JPG	☒
86	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
87	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
88	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
89	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
90	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
91	31/10/18 17:38	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
92	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
93	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
94	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
95	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
96	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
97	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
98	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
99	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
100	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
101	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
102	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
103	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
104	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
105	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
106	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
107	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
108	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
109	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
110	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
111	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
112	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
113	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
114	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
115	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
116	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
117	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
118	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
119	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
120	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
121	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
122	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
123	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
124	31/10/18 17:38	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/10/18 14:13	DRIVING & CERT INSURANCE.pdf	 Load PDF	
2	23/10/18 14:13	ESTIMATE.pdf	 Load PDF	
3	23/10/18 16:14	NEW CAR PRICE .pdf	 Load PDF	
4	23/10/18 16:14	SLR 3073H - PARF_COE Rebate Enquiry.pdf	 Load PDF	
5	30/10/18 17:38	SUPPLEMENTARY.pdf	 Load PDF	
6	31/10/18 17:38	SUPPLEMENTARY 2.pdf	 Load PDF	
7	02/09/19 14:56	ESTIMATE, SUPP 1 & 2 MARKED.pdf	 Load PDF	
8	27/09/19 13:38	Workshop Invoice	 Load PDF	
9	27/09/19 13:38	Discharge Voucher	 Load PDF	

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	19/10/18 11:36	Video - Accident	 Load AVI	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	19/10/18 11:50	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	19/10/18 11:43	Accident Photo		☒
2	19/10/18 11:43	Accident Photo		☒
3	19/10/18 11:43	Accident Photo		☒
4	19/10/18 11:43	Accident Photo		☒
5	19/10/18 11:43	Accident Photo		☒
6	19/10/18 11:43	Accident Photo		☒
7	19/10/18 11:43	Accident Photo		☒
8	19/10/18 11:43	Accident Photo		☒
9	19/10/18 11:43	Accident Photo		☒
10	19/10/18 11:43	Accident Photo		☒
11	19/10/18 11:43	Accident Photo		☒
12	19/10/18 11:43	Accident Photo		☒
13	19/10/18 11:43	Accident Photo		☒
14	19/10/18 11:43	Accident Photo		☒
15	19/10/18 11:43	Accident Photo		☒
16	19/10/18 11:43	Accident Photo		☒
17	19/10/18 11:43	Accident Photo		☒
18	19/10/18 11:45	ACCIDENT SCENE PHOTOS		☒
19	19/10/18 11:45	ACCIDENT SCENE PHOTOS		☒
20	19/10/18 11:45	ACCIDENT SCENE PHOTOS		☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	19/10/18 11:34	Sketch Plan		☒
2	19/10/18 11:34	Sketch Plan #2		☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18019103/ASBE2

Date: 27/09/2019

REFERENCE

Insured/Claimant: LI ZUOWEI Policy No: 1700037426
Date of Loss: 18/10/2018 Nature of Claim: OD Claim No: 3158783675SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR3073H**
Make & Model: AUDI A3, 999cc TFSI (A) Engine No: CHZ399301
Reg. Date: 08/08/2017 (Man. Year: 2017) Chassis No: WAUZZZ8V1J1003192
Colour: Black Odometer: 18162 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$97,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	62,418.76	42,311.64	20,107.12	32.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,764.00	12,624.00	4,140.00	24.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	79,182.76	54,935.64	24,247.12	30.62
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	78,882.76	54,635.64	24,247.12	30.74
+ GST 7.00/7.00% (S\$)	5,521.79	3,824.49	1,697.30	30.74
Nett Amount (S\$)	84,404.55	58,460.13	25,944.42	30.74

INSPECTION

Date of Assignment: 22/10/2018
Date Inspected: 22/10/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 21.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,739.00 FS	*1,391.20 FS
2	1		*FIXING PARTS FOR FRONT BUMPER	Not Necessary	161.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	66.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	140.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	460.00 FS	*- FS
6	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Not Necessary	508.00 FS	*- FS
7	2		*FRONT BUMPER COVER TRIM - LH / RH	Not Necessary	280.00 FS	*- FS
8	2		*FRONT WHEEL HOUSING LINER ADAPTER - LH / RH	Not Necessary	64.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,239.00 FS	*991.20 FS
10	1		*RADIATOR CLOSING LEMENT	Distorted	167.00 FS	*133.20 FS
11	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	328.00 FS	*- FS
12	1		*FOAM FILLER PIECE	Deformed	162.00 FS	*129.60 FS
13	1		*FRONT BUMPER SIDE REINFORCEMENT	Bent	633.00 FS	*506.00 FS
14	1		*FRONT BUMPER COVER	Cracked	105.00 FS	*83.60 FS
15	1		*STICKER FOR AIR CONDITIONER	Necessary	7.00 FS	*4.88 FS
16	1		*SIGN CAUTION	Necessary	12.00 FS	*9.28 FS
17	1		*FRONT FENDER - RH	Dented	746.00 FS	*596.80 FS
18	1		*FENDER ATTACHMENT PARTS	Not Necessary	62.00 FS	*- FS
19	1		*FRONT FENDER BRACKET - RH	Damaged	34.00 FS	*26.64 FS
20	1		*FRONT FENDER BRACE - RH	Damaged	84.00 FS	*67.04 FS
21	1		*BONNET	Distorted	2,755.00 FS	*2,204.00 FS
22	1		*BONNET ATTACHMENT PARTS	Not Necessary	141.00 FS	*- FS
23	2		*BONNET LID HINGE - LH / RH	Bent	106.00 FS	*84.64 FS
24	2		*BONNET STOP BUFFER	Not Necessary	9.00 FS	*- FS
25	1		*GAS FILLED STRUT	Not Necessary	105.00 FS	*- FS
26	1		*BONNET CATCH HOOK	Bent	78.00 FS	*62.24 FS
27	2		*BONNET STRIKER - LH / RH	Bent	192.00 FS	*152.96 FS
28	1		*EDGE PROTECTION	Necessary	24.00 FS	*18.88 FS
29	1		*BONNET CATCH HOOK	Bent	55.00 FS	*43.84 FS
30	2		*BONNET LID LOCK WITH MICRO	Damaged	353.00 FS	*282.40 FS
31	1		*BONNET BOWDEN CABLE	Damaged	50.00 FS	*40.00 FS
32	1		*BONNET LID LOCK CABLE	Damaged	64.00 FS	*51.12 FS
33	1		*BONNET COVER	Necessary	9.00 FS	*6.88 FS
34	2		*BONNET LOCK LATCH COVER	Not Necessary	7.00 FS	*- FS
35	1		*SIGNAL HORN - HIGH TONE	Not Necessary	177.00 FS	*- FS
36	1		*SIGNAL HORN - LOW TONE	Not Necessary	177.00 FS	*- FS
37	2		*LED HEADLIGHT - LH / RH	Cracked	9,776.00 FS	*7,820.80 FS
38	2		*LED HEADLIGHT POWER MODULE	Not Necessary	1,329.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	2		*LED HEADLIGHT CONTROL UNIT	Not Necessary	972.00 FS	*- FS
40	2		*LED WITH HEAT SINK - LH / RH	Not Necessary	1,250.00 FS	*- FS
41	2		*HEADLIGHT CYLINDER - LH / RH	Not Necessary	246.00 FS	*- FS
42	1		*HEADLIGHT WASHER HOSE	Not Necessary	57.00 FS	*- FS
43	1		*WASH WATER RESERVOIR	Not Necessary	177.00 FS	*- FS
44	1		*LOCK CARRIER	Distorted	638.00 FS	*510.00 FS
45	1		*A/C CONDENSER	Distorted	468.00 FS	*374.00 FS
46	1		*REFRIGERANT LINE FOR A/C CONDENSER	Not Necessary	582.00 FS	*- FS
47	1		*REFRIGERANT LINE FOR A/C COMPRESSOR	Not Necessary	447.00 FS	*- FS
48	1		*COOLER FOR COOLANT	Bent	828.00 FS	*662.40 FS
49	1		*ADDITIONAL COOLER FOR COOLANT	Bent	639.20 FS	*639.20 FS
50	4		*COOLANT CONCENTRATE 1.5 LTR	Necessary	133.00 FS	*65.28 FS
51	1		*RADIATOR FAN	Distorted	1,425.00 FS	*1,140.00 FS
52	2		*AIR GUIDE - LH / RH	Cracked	40.00 FS	*31.84 FS
53	1		*RADIATOR CORE SUPPORT SEAL - RH OUTER	Necessary	7.00 FS	*5.12 FS
54	1		*RADIATOR CORE SUPPORT AIR DUCT - UPPER CENTRE	Damaged	10.00 FS	*7.68 FS
55	1		*RADIATOR CORE SUPPORT AIR DUCT	Damaged	59.00 FS	*46.80 FS
56	1		*AIR FILTER	Cracked	242.00 FS	*193.60 FS
57	1		*SPRING BAND CLAMP	Not Necessary	18.00 FS	*- FS
58	1		*FRONT WINDSCREEN	Cracked	953.00 FS	*762.00 FS
59	1		*GEL FOIL FOR RAIN SENSOR	Necessary	127.00 FS	*101.20 FS
60	1		*MIRROR INSIDE CLAMP	Not Necessary	19.00 FS	*- FS
61	2		*WATER DEFLECTOR STRIP - LH / RH	Not Necessary	160.00 FS	*- FS
62	1		*FRONT FENDER - LH	Buckled	746.00 FS	*596.80 FS
63	1		*FENDER ATTACHMENT PARTS	Not Necessary	62.00 FS	*- FS
64	1		*FRONT FENDER BRACKET - LH	Damaged	34.00 FS	*26.64 FS
65	1		*FRONT FENDER BRACE - LH	Not Necessary	84.00 FS	*- FS
66	1		*PLEUM CHAMBER COVER	Deformed	156.00 FS	*124.80 FS
67	2		*BONNET SIDE SEAL - LH / RH	Not Necessary	72.00 FS	*- FS
68	1		*INTAKE MANIFOLD	Cracked	551.00 FS	*444.80 FS
69	3		*INTERCOOLER SEAL	Not Necessary	39.00 FS	*- FS
70	1		*CHARGE AIR COOLER	Dented	658.00 FS	*530.00 FS
71	1		*THROTTLE VALVE CONTROL ELEMENT	Not Necessary	953.00 FS	*- FS
72	1		*THROTTLE VALVE SEAL	Not Necessary	16.00 FS	*- FS
73	1		*RETAINING BAR	Not Necessary	14.00 FS	*- FS
74	1		*FRONT W/S SEALANT	Necessary	200.00 FS	*200.00 FS
75	1		*FRONT NO. PLATE	Bent	25.00 FS	*25.00 FS
76	1		*AIR BAG UNIT FOR STEERING WHEEL	Activated	3,111.00 FS	*2,488.80 FS
77	1		*AIRBAG UNIT	Activated	4,060.00 FS	*3,248.00 FS
78	2		*HEAD AIRBAG UNIT - LH / RH	Activated	3,384.00 FS	*2,707.20 FS
79	1		*KNEE AIRBAG UNIT	Activated	1,692.00 FS	*1,353.60 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
80	1		*DASH BOARD LOWER BOTTOM TRIM	Not Necessary	397.00 FS	*- FS
81	1		*AIR BAG CONTROL UNIT	Activated	1,538.00 FS	*1,230.40 FS
82	1		*CRASH SENSOR AIR BAG	Activated	716.00 FS	*572.40 FS
83	2		*THREE POINT AUTOMATIC SEAT - LH / RH	Activated	1,912.00 FS	*1,529.60 FS
84	2		*SEAT BELT HEIGHT ADJUSTER	Damaged	343.00 FS	*137.20 FS
85	1		*DASH BOARD WITH AIR DUCT	Torn	3,729.00 FS	*2,983.20 FS
86	1		*MOULDED HEADLINER	Crumpled	1,551.00 FS	*1,240.80 FS
87	1		*FRONT GAB HANDLE FOLDING	Not Necessary	248.00 FS	*- FS
88	2		*REAR GAB HANDLE FOLDING - LH / RH	Damaged	248.00 FS	*99.20 FS
89	2		*A PILLAR TRIM - LH / RH	Cut	282.00 FS	*224.80 FS
90	1		*COOLANT HOSE WITH QUICK RELEASE COUPLING	Cut	182.80 FS	*182.80 FS
91	1		*WIRING CONNETOR FOR ALTERNATOR	Cracked	6.24 FS	*6.24 FS
92	1		*NON RETURN VALVE	Damaged	40.16 FS	*40.16 FS
93	1		*WATER RESERVOIR	Repeated	141.60 FS	*141.60 FS
94	1		*WATER RESERVOIR END CAP	Missing	14.24 FS	*14.24 FS
95	1		*WATER RESERVOIR STRAINER	Missing	14.00 FS	*14.00 FS
96	1		*RADIATOR MOUNT BRACKET	Necessary	59.36 FS	*59.36 FS
97	1		*RADIATOR BUSH LOWER	Necessary	13.44 FS	*13.44 FS
98	1		*RADIATOR SEALING STRIP	Cut	11.04 FS	*11.04 FS
99	1		*INTAKE AIR DUCT	Cracked	20.32 FS	*20.32 FS
100	1		*AIR GUIDE	Cracked	39.76 FS	*39.76 FS
101	1		*VACUUM HOSE WITH NON-RETURN VALVE	Cracked	278.40 FS	*278.40 FS
102	1		*BONNET INSULATOR	Deformed	153.20 FS	*153.20 FS
103	1		*BONNET INSULATOR SCREW	Necessary	1.68 FS	*1.68 FS
104	1		*FENDER COVER	Necessary	28.16 FS	*28.16 FS
105	1		*FENDER COVER	Necessary	28.16 FS	*28.16 FS
106	1		*STEERING WHEEL	Cut	1,667.20 FS	*1,667.20 FS
107	1		*HEAD REST	Cut	496.80 FS	*496.80 FS
108	1		*SUNDRIES	Necessary	500.00 FS	*105.52 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 62,418.76 42,311.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,000.00	1,000.00
3	TO REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIR BAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING, BOTH CURTAIN BAGS AND KNEE AIRBAG	New	3,600.00	3,600.00
4	TO RENEW FRONT WINDSCREEN	New	480.00	480.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,000.00	4,000.00
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND BOTH A-PILLAR	New	4,700.00	2,800.00
7	TO CARRY OUT WHEEL ALIGNMENT	New	240.00	0.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (S\$)			16,764.00	12,624.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >